



In cooperation with Kentucky Agricultural Experiment Station, Warren County Soil Conservation District, and University of Kentucky

## Soil Survey of Warren County, Kentucky



## **How To Use This Soil Survey**

#### **General Soil Map**

The general soil map, which is a color map, shows the survey area divided into groups of associated soils called general soil map units. This map is useful in planning the use and management of large areas.

#### **Detailed Soil Maps**


The detailed soil maps can be useful in planning the use and management of small areas.


To find information about your area of interest, locate that area


on the **Index to Map Sheets**. Note the number of the map sheet and turn to that sheet.

Locate your area of interest on the map sheet. Note the map unit symbols that are in that area. Turn to the **Contents**, which lists the map units by symbol and name and shows the page where each map unit is described.


The **Contents** shows which table has data on a specific land use for each detailed soil map unit. Also see the **Contents** for sections of this publication that may address your specific needs.







MAP SHEET



AREA OF INTEREST

NOTE: Map unit symbols in a soil survey may consist only of numbers or letters, or they may be a combination of numbers and letters.

This soil survey is a publication of the National Cooperative Soil Survey, a joint effort of the United States Department of Agriculture and other Federal agencies, State agencies including the Agricultural Experiment Stations, and local agencies. The Natural Resources Conservation Service (formerly the Soil Conservation Service) has leadership for the Federal part of the National Cooperative Soil Survey.

Major fieldwork for this soil survey was completed in August 2001. Soil names and descriptions were approved in January 2004. Unless otherwise indicated, statements in this publication refer to conditions in the survey area in 2001. This survey was made cooperatively by the Natural Resources Conservation Service, the Kentucky Agricultural Experiment Station, the Warren County Soil Conservation District, and the University of Kentucky. It is part of the technical assistance furnished to the Warren County Soil Conservation District.

Soil maps in this survey may be copied without permission. Enlargement of these maps, however, could cause misunderstanding of the detail of mapping. If enlarged, maps do not show the small areas of contrasting soils that could have been shown at a larger scale.

The United States Department of Agriculture (USDA) prohibits discrimination in all of its programs on the basis of race, color, national origin, gender, religion, age, disability, political beliefs, sexual orientation, and marital or family status. (Not all prohibited bases apply to all programs.) Persons with disabilities who require alternative means for communication of program information (Braille, large print, audiotape, etc.) should contact the USDA's TARGET Center at 202-720-2600 (voice or TDD).

To file a complaint of discrimination, write USDA, Director, Office of Civil Rights, Room 326W, Whitten Building, 14th and Independence Avenue SW, Washington, DC 20250-9410, or call 202-720-5964 (voice or TDD). USDA is an equal opportunity provider and employer.

Cover: An area of Crider silt loam, 6 to 12 percent slopes. This soil is well suited to hay production. Livestock management is an important agricultural enterprise in Warren County.

Additional information about the Nation's natural resources is available on the Natural Resources Conservation Service home page on the World Wide Web. The address is http://www.nrcs.usda.gov.

## **Contents**

Cover 1	CuC—Crider-Urban land complex, 6 to 12
How To Use This Soil Survey3	percent slopes34
Contents5	DAM—Dam, large35
Foreword 9	Du—Dunning silty clay loam, ponded
General Nature of the Survey Area 11	EkB—Elk silt loam, 2 to 6 percent slopes,
How This Survey Was Made12	rarely flooded36
General Soil Map Units15	EpB—Epley silt loam, 2 to 6 percent slopes 37
Detailed Soil Map Units17	FeB—Fredonia-Vertrees complex, 2 to 6
BaB—Baxter gravelly silt loam, 2 to 6 percent	percent slopes, rocky38
slopes18	FeC—Fredonia-Vertrees complex, 6 to 12
BaC—Baxter gravelly silt loam, 6 to 12 percent	percent slopes, very rocky
slopes 18	FnB—Fredonia-Vertrees-Urban land complex,
BaD—Baxter gravelly silt loam, 12 to 20	2 to 6 percent slopes, rocky40
percent slopes19	FnC—Fredonia-Vertrees-Urban land complex,
BaE—Baxter gravelly silt loam, 20 to 30	6 to 12 percent slopes, very rocky 40
percent slopes20	FnC2—Fredonia-Vertrees-Urban land complex,
BbC3—Baxter gravelly silty clay loam, 6 to 12	6 to 12 percent slopes, eroded, rocky 41
percent slopes, severely eroded	FrC—Frondorf silt loam, 6 to 12 percent
BbD3—Baxter gravelly silty clay loam, 12 to	slopes42
20 percent slopes, severely eroded 22	FrD—Frondorf silt loam, 12 to 20 percent
BrB—Baxter-Urban land complex, 2 to 6	slopes43
percent slopes23	Gr—Grigsby sandy loam, frequently flooded 44
BrC—Baxter-Urban land complex, 6 to 12	HaB—Hammack silt loam, 2 to 6 percent
percent slopes23	slopes45
BrD—Baxter-Urban land complex, 12 to 20	La—Lawrence silt loam, rarely flooded 46
percent slopes25	Ld—Lindside silt loam, frequently flooded 46
CaB—Caneyville silt loam, 2 to 6 percent	Me—Melvin silt loam, frequently flooded 48
slopes25	Ne—Newark silt loam, frequently flooded 49
CaC—Caneyville silt loam, 6 to 12 percent	Nf—Newark silt loam, ponded
slopes 26	NhA—Nicholson silt loam, 0 to 2 percent
CaC3—Caneyville silty clay, 6 to 12 percent	slopes50
slopes, severely eroded27	NhB—Nicholson silt loam, 2 to 6 percent
CnD—Caneyville-Rock outcrop complex, 6 to	slopes51
20 percent slopes28	NhC—Nicholson silt loam, 6 to 12 percent
CnF—Caneyville-Rock outcrop complex, 20 to	slopes 52
60 percent slopes28	No—Nolin silt loam, frequently flooded 53
CoD—Caneyville-Urban land-Rock outcrop	Np—Nolin silt loam, ponded54
complex, 6 to 20 percent slopes30	OtA—Otwood silt loam, 0 to 2 percent slopes,
CoE—Caneyville-Urban land-Rock outcrop	rarely flooded54
complex, 20 to 30 percent slopes31	OtB—Otwood silt loam, 2 to 6 percent slopes,
CrB—Crider silt loam, 2 to 6 percent slopes 31	rarely flooded55
CrC—Crider silt loam, 6 to 12 percent slopes 33	PbA—Pembroke silt loam, 0 to 2 percent
CuB—Crider-Urban land complex, 2 to 6	slopes 57
percent slopes34	PeA—Pembroke-Urban land complex, 0 to 2
	percent slopes58

Pm—Pits, loamy, frequently flooded 58	Engineering Index Properties	87
Pq—Pits, quarry 59	Physical Properties	
RaF—Ramsey-Frondorf complex, 20 to 60	Chemical Properties	
percent slopes59	Water Features	
Ro—Robertsville silt loam, ponded	Soil Features	90
RxF—Rock outcrop-Caneyville complex, 20 to	Classification of the Soils	93
60 percent slopes61	Soil Series and Their Morphology	93
SaA—Sadler silt loam, 0 to 2 percent slopes 61	Baxter Series	
SaB—Sadler silt loam, 2 to 6 percent slopes 62	Caneyville Series	95
UaC—Udorthents, 0 to 20 percent slopes 63	Crider Series	
UaD—Udorthents, refuse substratum, 0 to 25	Dunning Series	96
percent slopes63	Elk Series	97
Ub—Urban land-Udorthents complex, 0 to 12	Epley Series	97
percent slopes64	Fredonia Series	
Uc—Urban land-Udorthents complex, clayey	Frondorf Series	99
substratum, hard bedrock 0-5 feet, 0 to 12	Grigsby Series	100
percent slopes65	Hammack Series	
Ud—Urban land-Udorthents complex, clayey	Lawrence Series	101
substratum, hard bedrock >5 feet, 0 to 12	Lindside Series	102
percent slopes66	Melvin Series	103
Us—Urban land-Udorthents complex,	Newark Series	103
smoothed, 0 to 15 percent slopes 67	Nicholson Series	104
VrC3—Vertrees silty clay loam, 6 to 12	Nolin Series	105
percent slopes, severely eroded	Otwood Series	105
VtC3—Vertrees-Urban land complex, 6 to 12	Pembroke Series	106
percent slopes, severely eroded	Ramsey Series	107
W—Water69	Robertsville Series	
WeB-Wellston silt loam, 2 to 6 percent	Sadler Series	109
slopes 69	Vertrees Series	110
WeC2—Wellston silt loam, 6 to 12 percent	Wellston Series	111
slopes, eroded70	Zanesville Series	111
ZaB—Zanesville silt loam, 2 to 6 percent	References	113
slopes71	Glossary	115
ZaC2—Zanesville silt loam, 6 to 12 percent	Tables	125
slopes, eroded72	Table 1.—Temperature and Precipitation	126
ZuB—Zanesville-Urban land complex, 2 to 6	Table 2.—Freeze Dates in Spring and Fall	
percent slopes73	Table 3.—Growing Season	127
Use and Management of the Soils75	Table 4.—Acreage and Proportionate Extent	
Interpretive Ratings75	of the Soils	128
Crops and Pasture75	Table 5.—Land Capability and Yields per Acre	
Forest Productivity and Management78	of Crops	
Recreation79	Table 6.—Land Capability and Yields per Acre	
Wildlife Habitat81	of Pasture and Hay	133
Engineering 82	Table 7.—Prime Farmland	
Soil Properties87	Table 8.—Forest Productivity	
	•	

Table 9.—Forestland Management, Part I	Table 14.—Building Site Interpretations for Urban Areas, Part II
Table 11.—Recreation Interpretations for	Table 19.—Engineering Index Properties 232
Urban Areas, Part II177 Table 12.—Wildlife Habitat180	Table 20.—Physical Properties of the Soils 241 Table 21.—Physical Properties of the Soils in
Table 13.—Building Site Development,	Urban Areas246
Part I 184	Table 22.—Chemical Properties of the Soils 249
Table 13.—Building Site Development,	Table 23.—Water Features
Part II 189	Table 24.—Soil Features
Table 14.—Building Site Interpretations for	Table 25.—Soil Features for Urban Areas 262
Urban Areas, Part I195	Table 26 —Classification of the Soils 264

Issued 2004

#### **Foreword**

This soil survey contains information that affects land use planning in this survey area. It contains predictions of soil behavior for selected land uses. The survey also highlights soil limitations, improvements needed to overcome the limitations, and the impact of selected land uses on the environment.

This soil survey is designed for many different users. Farmers, foresters, and agronomists can use it to evaluate the potential of the soil and the management needed for maximum food and fiber production. Planners, community officials, engineers, developers, builders, and home buyers can use the survey to plan land use, select sites for construction, and identify special practices needed to ensure proper performance. Conservationists, teachers, students, and specialists in recreation, wildlife management, waste disposal, and pollution control can use the survey to help them understand, protect, and enhance the environment.

Various land use regulations of Federal, State, and local governments may impose special restrictions on land use or land treatment. The information in this report is intended to identify soil properties that are used in making various land use or land treatment decisions. Statements made in this report are intended to help the land users identify and reduce the effects of soil limitations on various land uses. The landowner or user is responsible for identifying and complying with existing laws and regulations.

Great differences in soil properties can occur within short distances. Some soils are seasonally wet or subject to flooding. Some are shallow to bedrock. Some are too unstable to be used as a foundation for buildings or roads. Clayey or wet soils are poorly suited to use as septic tank absorption fields. A high water table makes a soil poorly suited to basements or underground installations.

These and many other soil properties that affect land use are described in this soil survey. Broad areas of soils are shown on the general soil map. The location of each soil is shown on the detailed soil maps. Each soil in the survey area is described. Information on specific uses is given for each soil. Help in using this publication and additional information are available at the local office of the Natural Resources Conservation Service or the Cooperative Extension Service.

David G. Sawyer State Conservationist Natural Resources Conservation Service

## Soil Survey of Warren County, Kentucky

By Michael J. Mitchell, Natural Resources Conservation Service

Fieldwork by Michael J. Mitchell, Natural Resources Conservation Service

United States Department of Agriculture, Natural Resources Conservation Service, in cooperation with

Kentucky Agricultural Experiment Station, Warren County Soil Conservation District, and University of Kentucky

Warren County is in the south-central part of Kentucky (fig. 1). It has a total area of about 547 square miles, or 350,496 acres. In 2000, according to the U.S. Census, the county had a population of 92,522 (4). Bowling Green, the county seat, is near the center of the county and has a population of about 48,300.

This soil survey updates the survey of Warren County published in 1981 *(5)*. It provides additional information and has larger maps, which show the soils in greater detail.

# Frankfort

Figure 1.—Location of Warren County in Kentucky.

#### **General Nature of the Survey Area**

This section contains information on the climate of Warren County. Information about the history of the survey area can be accessed at http://www.wku.edu/Library/200Years/cntyhist.htm (3).

#### Climate

Table 1 gives data on temperature and precipitation for the survey area as recorded at Bowling Green, Kentucky, in the period 1961 to 1990. Table 2 shows probable dates of the first freeze in fall and the last freeze in spring. Table 3 provides data on length of the growing season.

In winter, the average temperature is 35.9 degrees F and the average daily minimum temperature is 26.4 degrees. The lowest temperature on record, which occurred at Bowling Green on January 23, 1963, is -21 degrees. In summer, the average temperature is 76.1 degrees and the average daily maximum

temperature is 87.1 degrees. The highest recorded temperature, which occurred at Bowling Green on June 29, 1936, is 108 degrees.

Growing degree days are shown in table 1. They are equivalent to "heat units." During the month, growing degree days accumulate by the amount that the average temperature each day exceeds a base temperature (40 degrees F). The normal monthly accumulation is used to schedule single or successive plantings of a crop between the last freeze in spring and the first freeze in fall.

The average annual precipitation is 50.95 inches. Of this, 28.4 inches, or about 56 percent, usually falls in April through October. The growing season for most crops falls within this period. The heaviest 1-day rainfall during the period of record was 11.02 inches on April 29, 1937. Thunderstorms occur on about 53 days each year, and most occur between May and August.

The average seasonal snowfall is 12.8 inches. The greatest snow depth at any one time during the period of record was 13 inches on January 20, 1978. On the average, 12 days of the year have at least 1 inch of snow on the ground. The heaviest 1-day snowfall on record was more than 18 inches.

The average relative humidity in midafternoon is about 57 percent. Humidity is higher at night, and the average at dawn is about 84 percent. The sun shines 64 percent of the time possible in summer and 43 percent in winter. The prevailing wind is from the south. Average windspeed is highest, 10 miles per hour, in March.

#### **How This Survey Was Made**

This survey was made to provide information about the soils and miscellaneous areas in the survey area. The information includes a description of the soils and miscellaneous areas and their location and a discussion of their suitability, limitations, and management for specified uses. Soil scientists observed the steepness, length, and shape of the slopes; the general pattern of drainage; the kinds of crops and native plants; and the kinds of bedrock. They dug many holes to study the soil profile, which is the sequence of natural layers, or horizons, in a soil. The profile extends from the surface down into the unconsolidated material in which the soil formed. The unconsolidated material is devoid of roots and other living organisms and has not been changed by other biological activity.

The soils and miscellaneous areas in the survey area are in an orderly pattern that is related to the geology, landforms, relief, climate, and natural vegetation of the area. Each kind of soil and miscellaneous area is associated with a particular kind of landform or with a segment of the landform. By observing the soils and miscellaneous areas in the survey area and relating their position to specific segments of the landform, a soil scientist develops a concept or model of how they were formed. Thus, during mapping, this model enables the soil scientist to predict with a considerable degree of accuracy the kind of soil or miscellaneous area at a specific location on the landscape.

Commonly, individual soils on the landscape merge into one another as their characteristics gradually change. To construct an accurate soil map, however, soil scientists must determine the boundaries between the soils. They can observe only a limited number of soil profiles. Nevertheless, these observations, supplemented by an understanding of the soil-

vegetation-landscape relationship, are sufficient to verify predictions of the kinds of soil in an area and to determine the boundaries.

Soil scientists recorded the characteristics of the soil profiles that they studied. They noted soil color, texture, size and shape of soil aggregates, kind and amount of rock fragments, distribution of plant roots, reaction, and other features that enable them to identify soils. After describing the soils in the survey area and determining their properties, the soil scientists assigned the soils to taxonomic classes (units). Taxonomic classes are concepts. Each taxonomic class has a set of soil characteristics with precisely defined limits. The classes are used as a basis for comparison to classify soils systematically. Soil taxonomy, the system of taxonomic classification used in the United States, is based mainly on the kind and character of soil properties and the arrangement of horizons within the profile. After the soil scientists classified and named the soils in the survey area, they compared the individual soils with similar soils in the same taxonomic class in other areas so that they could confirm data and assemble additional data based on experience and research.

While a soil survey is in progress, samples of some of the soils in the area generally are collected for laboratory analyses and for engineering tests. Soil scientists interpret the data from these analyses and tests as well as the field-observed characteristics and the soil properties to determine the expected behavior of the soils under different uses. Interpretations for all of the soils are field tested through observation of the soils in different uses and under different levels of management. Some interpretations are modified to fit local conditions, and some new interpretations are developed to meet local needs. Data are assembled from other sources, such as research information, production records, and field experience of specialists. For example, data on crop yields under defined levels of management are assembled from farm records and from field or plot experiments on the same kinds of soil.

Predictions about soil behavior are based not only on soil properties but also on such variables as climate and biological activity. Soil conditions are predictable over long periods of time, but they are not predictable from year to year. For example, soil scientists can predict with a fairly high degree of accuracy that a given soil will have a high water table within certain depths in most years, but they cannot predict that a high water table will always be at a specific level in the soil on a specific date.

After soil scientists located and identified the

significant natural bodies of soil in the survey area, they drew the boundaries of these bodies on aerial photographs and identified each as a specific map unit. Aerial photographs show trees, buildings, fields, roads, and rivers, all of which help in locating boundaries accurately.

### **General Soil Map Units**

The general soil map shows broad areas that have a distinctive pattern of soils, relief, and drainage. Each map unit on the general soil map is a unique natural landscape. Typically, it consists of one or more major soils or miscellaneous areas and some minor soils or miscellaneous areas. It is named for the major soils or miscellaneous areas. The components of one map unit can occur in another but in a different pattern.

The general soil map can be used to compare the suitability of large areas for general land uses. Areas of suitable soils can be identified on the map.

Likewise, areas where the soils are not suitable can be identified.

Because of its small scale, the map is not suitable for planning the management of a farm or field or for selecting a site for a road or building or other structure. The soils in any one map unit differ from place to place in slope, depth, drainage, and other characteristics that affect management. The individual soil phases and characteristics are described in the "Detailed Soil Map Units" section.

### **Detailed Soil Map Units**

The map units delineated on the detailed soil maps represent the soils or miscellaneous areas in the survey area. The map unit descriptions in this section, along with the maps, can be used to determine the suitability and potential of a unit for specific uses. They also can be used to plan the management needed for those uses.

A map unit delineation on a soil map represents an area dominated by one or more major kinds of soil or miscellaneous areas. A map unit is identified and named according to the taxonomic classification of the dominant soils. Within a taxonomic class there are precisely defined limits for the properties of the soils. On the landscape, however, the soils are natural phenomena, and they have the characteristic variability of all natural phenomena. Thus, the range of some observed properties may extend beyond the limits defined for a taxonomic class. Areas of soils of a single taxonomic class rarely, if ever, can be mapped without including areas of other taxonomic classes. Consequently, every map unit is made up of the soils or miscellaneous areas for which it is named and some minor components that belong to taxonomic classes other than those of the major soils.

Most minor soils have properties similar to those of the dominant soil or soils in the map unit, and thus they do not affect use and management. These are called noncontrasting, or similar, components. They may or may not be mentioned in a particular map unit description. Other minor components, however, have properties and behavioral characteristics divergent enough to affect use or to require different management. These are called contrasting, or dissimilar, components. They generally are in small areas and could not be mapped separately because of the scale used. Some small areas of strongly contrasting soils or miscellaneous areas are identified by a special symbol on the maps. The contrasting components are mentioned in the map unit descriptions. A few areas of minor components may not have been observed, and consequently they are not mentioned in the descriptions, especially where the pattern was so complex that it was impractical to make enough observations to identify all the soils and miscellaneous areas on the landscape.

The presence of minor components in a map unit in no way diminishes the usefulness or accuracy of the data. The objective of mapping is not to delineate pure taxonomic classes but rather to separate the landscape into landforms or landform segments that have similar use and management requirements. The delineation of such segments on the map provides sufficient information for the development of resource plans. If intensive use of small areas is planned, however, onsite investigation is needed to define and locate the soils and miscellaneous areas.

An identifying symbol precedes the map unit name in the map unit descriptions. Each description includes general facts about the unit and gives the principal hazards and limitations to be considered in planning for specific uses.

Soils that have profiles that are almost alike make up a *soil series*. Except for differences in texture of the surface layer, all the soils of a series have major horizons that are similar in composition, thickness, and arrangement.

Soils of one series can differ in texture of the surface layer, slope, stoniness, salinity, degree of erosion, and other characteristics that affect their use. On the basis of such differences, a soil series is divided into *soil phases*. Most of the areas shown on the detailed soil maps are phases of soil series. The name of a soil phase commonly indicates a feature that affects use or management. For example, Baxter gravelly silty clay loam, 6 to 12 percent slopes, severely eroded, is a phase of the Baxter series.

Some map units are made up of two or more major soils or miscellaneous areas. These map units are complexes. A *complex* consists of two or more soils or miscellaneous areas in such an intricate pattern or in such small areas that they cannot be shown separately on the maps. The pattern and proportion of the soils or miscellaneous areas are somewhat similar in all areas. Crider-Urban land complex, 6 to 12 percent slopes, is an example.

This survey includes *miscellaneous areas*. These areas have little or no soil material and support little or no vegetation, or they define unique soil characteristics in the survey area that are relevant to the process of urbanization. Urban land-Udorthents

complex, clayey substratum, hard bedrock 0-5 feet, 0 to 12 percent slopes, is an example.

Table 4 gives the acreage and proportionate extent of each map unit. Other tables give properties of the soils and the limitations, capabilities, and potentials for many uses. The Glossary defines many of the terms used in describing the soils or miscellaneous areas.

## BaB—Baxter gravelly silt loam, 2 to 6 percent slopes

#### Setting

Landscape position: Undulating ridges

Size of areas: 3 to 51 acres Slope range: 2 to 6 percent

Parent material: Residuum from limestone

#### Composition

Baxter soil and similar inclusions: 90 percent

#### Contrasting Inclusions

Nicholson, Hammack, Crider, Caneyville, and Fredonia soils

#### Typical Profile

Surface layer:

0 to 8 inches—brown gravelly silt loam

Subsoil:

8 to 15 inches—yellowish red gravelly silty clay loam

15 to 61 inches—red gravelly clay 61 to 81 inches—red gravelly clay

#### Soil Properties and Qualities

Drainage class: Well drained Permeability: Moderately slow

Available water capacity: Moderate or high Soil reaction: Strongly acid or very strongly acid

High water table: None

Depth to bedrock: More than 60 inches

#### Use and Management

#### Cropland

Suitability: Well suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Suited

Management measures and considerations:

- Structures should be designed so that they conform to the natural slope.
- Topsoil should be stockpiled and used to reclaim areas that are disturbed during construction.
- Design modifications that overcome the shrink-swell potential are needed in areas of deep excavations.
- Careful use of equipment and good design practices prevent the runoff of off-site sediments.

#### Septic tank absorption fields

Suitability: Suited

Management measures and considerations:

- This soil is limited for septic systems because of the moderately slow permeability and the moderate shrink-swell potential in the lower part of the subsoil.
- An onsite investigation is needed to determine a suitable site.

#### Interpretive Groups

Land capability classification: 2e

## BaC—Baxter gravelly silt loam, 6 to 12 percent slopes

#### Setting

Landscape position: Rolling ridgetops and side slopes of depressions

Size of areas: 3 to 400 acres Slope range: 6 to 12 percent

Parent material: Residuum from limestone

#### Composition

Baxter soil and similar inclusions: 85 percent

#### **Contrasting Inclusions**

 Nicholson, Hammack, Crider, Caneyville, and Fredonia soils

#### Typical Profile

Surface layer:

0 to 8 inches—brown gravelly silt loam

Subsoil:

8 to 15 inches—yellowish red gravelly silty clay loam 15 to 61 inches—red gravelly clay

61 to 81 inches—red gravelly clay

#### Soil Properties and Qualities

Drainage class: Well drained Permeability: Moderately slow

Available water capacity: Moderate or high Soil reaction: Strongly acid or very strongly acid

High water table: None

Depth to bedrock: More than 60 inches

#### Use and Management

#### Cropland

Suitability: Suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Suited

Management measures and considerations:

• Structures should be designed so that they conform to the natural slope.

- Topsoil should be stockpiled and used to reclaim areas that are disturbed during construction.
- Design modifications that overcome the shrink-swell potential are needed in areas of deep excavations.
- Careful use of equipment and good design practices prevent the runoff of off-site sediments.

#### Septic tank absorption fields

Suitability: Suited

Management measures and considerations:

- This soil is limited for septic systems because of the moderately slow permeability, the slope, and the moderate shrink-swell potential in the lower part of the subsoil.
- An onsite investigation is needed to determine a suitable site.

#### Interpretive Groups

Land capability classification: 3e

## BaD—Baxter gravelly silt loam, 12 to 20 percent slopes

#### Setting

Landscape position: Hillsides and side slopes of

depressions

Size of areas: 3 to 261 acres Slope range: 12 to 20 percent

Parent material: Residuum from limestone

#### Composition

Baxter soil and similar inclusions: 85 percent

#### Contrasting Inclusions

- Caneyville and Fredonia soils
- Areas that have rock outcrop at the surface

#### Typical Profile

Surface layer:

0 to 8 inches—brown gravelly silt loam

Subsoil:

8 to 15 inches—yellowish red gravelly silty clay loam

15 to 61 inches—red gravelly clay 61 to 81 inches—red gravelly clay

#### Soil Properties and Qualities

Drainage class: Well drained Permeability: Moderately slow Available water capacity: Moderate

Soil reaction: Strongly acid or very strongly acid

High water table: None

Depth to bedrock: More than 60 inches

#### Use and Management

#### Cropland

Suitability: Poorly suited

Management measures and considerations:

- A management plan that includes long rotations in grass and legumes is needed to reduce the effects of erosion.
- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops are necessary in areas used as cropland.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Suited

Management measures and considerations:

- The slope limits some management practices.
- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Suited

Management measures and considerations:

- Some equipment use may be limited because of the slope.
- Chemical or mechanical treatments may be needed to decrease plant competition.
- See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Poorly suited

Management measures and considerations:

- Structures should be designed so that they conform to the natural slope.
- Topsoil should be stockpiled and used to reclaim areas that are disturbed during construction.
- Design modifications that overcome the shrink-swell potential are needed in areas of deep excavations.
- Careful use of equipment and good design practices prevent the runoff of off-site sediments.

#### Septic tank absorption fields

Suitability: Poorly suited

Management measures and considerations:

• Increasing the size of the septic tank filter field helps to overcome the permeability limitation.

- Trench walls of filter fields may be smeared and sealed off if the system is constructed when soil is too wet
- An onsite investigation is needed to determine a suitable site.

#### Interpretive Groups

Land capability classification: 4e

## BaE—Baxter gravelly silt loam, 20 to 30 percent slopes

#### Setting

Landscape position: Hillsides and steep walls around

depressions

Size of areas: 3 to 22 acres Slope range: 20 to 30 percent

Parent material: Residuum from limestone

#### Composition

Baxter soil and similar inclusions: 80 percent

#### Contrasting Inclusions

- Caneyville and Fredonia soils
- Areas that have rock outcrop at the surface, in sinkholes

#### Typical Profile

Surface layer:

0 to 8 inches—brown gravelly silt loam

Subsoil:

8 to 15 inches—yellowish red gravelly silty clay loam

15 to 61 inches—red gravelly clay 61 to 81 inches—red gravelly clay

#### Soil Properties and Qualities

Drainage class: Well drained
Permeability: Moderately slow
Available water capacity: Moderate

Soil reaction: Strongly acid or very strongly acid

High water table: None

Depth to bedrock: More than 60 inches

#### Use and Management

#### Cropland

Suitability: Unsuited

Management measures and considerations:

• Because of the slope, erosion hazard, and other soil properties, this soil should not be used as cropland.

#### Pasture and hay

Suitability for pasture: Suited

Suitability for hay: Poorly suited

Management measures and considerations:

- Because of the slope, this soil is unsafe for the operation of farm equipment in harvesting operations.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Suited

Management measures and considerations:

- The slope limits the use of forestry equipment in many timber operations.
- Chemical or mechanical treatments may be needed to decrease plant competition.
- See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Unsuited

Management measures and considerations:

• The slope severely limits road designs and commercial and residential uses.

#### Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

- The slope limits commercial and residential uses.
- An onsite investigation is needed to determine a suitable site.

#### Interpretive Groups

Land capability classification: 6e

## BbC3—Baxter gravelly silty clay loam, 6 to 12 percent slopes, severely eroded

#### Setting

Landscape position: Side slopes and areas around the rims of depressions

Size of areas: 3 to 15 acres Slope range: 6 to 12 percent

Parent material: Residuum from limestone

#### Composition

Baxter soil and similar inclusions: 85 percent

#### **Contrasting Inclusions**

• Crider, Caneyville, Nicholson, Hammack, and Fredonia soils

#### Typical Profile

Surface layer:

0 to 3 inches—dark yellowish brown gravelly silty clay loam

Subsoil:

3 to 61 inches—red gravelly clay 61 to 81 inches—red gravelly clay

#### Soil Properties and Qualities

Drainage class: Well drained
Permeability: Moderately slow
Available water capacity: Moderate

Soil reaction: Strongly acid or very strongly acid

High water table: None

Depth to bedrock: More than 60 inches

#### Use and Management

#### Cropland

Suitability: Suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Suited

Management measures and considerations:

- Areas around sinkholes are unstable and have a considerable risk of collapse if used for dwellings.
- Structures should be designed so that they conform to the natural slope.
- Topsoil should be stockpiled and used to reclaim areas that are disturbed during construction.

- Design modifications that overcome the shrink-swell potential are needed in areas of deep excavations.
- An onsite investigation is needed to determine site suitability.

#### Septic tank absorption fields

Suitability: Suited

Management measures and considerations:

- This soil is limited for septic systems because of the moderately slow permeability, the slope, and the moderate shrink-swell potential in the lower part of the subsoil.
- An onsite investigation is needed to determine site suitability and design.

#### Interpretive Groups

Land capability classification: 4e

## BbD3—Baxter gravelly silty clay loam, 12 to 20 percent slopes, severely eroded

#### Setting

Landscape position: Side slopes and areas around the

rims of depressions
Size of areas: 3 to 30 acres
Slope range: 12 to 20 percent

Parent material: Residuum from limestone

#### Composition

Baxter soil and similar inclusions: 85 percent

#### Contrasting Inclusions

- · Caneyville and Fredonia soils
- Areas that have rock outcrop on the surface

#### Typical Profile

Surface layer:

0 to 3 inches—dark yellowish brown gravelly silty clay loam

Subsoil:

3 to 61 inches—red gravelly clay 61 to 81 inches—red gravelly clay

#### Soil Properties and Qualities

Drainage class: Well drained
Permeability: Moderately slow
Available water capacity: Moderate

Soil reaction: Strongly acid or very strongly acid

High water table: None

Depth to bedrock: More than 60 inches

#### Use and Management

#### Cropland

Suitability: Poorly suited

Management measures and considerations:

• Because of the slope, the past effects of erosion, and the shape and size of the map unit, this soil is poorly suited to cropland.

#### Pasture and hay

Suitability: Suited

Management measures and considerations:

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Poorly suited

Management measures and considerations:

- Areas around sinkholes are unstable and have a considerable risk of collapse if used for dwellings.
- Structures should be designed so that they conform to the natural slope.
- Topsoil should be stockpiled and used to reclaim areas that are disturbed during construction.
- Design modifications that overcome the shrink-swell potential are needed in areas of deep excavations.
- An onsite investigation is needed to determine site suitability.

#### Septic tank absorption fields

Suitability: Poorly suited

Management measures and considerations:

- This soil is limited for septic systems because of the moderately slow permeability, the slope, and the moderate shrink-swell potential in the lower part of the subsoil.
- An onsite investigation is needed to determine site suitability and design.

#### Interpretive Groups

Land capability classification: 6e

## BrB—Baxter-Urban land complex, 2 to 6 percent slopes

#### Setting

Location: In and around the city of Bowling Green

#### Composition

Baxter soil and similar inclusions: 60 percent Urban land: 30 percent

#### **Contrasting Inclusions**

 Nicholson, Crider, Caneyville, Nolin, Pembroke, Newark, and Fredonia soils; Udorthents; and areas of rock outcrop

#### Typical Profile

#### **Baxter**

Surface layer:

0 to 8 inches—brown gravelly silt loam

Subsoil:

8 to 15 inches—yellowish red gravelly silty clay loam 15 to 61 inches—red gravelly clay 61 to 81 inches—red gravelly clay

#### **Urban land**

Most of the Urban land consists of areas where 85 to 90 percent of the surface is covered by streets, buildings, parking lots, driveways, railroad yards, or airports. The remainder consists of cut and fill areas of soil material imported onto the site or disturbed in the process of urbanization.

#### Soil Properties and Qualities

• See the interpretations tables for map units in urban areas.

#### Use and Management

#### Residential and commercial structures

Suitability: Suited

Management measures and considerations:

- Designing structures that conform to the natural slope reduces the amount of cutting or filling needed.
- Topsoil may need to be stockpiled and used to reclaim areas that are disturbed during construction.
- Careful use of equipment and good site conservation measures prevent the discharge of sediment onto adjacent property or into streams.
- Soil compaction is a problem around construction sites. Sites may require aeration or deep tillage and reseeding.
- Yards may be subject to periods of flooding if the soil

is compacted. Shallow diversions may be needed to remove surface runoff or ponding in low areas.

- Modifications in the design of footings and basements that overcome the shrink-swell potential are needed in areas of deep excavations.
- Diverting runoff from gutters and driveways away from structures reduces the chance of differential settling or cracking of foundations caused by the shrink-swell potential.

#### Septic tank absorption fields

Suitability: Suited

Management measures and considerations:

- The Baxter soil is limited for septic systems because of the moderately slow permeability and the moderate shrink-swell potential in the lower part of the subsoil.
- Lot design for structures and driveways needs to allow sufficient area for a septic field.
- An onsite investigation is needed to determine a suitable site.

#### Interpretive Groups

Land capability classification: None assigned

## BrC—Baxter-Urban land complex, 6 to 12 percent slopes

#### Setting

Location: In and around the city of Bowling Green (fig. 2)

#### Composition

Baxter soil and similar inclusions: 55 percent Urban land: 30 percent

#### Contrasting Inclusions

• Nicholson, Crider, Caneyville, Nolin, Newark, and Fredonia soils; Udorthents; and areas of rock outcrop

#### Typical Profile

#### **Baxter**

Surface layer:

0 to 8 inches—brown gravelly silt loam

Subsoil:

8 to 15 inches—yellowish red gravelly silty clay loam 15 to 61 inches—red gravelly clay 61 to 81 inches—red gravelly clay

#### **Urban land**

Most of the Urban land consists of areas where 85 to 90 percent of the surface is covered by streets, buildings, parking lots, driveways, railroad yards, or



Figure 2.—An area of Baxter-Urban land complex, 6 to 12 percent slopes. This map unit is predominantly used for subdivision development.

airports. The remainder consists of cut and fill areas of soil material imported onto the site or disturbed in the process of urbanization.

#### Soil Properties and Qualities

• See the interpretations tables for map units in urban areas.

#### Use and Management

#### Residential and commercial structures

Suitability: Suited

Management measures and considerations:

- Designing structures that conform to the natural slope reduces the amount of cutting or filling needed.
- Topsoil may need to be stockpiled and used to reclaim areas that are disturbed during construction.
- Careful use of equipment and good site conservation measures prevent the discharge of sediment onto adjacent property or into streams.

- Soil compaction is a problem around construction sites. Sites may require aeration or deep tillage and reseeding.
- Yards may be subject to rill and gully erosion if the soil is compacted. Shallow diversions may be needed to remove surface runoff.
- Modifications in the design of footings and basements that overcome the shrink-swell potential are needed in areas of deep excavations.
- Diverting runoff from gutters and driveways away from structures reduces the chance of differential settling or cracking of foundations caused by the shrink-swell potential.

#### Septic tank absorption fields

Suitability: Suited

Management measures and considerations:

• The Baxter soil is limited for septic systems because of the moderately slow permeability and the moderate shrink-swell potential in the lower part of the subsoil.

- Lot design for structures and driveways needs to allow sufficient area for a septic field and conform to the slope.
- An onsite investigation is needed to determine a suitable site.

#### Interpretive Groups

Land capability classification: None assigned

## BrD—Baxter-Urban land complex, 12 to 20 percent slopes

#### Setting

Location: In and around the city of Bowling Green

#### Composition

Baxter soil and similar inclusions: 60 percent Urban land: 25 percent

#### Contrasting Inclusions

 Crider, Caneyville, and Fredonia soils; Udorthents; and areas of rock outcrop

#### Typical Profile

#### Baxter

Surface layer:

0 to 8 inches—brown gravelly silt loam

Subsoil:

8 to 15 inches—yellowish red gravelly silty clay loam 15 to 61 inches—red gravelly clay 61 to 81 inches—red gravelly clay

#### **Urban land**

Most of the Urban land consists of areas where 85 to 90 percent of the surface is covered by streets, buildings, parking lots, driveways, railroad yards, or airports. The remainder consists of cut and fill areas of soil material imported onto the site or disturbed in the process of urbanization.

#### Soil Properties and Qualities

• See the interpretations tables for map units in urban areas.

#### Use and Management

#### Residential and commercial structures

Suitability: Poorly suited

Management measures and considerations:

• The slope is a limitation affecting residential and commercial structures.

- Designing structures that conform to the natural slope reduces the amount of cutting or filling needed.
- Topsoil may need to be stockpiled and used to reclaim areas that are disturbed during construction.
- Careful use of equipment and good site conservation measures are needed to prevent the discharge of sediment onto adjacent property or into streams.
- Soil compaction is a problem around construction sites. Sites may require aeration or deep tillage and reseeding.
- Yards are subject to rill and gully erosion if the soil is compacted. Shallow diversions may be needed to remove surface runoff.
- Modifications in the design of footings and basements that overcome the shrink-swell potential are needed in areas of deep excavations.
- Diverting runoff from gutters and driveways away from structures reduces the chance of differential settling or cracking of foundations caused by the shrink-swell potential.

#### Septic tank absorption fields

Suitability: Suited

Management measures and considerations:

- The Baxter soil is limited for septic systems because of the slope, the moderately slow permeability, and the moderate shrink-swell potential in the lower part of the subsoil.
- Lot design for structures and driveways needs to allow sufficient area for a septic field and conform to the slope.
- An onsite investigation is needed to determine a suitable site.

#### Interpretive Groups

Land capability classification: None assigned

## CaB—Caneyville silt loam, 2 to 6 percent slopes

#### Setting

Landscape position: Undulating ridges Size of areas: 5 to 15 acres Slope range: 2 to 6 percent

Parent material: Residuum from limestone

#### Composition

Caneyville soil and similar inclusions: 85 percent

#### Contrasting Inclusions

• Nicholson, Pembroke, Crider, and Vertrees soils

#### Typical Profile

Surface layer:

0 to 6 inches-brown silt loam

Subsoil:

6 to 11 inches—yellowish red silty clay 11 to 21 inches—yellowish red clay 21 to 27 inches—dark reddish brown clay 27 inches—limestone bedrock

#### Soil Properties and Qualities

Drainage class: Well drained Permeability: Slow or very slow

Available water capacity: Moderate or low Soil reaction: Strongly acid or moderately acid

High water table: None

Depth to bedrock: 20 to 40 inches

#### Use and Management

#### Cropland

Suitability: Suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Suited

Management measures and considerations:

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Hay yields may be reduced in dry years because of a limited available water capacity.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Unsuited

Management measures and considerations:

 This soil is severely limited for dwellings because of the depth to bedrock, slow permeability, and shrinkswell potential.

#### Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• This soil is severely limited for septic systems because of the depth to bedrock, slow permeability, and shrink-swell potential in the lower part of the subsoil.

#### Interpretive Groups

Land capability classification: 3e

## CaC—Caneyville silt loam, 6 to 12 percent slopes

#### Setting

Landscape position: Rolling ridges Size of areas: 5 to 20 acres Slope range: 6 to 12 percent

Parent material: Residuum from limestone

#### Composition

Caneyville soil and similar inclusions: 85 percent

#### Contrasting Inclusions

· Crider, Baxter, and Vertrees soils

#### Typical Profile

Surface layer:

0 to 6 inches—brown silt loam

Subsoil:

6 to 11 inches—yellowish red silty clay 11 to 21 inches—yellowish red clay 21 to 27 inches—dark reddish brown clay 27 inches—limestone bedrock

#### Soil Properties and Qualities

Drainage class: Well drained Permeability: Slow or very slow

Available water capacity: Moderate or low Soil reaction: Strongly acid or moderately acid

High water table: None

Depth to bedrock: 20 to 40 inches

#### Use and Management

#### Cropland

Suitability: Poorly suited

Management measures and considerations:

• This soil is not suited to use as continuous cropland. It should be managed in a long rotation in which the soil is kept in vegetative cover for several seasons following cultivation.

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Suited

Management measures and considerations:

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Hay yields may be reduced in dry years because of a limited available water capacity.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Unsuited

Management measures and considerations:

 This soil is severely limited for dwellings because of the depth to bedrock, slow permeability, and shrinkswell potential.

#### Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

 This soil is severely limited for septic systems because of the depth to bedrock, slow permeability, and shrink-swell potential in the lower part of the subsoil.

#### Interpretive Groups

Land capability classification: 4e

## CaC3—Caneyville silty clay, 6 to 12 percent slopes, severely eroded

#### Setting

Landscape position: Rolling ridges Size of areas: 5 to 20 acres

Slope range: 6 to 12 percent

Parent material: Residuum from limestone

#### Composition

Caneyville soil and similar inclusions: 85 percent

#### Contrasting Inclusions

· Crider, Baxter, and Vertrees soils

#### Typical Profile

Surface layer:

0 to 3 inches—brown silty clay

Subsoil:

3 to 27 inches—yellowish red clay 27 inches—limestone bedrock

#### Soil Properties and Qualities

Drainage class: Well drained Permeability: Slow or very slow Available water capacity: Low

Soil reaction: Strongly acid or moderately acid

High water table: None

Depth to bedrock: 20 to 40 inches

#### Use and Management

#### Cropland

Suitability: Unsuited

Management measures and considerations:

• Because of the past effects of erosion, this soil is unsuited to cropland.

#### Pasture and hay

Suitability: Suited

Management measures and considerations:

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Hay yields may be reduced in dry years because of a limited available water capacity.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Unsuited

Management measures and considerations:

 This soil is severely limited for dwellings because of the depth to bedrock, slow permeability, and shrinkswell potential.

#### Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• This soil is severely limited for septic systems because of the depth to bedrock, slow permeability, and shrink-swell potential in the lower part of the subsoil.

#### Interpretive Groups

Land capability classification: 6e

#### CnD—Caneyville-Rock outcrop complex, 6 to 20 percent slopes

#### Setting

Landscape position: Hillsides Size of areas: 10 to 40 acres Slope range: 6 to 20 percent

Parent material: Residuum from limestone

#### Composition

Caneyville soil and similar inclusions: 65 percent

Rock outcrop: 25 percent

#### Contrasting Inclusions

· Crider, Baxter, and Vertrees soils

#### Typical Profile

#### Caneyville

Surface laver:

0 to 6 inches—brown silt loam

Subsoil:

6 to 11 inches—yellowish red silty clay 11 to 21 inches—yellowish red clay 21 to 27 inches—dark reddish brown clav

27 inches—limestone bedrock

#### **Rock outcrop**

This part of the map unit consists of large outcrops of limestone that extend from several inches to 3 feet above the soil surface in horizontal bands, or it occurs as individual blocks of limestone protruding from the surface.

#### Properties and Qualities of the Caneyville Soil

Drainage class: Well drained Permeability: Slow or very slow

Available water capacity: Moderate or low Soil reaction: Strongly acid or moderately acid

High water table: None

Depth to bedrock: 20 to 40 inches

#### Use and Management

#### Cropland

Suitability: Unsuited

Management measures and considerations:

 This map unit is unsuited to cropland because of the numerous rock outcrops, slope, and low available water capacity.

#### Pasture and hay

Suitability for pasture: Suited Suitability for hay: Poorly suited

Management measures and considerations:

- This map unit is poorly suited to hay production because of the slope and numerous rock outcrops.
- The use of farm equipment in pasture management is limited in most areas.

#### Woodland

Suitability: Suited (fig. 3)

Management measures and considerations:

 See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Unsuited

Management measures and considerations:

• This map unit is severely limited for dwellings because of the areas of rock outcrop, depth to bedrock, slow permeability, and shrink-swell potential.

#### Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

 This map unit is severely limited for septic systems because of the numerous rock outcrops, depth to bedrock, slow permeability, and shrink-swell potential in the lower part of the subsoil.

#### Interpretive Groups

Land capability classification: 6s

#### CnF—Caneyville-Rock outcrop complex, 20 to 60 percent slopes

#### Setting

Landscape position: Steep hillsides Size of areas: 10 to 40 acres Slope range: 20 to 60 percent

Parent material: Residuum from limestone



Figure 3.—An area of Caneyville-Rock outcrop complex, 6 to 20 percent slopes. This map unit is suited to woodland. Soil depth and rock outcrops extremely limit most other uses.

#### Composition

Caneyville soil and similar inclusions: 65 percent Rock outcrop: 25 percent

#### Contrasting Inclusions

· Baxter and Vertrees soils

#### Typical Profile

#### Caneyville

Surface layer: 0 to 6 inches—brown silt loam

Subsoil:

6 to 11 inches—yellowish red silty clay 11 to 21 inches—yellowish red clay 21 to 27 inches—dark reddish brown clay 27 inches—limestone bedrock

#### **Rock outcrop**

This part of the map unit consists of large outcrops of limestone that extend from several inches to 3 feet above the soil surface in horizontal bands, or it occurs as individual blocks of limestone protruding from the surface.

#### Properties and Qualities of the Caneyville Soil

Drainage class: Well drained Permeability: Slow or very slow

Available water capacity: Moderate or low Soil reaction: Strongly acid or moderately acid

High water table: None

Depth to bedrock: 20 to 40 inches

#### **Use and Management**

#### Cropland

Suitability: Unsuited

Management measures and considerations:

• This map unit is unsuited to cropland because of the numerous rock outcrops, slope, and low available water capacity.

#### Pasture and hay

Suitability: Unsuited

Management measures and considerations:

• Because of the slope and numerous rock outcrops, the operation of farm equipment in pasture management is difficult and unsafe.

#### Woodland

Suitability: Poorly suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Unsuited

Management measures and considerations:

• This map unit is severely limited for dwellings because of the slope, areas of rock outcrop, depth to bedrock, slow permeability, and shrink-swell potential.

#### Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• This map unit is severely limited for septic systems because of the slope, numerous rock outcrops, depth to bedrock, slow permeability, and shrink-swell potential in the lower part of the subsoil.

#### Interpretive Groups

Land capability classification: 7s

## CoD—Caneyville-Urban land-Rock outcrop complex, 6 to 20 percent slopes

#### Setting

Location: Hillsides in and around the city of Bowling Green

#### Composition

Caneyville soil and similar inclusions: 40 percent

Urban land: 25 percent Rock outcrop: 20 percent

#### Contrasting Inclusions

· Baxter and Vertrees soils

#### Typical Profile

#### Caneyville

Surface layer:

0 to 6 inches—brown silt loam

Subsoil:

6 to 11 inches—yellowish red silty clay 11 to 21 inches—yellowish red clay 21 to 27 inches—dark reddish brown clay

27 inches—limestone bedrock

#### Urban land

Most of the Urban land consists of areas where 85 to 90 percent of the surface is covered by streets, buildings, parking lots, driveways, railroad yards, or airports. The remainder consists of cut and fill areas of soil material imported onto the site or disturbed in the process of urbanization.

#### **Rock outcrop**

This part of the map unit consists of large outcrops of limestone that extend from several inches to 3 feet above the soil surface in horizontal bands, or it occurs as individual blocks of limestone protruding from the surface.

#### Soil Properties and Qualities

See the interpretations tables for map units in urban areas.

#### Use and Management

#### Residential and commercial structures

Suitability: Poorly suited

Management measures and considerations:

- Deep excavations for structures and driveways are difficult to make because of the depth to bedrock and rock outcrops.
- Modifications in the design of footings that overcome the shrink-swell potential are needed for excavations.
- Rock outcrops interfere with construction and excavation in most areas of the map unit.
- Diverting runoff from gutters and driveways away from structures reduces the chance of differential settling or cracking of foundations caused by the shrink-swell potential.
- Soil compaction is a problem around construction sites. Sites may require aeration or deep tillage and reseeding.
- Subsurface sewerage pipes and utility lines may be

subject to settling or cracking because of the shrinkswell potential.

#### Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• This map unit is severely limited for septic systems because of the numerous rock outcrops, depth to bedrock, slow permeability, and shrink-swell potential in the lower part of the subsoil.

#### Interpretive Groups

Land capability classification: None assigned

## CoE—Caneyville-Urban land-Rock outcrop complex, 20 to 30 percent slopes

#### Setting

Location: Hillsides in and around the city of Bowling Green

#### Composition

Caneyville soil and similar inclusions: 40 percent

Urban land: 25 percent Rock outcrop: 20 percent

#### **Contrasting Inclusions**

· Baxter and Vertrees soils

#### Typical Profile

#### Caneyville

Surface layer:

0 to 6 inches—brown silt loam

Subsoil:

6 to 11 inches—yellowish red silty clay 11 to 21 inches—yellowish red clay 21 to 27 inches—dark reddish brown clay

27 inches—limestone bedrock

#### **Urban land**

Most of the Urban land consists of areas where 85 to 90 percent of the surface is covered by streets, buildings, parking lots, driveways, railroad yards, or airports. The remainder consists of cut and fill areas of soil material imported onto the site or disturbed in the process of urbanization.

#### **Rock outcrop**

This part of the map unit consists of large outcrops of limestone that extend from several inches to 3 feet above the soil surface in horizontal bands, or it occurs as individual blocks of limestone protruding from the surface.

#### Soil Properties and Qualities

 See the interpretations tables for map units in urban areas.

#### Use and Management

#### Residential and commercial structures

Suitability: Poorly suited

Management measures and considerations:

- Deep excavations for structures and driveways are difficult to make because of the slope, depth to bedrock, and rock outcrops.
- Modifications in the design of footings that overcome the shrink-swell potential are needed for excavations.
- Rock outcrops interfere with construction and excavation in most areas of the map unit.
- Diverting runoff from gutters and driveways away from structures reduces the chance of differential settling or cracking of foundations caused by the shrink-swell potential.
- Soil compaction is a problem around construction sites. Sites may require aeration or deep tillage and reseeding.
- Subsurface sewerage pipes and utility lines may be subject to settling or cracking because of the shrink-swell potential.

#### Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• This map unit is severely limited for septic systems because of the numerous rock outcrops, slope, depth to bedrock, slow permeability, and shrink-swell potential in the lower part of the subsoil.

#### Interpretive Groups

Land capability classification: None assigned

## CrB—Crider silt loam, 2 to 6 percent slopes

#### Setting

Landscape position: Undulating ridges

Size of areas: 5 to 150 acres Slope range: 2 to 6 percent

Parent material: Loess and residuum from limestone

#### Composition

Crider soil and similar inclusions: 90 percent



Figure 4.—An area of Crider silt loam, 2 to 6 percent slopes. This soil is well suited to most agronomic crops. High yields can be expected if management reduces the risk of erosion.

#### **Contrasting Inclusions**

• Nicholson, Baxter, Caneyville, and Fredonia soils

#### Typical Profile

Surface layer:

0 to 9 inches—brown silt loam

Subsoil:

9 to 28 inches—strong brown and yellowish red silty

clay loam

28 to 50 inches—red silty clay loam 50 to 80 inches—dark red clay

#### Soil Properties and Qualities

Drainage class: Well drained Permeability: Moderate Available water capacity: High

Soil reaction: Neutral to very strongly acid

High water table: None

Depth to bedrock: More than 60 inches

#### Use and Management

#### Cropland

Suitability: Well suited (fig. 4)

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Well suited

Management measures and considerations:

• Careful use of equipment and good design practices prevent the runoff of off-site sediments.

#### Septic tank absorption fields

Suitability: Well suited

Management measures and considerations:

• An onsite investigation is needed in eroded areas to determine a suitable site.

#### Interpretive Groups

Land capability classification: 2e

## CrC—Crider silt loam, 6 to 12 percent slopes

#### Setting

Landscape position: Rolling ridges Size of areas: 5 to 30 acres Slope range: 6 to 12 percent

Parent material: Loess and residuum from limestone

#### Composition

Crider soil and similar inclusions: 85 percent

#### Contrasting Inclusions

· Nicholson, Baxter, Caneyville, and Fredonia soils

#### Typical Profile

Surface layer:

0 to 9 inches—brown silt loam

Subsoil:

9 to 28 inches—strong brown and yellowish red silty clay loam

28 to 50 inches—red silty clay loam 50 to 80 inches—dark red clay

#### Soil Properties and Qualities

Drainage class: Well drained Permeability: Moderate Available water capacity: High

Soil reaction: Neutral to very strongly acid

High water table: None

Depth to bedrock: More than 60 inches

#### Use and Management

#### Cropland

Suitability: Well suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Well suited

Management measures and considerations:

- Structures should be designed so that they conform to the natural slope.
- Topsoil should be stockpiled and used to reclaim areas that are disturbed during construction.
- Careful use of equipment and good design practices prevent the runoff of off-site sediments.

#### Septic tank absorption fields

Suitability: Well suited

Management measures and considerations:

- Filter lines should be installed on the contour and conform to the slope.
- An onsite investigation is needed in eroded areas to determine a suitable site.

#### Interpretive Groups

Land capability classification: 3e

## CuB—Crider-Urban land complex, 2 to 6 percent slopes

#### Setting

Location: In and around the city of Bowling Green

#### Composition

Crider soil and similar inclusions: 55 percent

Urban land: 35 percent

#### Contrasting Inclusions

• Nicholson, Caneyville, Nolin, Newark, Fredonia, and Vertrees soils and Udorthents

#### Typical Profile

#### Crider

Surface layer:

0 to 9 inches—brown silt loam

Subsoil:

9 to 28 inches—strong brown and yellowish red silty clay loam

28 to 50 inches—red silty clay loam

50 to 80 inches—dark red clay

#### **Urban land**

Most of the Urban land consists of areas where 85 to 90 percent of the surface is covered by streets, buildings, parking lots, driveways, railroad yards, or airports. The remainder consists of cut and fill areas of soil material imported onto the site or disturbed in the process of urbanization.

#### Soil Properties and Qualities

• See the interpretations tables for map units in urban areas.

#### Use and Management

#### Residential and commercial structures

Suitability: Well suited

Management measures and considerations:

- Designing structures that conform to the natural slope reduces the amount of cutting or filling needed.
- Topsoil may need to be stockpiled and used to reclaim areas that are disturbed during construction.
- · Careful use of equipment and good site

conservation measures prevent the discharge of sediment onto adjacent property or into streams.

- Soil compaction is a problem around construction sites. Sites may require aeration or deep tillage and reseeding.
- Yards may be subject to periods of flooding if the soil is compacted. Shallow diversions may be needed to remove surface runoff and ponding in low areas.
- Diverting runoff from gutters and driveways away from structures reduces the chance of differential settling.

#### Septic tank absorption fields

Suitability: Well suited

Management measures and considerations:

 Most areas of this map unit can be used for septic tank filter fields.

#### Interpretive Groups

Land capability classification: None assigned

## CuC—Crider-Urban land complex, 6 to 12 percent slopes

#### Setting

Location: In and around the city of Bowling Green

#### Composition

Crider soil and similar inclusions: 55 percent

Urban land: 35 percent

#### Contrasting Inclusions

 Nicholson, Caneyville, Nolin, Newark, and Fredonia soils and Udorthents

#### Typical Profile

#### Crider

Surface layer:

0 to 9 inches—brown silt loam

Subsoil:

9 to 28 inches—strong brown and yellowish red silty clay loam

28 to 50 inches—red silty clay loam

50 to 80 inches—dark red clay

#### **Urban land**

Most of the Urban land consists of areas where 85 to 90 percent of the surface is covered by streets, buildings, parking lots, driveways, railroad yards, or airports. The remainder consists of cut and fill areas of soil material imported onto the site or disturbed in the process of urbanization.

#### Soil Properties and Qualities

• See the interpretations tables for map units in urban areas.

#### Use and Management

#### Residential and commercial structures

Suitability: Well suited

Management measures and considerations:

- Designing structures that conform to the natural slope reduces the amount of cutting or filling needed.
- Topsoil may need to be stockpiled and used to reclaim areas that are disturbed during construction.
- Careful use of equipment and good site conservation measures prevent the discharge of sediment onto adjacent property or into streams.
- Soil compaction is a problem around construction sites. Sites may require aeration or deep tillage and reseeding.
- Yards may be subject to rill and gully erosion if the soil is compacted. Shallow diversions may be needed to remove surface runoff.
- Diverting runoff from gutters and driveways away from structures reduces the chance of differential settling.

#### Septic tank absorption fields

Suitability: Well suited

Management measures and considerations:

- The slope is a limitation affecting septic systems. Care is needed in layout and design in order to make the system conform to the natural slope of the lot.
- An onsite investigation is recommended to determine a suitable site.

#### Interpretive Groups

Land capability classification: None assigned

#### DAM—Dam, large

#### Setting

Shape of areas: Linear to parabolic Size of areas: 3 to 18 acres

#### Composition

This map unit consists of earthen embankments or berms that are constructed across natural drainage channels to impound water. The embankments or berms are made up of soil and rock materials excavated from the site or adjacent areas. The materials are shaped and compacted by earthmoving equipment. The embankments are vegetated, and

some are protected with large stones or riprap. These small watershed dams average 30 to 40 feet in height and width.

#### Use and Management

This map unit is in several small watersheds across the county, mostly in the northern part. These impoundments are used for flood prevention and control, as municipal water supplies, for fire protection, as wildlife habitat, and for fishing and recreational uses.

#### Interpretive Groups

Land capability classification: None assigned

#### Du—Dunning silty clay loam, ponded

#### Setting

Landscape position: Flood plains and depressions

Size of areas: 3 to 65 acres Slope range: 0 to 2 percent

Parent material: Fine textured alluvium

#### Composition

Dunning soil and similar inclusions: 85 percent

#### Contrasting Inclusions

• Lawrence, Newark, Robertsville, and Melvin soils

#### Typical Profile

Surface layer:

0 to 10 inches—very dark gray silty clay loam

Subsoil

10 to 25 inches—dark gray silty clay 25 to 43 inches—dark gray clay 43 to 71 inches—dark gray clay

#### 3 ., . .,

Drainage class: Very poorly drained or poorly drained

Soil Properties and Qualities

Permeability: Slow or very slow Available water capacity: High

Soil reaction: Moderately acid to slightly alkaline High water table: At or above the surface from

December through May

Ponding: Frequent for long to brief periods from

December through May

Depth to bedrock: More than 60 inches

#### Use and Management

#### Cropland

Suitability: Poorly suited

Management measures and considerations:

- In previously drained areas, planting and harvesting operations can be hindered by wetness or ponding.
- This soil is subject to crusting and clodding if tilled when the moisture content is high.

#### Pasture and hay

Suitability: Suited

Management measures and considerations:

- Selecting forage plants that can tolerate saturated conditions for extended periods is recommended.
- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Deferring livestock grazing until early summer minimizes compaction of the soil surface and prevents damage to forages.

#### Woodland

Suitability: Poorly suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Unsuited

Management measures and considerations:

 Because of the seasonal wetness and ponding, this soil is unsuited to residential and commercial structures.

#### Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• Because of the seasonal high water table and ponding, this soil is unsuited to septic tank filter fields.

#### Interpretive Groups

Land capability classification: 4w

## EkB—Elk silt loam, 2 to 6 percent slopes, rarely flooded

#### Setting

Landscape position: Undulating stream terraces

Size of areas: 3 to 15 acres Slope range: 2 to 6 percent Parent material: Alluvium

#### Composition

Elk soil and similar inclusions: 80 percent

#### Contrasting Inclusions

Newark, Nolin, and Otwood soils

#### Typical Profile

Surface layer:

0 to 10 inches—brown silt loam

Subsoil.

10 to 20 inches—brown silt loam 20 to 32 inches—brown silty clay loam

32 to 42 inches—strong brown silty clay loam 42 to 65 inches—yellowish brown silty clay loam

#### Soil Properties and Qualities

Drainage class: Well drained Permeability: Moderate Available water capacity: High

Soil reaction: Strongly acid or moderately acid

High water table: None

Flooding: Rare from January through April Depth to bedrock: More than 60 inches

#### Use and Management

#### Cropland

Suitability: Well suited

Management measures and considerations:

- Planting operations may be delayed in some years because of the flooding.
- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Poorly suited

Management measures and considerations:

• This soil is subject to flooding in some years.

• Locating structures in the higher areas is recommended.

## Septic tank absorption fields

Suitability: Suited

Management measures and considerations:

• An onsite investigation is needed to locate a suitable site and determine if the site is subject to flooding.

## Interpretive Groups

Land capability classification: 2e

## EpB—Epley silt loam, 2 to 6 percent slopes

## Setting

Landscape position: Undulating ridges and stream

terraces

Size of areas: 8 to 25 acres Slope range: 2 to 6 percent

Parent material: Silty alluvium and residuum from

shale

## Composition

Epley soil and similar inclusions: 85 percent

#### Contrasting Inclusions

• Caneyville, Lawrence, Zanesville, and Otwood soils

### Typical Profile

Surface layer:

0 to 9 inches—brown silt loam

Subsoil:

9 to 24 inches—yellowish brown silt loam

24 to 41 inches—brown and dark yellowish brown silty clay that has gray and brown mottles

Substratum:

41 to 65 inches—yellowish brown clay that has brown mottles

## Soil Properties and Qualities

Drainage class: Moderately well drained

Permeability: Slow or very slow Available water capacity: High

Soil reaction: Very strongly acid to moderately acid High water table: At a depth of 1.5 to 2.0 feet from

December through April

Depth to bedrock: More than 60 inches

### **Use and Management**

## Cropland

Suitability: Suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Planting later in spring, when the water table has receded, helps to prevent crusting and rutting of the soil surface.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

## Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Deferring grazing until later in spring, when the water table has receded, helps to prevent soil compaction and improve forage growth.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

 See the tables on forest productivity and forestland management.

## **Dwellings**

Suitability: Unsuited

Management measures and considerations:

- This soil is unsuited to dwellings because of the seasonal wetness and shrink-swell potential.
- Other sites in the survey area should be considered for dwellings.

#### Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• This soil is unsuited to septic tank filter fields because of the high water table, very slow permeability, and shrink-swell potential.

## Interpretive Groups

Land capability classification: 2e

## FeB—Fredonia-Vertrees complex, 2 to 6 percent slopes, rocky

#### Setting

Landscape position: Undulating ridges

Size of areas: 2 to 20 acres Slope range: 2 to 6 percent

Parent material: Residuum from limestone

#### Composition

Fredonia soil: 50 percent Vertrees soil: 35 percent

#### **Inclusions**

Nicholson, Pembroke, and Crider soils and rock outcrop

## Typical Profile

#### Fredonia

Surface layer:

0 to 5 inches—brown silt loam

Subsoil:

5 to 22 inches—dark red silty clay 22 to 37 inches—dusky red clay 37 inches—limestone bedrock

#### **Vertrees**

Surface layer:

0 to 4 inches—brown silt loam

Subsurface layer:

4 to 6 inches—yellowish brown silt loam

Subsoil:

6 to 15 inches—red silty clay

15 to 80 inches—red and dark red clay

## Soil Properties and Qualities

Drainage class: Well drained

Permeability: Moderately slow or slow

Available water capacity: Fredonia—moderate or low;

Vertrees—high

Soil reaction: Fredonia—strongly acid to slightly acid;

Vertrees—strongly acid or moderately acid

High water table: None

Depth to bedrock: Fredonia—20 to 40 inches;

Vertrees—more than 60 inches

### **Use and Management**

## Cropland

Suitability: Suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- The numerous rock outcrops can hinder cultivation and harvesting operations.
- The depth to bedrock limits rooting depth in most areas
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

## Pasture and hay

Suitability: Suited

Management measures and considerations:

- Rock outcrops can hinder management operations for pasture and hay in some areas.
- Because of the limited available water capacity and depth to bedrock, hay yields may be reduced in dry years.
- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Poorly suited

Management measures and considerations:

• The depth to bedrock, areas of rock outcrop, and shrink-swell potential are limitations affecting dwellings.

#### Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• These soils are limited for septic tank filter fields because of the depth to bedrock, areas of rock outcrop, slow permeability, and shrink-swell potential.

### Interpretive Groups

Land capability classification: 3e

## FeC—Fredonia-Vertrees complex, 6 to 12 percent slopes, very rocky

## Setting

Landscape position: Rolling ridges and side slopes

Size of areas: 5 to 200 acres Slope range: 6 to 12 percent

Parent material: Residuum from limestone

## Composition

Fredonia soil: 50 percent Vertrees soil: 30 percent

#### **Inclusions**

Crider, Baxter, and Caneyville soils and rock outcrop

## Typical Profile

#### **Fredonia**

Surface layer:

0 to 5 inches—brown silt loam

Subsoil:

5 to 22 inches—dark red silty clay 22 to 37 inches—dusky red clay 37 inches—limestone bedrock

#### **Vertrees**

Surface layer:

0 to 4 inches—brown silt loam

Subsurface layer:

4 to 6 inches—yellowish brown silt loam

Subsoil:

6 to 15 inches—red silty clay

15 to 80 inches—red and dark red clay

## Soil Properties and Qualities

Drainage class: Well drained

Permeability: Moderately slow or slow

Available water capacity: Fredonia—moderate or low;

Vertrees—high

Soil reaction: Fredonia—strongly acid to slightly acid;

Vertrees—strongly acid or moderately acid

High water table: None

Depth to bedrock: Fredonia—20 to 40 inches;

Vertrees—more than 60 inches

### **Use and Management**

## Cropland

Suitability: Poorly suited

Management measures and considerations:

- The numerous rock outcrops hinder cultivation and harvesting operations.
- The depth to bedrock limits rooting depth in most areas.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Suited

Management measures and considerations:

- Rock outcrops can hinder management operations for pasture and hay in some areas.
- Because of the limited available water capacity and depth to bedrock, hay yields may be reduced in dry years.
- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

## **Dwellings**

Suitability: Poorly suited

Management measures and considerations:

• The depth to bedrock, slope, areas of rock outcrop, and shrink-swell potential are severe limitations affecting structures.

#### Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• These soils are limited for septic tank filter fields because of the depth to bedrock, slope, areas of rock outcrop, slow permeability, and shrink-swell potential.

### Interpretive Groups

Land capability classification: 4e

## FnB—Fredonia-Vertrees-Urban land complex, 2 to 6 percent slopes, rocky

### Setting

Landscape position: Undulating ridges

Size of areas: 2 to 20 acres Slope range: 2 to 6 percent

Parent material: Residuum from limestone

#### Composition

Fredonia soil: 37 percent Vertrees soil: 30 percent Urban land: 25 percent

#### **Inclusions**

Nicholson, Pembroke, and Crider soils and rock outcrop

## Typical Profile

#### Fredonia

Surface layer:

0 to 5 inches—brown silt loam

Subsoil:

5 to 22 inches—dark red silty clay 22 to 37 inches—dusky red clay 37 inches—limestone bedrock

## **Vertrees**

Surface laver:

0 to 4 inches—brown silt loam

Subsurface layer:

4 to 6 inches—yellowish brown silt loam

Subsoil:

6 to 15 inches—red silty clay 15 to 80 inches—red and dark red clay

#### **Urban land**

Most of the Urban land consists of areas where 85 to 90 percent of the surface is covered by streets, buildings, parking lots, driveways, railroad yards, or airports. The remainder consists of cut and fill areas of soil material imported onto the site or disturbed in the process of urbanization.

#### Soil Properties and Qualities

• See the interpretations tables for map units in urban areas.

## Use and Management

## Residential and commercial structures

Suitability: Suited

Management measures and considerations:

- Designing structures that conform to the natural slope reduces the amount of cutting or filling needed and helps to overcome the depth to bedrock limitation.
- Topsoil may need to be stockpiled and used to reclaim areas that are disturbed during construction.
- Careful use of equipment and good site conservation measures prevent the discharge of sediment onto adjacent property or into streams.
- Soil compaction is a problem around construction sites. Sites may require aeration or deep tillage and reseeding.
- Yards may be subject to periods of flooding or ponding where the soil is compacted. Shallow diversions may be needed to remove surface runoff or ponding in low areas.
- Modifications in the design of footings and basements that overcome the shrink-swell potential and depth to bedrock limitation are needed in areas of deep excavations.
- Diverting runoff from gutters and driveways away from structures reduces the chance of differential settling or cracking of foundations caused by the shrink-swell potential.

#### Septic tank absorption fields

Suitability: Poorly suited

Management measures and considerations:

- These soils are limited for septic systems because of the depth to bedrock, areas of rock outcrop, slow permeability, and moderate shrink-swell potential in the lower part of the subsoil.
- In the lot design for structures and cuts for driveways, the depth to bedrock needs to be considered and a sufficient area for a septic field needs to be allowed.
- An onsite investigation is needed to determine if a site is suitable.

## Interpretive Groups

Land capability classification: None assigned

# FnC—Fredonia-Vertrees-Urban land complex, 6 to 12 percent slopes, very rocky

#### Setting

Landscape position: Rolling ridges Size of areas: 5 to 200 acres Slope range: 6 to 12 percent

Parent material: Residuum from limestone

### Composition

Fredonia soil: 37 percent Vertrees soil: 27 percent Urban land: 25 percent

## **Contrasting Inclusions**

· Baxter and Crider soils and rock outcrop

## Typical Profile

#### Fredonia

Surface layer:

0 to 5 inches—brown silt loam

Subsoil:

5 to 22 inches—dark red silty clay 22 to 37 inches—dusky red clay 37 inches—limestone bedrock

#### Vertrees

Surface layer:

0 to 4 inches—brown silt loam

Subsurface layer:

4 to 6 inches—yellowish brown silt loam

Subsoil:

6 to 15 inches—red silty clay 15 to 80 inches—red and dark red clay

#### **Urban land**

Most of the Urban land consists of areas where 85 to 90 percent of the surface is covered by streets, buildings, parking lots, driveways, railroad yards, or airports. The remainder consists of cut and fill areas of soil material imported onto the site or disturbed in the process of urbanization.

## Soil Properties and Qualities

 See the interpretations tables for map units in urban areas.

### Use and Management

#### Residential and commercial structures

Suitability: Poorly suited

Management measures and considerations:

- Designing structures that conform to the natural slope reduces the amount of cutting or filling needed and helps to overcome the depth to bedrock limitation.
- Topsoil may need to be stockpiled and used to reclaim areas that are disturbed during construction.
- Careful use of equipment and good site conservation measures prevent the discharge of sediment onto adjacent property or into streams.

- Soil compaction is a problem around construction sites. Sites may require aeration or deep tillage and reseeding.
- Yards may be subject to rill and gully erosion if the soil is compacted. Shallow diversions may be needed to remove surface runoff.
- Modifications in the design of footings and basements that overcome the limitations caused by the shrink-swell potential, areas of rock outcrop, and depth to bedrock are needed for deep excavations.
- Diverting runoff from gutters and driveways away from structures reduces the chance of differential settling or cracking of foundations caused by the shrink-swell potential.

### Septic tank absorption fields

Suitability: Poorly suited

Management measures and considerations:

- These soils are limited for septic systems because of the slope, depth to bedrock, areas of rock outcrop, slow permeability, and shrink-swell potential in the lower part of the subsoil.
- In the lot design for structures and cuts for driveways, the slope and depth to bedrock need to be considered and a sufficient area for a septic field needs to be allowed.
- An onsite investigation is needed to determine if a site is suitable.

#### Interpretive Groups

Land capability classification: None assigned

# FnC2—Fredonia-Vertrees-Urban land complex, 6 to 12 percent slopes, eroded, rocky

#### Setting

Landscape position: Rolling ridges Size of areas: 5 to 100 acres Slope range: 6 to 12 percent

Parent material: Residuum from limestone

#### Composition

Fredonia soil: 37 percent Vertrees soil: 30 percent Urban land: 25 percent

## Inclusions

Baxter and Crider soils and rock outcrop

## Typical Profile

#### Fredonia

Surface layer:

0 to 3 inches—brown silt loam

Subsoil:

3 to 22 inches—dark red silty clay 22 to 37 inches—dusky red clay 37 inches—limestone bedrock

#### Vertrees

Surface layer:

0 to 3 inches—brown silt loam

Subsoil:

3 to 15 inches—red silty clay 15 to 80 inches—red and dark red clay

#### **Urban land**

Most of the Urban land consists of areas where 85 to 90 percent of the surface is covered by streets, buildings, parking lots, driveways, railroad yards, or airports. The remainder consists of cut and fill areas of soil material imported onto the site or disturbed in the process of urbanization.

## Soil Properties and Qualities

• See the interpretations tables for map units in urban areas.

#### Use and Management

#### Residential and commercial structures

Suitability: Poorly suited

Management measures and considerations:

- Designing structures that conform to the natural slope reduces the amount of cutting or filling needed and helps to overcome the depth to bedrock limitation.
- Stockpiling topsoil is critical in reclaiming areas disturbed during construction.
- Careful use of equipment and good site conservation measures prevent the discharge of sediment onto adjacent property or into streams.
- Soil compaction is a problem around construction sites because of the past effects of erosion. Sites require aeration or deep tillage and reseeding.
- Yards are subject to rill and gully erosion if the soil is compacted. Shallow diversions may be needed to remove surface runoff.
- Modifications in the design of footings and basements that overcome the limitations caused by the shrink-swell potential, areas of rock outcrop, and depth to bedrock are needed for deep excavations.

• Diverting runoff from gutters and driveways away from structures reduces the chance of differential settling or cracking of foundations caused by the shrink-swell potential.

## Septic tank absorption fields

Suitability: Poorly suited

Management measures and considerations:

- These soils are limited for septic systems because of the slope, depth to bedrock, areas of rock outcrop, slow permeability, and shrink-swell potential in the lower part of the subsoil.
- In the lot design for structures and cuts for driveways, the slope and depth to bedrock need to be considered and a sufficient area for a septic field needs to be allowed.
- An onsite investigation is needed to determine if a site is suitable.

## Interpretive Groups

Land capability classification: None assigned

## FrC—Frondorf silt loam, 6 to 12 percent slopes

## Setting

Landscape position: Rolling ridgetops

Size of areas: 5 to 40 acres Slope range: 6 to 12 percent

Parent material: Residuum from sandstone and

siltstone

#### Composition

Frondorf soil and similar inclusions: 85 percent

### **Contrasting Inclusions**

Wellston, Sadler, Zanesville, and Ramsey soils

## Typical Profile

Surface layer:

0 to 5 inches—brown silt loam

Subsoil:

5 to 18 inches—strong brown and yellowish brown silty clay loam

18 to 26 inches—very channery silty clay loam 26 inches—hard sandstone

### Soil Properties and Qualities

Drainage class: Well drained

Permeability: Moderate or moderately rapid Available water capacity: Moderate or low Soil reaction: Strongly acid or very strongly acid

High water table: None

Depth to bedrock: 20 to 40 inches

#### Use and Management

## Cropland

Suitability: Suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting and winter cover crops reduce the risk of soil erosion and increase the available moisture.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

## Pasture and hay

Suitability: Suited

Management measures and considerations:

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Hay yields may be low in dry years because of a limited available water capacity.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

### **Dwellings**

Suitability: Suited

Management measures and considerations:

- Structures should be designed so that they conform to the natural slope.
- Topsoil should be stockpiled and used to reclaim areas that are disturbed during construction.
- Deep excavations are impractical because of the limited depth to bedrock.
- Careful use of equipment and good design practices prevent the runoff of off-site sediments.

#### Septic tank absorption fields

Suitability: Suited

Management measures and considerations:

- This soil is limited for septic tank filter fields by the depth to bedrock.
- An onsite investigation is needed to determine a suitable site.

## Interpretive Groups

Land capability classification: 3e

## FrD—Frondorf silt loam, 12 to 20 percent slopes

#### Setting

Landscape position: Hillsides Size of areas: 10 to 55 acres Slope range: 12 to 20 percent

Parent material: Residuum from sandstone and

siltstone

#### Composition

Frondorf soil and similar inclusions: 85 percent

## Contrasting Inclusions

• Wellston, Zanesville, and Ramsey soils

## Typical Profile

Surface layer:

0 to 5 inches—brown silt loam

Subsoil:

5 to 18 inches—strong brown and yellowish brown silty clay loam

18 to 26 inches—very channery silty clay loam 26 inches—hard sandstone

#### Soil Properties and Qualities

Drainage class: Well drained

Permeability: Moderate or moderately rapid
Available water capacity: Moderate or low
Soil reaction: Strongly acid or very strongly acid

High water table: None

Depth to bedrock: 20 to 40 inches

### Use and Management

### Cropland

Suitability: Poorly suited

Management measures and considerations:

- A management plan that includes long rotations in grass and legumes is needed to reduce the effects of erosion and help increase moisture storage.
- Practices that include minimum tillage or no-till planting and winter cover crops reduce the risk of soil erosion and increase the available moisture capacity. These practices are necessary in areas used as cropland.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of

fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Suited

Management measures and considerations:

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Hay yields may be low in dry years because of a limited available water capacity.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Suited

Management measures and considerations:

- Structures should be designed so that they conform to the natural slope.
- Topsoil should be stockpiled and used to reclaim areas that are disturbed during construction.
- Deep excavations are impractical because of the limited depth to bedrock.
- Careful use of equipment and good design practices prevent the runoff of off-site sediments.

#### Septic tank absorption fields

Suitability: Suited

Management measures and considerations:

- This soil is limited for septic tank filter fields by the depth to bedrock and slope.
- An onsite investigation is needed to determine a suitable site.

### Interpretive Groups

Land capability classification: 4e

## Gr—Grigsby sandy loam, frequently flooded

#### Setting

Landscape position: Flood plains of the Barren and

Green Rivers

Size of areas: 10 to 30 acres Slope range: 0 to 2 percent Parent material: Loamy alluvium

### Composition

Grigsby soil and similar inclusions: 90 percent

## **Contrasting Inclusions**

· Newark, Lindside, and Nolin soils

## Typical Profile

Surface layer:

0 to 9 inches—dark yellowish brown sandy loam

Subsoil:

9 to 21 inches—dark yellowish brown sandy loam

21 to 26 inches—brown sandy loam

26 to 41 inches—yellowish brown sandy loam 41 to 80 inches—dark yellowish brown loam

## Soil Properties and Qualities

Drainage class: Well drained

Permeability: Moderate or moderately rapid

Available water capacity: High

Soil reaction: Moderately acid to neutral

High water table: At a depth of more than 6 feet Flooding: Frequent for brief periods from December

through May

Depth to bedrock: More than 60 inches

## Use and Management

## Cropland

Suitability: Suited

Management measures and considerations:

- The frequent flooding is a management concern.
- Planting later in spring, when the risk of flooding has receded, helps to prevent damage to young plants.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Grazing should be deferred until later in spring when the risk of flooding has receded.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

## Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Unsuited

Management measures and considerations:

- This soil is unsuited to dwellings because of the risk of flooding.
- Other sites in the survey area should be considered for dwellings.

### Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• This soil is unsuited to septic tank filter fields because of the risk of flooding.

## Interpretive Groups

Land capability classification: 2w

## HaB—Hammack silt loam, 2 to 6 percent slopes

## Setting

Landscape position: Undulating ridges

Size of areas: 20 to 200 acres Slope range: 2 to 6 percent

Parent material: Loess and residuum from limestone

#### Composition

Hammack soil and similar inclusions: 85 percent

### Contrasting Inclusions

Nicholson, Baxter, Crider, Caneyville, and Fredonia soils

### Typical Profile

Surface layer:

0 to 9 inches—brown silt loam

Subsoil:

9 to 17 inches—brown silt loam

17 to 30 inches—yellowish red silty clay loam

30 to 41 inches—yellowish red, light brownish gray, and pale brown very gravelly silt loam

41 to 84 inches—dark red gravelly clay and clay

### Soil Properties and Qualities

Drainage class: Well drained Permeability: Moderately slow Available water capacity: High

Soil reaction: Very strongly acid to moderately acid

High water table: None

Depth to bedrock: More than 60 inches

## Use and Management

#### Cropland

Suitability: Well suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Well suited

Management measures and considerations:

- Structures should be designed so that they conform to the natural slope.
- Topsoil should be stockpiled and used to reclaim areas that are disturbed during construction.
- Design modifications that overcome the shrink-swell potential are needed in areas of deep excavations.
- Careful use of equipment and good design practices prevent the runoff of off-site sediments.

#### Septic tank absorption fields

Suitability: Suited

Management measures and considerations:

- This soil is limited for septic systems because of the moderately slow permeability and the moderate shrink-swell potential in the lower part of the subsoil.
- An onsite investigation is needed to determine a suitable site.

### Interpretive Groups

Land capability classification: 2e

## La—Lawrence silt loam, rarely flooded

#### Setting

Landscape position: Nearly level stream terraces

Size of areas: 8 to 25 acres Slope range: 0 to 2 percent Parent material: Silty alluvium

#### Composition

Lawrence soil and similar inclusions: 90 percent

## Contrasting Inclusions

 Otwood, Melvin, Newark, Nolin, Elk, and Robertsville soils

## Typical Profile

Surface layer:

0 to 7 inches—grayish brown silt loam

Subsoil:

7 to 14 inches—yellowish brown silty clay loam that has light yellowish brown mottles

14 to 18 inches—yellowish brown silty clay loam that has gray and brown mottles

18 to 65 inches—gray and yellowish brown silty clay loam fragipan

## Soil Properties and Qualities

Drainage class: Somewhat poorly drained

Permeability: Moderate above the fragipan and slow

or very slow in the fragipan Available water capacity: High

Soil reaction: Very strongly acid or strongly acid High water table: At a depth of 1.0 to 1.5 feet from

December through April

Flooding: Rare

Depth to bedrock: More than 60 inches

### Use and Management

### Cropland

Suitability: Suited

Management measures and considerations:

- The seasonal wetness limits the planting and harvesting of some crops.
- Because of the wetness in early spring, planting short-season annuals, such as soybeans, is recommended.

#### Pasture and hay

Suitability: Well suited

Management measures and considerations:

• Selecting forage plants that can tolerate short

periods of wetness, such as tall fescue and ladino clover, is recommended.

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Deferring livestock grazing until later in spring or until early summer, when the water table has receded, helps to prevent soil compaction and improve forage growth.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

 See the tables on forest productivity and forestland management.

## **Dwellings**

Suitability: Unsuited

Management measures and considerations:

- This soil is unsuited to dwellings because of the seasonal wetness caused by the perched water table, the slow permeability in the subsoil, and the risk of flooding.
- Other sites in the survey area should be considered for dwellings.

## Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• This soil is unsuited to septic tank filter fields because of the high water table, very slow permeability, and risk of flooding.

## Interpretive Groups

Land capability classification: 3w

## Ld-Lindside silt loam, frequently flooded

### Setting

Landscape position: Flood plains Size of areas: 3 to 40 acres Slope range: 0 to 2 percent Parent material: Silty alluvium

#### Composition

Lindside soil and similar inclusions: 90 percent

## Contrasting Inclusions

• Melvin, Newark, and Nolin soils



Figure 5.—An area of Lindside silt loam, frequently flooded. Seasonal wetness and flooding limit the planting and harvesting of some crops.

## Typical Profile

Surface layer:

0 to 10 inches-brown silt loam

Subsoil:

10 to 16 inches—brown silt loam

16 to 42 inches—brown silty clay loam that has gray and yellowish brown mottles

Substratum:

42 to 65 inches—light brownish gray, light gray, dark brown, and light yellowish brown silt loam

## Soil Properties and Qualities

Drainage class: Moderately well drained

Permeability: Moderate
Available water capacity: High

Soil reaction: Very strongly acid or strongly acid High water table: At a depth of 1.5 to 2.0 feet from

December through April

Flooding: Frequent for very brief periods from December through May

Depth to bedrock: More than 60 inches

## Use and Management

#### Cropland

Suitability: Suited

Management measures and considerations:

- The flooding and seasonal wetness limit the planting and harvesting of some crops (fig. 5).
- Because of the risk of flooding, planting shortseason annuals, such as soybeans, later in spring is recommended.

## Pasture and hay

Suitability: Suited

Management measures and considerations:

• Selecting forage plants that can tolerate short

periods of wetness, such as tall fescue and ladino clover, is recommended.

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Deferring livestock grazing until later in spring or until early summer, when the risk of flooding is lesser, helps to prevent loss of livestock and improve forage growth.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

## **Dwellings**

Suitability: Unsuited

Management measures and considerations:

- This soil is unsuited to dwellings because of the risk of flooding and seasonal wetness.
- Other sites in the survey area should be considered for dwellings.

#### Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• This soil is unsuited to septic tank filter fields because of the high water table and risk of flooding.

#### Interpretive Groups

Land capability classification: 3w

### Me—Melvin silt loam, frequently flooded

#### Setting

Landscape position: Flood plains Size of areas: 5 to 70 acres Slope range: 0 to 2 percent Parent material: Silty alluvium

## Composition

Melvin soil and similar inclusions: 80 percent

#### Contrasting Inclusions

· Newark, Lindside, and Nolin soils

### Typical Profile

Surface layer:

0 to 9 inches—grayish brown silt loam that has brown mottles

Subsoil:

9 to 33 inches—light brownish gray silty clay loam that has brown mottles

Substratum:

33 to 62 inches—light brownish gray silty clay loam that has brown mottles

## Soil Properties and Qualities

Drainage class: Poorly drained Permeability: Moderate

Available water capacity: High

Soil reaction: Moderately acid to moderately alkaline High water table: At the surface from December

through April

Flooding: Frequent for long periods from December

through April

Depth to bedrock: More than 60 inches

## Use and Management

## Cropland

Suitability: Poorly suited

Management measures and considerations:

• The flooding and seasonal wetness limit the planting and harvesting of most crops.

### Pasture and hay

Suitability: Poorly suited

Management measures and considerations:

• Selecting forage plants that can tolerate long periods of wetness, such as tall fescue and ladino clover, is recommended.

#### Woodland

Suitability: Suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Unsuited

Management measures and considerations:

- This soil is unsuited to dwellings because of the risk of flooding and seasonal wetness.
- Other sites in the survey area should be considered for dwellings.

#### Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• This soil is unsuited to septic tank filter fields because of the high water table and risk of flooding.

## Interpretive Groups

Land capability classification: 4w

## Ne—Newark silt loam, frequently flooded

## Setting

Landscape position: Flood plains Size of areas: 4 to 80 acres Slope range: 0 to 2 percent Parent material: Silty alluvium

#### Composition

Newark soil and similar inclusions: 90 percent

## **Contrasting Inclusions**

• Lindside, Melvin, Nolin, Grigsby, and Lawrence soils

## Typical Profile

Surface layer:

0 to 11 inches—brown silt loam

Subsoil:

11 to 18 inches—yellowish brown silt loam that has gray mottles

18 to 28 inches—light brownish gray silt loam that has brown mottles

Substratum:

28 to 65 inches—light brownish gray silt loam that has brown and black mottles

## Soil Properties and Qualities

Drainage class: Somewhat poorly drained

Permeability: Moderate
Available water capacity: High

Soil reaction: Moderately acid to slightly alkaline High water table: At a depth of 1.0 to 1.5 feet from

December through May

Flooding: Frequent for brief periods from December

through May

Depth to bedrock: More than 60 inches

## Use and Management

#### Cropland

Suitability: Suited

Management measures and considerations:

- The flooding and seasonal wetness limit the planting and harvesting of some crops.
- Because of the wetness in spring, planting shortseason annuals, such as soybeans, is recommended.

## Pasture and hay

Suitability: Suited

Management measures and considerations:

- Selecting forage plants that can tolerate short periods of wetness, such as tall fescue and ladino clover, is recommended.
- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Deferring livestock grazing until later in spring or until early summer, when the water table has receded, helps to prevent soil compaction and improve forage growth.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

## **Dwellings**

Suitability: Unsuited

Management measures and considerations:

- This soil is unsuited to dwellings because of the risk of flooding and seasonal wetness.
- Other sites in the survey area should be considered for dwelllings.

#### Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

 This soil is unsuited to septic tank filter fields because of the high water table and risk of flooding.

#### Interpretive Groups

Land capability classification: 3w

## Nf—Newark silt loam, ponded

## Setting

Landscape position: Depressions Size of areas: 3 to 18 acres Slope range: 0 to 2 percent Parent material: Silty alluvium

#### Composition

Newark soil and similar inclusions: 90 percent

## Contrasting Inclusions

· Lindside, Melvin, and Dunning soils

## Typical Profile

Surface layer:

0 to 11 inches-brown silt loam

Subsoil:

11 to 18 inches—yellowish brown silt loam that has gray mottles

18 to 28 inches—light brownish gray silt loam that has brown mottles

Substratum:

28 to 65 inches—light brownish gray silt loam that has brown and black mottles

## Soil Properties and Qualities

Drainage class: Somewhat poorly drained

Permeability: Moderate
Available water capacity: High

Soil reaction: Moderately acid to slightly alkaline High water table: At the surface to a depth of 1.5 feet

from December through May

Ponding: Frequent for brief to long periods from

December through May

Depth to bedrock: More than 60 inches

## Use and Management

### Cropland

Suitability: Poorly suited

Management measures and considerations:

- The ponding and seasonal wetness limit the planting and harvesting of most crops.
- Because of the risk of ponding in spring, planting short-season annuals, such as soybeans, is recommended.

## Pasture and hay

Suitability: Suited

Management measures and considerations:

- Selecting forage plants that can tolerate periods of wetness, such as tall fescue and ladino clover, is recommended.
- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Deferring livestock grazing until early summer, when the water table has receded and the risk of ponding is lesser, helps to prevent soil compaction and improve forage growth.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

## Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Unsuited

Management measures and considerations:

- This soil is unsuited to dwellings because of the risk of ponding and seasonal wetness.
- Other sites in the survey area should be considered for dwellings.

### Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• This soil is unsuited to septic tank filter fields because of the high water table and risk of ponding.

## Interpretive Groups

Land capability classification: 4w

## NhA—Nicholson silt loam, 0 to 2 percent slopes

## Setting

Landscape position: Nearly level ridgetops

Size of areas: 2 to 60 acres Slope range: 0 to 2 percent

Parent material: Loess and residuum of limestone

#### Composition

Nicholson soil and similar inclusions: 80 percent

### Contrasting Inclusions

 Crider, Lawrence, Newark, Pembroke, Nolin, and Robertsville soils

#### Typical Profile

Surface layer:

0 to 6 inches—dark grayish brown silt loam

Subsoil:

6 to 19 inches—yellowish brown silty clay loam

19 to 25 inches—yellowish brown silty clay loam that has red and brown mottles

25 to 37 inches—yellowish brown silt loam fragipan that has gray and brown mottles

37 to 57 inches—red clay that has gray, brown, and black mottles

#### Substratum:

57 to 62 inches—yellowish brown clay that has gray mottles

## Soil Properties and Qualities

Drainage class: Moderately well drained

Permeability: Moderate above the fragipan and slow

or very slow in the fragipan Available water capacity: High

Soil reaction: Strongly acid to slightly acid High water table: At a depth of 1.5 to 2.0 feet from

December through April

Depth to bedrock: More than 60 inches

## Use and Management

## Cropland

Suitability: Well suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Planting later in spring, when the water table has receded, helps to prevent crusting and rutting of the soil surface.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Selecting forage plants that can tolerate short periods of wetness, such as tall fescue and ladino clover, is recommended.
- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Deferring livestock grazing until later in spring or until early summer, when the water table has receded, helps to prevent soil compaction and improve forage growth.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Poorly suited

Management measures and considerations:

• This soil is poorly suited to dwellings because of the seasonal wetness caused by the perched water table and slow permeability in the subsoil.

## Septic tank absorption fields

Suitability: Poorly suited

Management measures and considerations:

 This soil is poorly suited to septic tank filter fields because of the high water table and very slow permeability.

## Interpretive Groups

Land capability classification: 2w

## NhB—Nicholson silt loam, 2 to 6 percent slopes

## Setting

Landscape position: Undulating ridges

Size of areas: 2 to 300 acres Slope range: 2 to 6 percent

Parent material: Loess and residuum of limestone

## Composition

Nicholson soil and similar inclusions: 80 percent

## Contrasting Inclusions

 Crider, Lawrence, Newark, Nolin, Lindside, and Robertsville soils

## Typical Profile

Surface layer:

0 to 6 inches—dark grayish brown silt loam

Subsoil:

6 to 19 inches—yellowish brown silty clay loam

19 to 25 inches—yellowish brown silty clay loam that has red and brown mottles

25 to 37 inches—yellowish brown silt loam fragipan that has gray and brown mottles

37 to 57 inches—red clay that has gray, brown, and black mottles

Substratum:

57 to 62 inches—yellowish brown clay that has gray mottles

## Soil Properties and Qualities

Drainage class: Moderately well drained

Permeability: Moderate above the fragipan and slow

or very slow in the fragipan Available water capacity: High

Soil reaction: Strongly acid to slightly acid

High water table: At a depth of 1.5 to 2.0 feet from

December through April

Depth to bedrock: More than 60 inches

### **Use and Management**

#### Cropland

Suitability: Well suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Planting later in spring, when the water table has receded, helps to prevent crusting and rutting of the soil surface.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Selecting forage plants that can tolerate short periods of wetness, such as tall fescue and ladino clover, is recommended.
- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Deferring livestock grazing until later in spring or until early summer, when the water table has receded, helps to prevent soil compaction and improve forage growth.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Poorly suited

Management measures and considerations:

• This soil is poorly suited to dwellings because of the seasonal wetness caused by the perched water table and slow permeability in the subsoil.

## Septic tank absorption fields

Suitability: Poorly suited

Management measures and considerations:

 This soil is poorly suited to septic tank filter fields because of the high water table and very slow permeability.

### Interpretive Groups

Land capability classification: 2e

## NhC—Nicholson silt loam, 6 to 12 percent slopes

### Setting

Landscape position: Rolling ridges and side slopes

Size of areas: 5 to 15 acres Slope range: 6 to 12 percent

Parent material: Loess and residuum of limestone

#### Composition

Nicholson soil and similar inclusions: 80 percent

## Contrasting Inclusions

 Crider, Lawrence, Newark, Nolin, Lindside, and Robertsville soils

## Typical Profile

Surface layer:

0 to 6 inches—dark grayish brown silt loam

Subsoil:

6 to 19 inches—yellowish brown silty clay loam

19 to 25 inches—yellowish brown silty clay loam that has red and brown mottles

25 to 37 inches—yellowish brown silt loam fragipan that has gray and brown mottles

37 to 57 inches—red clay that has gray, brown, and black mottles

Substratum:

57 to 62 inches—yellowish brown clay that has gray mottles

#### Soil Properties and Qualities

Drainage class: Moderately well drained

Permeability: Moderate above the fragipan and slow

or very slow in the fragipan Available water capacity: High

Soil reaction: Strongly acid to slightly acid

High water table: At a depth of 1.5 to 2.0 feet from

December through April

Depth to bedrock: More than 60 inches

## Use and Management

## Cropland

Suitability: Suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Planting later in spring, when the water table has receded, helps to prevent crusting and rutting of the soil surface.

 Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Selecting forage plants that can tolerate short periods of wetness, such as tall fescue and ladino clover, is recommended.
- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Deferring livestock grazing until later in spring or until early summer, when the water table has receded, helps to prevent soil compaction and improve forage growth.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

## **Dwellings**

Suitability: Poorly suited

Management measures and considerations:

• This soil is poorly suited to dwellings because of the slope, seasonal wetness caused by the perched water table, and slow permeability in the subsoil.

### Septic tank absorption fields

Suitability: Poorly suited

Management measures and considerations:

• This soil is poorly suited to septic tank filter fields because of the slope, high water table, and very slow permeability.

#### Interpretive Groups

Land capability classification: 3e

## No—Nolin silt loam, frequently flooded

#### Setting

Landscape position: Flood plains Size of areas: 10 to 30 acres Slope range: 0 to 2 percent Parent material: Silty alluvium

## Composition

Nolin soil and similar inclusions: 90 percent

## Contrasting Inclusions

• Newark, Lindside, Melvin, Grigsby, and Elk soils

## Typical Profile

Surface layer:

0 to 9 inches—brown silt loam

Subsoil:

9 to 65 inches—dark yellowish brown silt loam

## Soil Properties and Qualities

Drainage class: Well drained Permeability: Moderate Available water capacity: High

Soil reaction: Strongly acid to moderately alkaline High water table: At a depth of more than 6 feet Flooding: Frequent for brief periods from December

through May

Depth to bedrock: More than 60 inches

## Use and Management

#### Cropland

Suitability: Suited

Management measures and considerations:

- The frequent flooding is the major management concern.
- Planting later in spring, when the risk of flooding has receded, helps to prevent damage to young plants.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Grazing should be deferred until later in spring when the risk of flooding has receded.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

## **Dwellings**

Suitability: Unsuited

Management measures and considerations:

- This soil is unsuited to dwellings because of the risk of flooding.
- Other sites in the survey area should be considered for dwellings.

## Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:
This soil is unsuited to septic tank filter fields because of the risk of flooding.

## Interpretive Groups

Land capability classification: 2w

## Np—Nolin silt loam, ponded

## Setting

Landscape position: Depressions Size of areas: 2 to 8 acres Slope range: 0 to 2 percent Parent material: Silty alluvium

## Composition

Nolin soil and similar inclusions: 90 percent

#### Contrasting Inclusions

Newark and Lindside soils

#### Typical Profile

Surface layer:

0 to 9 inches—brown silt loam

Subsoil:

9 to 65 inches—dark yellowish brown silt loam

## Soil Properties and Qualities

Drainage class: Well drained Permeability: Moderate Available water capacity: High

Soil reaction: Strongly acid to moderately alkaline High water table: At the surface to a depth of more

than 6 feet

Ponding: Frequent for brief periods from December

through May

Depth to bedrock: More than 60 inches

## Use and Management

## Cropland

Suitability: Poorly suited

Management measures and considerations:

- The ponding limits the planting and harvesting of many early season crops and small grains.
- Because of the risk of ponding, planting shortseason annuals, such as soybeans, later in spring is recommended.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

## Pasture and hay

Suitability: Suited

Management measures and considerations:

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Grazing should be deferred until later in spring or until early summer, when the risk of ponding has receded.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

## **Dwellings**

Suitability: Unsuited

Management measures and considerations:

- This soil is unsuited to dwellings because of the instability of sinkholes and the risk of ponding.
- Other sites in the survey area should be considered for dwellings.

#### Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• This soil is unsuited to septic tank filter fields because of the risk of ponding and the possibility of collapse into ground-water aquifers.

#### Interpretive Groups

Land capability classification: 3w

## OtA—Otwood silt loam, 0 to 2 percent slopes, rarely flooded

## Setting

Landscape position: Nearly level stream terraces Size of areas: 4 to 18 acres

Slope range: 0 to 2 percent Parent material: Silty alluvium

#### Composition

Otwood soil and similar inclusions: 90 percent

## **Contrasting Inclusions**

· Lawrence, Lindside, Newark, Nolin, and Elk soils

## Typical Profile

Surface layer:

0 to 6 inches—dark grayish brown silt loam

Subsoil:

6 to 20 inches—yellowish brown and brown silt loam that has pale brown and yellowish brown mottles

20 to 28 inches—pale brown silt loam that has gray and yellowish brown mottles

28 to 37 inches—light brownish gray and pale brown silt loam fragipan that has brown and yellowish brown mottles

37 to 44 inches—light brownish gray silt loam that has pale brown and very pale brown mottles

44 to 80 inches—brown silt loam that has brown and black mottles

## Soil Properties and Qualities

Drainage class: Moderately well drained

Permeability: Moderate above the fragipan and slow

or very slow in the fragipan Available water capacity: High

Soil reaction: Strongly acid to slightly acid High water table: At a depth of 1.5 to 2.0 feet from

Describes the self-Assil

December through April

Flooding: Rare

Depth to bedrock: More than 60 inches

### **Use and Management**

## Cropland

Suitability: Well suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Planting later in spring, when the water table has receded, helps to prevent crusting and rutting of the soil surface.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

## Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Selecting forage plants that can tolerate short periods of wetness, such as tall fescue and ladino clover, is recommended.
- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Deferring livestock grazing until later in spring or until early summer, when the water table has receded, helps to prevent soil compaction and improve forage growth.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Unsuited

Management measures and considerations:

 This soil is poorly suited to dwellings because of the risk of flooding, seasonal wetness caused by the perched water table, and slow permeability in the subsoil.

## Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• This soil is poorly suited to septic tank filter fields because of the risk of flooding, high water table, and very slow permeability.

## Interpretive Groups

Land capability classification: 2w

## OtB—Otwood silt loam, 2 to 6 percent slopes, rarely flooded

## Setting

Landscape position: Undulating stream terraces

Size of areas: 2 to 30 acres Slope range: 2 to 6 percent Parent material: Silty alluvium

#### Composition

Otwood soil and similar inclusions: 90 percent

### Contrasting Inclusions

• Lawrence, Lindside, Newark, Nolin, and Elk soils



Figure 6.—Corn residue on Otwood silt loam, 2 to 6 percent slopes, rarely flooded. This soil is well suited to most crops if they are planted later in spring, after the risk of flooding has passed.

## Typical Profile

Surface layer:

0 to 6 inches—dark grayish brown silt loam

#### Subsoil:

6 to 20 inches—yellowish brown and brown silt loam that has pale brown and yellowish brown mottles

20 to 28 inches—pale brown silt loam that has gray and yellowish brown mottles

28 to 37 inches—light brownish gray and pale brown silt loam fragipan that has brown and yellowish brown mottles

37 to 44 inches—light brownish gray silt loam that has pale brown and very pale brown mottles

44 to 80 inches—brown silt loam that has brown and black mottles

## Soil Properties and Qualities

Drainage class: Moderately well drained

Permeability: Moderate above the fragipan and slow

or very slow in the fragipan Available water capacity: High

Soil reaction: Strongly acid to slightly acid

High water table: At a depth of 1.5 to 2.0 feet from

December through April

Flooding: Rare

Depth to bedrock: More than 60 inches

### Use and Management

## Cropland

Suitability: Well suited (fig. 6)

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Planting later in spring, when the water table has receded, helps to prevent crusting and rutting of the soil surface.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

## Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Selecting forage plants that can tolerate short periods of wetness, such as tall fescue and ladino clover, is recommended.
- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Deferring livestock grazing until later in spring or until early summer, when the water table has receded, helps to prevent soil compaction and improve forage growth.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

## **Dwellings**

Suitability: Unsuited

Management measures and considerations:

• This soil is poorly suited to dwellings because of the risk of flooding, seasonal wetness caused by the perched water table, and slow permeability in the subsoil.

## Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• This soil is poorly suited to septic tank filter fields because of the risk of flooding, high water table, and very slow permeability.

## Interpretive Groups

Land capability classification: 2e

## PbA—Pembroke silt loam, 0 to 2 percent slopes

## Setting

Landscape position: Nearly level ridges

Size of areas: 3 to 15 acres Slope range: 0 to 2 percent

Parent material: Loess and residuum from limestone

#### Composition

Pembroke soil and similar inclusions: 90 percent

## Contrasting Inclusions

Nicholson, Vertrees, and Fredonia soils

## Typical Profile

Surface layer:

0 to 9 inches—dark brown silt loam

Subsoil:

9 to 18 inches—reddish brown silt loam

18 to 62 inches—yellowish red, red, and dark red silty clay loam

62 to 80 inches—dark red silty clay

## Soil Properties and Qualities

Drainage class: Well drained

Permeability: Moderate or moderately slow

Available water capacity: High

Soil reaction: Moderately acid to very strongly acid

High water table: None

Depth to bedrock: More than 60 inches

## Use and Management

## Cropland

Suitability: Well suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

## Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

## **Dwellings**

Suitability: Well suited

Management measures and considerations:

• Careful use of equipment and good design practices prevent the runoff of off-site sediments.

## Septic tank absorption fields

Suitability: Well suited

Management measures and considerations:

• An onsite investigation is needed in eroded areas to determine a suitable site.

## Interpretive Groups

Land capability classification: 1

## PeA—Pembroke-Urban land complex, 0 to 2 percent slopes

## Setting

Location: In and around the city of Bowling Green

### Composition

Pembroke soil and similar inclusions: 65 percent Urban land: 25 percent

#### Contrasting Inclusions

 Nolin, Crider, Nicholson, and Vertrees soils and Udorthents

#### Typical Profile

#### Pembroke

Surface layer:

0 to 9 inches—dark brown silt loam

Subsoil:

9 to 18 inches—reddish brown silt loam

18 to 62 inches—yellowish red, red, and dark red silty clay loam

62 to 80 inches—dark red silty clay

#### **Urban land**

Most of the Urban land consists of areas where 85 to 90 percent of the surface is covered by streets, buildings, parking lots, driveways, railroad yards, or airports. The remainder consists of cut and fill areas of

soil material imported onto the site or disturbed in the process of urbanization.

## Soil Properties and Qualities

See the interpretations tables for map units in urban areas.

## Use and Management

#### Residential and commercial structures

Suitability: Well suited

Management measures and considerations:

- Designing structures that conform to the natural slope reduces the amount of cutting or filling needed.
- Topsoil may need to be stockpiled and used to reclaim areas that are disturbed during construction.
- Careful use of equipment and good site conservation measures prevent the discharge of sediment onto adjacent property or into streams.
- Soil compaction is a problem around construction sites. Sites may require aeration or deep tillage and reseeding.
- Yards may be subject to periods of flooding if the soil is compacted. Shallow diversions may be needed to remove surface runoff and ponding in low areas.
- Diverting runoff from gutters and driveways away from structures reduces the chance of differential settling.

## Septic tank absorption fields

Suitability: Well suited

Management measures and considerations:

 Most areas of this map unit can be used for septic tank filter fields.

## Interpretive Groups

Land capability classification: None assigned

## Pm—Pits, loamy, frequently flooded

#### Setting

Location: In and around the city of Bowling Green on flood plains

Size of areas: 3 to 19 acres

## Composition

Approximately 95 percent of this map unit consists of excavated loamy material that was deposited by streams or rivers. Approximately 5 percent of the map unit consists of areas that have not been disturbed and piles of loamy alluvial material that has been exposed.

## **Use and Management**

This map unit has one active pit and several pits that have been abandoned. The soil is excavated for use as fill cover, topsoil, daily cover for landfill, and other landscaping needs. Most pits are rough and difficult to traverse, and some are 20 feet deep or more.

## Interpretive Groups

Land capability classification: None assigned

## Pq—Pits, quarry

## Setting

Location: In and around the city of Bowling Green Size of areas: 2 to 10 acres

## Composition

Approximately 90 percent of this map unit consists of excavated pits with exposed limestone walls. Most pits have vertical walls extending to a depth of 50 feet or more. Some pits are filled with water. Approximately 10 percent of the map unit consists of areas of spoil material made up of limestone rock and soil material.

## Use and Management

This map unit has one active quarry and several quarries that have been abandoned. The soil is excavated and set aside for reclamation or sold as topsoil or fill material. The pits consist of nearly vertical walls of limestone rock and are 50 feet or more deep. The rock material is removed and processed into various sizes for commercial use. The processed and graded rock is used in the construction and highway industries.

## Interpretive Groups

Land capability classification: None assigned

## RaF—Ramsey-Frondorf complex, 20 to 60 percent slopes

## Setting

Landscape position: Steep hillsides Size of areas: 15 to 500 acres Slope range: 20 to 60 percent

Parent material: Residuum from sandstone

## Composition

Ramsey soil: 75 percent Frondorf soil: 20 percent

#### Inclusions

· Wellston soils and areas of rock outcrop

## Typical Profile

#### Ramsey

Surface layer:

0 to 1 inch—dark grayish brown loam

Subsurface layer:

1 to 4 inches—brown channery loam

Subsoil:

4 to 12 inches—yellowish brown channery loam 12 to 19 inches—light yellowish brown channery loam 19 inches—sandstone bedrock

#### **Frondorf**

Surface layer:

0 to 5 inches-brown silt loam

Subsoil:

5 to 18 inches—strong brown and yellowish brown silty clay loam

18 to 26 inches—very channery silty clay loam 26 inches—hard sandstone

## Soil Properties and Qualities

Drainage class: Ramsey—somewhat excessively

drained; Frondorf—well drained

Permeability: Ramsey—rapid; Frondorf—moderately

rapid

Available water capacity: Low

Soil reaction: Strongly acid or very strongly acid

High water table: None

Depth to bedrock: Ramsey—less than 20 inches;

Frondorf—20 to 40 inches

#### Use and Management

## Cropland

Suitability: Unsuited

Management measures and considerations:

 These soils are unsuited to cropland because of the slope, low available water capacity, and depth to bedrock.

## Pasture and hay

Suitability: Unsuited

Management measures and considerations:

• These soils are unsuited to pasture and hay because of the slope, low available water capacity, and difficulty in operating farm machinery.

#### Woodland

Suitability: Poorly suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Unsuited

Management measures and considerations:

• These soils are unsuited to dwellings and commercial structures because of the slope and depth to bedrock.

#### Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• These soils are unsuited to septic tank filter fields because of the depth to bedrock and slope.

## Interpretive Groups

Land capability classification: 7s

## Ro—Robertsville silt loam, ponded

## Setting

Landscape position: Nearly level stream terraces and

flood plain depressions Size of areas: 3 to 90 acres Slope range: 0 to 2 percent Parent material: Silty alluvium

#### Composition

Robertsville soil and similar inclusions: 90 percent

#### Contrasting Inclusions

• Lawrence, Newark, Melvin, and Dunning soils

## Typical Profile

Surface layer:

0 to 10 inches—dark grayish brown silt loam that has brown mottles

Subsoil:

10 to 28 inches—light gray silt loam that has brown

28 to 40 inches—gray silty clay loam fragipan that has brown and black mottles

Substratum:

40 to 71 inches—gray, red, and yellowish red silty clay

#### Soil Properties and Qualities

Drainage class: Poorly drained

Permeability: Moderate above the fragipan and slow

or very slow in the fragipan

Available water capacity: High

Soil reaction: Strongly acid to extremely acid High water table: At or above the surface from

December through May

Ponding: Frequent for long to brief periods from

December through May

Flooding: Frequent for brief periods from December

through April

Depth to bedrock: More than 60 inches

## Use and Management

### Cropland

Suitability: Poorly suited

Management measures and considerations:

- In previously drained areas, planting and harvesting operations can be hindered by wetness or ponding.
- This soil is subject to crusting and clodding if tilled when the moisture content is high.

#### Pasture and hay

Suitability: Suited

Management measures and considerations:

- Selecting forage plants that can tolerate saturated conditions for extended periods is recommended.
- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Deferring livestock grazing until early summer helps to minimize compaction of the soil surface and prevent damage to forages.

#### Woodland

Suitability: Poorly suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

## **Dwellings**

Suitability: Unsuited

Management measures and considerations:

• Because of the seasonal wetness, flooding, and ponding, this soil is unsuited to residential and commercial structures.

## Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• Because of the seasonal high water table, flooding, and ponding, this soil is unsuited to septic tank filter fields.

## Interpretive Groups

Land capability classification: 4w

## RxF—Rock outcrop-Caneyville complex, 20 to 60 percent slopes

### Setting

Landscape position: Steep hillsides Size of areas: 7 to 100 acres Slope range: 20 to 60 percent

Parent material: Limestone bedrock and residuum

from limestone

## Composition

Rock outcrop: 55 percent Caneyville soil: 33 percent

#### **Inclusions**

Fredonia and Vertrees soils

## Typical Profile

#### **Rock outcrop**

This part of the map unit consists of large outcrops of limestone that extend from several inches to 3 feet above the soil surface in horizontal bands, or it occurs as individual blocks of limestone protruding from the surface. Also included are nearly vertical bluffs of limestone that extend from 25 to more than 100 feet in height.

## Caneyville

Surface layer:

0 to 6 inches—brown silt loam

Subsoil:

6 to 11 inches—yellowish red silty clay 11 to 21 inches—yellowish red clay 21 to 27 inches—dark reddish brown clay 27 inches—limestone bedrock

## Properties and Qualities of the Caneyville Soil

Drainage class: Well drained Permeability: Slow or very slow Available water capacity: Low

Soil reaction: Strongly acid or moderately acid

High water table: None

Depth to bedrock: 20 to 40 inches

#### Use and Management

### Cropland

Suitability: Unsuited

Management measures and considerations:

• This map unit is unsuited to cropland because of the numerous rock outcrops, slope, low available water capacity, and depth to bedrock.

## Pasture and hay

Suitability: Unsuited

Management measures and considerations:

 This map unit is unsuited to pasture and hay because of the numerous rock outcrops, slope, low available water capacity, and difficulty in operating farm machinery.

#### Woodland

Suitability: Poorly suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Unsuited

Management measures and considerations:

• This map unit is unsuited to dwellings and commercial structures because of the numerous rock outcrops, slope, and depth to bedrock.

#### Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• This map unit is unsuited to septic tank filter fields because of the numerous rock outcrops, depth to bedrock, and slope.

## Interpretive Groups

Land capability classification: 7s

## SaA—Sadler silt loam, 0 to 2 percent slopes

#### Settina

Landscape position: Nearly level ridgetops

Size of areas: 2 to 20 acres Slope range: 0 to 2 percent

Parent material: Loess and residuum of sandstone

#### Composition

Sadler soil and similar inclusions: 85 percent

## **Contrasting Inclusions**

• Zanesville, Frondorf, Wellston, and Newark soils

#### Typical Profile

Surface layer:

0 to 9 inches—brown silt loam

Subsoil:

9 to 23 inches—brownish yellow silty clay loam that has yellowish brown and brown mottles

- 23 to 26 inches—brown and yellowish brown silt loam that has pale brown and light brownish gray mottles
- 26 to 56 inches—brownish yellow, grayish brown, and yellowish brown silty clay loam fragipan that has light yellowish brown, brown, and black mottles
- 56 to 65 inches—light brownish gray silt loam that has gray, strong brown, and black mottles

65 inches—hard sandstone bedrock

## Soil Properties and Qualities

Drainage class: Moderately well drained

Permeability: Moderate above the fragipan and slow

or very slow in the fragipan Available water capacity: High

Soil reaction: Strongly acid or very strongly acid High water table: At a depth of 1.5 to 2.0 feet from

December through April

Depth to bedrock: More than 60 inches

### Use and Management

#### Cropland

Suitability: Well suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Planting later in spring, when the water table has receded, helps to prevent crusting and rutting of the soil surface.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

## Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Selecting forage plants that can tolerate short periods of wetness, such as tall fescue and ladino clover, is recommended.
- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Deferring livestock grazing until later in spring or until early summer, when the water table has receded, helps to prevent soil compaction and improve forage growth.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Poorly suited

Management measures and considerations:

• This soil is poorly suited to dwellings because of the seasonal wetness caused by the perched water table and slow permeability in the subsoil.

#### Septic tank absorption fields

Suitability: Poorly suited

Management measures and considerations:

 This soil is poorly suited to septic tank filter fields because of the high water table and very slow permeability.

## Interpretive Groups

Land capability classification: 2w

## SaB—Sadler silt loam, 2 to 6 percent slopes

#### Setting

Landscape position: Undulating ridges

Size of areas: 4 to 90 acres Slope range: 2 to 6 percent

Parent material: Loess and residuum of sandstone

#### Composition

Sadler soil and similar inclusions: 85 percent

### Contrasting Inclusions

 Zanesville, Frondorf, Lawrence, Newark, and Wellston soils

### Typical Profile

Surface layer:

0 to 9 inches—brown silt loam

Subsoil:

- 9 to 23 inches—brownish yellow silty clay loam that has yellowish brown and brown mottles
- 23 to 26 inches—brown and yellowish brown silt loam that has pale brown and light brownish gray mottles
- 26 to 56 inches—brownish yellow, grayish brown, and yellowish brown silty clay loam fragipan that has light yellowish brown, brown, and black mottles
- 56 to 65 inches—light brownish gray silt loam that has gray, strong brown, and black mottles

65 inches—hard sandstone bedrock

## Soil Properties and Qualities

Drainage class: Moderately well drained

Permeability: Moderate above the fragipan and slow

or very slow in the fragipan Available water capacity: High

Soil reaction: Strongly acid or very strongly acid High water table: At a depth of 1.5 to 2.0 feet from

December through April

Depth to bedrock: More than 60 inches

## Use and Management

### Cropland

Suitability: Well suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Planting later in spring, when the water table has receded, helps to prevent crusting and rutting of the soil surface.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Selecting forage plants that can tolerate short periods of wetness, such as tall fescue and ladino clover, is recommended.
- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Deferring livestock grazing until later in spring or until early summer, when the water table has receded, helps to prevent soil compaction and improve forage growth.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Poorly suited

Management measures and considerations:

• This soil is poorly suited to dwellings because of the seasonal wetness caused by the perched water table and slow permeability in the subsoil.

## Septic tank absorption fields

Suitability: Poorly suited

Management measures and considerations:

 This soil is poorly suited to septic tank filter fields because of the high water table and very slow permeability.

## Interpretive Groups

Land capability classification: 2e

## UaC—Udorthents, 0 to 20 percent slopes

## Setting

Location: In and around the city of Bowling Green

## Composition

Udorthents: 95 percent

#### Inclusions

· Crider, Vertrees, and Pembroke soils

## Typical Profile

This map unit consists of nearly level to moderately steep areas of soils and rock material that have been cut, graded, and filled during the process of urbanization. Most of the natural soil has been removed or altered to the extent that it no longer can be classified at the series level.

#### Soil Properties and Qualities

In most areas of the map unit, the surface is covered with broken bits of concrete, bricks, limestone rock, debris from construction, and clay or other fill materials (fig. 7). These materials are more than 8 feet deep in some areas.

#### Use and Management

All intended uses require an onsite investigation and careful examination of existing materials at the site.

#### Interpretive Groups

Land capability classification: None assigned

## UaD—Udorthents, refuse substratum, 0 to 25 percent slopes

### Setting

Location: In and around the city of Bowling Green



Figure 7.—An area of Udorthents, 0 to 20 percent slopes. Most areas of this map unit are covered with broken bits of concrete, bricks, limestone rock, debris from construction, and clay or other fill materials.

## Composition

Udorthents: 95 percent

#### **Inclusions**

• Crider, Vertrees, and Pembroke soils

## Typical Profile

This map unit is made up of reclaimed areas that were previously used as solid waste landfills. It consists of nearly level to moderately steep areas of soils and rock material that have been filled during the process of solid waste disposal. The natural soil has been removed and redeposited in alternating layers with solid waste material at varying depths.

#### Soil Properties and Qualities

In most areas of the map unit, the surface has been smoothed and graded and planted in grass and legumes.

## Use and Management

The primary uses of this map unit are athletic fields, picnic areas, and small parks. Most areas are established in stands of grass and legumes. Some areas have been planted in small shrubs and trees.

### Interpretive Groups

Land capability classification: None assigned

## Ub—Urban land-Udorthents complex, 0 to 12 percent slopes

### Setting

Location: In and around the city of Bowling Green

## Composition

Urban land: 75 percent Udorthents: 22 percent

#### Inclusions

· Crider, Nicholson, and Baxter soils

## Typical Profile

#### **Urban land**

Most of the Urban land consists of areas where 85 to 90 percent of the surface is covered by streets, buildings, parking lots, driveways, railroad yards, or airports. The remainder consists of cut and fill areas of soil material imported onto the site or disturbed in the process of urbanization.

#### **Udorthents**

This part of the map unit consists of nearly level and rolling areas of soils and rock material that have been cut, graded, and filled during the process of urbanization. Most of the natural soil has been removed or altered to the extent that it no longer can be classified at the series level.

## Soil Properties and Qualities

• See the interpretations tables for map units in urban areas.

## Use and Management

#### Residential and commercial structures

Suitability: Suited

Management measures and considerations:

- Designing structures that conform to the natural slope reduces the amount of cutting or filling needed.
- Topsoil may need to be stockpiled and used to reclaim areas that are disturbed during construction.
- Careful use of equipment and good site conservation measures prevent the discharge of sediment onto adjacent property or into streams.
- Soil compaction is a problem around construction sites. Sites may require aeration or deep tillage and reseeding.
- Yards may be subject to periods of flooding if the soil is compacted. Shallow diversions may be needed to remove surface runoff and ponding in low areas.
- Diverting runoff from gutters and driveways away from structures reduces the chance of differential settling.

## Septic tank absorption fields

Suitability: Unknown

Management measures and considerations:

 All areas of this map unit require an onsite investigation if the unit is to be used for septic tank filter fields.

## Interpretive Groups

Land capability classification: None assigned

# Uc—Urban land-Udorthents complex, clayey substratum, hard bedrock 0-5 feet, 0 to 12 percent slopes

#### Setting

Location: In and around the city of Bowling Green

## Composition

Urban land: 50 percent Udorthents: 30 percent

#### **Inclusions**

• Crider, Vertrees, Caneyville, and Baxter soils

## Typical Profile

#### Urban land

Most of the Urban land consists of areas where 85 to 90 percent of the surface is covered by streets, buildings, parking lots, driveways, railroad yards, or airports. The remainder consists of cut and fill areas of soil material imported onto the site or disturbed in the process of urbanization.

#### **Udorthents**

This part of the map unit consists of nearly level and rolling areas of soils and rock material that have been cut, graded, and filled during the process of urbanization. Most of the natural soil has been removed or altered to the extent that it no longer can be classified at the series level. The soil material consists of reworked clay mixed with chert gravel and cobbles. Hard limestone bedrock is at a depth of less than 5 feet.

## Soil Properties and Qualities

 See the interpretations tables for map units in urban areas.

## Use and Management

#### Residential and commercial structures

Suitability: Suited (fig. 8)

Management measures and considerations:

- The design of structures and driveways should conform to the natural slope, and shallower excavations should be considered because of the depth to hard bedrock.
- Design modifications that overcome the shrink-swell potential are needed for excavations.



Figure 8.—An area of Urban land-Udorthents complex, clayey substratum, hard bedrock 0-5 feet, 0 to 12 percent slopes. Excavations are limited to dwellings without basements because of the depth to bedrock.

- Stockpiling topsoil, if available, or planning to import topsoil to the site is necessary in order to reclaim areas disturbed during construction.
- Careful use of equipment and good site conservation measures prevent the discharge of sediment onto adjacent property or into streams.
- Soil compaction is a severe problem around construction sites. Sites require aeration or deep tillage and reseeding.
- Yards may be subject to ponding in low areas where the soil is compacted. Shallow diversions may be needed to remove surface runoff from low areas.
- Diverting runoff from gutters and driveways away from structures reduces the chance of differential settling.

## Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

• All areas of this map unit require central sewerage because of the slow or very slow permeability in the subsoil and the depth to hard bedrock.

### Interpretive Groups

Land capability classification: None assigned

## Ud—Urban land-Udorthents complex, clayey substratum, hard bedrock >5 feet, 0 to 12 percent slopes

#### Setting

Location: In and around the city of Bowling Green

## Composition

Urban land: 75 percent Udorthents: 20 percent

#### **Inclusions**

· Crider, Vertrees, Caneyville, and Baxter soils

## Typical Profile

#### **Urban land**

Most of the Urban land consists of areas where 85 to 90 percent of the surface is covered by streets, buildings, parking lots, driveways, railroad yards, or airports. The remainder consists of cut and fill areas of soil material imported onto the site or disturbed in the process of urbanization.

#### **Udorthents**

This part of the map unit consists of nearly level and rolling areas of soils and rock material that have been cut, graded, and filled during the process of urbanization. Most of the natural soil has been removed or altered to the extent that it no longer can be classified at the series level. The soil material consists of reworked clay mixed with chert gravel and cobbles. Hard limestone bedrock is at a depth of more than 5 feet.

## Soil Properties and Qualities

• See the interpretations tables for map units in urban areas.

## Use and Management

#### Residential and commercial structures

Suitability: Suited

Management measures and considerations:

- Designing structures that conform to the natural slope reduces the amount of cutting or filling needed.
- Design modifications that overcome the shrink-swell potential are needed in areas of deep excavations.
- Stockpiling topsoil, if available, or planning to import topsoil to the site is necessary in order to reclaim areas disturbed during construction.
- Careful use of equipment and good site conservation measures prevent the discharge of sediment onto adjacent property or into streams.
- Soil compaction is a severe problem around construction sites. Sites require aeration or deep tillage and reseeding.
- Yards may be subject to ponding in low areas where the soil is compacted. Shallow diversions may be needed to remove surface runoff from low areas.
- Diverting runoff from gutters and driveways away from structures reduces the chance of differential settling.

## Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

 All areas of this map unit require central sewerage because of the slow or very slow permeability in the subsoil and soil compaction.

### Interpretive Groups

Land capability classification: None assigned

## Us—Urban land-Udorthents complex, smoothed, 0 to 15 percent slopes

#### Setting

Location: Primarily on Interstate 65 and major U.S. and State highways bisecting Warren County and around the city of Bowling Green

## Composition

Urban land: 60 percent Udorthents: 40 percent

## Typical Profile

#### **Urban land**

Urban land mainly consists of areas where the surface is covered by asphalt, such as major highway lanes, parking areas, and access ramps.

#### **Udorthents**

This part of the map unit consists of nearly level to moderately steep areas of soil and rock material that have been filled, shaped, and graded for road shoulders and medians between road surfaces.

#### Soil Properties and Qualities

 See the interpretations tables for map units in urban areas.

### Use and Management

#### Residential and commercial structures

Suitability: Unsuited

Management measures and considerations:

• This map unit consists of soil material used for major highways and is unsuited to use for structures.

## Septic tank absorption fields

Suitability: Unsuited

Management measures and considerations:

 All areas in this map unit are in major highways and are not suited to use as septic tank filter fields.

## Interpretive Groups

Land capability classification: None assigned

## VrC3—Vertrees silty clay loam, 6 to 12 percent slopes, severely eroded

#### Setting

Landscape position: Side slopes and areas around the

rims of depressions
Size of areas: 3 to 25 acres
Slope range: 6 to 12 percent

Parent material: Residuum from limestone

## Composition

Vertrees soil and similar inclusions: 85 percent

## Contrasting Inclusions

• Crider, Newark, Nolin, Baxter, and Fredonia soils

## Typical Profile

Surface layer:

0 to 3 inches—reddish brown silty clay loam

Subsoil:

3 to 20 inches—red clay 20 to 80 inches—dusky red clay

## Soil Properties and Qualities

Drainage class: Well drained

Permeability: Moderately slow or slow Available water capacity: Moderate

Soil reaction: Strongly acid or moderately acid

High water table: None

Depth to bedrock: More than 60 inches

#### Use and Management

#### Cropland

Suitability: Suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Well suited

Management measures and considerations:

• Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.

• Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

## **Dwellings**

Suitability: Suited

Management measures and considerations:

- Areas around sinkholes are unstable and have a considerable risk of collapse if used for dwellings.
- Structures should be designed so that they conform to the natural slope.
- Topsoil should be stockpiled and used to reclaim areas that are disturbed during construction.
- Design modifications that overcome the shrink-swell potential are needed in areas of deep excavations.

## Septic tank absorption fields

Suitability: Poorly suited

Management measures and considerations:

- This soil is limited for septic systems because of the slow permeability, slope, and moderate shrink-swell potential in the lower part of the subsoil.
- An onsite investigation is needed to determine site suitability and design.

#### Interpretive Groups

Land capability classification: 4e

## VtC3—Vertrees-Urban land complex, 6 to 12 percent slopes, severely eroded

#### Setting

Location: In and around the city of Bowling Green

#### Composition

Vertrees soil and similar inclusions: 60 percent Urban land: 25 percent

#### Contrasting Inclusions

Udorthents and Baxter, Newark, and Nolin soils

### Typical Profile

## **Vertrees**

Surface layer:

0 to 3 inches—reddish brown silty clay loam

Subsoil:

3 to 20 inches—red clay 20 to 80 inches—dusky red clay

#### **Urban land**

Most of the Urban land consists of areas where 85 to 90 percent of the surface is covered by streets, buildings, parking lots, driveways, railroad yards, or airports. The remainder consists of cut and fill areas of soil material imported onto the site or disturbed in the process of urbanization.

## Soil Properties and Qualities

• See the interpretations tables for map units in urban areas.

## Use and Management

#### Residential and commercial structures

Suitability: Suited

Management measures and considerations:

- Designing structures that conform to the natural slope reduces the amount of cutting or filling needed.
- Topsoil may need to be stockpiled and used to reclaim areas that are disturbed during construction.
- Careful use of equipment and good site conservation measures prevent the discharge of sediment onto adjacent property or into streams.
- Soil compaction is a problem around construction sites. Sites may require aeration or deep tillage and reseeding.
- Yards may be subject to rill and gully erosion if the soil is compacted. Shallow diversions may be needed to remove surface runoff.
- Modifications in the design of footings and basements that overcome the shrink-swell potential are needed in areas of deep excavations.
- Diverting runoff from gutters and driveways away from structures reduces the chance of differential settling or cracking of foundations caused by the shrink-swell potential.

### Septic tank absorption fields

Suitability: Poorly suited

Management measures and considerations:

- This soil is limited for septic systems because of the slow permeability and moderate shrink-swell potential in the lower part of the subsoil.
- Lot design for structures and driveways needs to allow sufficient area for a septic field and conform to the slope.
- An onsite investigation is needed to determine a suitable site.

## Interpretive Groups

Land capability classification: None assigned

#### W—Water

## Setting

This map unit consists of small to large constructed or natural bodies of water. It includes small tributaries, creeks, and rivers and water areas at the head of drainageways and in depressions. It occurs throughout the survey area. This unit makes up 3,650 acres in Warren County. Individual areas are irregular in shape and range from 3 to more than 89 acres in size.

## Composition

This map unit includes small ponds and moderately sized impoundments, such as Shanty Hollow Lake and Dewey Lake. Several major rivers and large streams flow through the survey area. They include the Green, Barren, and Gasper Rivers and Drake's Creek.

## Use and Management

This map unit is used for fishing, canoeing, and other recreational activities, as a source of municipal and irrigation water storage, and for fire protection.

#### Interpretive Groups

Land capability classification: None assigned

## WeB—Wellston silt loam, 2 to 6 percent slopes

#### Setting

Landscape position: Undulating ridges

Size of areas: 2 to 15 acres Slope range: 2 to 6 percent

Parent material: Loess and residuum from sandstone

#### Composition

Wellston soil and similar inclusions: 90 percent

#### Contrasting Inclusions

Zanesville, Sadler, Frondorf, and Newark soils

## Typical Profile

Surface layer:

0 to 8 inches—brown silt loam

Subsurface layer:

8 to 13 inches—yellowish brown silt loam

Subsoil:

13 to 30 inches—strong brown silty clay loam that has brown and pale brown mottles

30 to 46 inches—strong brown gravelly clay loam 46 inches—hard sandstone bedrock

## Soil Properties and Qualities

Drainage class: Well drained Permeability: Moderate Available water capacity: High

Soil reaction: Strongly acid or very strongly acid

High water table: None

Depth to bedrock: 40 to 60 inches

## Use and Management

#### Cropland

Suitability: Well suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

### Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

## **Dwellings**

Suitability: Well suited

Management measures and considerations:

- Careful use of equipment and good design practices prevent the runoff of off-site sediments.
- Deep excavations are limited by the depth to bedrock.

## Septic tank absorption fields

Suitability: Suited

Management measures and considerations:

- The depth to bedrock is a limitation affecting filter field trenches.
- An onsite investigation is needed in eroded areas to determine a suitable site.

## Interpretive Groups

Land capability classification: 2e

## WeC2—Wellston silt loam, 6 to 12 percent slopes, eroded

## Setting

Landscape position: Rolling ridges Size of areas: 2 to 30 acres Slope range: 6 to 12 percent

Parent material: Loess and residuum from sandstone

## Composition

Wellston soil and similar inclusions: 85 percent

## Contrasting Inclusions

· Zanesville, Sadler, Frondorf, and Newark soils

## Typical Profile

Surface layer:

0 to 5 inches—brown silt loam

Subsoil:

5 to 30 inches—strong brown silty clay loam 30 to 46 inches—strong brown gravelly clay loam 46 inches—hard sandstone bedrock

## Soil Properties and Qualities

Drainage class: Well drained Permeability: Moderate Available water capacity: High

Soil reaction: Strongly acid or very strongly acid

High water table: None

Depth to bedrock: 40 to 60 inches

#### Use and Management

## Cropland

Suitability: Suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

## Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Suited

Management measures and considerations:

- Structures should be designed so that they conform to the natural slope.
- Topsoil should be stockpiled and used to reclaim areas that are disturbed during construction.
- Careful use of equipment and good design practices prevent the runoff of off-site sediments.
- Deep excavations are limited by the depth to bedrock.

#### Septic tank absorption fields

Suitability: Suited

Management measures and considerations:

- Filter lines should be installed on the contour and conform to the slope.
- An onsite investigation is needed in eroded areas to determine a suitable site.
- The depth to bedrock is a limitation affecting filter field trenches.

## Interpretive Groups

Land capability classification: 3e

## ZaB—Zanesville silt loam, 2 to 6 percent slopes

## Setting

Landscape position: Undulating ridges

Size of areas: 2 to 200 acres Slope range: 2 to 6 percent

Parent material: Loess and residuum of sandstone

### Composition

Zanesville soil and similar inclusions: 85 percent

## Contrasting Inclusions

Lawrence, Sadler, Frondorf, Ramsey, and Wellston soils

## Typical Profile

Surface layer:

0 to 8 inches—dark grayish brown silt loam

Subsoil

8 to 16 inches—strong brown silty clay loam 16 to 23 inches—yellowish brown silty clay loam 23 to 35 inches—yellowish brown silty clay loam fragipan that has gray and brown mottles

35 to 45 inches—yellowish brown silty clay loam fragipan that has gray mottles

Substratum:

45 to 56 inches—yellowish brown clay loam that has gray mottles

56 inches—hard sandstone bedrock

### Soil Properties and Qualities

Drainage class: Moderately well drained

Permeability: Moderate above the fragipan and slow

or very slow in the fragipan Available water capacity: High

Soil reaction: Strongly acid or very strongly acid High water table: At a depth of 1.5 to 2.0 feet from

December through April Depth to bedrock: 40 to 60 inches

#### Use and Management

#### Cropland

Suitability: Well suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Planting later in spring, when the water table has receded, helps to prevent crusting and rutting of the soil surface.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Selecting forage plants that can tolerate short periods of wetness, such as tall fescue and ladino clover, is recommended.
- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.

- Deferring livestock grazing until later in spring or until early summer, when the water table has receded, helps to prevent soil compaction and improve forage growth.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

## **Dwellings**

Suitability: Poorly suited

Management measures and considerations:

• This soil is poorly suited to dwellings because of the seasonal wetness caused by the perched water table and slow permeability in the subsoil.

## Septic tank absorption fields

Suitability: Poorly suited

Management measures and considerations:

• This soil is poorly suited to septic tank filter fields because of the high water table and very slow permeability.

## Interpretive Groups

Land capability classification: 2e

## ZaC2—Zanesville silt loam, 6 to 12 percent slopes, eroded

## Setting

Landscape position: Rolling ridges and side slopes

Size of areas: 5 to 65 acres Slope range: 6 to 12 percent

Parent material: Loess and residuum of sandstone

#### Composition

Zanesville soil and similar inclusions: 80 percent

## **Contrasting Inclusions**

• Frondorf, Sadler, Ramsey, and Wellston soils

#### Typical Profile

Surface layer:

0 to 5 inches—dark yellowish brown silt loam

Subsoil:

5 to 20 inches—yellowish brown silty clay loam

20 to 45 inches—yellowish brown silt loam fragipan that has gray and brown mottles

Substratum:

45 to 56 inches—yellowish brown clay loam that has gray, brown, and black mottles
56 inches—hard sandstone bedrock

#### Soil Properties and Qualities

Drainage class: Moderately well drained

Permeability: Moderate above the fragipan and slow

or very slow in the fragipan Available water capacity: High

Soil reaction: Strongly acid to slightly acid

High water table: At a depth of 1.5 to 2.0 feet from

December through April Depth to bedrock: 40 to 60 inches

## Use and Management

#### Cropland

Suitability: Suited

Management measures and considerations:

- Practices that include minimum tillage or no-till planting, farming on the contour, grassed waterways, and winter cover crops reduce the risk of soil erosion.
- Planting later in spring, when the water table has receded, helps to prevent crusting and rutting of the soil surface.
- Nutrient management practices, such as soil tests, returning crop residue to the soil, and timing of fertilizer and chemical treatments, help to improve soil health and productivity.

#### Pasture and hay

Suitability: Well suited

Management measures and considerations:

- Selecting forage plants that can tolerate short periods of wetness, such as tall fescue and ladino clover, is recommended.
- Periodic clipping and mowing helps to maintain uniform growth and discourages weed competition.
- Deferring livestock grazing until later in spring or until early summer, when the water table has receded, helps to prevent soil compaction and improve forage growth.
- Proper stocking rates, lime and fertilizer programs, and pasture rotation increase the quality and quantity of forages.

#### Woodland

Suitability: Well suited

Management measures and considerations:

• See the tables on forest productivity and forestland management.

#### **Dwellings**

Suitability: Poorly suited

Management measures and considerations:

• This soil is poorly suited to dwellings because of the slope, seasonal wetness caused by the perched water table, and slow permeability in the subsoil.

#### Septic tank absorption fields

Suitability: Poorly suited

Management measures and considerations:

 This soil is poorly suited to septic tank filter fields because of the slope, high water table, and very slow permeability.

# Interpretive Groups

Land capability classification: 3e

# ZuB—Zanesville-Urban land complex, 2 to 6 percent slopes

#### Setting

Location: In and around the city of Richardsville

# Composition

Zanesville soil and similar inclusions: 65 percent Urban land: 25 percent

#### **Contrasting Inclusions**

 Wellston, Frondorf, Lawrence, and Sadler soils and Udorthents

# Typical Profile

# Zanesville

Surface layer:

0 to 8 inches—dark grayish brown silt loam

#### Subsoil:

8 to 16 inches—strong brown silty clay loam
16 to 23 inches—yellowish brown silty clay loam
23 to 35 inches—yellowish brown silty clay loam
fragipan that has gray and brown mottles
35 to 45 inches—yellowish brown silty clay loam
fragipan that has gray mottles

Substratum:

45 to 56 inches—yellowish brown clay loam that has gray mottles

56 inches—hard sandstone bedrock

#### Urban land

Most of the Urban land consists of areas where 85 to 90 percent of the surface is covered by streets, buildings, parking lots, driveways, railroad yards, or airports. The remainder consists of cut and fill areas of soil material imported onto the site or disturbed in the process of urbanization.

# Soil Properties and Qualities

• See the interpretations tables for map units in urban areas.

# Use and Management

#### Residential and commercial structures

Suitability: Suited

Management measures and considerations:

- Designing structures that conform to the natural slope reduces the amount of cutting or filling needed.
- Topsoil may need to be stockpiled and used to reclaim areas that are disturbed during construction.
- Careful use of equipment and good site conservation measures prevent the discharge of sediment onto adjacent property or into streams.
- Soil compaction is a problem around construction sites. Sites may require aeration or deep tillage and reseeding.
- Yards may be subject to periods of ponding if the soil is compacted. Shallow diversions may be needed to remove surface runoff from low areas.
- Modifications in the design of footings and basements that overcome the depth to bedrock limitation are needed in areas of deep excavations.
- Diverting runoff from gutters and driveways away from structures reduces the chance of differential settling or cracking of foundations.

#### Septic tank absorption fields

Suitability: Poorly suited

Management measures and considerations:

- The Zanesville soil is limited for septic systems because of the slow permeability and wetness caused by the perched water table.
- Lot design for structures and driveways needs to allow sufficient area for a septic field.
- An onsite investigation is needed to determine site suitability.

#### Interpretive Groups

Land capability classification: None assigned

# Use and Management of the Soils

This soil survey is an inventory and evaluation of the soils in the survey area. It can be used to adjust land uses to the limitations and potentials of natural resources and the environment. Also, it can help to prevent soil-related failures in land uses.

In preparing a soil survey, soil scientists, conservationists, engineers, and others collect extensive field data about the nature and behavioral characteristics of the soils. They collect data on erosion, droughtiness, flooding, and other factors that affect various soil uses and management. Field experience and collected data on soil properties and performance are used as a basis in predicting soil behavior.

Information in this section can be used to plan the use and management of soils for crops, pasture, and forest; as sites for buildings, sanitary facilities, highways and other transportation systems, and parks and other recreational facilities; and as wildlife habitat. It can be used to identify the potentials and limitations of each soil for specific land uses and to help prevent construction failures caused by unfavorable soil properties.

Planners and others using soil survey information can evaluate the effect of specific land uses on productivity and on the environment in all or part of the survey area. The survey can help planners to maintain or create a land use pattern in harmony with the natural soil.

Contractors can use this survey to locate sources of sand and gravel, roadfill, and topsoil. They can use it to identify areas where bedrock, wetness, or very firm soil layers can cause difficulty in excavation.

Health officials, highway officials, engineers, and others may also find this survey useful. The survey can help them plan the safe disposal of wastes and locate sites for pavements, sidewalks, campgrounds, playgrounds, lawns, and trees and shrubs.

# **Interpretive Ratings**

The interpretive tables in this survey rate the soils in the survey area for various uses. Many of the tables identify the limitations that affect specified uses and indicate the severity of those limitations. The ratings in these tables are both verbal and numerical.

#### **Rating Class Terms**

Rating classes are expressed in the tables in terms that indicate the extent to which the soils are limited by all of the soil features that affect a specified use or in terms that indicate the suitability of the soils for the use. Thus, the tables may show limitation classes or suitability classes. Terms for the limitation classes are not limited, somewhat limited, and very limited. The suitability ratings are expressed as well suited, moderately well suited, poorly suited, and unsuited or as good, fair, and poor.

#### **Numerical Ratings**

Numerical ratings in the tables indicate the relative severity of individual limitations. The ratings are shown as decimal fractions ranging from 0.00 to 1.00. They indicate gradations between the point at which a soil feature has the greatest negative impact on the use and the point at which the soil feature is not a limitation. The limitations appear in order from the most limiting to the least limiting. Thus, if more than one limitation is identified, the most severe limitation is listed first and the least severe one is listed last.

## **Crops and Pasture**

General management needed for crops and pasture is suggested in this section (fig. 9). The estimated yields of the main crops and pasture plants are listed, the system of land capability classification used by the Natural Resources Conservation Service is explained, and prime farmland is described.

Planners of management systems for individual fields or farms should consider the detailed information given in the description of each soil under the heading "Detailed Soil Map Units." Specific information can be obtained from the local office of the Natural Resources Conservation Service or the Cooperative Extension Service.



Figure 9.—Rotating crops with pasture and hay plants is an excellent management practice for cropland. This practice helps to control erosion and improve soil quality.

# **Yields per Acre**

The average yields per acre that can be expected of the principal crops under a high level of management are shown in tables 5 and 6. In any given year, yields may be higher or lower than those indicated in the tables because of variations in rainfall and other climatic factors. The land capability classification of map units in the survey area also is shown in the tables.

The yields are based mainly on the experience and records of farmers, conservationists, and extension agents. Available yield data from nearby counties and results of field trials and demonstrations also are considered.

The management needed to obtain the indicated yields of the various crops depends on the kind of soil and the crop. Management can include drainage, erosion control, and protection from flooding; the proper planting and seeding rates; suitable high-

yielding crop varieties; appropriate and timely tillage; control of weeds, plant diseases, and harmful insects; favorable soil reaction and optimum levels of nitrogen, phosphorus, potassium, and trace elements for each crop; effective use of crop residue, barnyard manure, and green manure crops; and harvesting that ensures the smallest possible loss.

The estimated yields reflect the productive capacity of each soil for each of the principal crops. Yields are likely to increase as new production technology is developed. The productivity of a given soil compared with that of other soils, however, is not likely to change.

Crops other than those shown in tables 5 and 6 are grown in the survey area, but estimated yields are not listed because the acreage of such crops is small. The local office of the Natural Resources Conservation Service or of the Cooperative Extension Service can provide information about the management and productivity of the soils for those crops.

# **Land Capability Classification**

Land capability classification is one of a number of interpretative groupings made primarily for agricultural purposes (10). Crops that require special management are excluded. The soils are grouped according to their limitations for agronomic uses, the risk of damage if they are used for crops, and the way they respond to management. The criteria used in grouping the soils do not include major and generally expensive landforming that would change slope, depth, or other characteristics of the soils, nor do they include possible, but unlikely, major reclamation projects.

In the capability system, soils are generally grouped at two levels—capability class and subclass.

Capability classes, the broadest groups, are designated by the numbers 1 through 8. The numbers indicate progressively greater limitations and narrower choices for agronomic uses. The classes are defined as follows:

Class 1 soils have slight limitations that restrict their use.

Class 2 soils have moderate limitations that restrict the choice of plants or that require moderate conservation practices.

Class 3 soils have severe limitations that restrict the choice of plants or that require special conservation practices, or both.

Class 4 soils have very severe limitations that restrict the choice of plants or that require very careful management, or both.

Class 5 soils are subject to little or no erosion but have other limitations, impractical to remove, that restrict their use mainly to pasture, forest, or wildlife habitat.

Class 6 soils have severe limitations that make them generally unsuitable for cultivation and that restrict their use mainly to pasture, forest, or wildlife habitat.

Class 7 soils have very severe limitations that make them unsuitable for cultivation and that restrict their use mainly to forest or wildlife habitat.

Class 8 soils and miscellaneous areas have limitations that preclude commercial plant production and that restrict their use to recreational purposes, wildlife habitat, watershed, or esthetic purposes.

Capability subclasses are soil groups within one class. They are designated by adding a small letter, e, w, or s to the class numeral, for example, 2e. The letter e shows that the main hazard is the risk of erosion unless close-growing plant cover is maintained; w shows that water in or on the soil interferes with plant growth, cultivation, or both; and s shows that the soil is limited mainly because it is

shallow, droughty, stony, or has numerous rock outcrops.

In class 1 there are no subclasses because the soils of this class have few limitations. Class 5 contains only the subclasses indicated by w or s, because the soils in class 5 are subject to little or no erosion. They have other limitations that restrict their use to pasture, forest, wildlife habitat, or recreation.

The capability classification of map units in this survey area is given in the section "Detailed Soil Map Units" and in tables 5 and 6.

#### **Prime Farmland**

Prime farmland is one of several kinds of important farmland defined by the U.S. Department of Agriculture. It is of major importance in meeting the Nation's short- and long-range needs for food and fiber. Because the supply of high-quality farmland is limited, the U.S. Department of Agriculture recognizes that responsible levels of government, as well as individuals, should encourage and facilitate the wise use of our Nation's prime farmland.

Prime farmland, as defined by the U.S. Department of Agriculture, is land that has the best combination of physical and chemical characteristics for producing food, feed, forage, fiber, and oilseed crops and is available for these uses. It could be cultivated land, pasture, forest, or other land, but it is not urban or built-up land or water areas. The soil qualities, growing season, and moisture supply are those needed for the soil to economically produce sustained high yields of crops when proper management, including water management, and acceptable farming methods are applied. In general, prime farmland has an adequate and dependable supply of moisture from precipitation or irrigation, a favorable temperature and growing season, acceptable acidity or alkalinity, and few or no rocks. It is permeable to water and air. It is not excessively erodible or saturated with water for long periods, and it either is not frequently flooded during the growing season or is protected from flooding. Slope ranges mainly from 0 to 6 percent. More detailed information about the criteria for prime farmland is available at the local office of the Natural Resources Conservation Service.

A recent trend in land use in large parts of the survey area has been the loss of prime farmland to industrial, residential, and urban uses. The loss of prime farmland to other uses puts pressure on marginal lands, which generally are more erodible, droughty, and less productive and cannot be easily cultivated.

The map units in the survey area that are considered prime farmland are listed in table 7. This

list does not constitute a recommendation for a particular land use. On some soils included in the list, measures that overcome a hazard or limitation, such as flooding, wetness, and droughtiness, are needed. Onsite evaluation is needed to determine whether or not the hazard or limitation has been overcome by corrective measures. The extent of each listed map unit is shown in table 4. The location is shown on the detailed soil maps. The soil qualities that affect use and management are described under the heading "Detailed Soil Map Units."

# **Forest Productivity and Management**

The tables in this section can help forest owners or managers plan the use of soils for wood production. They show the potential productivity of the soils for trees and rate the soils according to the limitations that affect various aspects of forest management.

#### **Forest Productivity**

In table 8, the *potential productivity* of merchantable or *common trees* on a soil is expressed as a site index and as a volume number. The *site index* is the average height, in feet, that dominant and codominant trees of a given species attain in a specified number of years. The site index applies to fully stocked, evenaged, unmanaged stands. Commonly grown trees are those that forest managers generally favor in intermediate or improvement cuttings. They are selected on the basis of growth rate, quality, value, and marketability. More detailed information regarding site index is available in the "National Forestry Manual," which is available in local offices of the Natural Resources Conservation Service or on the Internet (7).

The volume of wood fiber, a number, is the yield likely to be produced by the most important tree species. This number, expressed as cubic feet per acre per year and calculated at the age of culmination of the mean annual increment (CMAI), indicates the amount of fiber produced in a fully stocked, evenaged, unmanaged stand.

Trees to manage are those that are preferred for planting, seeding, or natural regeneration and those that remain in the stand after thinning or partial harvest.

#### **Forest Management**

In table 9, parts I through V, interpretive ratings are given for various aspects of forest management. The ratings are both verbal and numerical.

Some rating class terms indicate the degree to which the soils are suited to a specified forest

management practice. Well suited indicates that the soil has features that are favorable for the specified practice and has no limitations. Good performance can be expected, and little or no maintenance is needed. Moderately well suited indicates that the soil has features that are moderately favorable for the specified practice. One or more soil properties are less than desirable, and fair performance can be expected. Some maintenance is needed. Poorly suited indicates that the soil has one or more properties that are unfavorable for the specified practice. Overcoming the unfavorable properties requires special design, extra maintenance, and costly alteration. Unsuited indicates that the expected performance of the soil is unacceptable for the specified practice or that extreme measures are needed to overcome the undesirable soil properties.

Numerical ratings in the tables indicate the severity of individual limitations. The ratings are shown as decimal fractions ranging from 0.00 to 1.00. They indicate gradations between the point at which a soil feature has the greatest negative impact on the specified forest management practice (1.00) and the point at which the soil feature is not a limitation (0.00).

Rating class terms for fire damage and seedling mortality are expressed as *low, moderate,* and *high.* Where these terms are used, the numerical ratings indicate gradations between the point at which the potential for fire damage or seedling mortality is highest (1.00) and the point at which the potential is lowest (0.00).

The paragraphs that follow indicate the soil properties considered in rating the soils for forest management practices. More detailed information about the criteria used in the ratings is available in the "National Forestry Manual," which is available in local offices of the Natural Resources Conservation Service or on the Internet (7).

For limitations affecting construction of haul roads and log landings, the ratings are based on slope, flooding, permafrost, plasticity index, the hazard of soil slippage, content of sand, the Unified classification, rock fragments on or below the surface, depth to a restrictive layer that is indurated, depth to a water table, and ponding. The limitations are described as slight, moderate, or severe. A rating of slight indicates that no significant limitations affect construction activities, moderate indicates that one or more limitations can cause some difficulty in construction, and severe indicates that one or more limitations can make construction very difficult or very costly.

The ratings of *suitability for log landings* are based on slope, rock fragments on the surface, plasticity index, content of sand, the Unified classification, depth

to a water table, ponding, flooding, and the hazard of soil slippage. The soils are described as well suited, moderately suited, or poorly suited to use as log landings.

Ratings in the column *soil rutting hazard* are based on depth to a water table, rock fragments on or below the surface, the Unified classification, depth to a restrictive layer, and slope. Ruts form as a result of the operation of forest equipment. The hazard is described as slight, moderate, or severe. A rating of *slight* indicates that the soil is subject to little or no rutting, *moderate* indicates that rutting is likely, and *severe* indicates that ruts form readily.

Ratings in the column hazard of off-road or off-trail erosion are based on slope and on soil erodibility factor K. The soil loss is caused by sheet or rill erosion in off-road or off-trail areas where 50 to 75 percent of the surface has been exposed by logging, grazing, mining, or other kinds of disturbance. The hazard is described as slight, moderate, severe, or very severe. A rating of *slight* indicates that erosion is unlikely under ordinary climatic conditions; moderate indicates that some erosion is likely and that erosion-control measures may be needed; severe indicates that erosion is very likely and that erosion-control measures, including revegetation of bare areas, are advised; and very severe indicates that significant erosion is expected, loss of soil productivity and offsite damage are likely, and erosion-control measures are costly and generally impractical.

Ratings in the column hazard of erosion on roads and trails are based on the soil erodibility factor K, slope, and content of rock fragments. The ratings apply to unsurfaced roads and trails. The hazard is described as slight, moderate, or severe. A rating of slight indicates that little or no erosion is likely; moderate indicates that some erosion is likely, that the roads or trails may require occasional maintenance, and that simple erosion-control measures are needed; and severe indicates that significant erosion is expected, that the roads or trails require frequent maintenance, and that costly erosion-control measures are needed.

Ratings in the column *suitability for roads (natural surface)* are based on slope, rock fragments on the surface, plasticity index, content of sand, the Unified classification, depth to a water table, ponding, flooding, and the hazard of soil slippage. The ratings indicate the suitability for using the natural surface of the soil for roads. The soils are described as well suited, moderately well suited, or poorly suited to this use.

Ratings in the columns *suitability for hand planting* and *suitability for mechanical planting* are based on

slope, depth to a restrictive layer, content of sand, plasticity index, rock fragments on or below the surface, depth to a water table, and ponding. The soils are described as well suited, moderately well suited, poorly suited, or unsuited to these methods of planting. It is assumed that necessary site preparation is completed before seedlings are planted.

Ratings in the column *suitability for use of* harvesting equipment are based on slope, rock fragments on the surface, plasticity index, content of sand, the Unified classification, depth to a water table, and ponding. The soils are described as well suited, moderately well suited, or poorly suited to this use.

Ratings in the column *suitability for mechanical site preparation* (*surface*) are based on slope, depth to a restrictive layer, plasticity index, rock fragments on or below the surface, depth to a water table, and ponding. The soils are described as well suited, poorly suited, or unsuited to this management activity. The part of the soil from the surface to a depth of about 1 foot is considered in the ratings.

Ratings in the column *suitability for mechanical site preparation (deep)* are based on slope, depth to a restrictive layer, rock fragments on or below the surface, depth to a water table, and ponding. The soils are described as well suited, poorly suited, or unsuited to this management activity. The part of the soil from the surface to a depth of about 3 feet is considered in the ratings.

Ratings in the column *potential for damage to soil* by fire are based on texture of the surface layer, content of rock fragments and organic matter in the surface layer, thickness of the surface layer, and slope. The soils are described as having a low, moderate, or high potential for this kind of damage. The ratings indicate an evaluation of the potential impact of prescribed fires or wildfires that are intense enough to remove the duff layer and consume organic matter in the surface layer.

Ratings in the column *potential for seedling mortality* are based on flooding, ponding, depth to a water table, content of lime, reaction, salinity, available water capacity, soil moisture regime, soil temperature regime, aspect, and slope. The soils are described as having a low, moderate, or high potential for seedling mortality.

#### Recreation

The soils of the survey area are rated in table 10, parts I and II, and table 11, parts I and II, according to limitations that affect their suitability for recreation. The ratings are both verbal and numerical. Rating class terms indicate the extent to which the soils are limited

by all of the soil features that affect the recreational uses. *Not limited* indicates that the soil has features that are very favorable for the specified use. Good performance and very low maintenance can be expected. *Somewhat limited* indicates that the soil has features that are moderately favorable for the specified use. The limitations can be overcome or minimized by special planning, design, or installation. Fair performance and moderate maintenance can be expected. *Very limited* indicates that the soil has one or more features that are unfavorable for the specified use. The limitations generally cannot be overcome without major soil reclamation, special design, or expensive installation procedures. Poor performance and high maintenance can be expected.

Numerical ratings in the tables indicate the severity of individual limitations. The ratings are shown as decimal fractions ranging from 0.00 to 1.00. They indicate gradations between the point at which a soil feature has the greatest negative impact on the use (1.00) and the point at which the soil feature is not a limitation (0.00).

The ratings in the tables are based on restrictive soil features, such as wetness, slope, and texture of the surface layer. Susceptibility to flooding is considered. Not considered in the ratings, but important in evaluating a site, are the location and accessibility of the area, the size and shape of the area and its scenic quality, vegetation, access to water, potential water impoundment sites, and access to public sewer lines. The capacity of the soil to absorb septic tank effluent and the ability of the soil to support vegetation also are important. Soils that are subject to flooding are limited for recreational uses by the duration and intensity of flooding and the season when flooding occurs. In planning recreational facilities, onsite assessment of the height, duration, intensity, and frequency of flooding is essential.

The information in tables 10 and 11 can be supplemented by other information in this survey, for example, interpretations for building site development, construction materials, sanitary facilities, and water management.

Camp areas require site preparation, such as shaping and leveling the tent and parking areas, stabilizing roads and intensively used areas, and installing sanitary facilities and utility lines. Camp areas are subject to heavy foot traffic and some vehicular traffic. The ratings are based on the soil properties that affect the ease of developing camp areas and the performance of the areas after development. Slope, stoniness, and depth to bedrock are the main concerns affecting the development of camp areas.

The soil properties that affect the performance of the areas after development are those that influence trafficability and promote the growth of vegetation, especially in heavily used areas. For good trafficability, the surface of camp areas should absorb rainfall readily, remain firm under heavy foot traffic, and not be dusty when dry. The soil properties that influence trafficability are texture of the surface layer, depth to a water table, ponding, flooding, permeability, and large stones. The soil properties that affect the growth of plants are depth to bedrock, permeability, and toxic substances in the soil.

Picnic areas are subject to heavy foot traffic. Most vehicular traffic is confined to access roads and parking areas. The ratings are based on the soil properties that affect the ease of developing picnic areas and that influence trafficability and the growth of vegetation after development. Slope and stoniness are the main concerns affecting the development of picnic areas. For good trafficability, the surface of picnic areas should absorb rainfall readily, remain firm under heavy foot traffic, and not be dusty when dry. The soil properties that influence trafficability are texture of the surface layer, depth to a water table, ponding, flooding, permeability, and large stones. The soil properties that affect the growth of plants are depth to bedrock, permeability, and toxic substances in the soil.

Playgrounds require soils that are nearly level, are free of stones, and can withstand intensive foot traffic. The ratings are based on the soil properties that affect the ease of developing playgrounds and that influence trafficability and the growth of vegetation after development. Slope and stoniness are the main concerns affecting the development of playgrounds. For good trafficability, the surface of the playgrounds should absorb rainfall readily, remain firm under heavy foot traffic, and not be dusty when dry. The soil properties that influence trafficability are texture of the surface layer, depth to a water table, ponding, flooding, permeability, and large stones. The soil properties that affect the growth of plants are depth to bedrock, permeability, and toxic substances in the soil.

Paths and trails for hiking and horseback riding should require little or no slope modification through cutting and filling. The ratings are based on the soil properties that affect trafficability and erodibility. These properties are stoniness, depth to a water table, ponding, flooding, slope, and texture of the surface layer.

Off-road motorcycle trails require little or no site preparation. They are not covered with surfacing material or vegetation. Considerable compaction of the soil material is likely. The ratings are based on the soil properties that influence erodibility, trafficability,

dustiness, and the ease of revegetation. These properties are stoniness, slope, depth to a water table, ponding, flooding, and texture of the surface layer.

Golf fairways are subject to heavy foot traffic and some light vehicular traffic. Cutting or filling may be required. Irrigation is not considered in the ratings. The ratings are based on the soil properties that affect plant growth and trafficability after vegetation is established. The properties that affect plant growth are reaction; depth to a water table; ponding; depth to bedrock; the available water capacity in the upper 40 inches; the content of salts, sodium, or calcium carbonate; and sulfidic materials. The properties that affect trafficability are flooding, depth to a water table, ponding, slope, stoniness, and the amount of sand, clay, or organic matter in the surface layer. The suitability of the soil for traps, tees, roughs, and greens is not considered in the ratings.

## Wildlife Habitat

Soils affect the kind and amount of vegetation that is available to wildlife as food and cover. They also affect the construction of water impoundments. The kind and abundance of wildlife depend largely on the amount and distribution of food, cover, and water. Wildlife habitat can be created or improved by planting the appropriate vegetation, by maintaining the existing plant cover, or by promoting the natural establishment of desirable plants.

In table 12, the soils in the survey area are rated according to their potential for providing habitat for various kinds of wildlife. This information can be used in planning parks, wildlife refuges, nature study areas, and other developments for wildlife; in selecting soils that are suitable for establishing, improving, or maintaining specific elements of wildlife habitat; and in determining the intensity of management needed for each element of the habitat.

The potential of the soil is rated good, fair, poor, or very poor. A rating of *good* indicates that the element or kind of habitat is easily established, improved, or maintained. Few or no limitations affect management, and satisfactory results can be expected. A rating of *fair* indicates that the element or kind of habitat can be established, improved, or maintained in most places. Moderately intensive management is required for satisfactory results. A rating of *poor* indicates that limitations are severe for the designated element or kind of habitat. Habitat can be created, improved, or maintained in most places, but management is difficult and must be intensive. A rating of *very poor* indicates that restrictions for the element or kind of habitat are very severe and that unsatisfactory results can be

expected. Creating, improving, or maintaining habitat is impractical or impossible.

The elements of wildlife habitat are described in the following paragraphs.

Grain and seed crops are domestic grains and seed-producing herbaceous plants. Soil properties and features that affect the growth of grain and seed crops are depth of the root zone, texture of the surface layer, available water capacity, wetness, slope, surface stoniness, and flooding. Soil temperature and soil moisture also are considerations. Examples of grain and seed crops are corn, soybeans, grain sorghum, wheat, and oats.

*Grasses and legumes* are domestic perennial grasses and herbaceous legumes. Soil properties and features that affect the growth of grasses and legumes are depth of the root zone, texture of the surface layer, available water capacity, wetness, surface stoniness, flooding, and slope. Soil temperature and soil moisture also are considerations. Examples of grasses and legumes are tall fescue, orchardgrass, annual lespedeza, clover, and alfalfa.

Wild herbaceous plants are native or naturally established grasses and forbs, including weeds. Soil properties and features that affect the growth of these plants are depth of the root zone, texture of the surface layer, available water capacity, wetness, surface stoniness, and flooding. Soil temperature and soil moisture also are considerations. Examples of wild herbaceous plants are bluestem, panicum, carpetgrass, switchgrass, greenbrier, and eastern gamagrass.

Hardwood trees and woody understory produce nuts or other fruit, buds, catkins, twigs, bark, and foliage. Soil properties and features that affect the growth of hardwood trees and shrubs are depth of the root zone, available water capacity, and wetness. Examples of these plants are oak, poplar, cherry, sweetgum, apple, hawthorn, dogwood, hickory, blackberry, and blueberry. Examples of fruit-producing shrubs that are suitable for planting on soils rated good are shrub lespedeza, autumn-olive, and crabapple.

Coniferous plants furnish browse and seeds. Soil properties and features that affect the growth of coniferous trees, shrubs, and ground cover are depth of the root zone, available water capacity, and wetness. Examples of coniferous plants are pine and redcedar.

Wetland plants are annual and perennial wild herbaceous plants that grow on moist or wet sites. Submerged or floating aquatic plants are excluded. Soil properties and features affecting wetland plants are texture of the surface layer, wetness, reaction,

salinity, slope, and surface stoniness. Examples of wetland plants are smartweed, wild millet, wildrice, cattail, rushes, sedges, and reeds.

Shallow water areas have an average depth of less than 5 feet. Some are naturally wet areas. Others are created by dams, levees, or other water-control structures. Soil properties and features affecting shallow water areas are depth to bedrock, wetness, surface stoniness, slope, and permeability. Examples of shallow water areas are marshes, waterfowl feeding areas, and ponds. Examples of shallow water plants are coontail, common duckweed, spatterdock, cattail, lily, arrowhead, and water milfoil.

The habitat for various kinds of wildlife is described in the following paragraphs.

Habitat for openland wildlife consists of cropland, pasture, meadows, and areas that are overgrown with grasses, herbs, shrubs, and vines. These areas produce grain and seed crops, grasses and legumes, and wild herbaceous plants. Wildlife attracted to these areas include bobwhite quail, meadowlark, field sparrow, cottontail rabbit, and red fox.

Habitat for woodland wildlife consists of areas of deciduous and/or coniferous plants and associated grasses, legumes, and wild herbaceous plants. Wildlife attracted to these areas include wild turkey, woodcock, thrushes, woodpeckers, squirrels, gray fox, raccoon, deer, and bear.

Habitat for wetland wildlife consists of open, marshy or swampy shallow water areas. Some of the wildlife attracted to such areas are ducks, geese, herons, shore birds, muskrat, otter, and beaver.

# **Engineering**

This section provides information for planning land uses related to urban development and to water management. Soils are rated for various uses, and the most limiting features are identified. Ratings are given for building site development, sanitary facilities, construction materials, and water management. The ratings are based on observed performance of the soils and on the estimated data and test data in the "Soil Properties" section.

Information in this section is intended for land use planning, for evaluating land use alternatives, and for planning site investigations prior to design and construction. The information, however, has limitations. For example, estimates and other data generally apply only to that part of the soil between the surface and a depth of 5 to 7 feet. Because of the map scale, small areas of different soils may be included within the mapped areas of a specific soil.

The information is not site specific and does not

eliminate the need for onsite investigation of the soils or for testing and analysis by personnel experienced in the design and construction of engineering works.

Government ordinances and regulations that restrict certain land uses or impose specific design criteria were not considered in preparing the information in this section. Local ordinances and regulations should be considered in planning, in site selection, and in design.

Soil properties, site features, and observed performance were considered in determining the ratings in this section. During the fieldwork for this soil survey, determinations were made about particle-size distribution, liquid limit, plasticity index, soil reaction, depth to bedrock, hardness of bedrock within 5 to 7 feet of the surface, soil wetness, depth to a water table, ponding, slope, likelihood of flooding, natural soil structure aggregation, and soil density. Data were collected about kinds of clay minerals, mineralogy of the sand and silt fractions, and the kinds of adsorbed cations. Estimates were made for erodibility, permeability, corrosivity, shrink-swell potential, available water capacity, and other behavioral characteristics affecting engineering uses.

This information can be used to evaluate the potential of areas for residential, commercial, industrial, and recreational uses; make preliminary estimates of construction conditions; evaluate alternative routes for roads, streets, highways, pipelines, and underground cables; evaluate alternative sites for sanitary landfills, septic tank absorption fields, and sewage lagoons; plan detailed onsite investigations of soils and geology; locate potential sources of gravel, sand, earthfill, and topsoil; plan structures for soil and water conservation; and predict performance of proposed small structures and pavements by comparing the performance of existing similar structures on the same or similar soils.

The information in the tables, along with the soil maps, the soil descriptions, and other data provided in this survey, can be used to make additional interpretations.

Some of the terms used in this soil survey have a special meaning in soil science and are defined in the Glossary.

# **Building Site Development**

Soil properties influence the development of building sites, including the selection of the site, the design of the structure, construction, performance after construction, and maintenance. Table 13, parts I and II, and table 14, parts I and II, show the degree and kind of soil limitations that affect dwellings with and without basements, small commercial buildings,

local roads and streets, shallow excavations, and lawns and landscaping.

The ratings in the tables are both verbal and numerical. Rating class terms indicate the extent to which the soils are limited by all of the soil features that affect building site development. Not limited indicates that the soil has features that are very favorable for the specified use. Good performance and very low maintenance can be expected. Somewhat limited indicates that the soil has features that are moderately favorable for the specified use. The limitations can be overcome or minimized by special planning, design, or installation. Fair performance and moderate maintenance can be expected. Very limited indicates that the soil has one or more features that are unfavorable for the specified use. The limitations generally cannot be overcome without major soil reclamation, special design, or expensive installation procedures. Poor performance and high maintenance can be expected.

Numerical ratings in the tables indicate the severity of individual limitations. The ratings are shown as decimal fractions ranging from 0.00 to 1.00. They indicate gradations between the point at which a soil feature has the greatest negative impact on the use (1.00) and the point at which the soil feature is not a limitation (0.00).

Dwellings are single-family houses of three stories or less. For dwellings without basements, the foundation is assumed to consist of spread footings of reinforced concrete built on undisturbed soil at a depth of 2 feet or at the depth of maximum frost penetration, whichever is deeper. For dwellings with basements, the foundation is assumed to consist of spread footings of reinforced concrete built on undisturbed soil at a depth of about 7 feet. The ratings for dwellings are based on the soil properties that affect the capacity of the soil to support a load without movement and on the properties that affect excavation and construction costs. The properties that affect the load-supporting capacity include depth to a water table, ponding, flooding, subsidence, linear extensibility (shrink-swell potential), and compressibility. Compressibility is inferred from the Unified classification. The properties that affect the ease and amount of excavation include depth to a water table, ponding, flooding, slope, depth to bedrock, hardness of bedrock, and the amount and size of rock fragments.

Small commercial buildings are structures that are less than three stories high and do not have basements. The foundation is assumed to consist of spread footings of reinforced concrete built on undisturbed soil at a depth of 2 feet or at the depth of

maximum frost penetration, whichever is deeper. The ratings are based on the soil properties that affect the capacity of the soil to support a load without movement and on the properties that affect excavation and construction costs. The properties that affect the load-supporting capacity include depth to a water table, ponding, flooding, subsidence, linear extensibility (shrink-swell potential), and compressibility (which is inferred from the Unified classification). The properties that affect the ease and amount of excavation include flooding, depth to a water table, ponding, slope, depth to bedrock, hardness of bedrock, and the amount and size of rock fragments.

Local roads and streets have an all-weather surface and carry automobile and light truck traffic all year. They have a subgrade of cut or fill soil material; a base of gravel, crushed rock, or soil material stabilized by lime or cement; and a surface of flexible material (asphalt), rigid material (concrete), or gravel with a binder. The ratings are based on the soil properties that affect the ease of excavation and grading and the traffic-supporting capacity. The properties that affect the ease of excavation and grading are depth to bedrock, hardness of bedrock, depth to a water table, ponding, flooding, the amount of large stones, and slope. The properties that affect the traffic-supporting capacity are soil strength (as inferred from the AASHTO group index number), subsidence, linear extensibility (shrink-swell potential), the potential for frost action, depth to a water table, and ponding.

Shallow excavations are trenches or holes dug to a maximum depth of 5 or 6 feet for graves, utility lines, open ditches, or other purposes. The ratings are based on the soil properties that influence the ease of digging and the resistance to sloughing. Depth to bedrock, hardness of bedrock, the amount of large stones, and dense layers influence the ease of digging, filling, and compacting. Depth to the seasonal high water table, flooding, and ponding may restrict the period when excavations can be made. Slope influences the ease of using machinery. Soil texture, depth to the water table, and linear extensibility (shrink-swell potential) influence the resistance to sloughing.

Lawns and landscaping require soils on which turf and ornamental trees and shrubs can be established and maintained. Irrigation is not considered in the ratings. The ratings are based on the soil properties that affect plant growth and trafficability after vegetation is established. The properties that affect plant growth are reaction, depth to a water table, ponding, depth to bedrock, and the available water capacity in the upper 40 inches. The properties that

affect trafficability are flooding, depth to a water table, ponding, slope, stoniness, and the amount of sand, clay, or organic matter in the surface layer.

#### **Sanitary Facilities**

Table 15, parts I and II, and table 16 show the degree and kind of soil limitations that affect septic tank absorption fields, sewage lagoons, sanitary landfills, and daily cover for landfill. The ratings are both verbal and numerical. Rating class terms indicate the extent to which the soils are limited by all of the soil features that affect these uses. Not limited indicates that the soil has features that are very favorable for the specified use. Good performance and very low maintenance can be expected. *Somewhat limited* indicates that the soil has features that are moderately favorable for the specified use. The limitations can be overcome or minimized by special planning, design, or installation. Fair performance and moderate maintenance can be expected. Very limited indicates that the soil has one or more features that are unfavorable for the specified use. The limitations generally cannot be overcome without major soil reclamation, special design, or expensive installation procedures. Poor performance and high maintenance can be expected.

Numerical ratings in the tables indicate the severity of individual limitations. The ratings are shown as decimal fractions ranging from 0.00 to 1.00. They indicate gradations between the point at which a soil feature has the greatest negative impact on the use (1.00) and the point at which the soil feature is not a limitation (0.00).

Septic tank absorption fields are areas in which effluent from a septic tank is distributed into the soil through subsurface tiles or perforated pipe. Only that part of the soil between depths of 24 and 60 inches is evaluated. The ratings are based on the soil properties that affect absorption of the effluent, construction and maintenance of the system, and public health. Permeability, depth to a water table, ponding, depth to bedrock, and flooding affect absorption of the effluent. Stones, boulders, and bedrock interfere with installation. Excessive slope may cause lateral seepage and surfacing of the effluent in downslope areas.

Some soils are underlain by loose sand and gravel or fractured bedrock at a depth of less than 4 feet below the distribution lines. In these soils the absorption field may not adequately filter the effluent, particularly when the system is new. As a result, the ground water may become contaminated.

Sewage lagoons are shallow ponds constructed to hold sewage while aerobic bacteria decompose the

solid and liquid wastes. Lagoons should have a nearly level floor surrounded by cut slopes or embankments of compacted soil. Nearly impervious soil material for the lagoon floor and sides is required to minimize seepage and contamination of ground water. Considered in the ratings are slope, permeability, depth to a water table, ponding, depth to bedrock, flooding, large stones, and content of organic matter.

Soil permeability is a critical property affecting the suitability for sewage lagoons. Most porous soils eventually become sealed when they are used as sites for sewage lagoons. Until sealing occurs, however, the hazard of pollution is severe. Soils that have a permeability rate of more than 2 inches per hour are too porous for the proper functioning of sewage lagoons. In these soils, seepage of the effluent can result in contamination of the ground water. Ground-water contamination is also a hazard if fractured bedrock is within a depth of 40 inches, if the water table is high enough to raise the level of sewage in the lagoon, or if floodwater overtops the lagoon.

A high content of organic matter is detrimental to proper functioning of the lagoon because it inhibits aerobic activity. Slope and bedrock can cause construction problems, and large stones can hinder compaction of the lagoon floor. If the lagoon is to be uniformly deep throughout, the slope must be gentle enough and the soil material must be thick enough over bedrock to make land smoothing practical.

A trench sanitary landfill is an area where solid waste is placed in successive layers in an excavated trench. The waste is spread, compacted, and covered daily with a thin layer of soil excavated at the site. When the trench is full, a final cover of soil material at least 2 feet thick is placed over the landfill. The ratings in the table are based on the soil properties that affect the risk of pollution, the ease of excavation, trafficability, and revegetation. These properties include permeability, depth to bedrock, depth to a water table, ponding, slope, flooding, texture, stones and boulders, soil reaction, and content of salts and sodium. Unless otherwise stated, the ratings apply only to that part of the soil within a depth of about 6 feet. For deeper trenches, onsite investigation may be needed.

Hard bedrock, creviced bedrock, or highly permeable strata in or directly below the proposed trench bottom can affect the ease of excavation and the hazard of ground-water pollution. Slope affects construction of the trenches and the movement of surface water around the landfill. It also affects the construction and performance of roads in areas of the landfill.

Soil texture and consistence affect the ease with

which the trench is dug and the ease with which the soil can be used as daily or final cover. They determine the workability of the soil when dry and when wet. Soils that are plastic and sticky when wet are difficult to excavate, grade, or compact and are difficult to place as a uniformly thick cover over a layer of refuse.

The soil material used as the final cover for a trench landfill should be suitable for plants. It should not have excess sodium or salts and should not be too acid. The surface layer generally has the best workability, the highest content of organic matter, and the best potential for plants. Material from the surface layer should be stockpiled for use as the final cover.

In an area sanitary landfill, solid waste is placed in successive layers on the surface of the soil. The waste is spread, compacted, and covered daily with a thin layer of soil from a source away from the site. A final cover of soil material at least 2 feet thick is placed over the completed landfill. The ratings in the table are based on the soil properties that affect trafficability and the risk of pollution. These properties include flooding, permeability, depth to a water table, ponding, slope, and depth to bedrock.

Flooding is a serious problem because it can result in pollution in areas downstream from the landfill. If permeability is too rapid or if fractured bedrock or the water table is close to the surface, the leachate can contaminate the water supply. Slope is a consideration because of the extra grading required to maintain roads in the steeper areas of the landfill. Also, leachate may flow along the surface of the soils in the steeper areas and cause difficult seepage problems.

Daily cover for landfill is the soil material that is used to cover compacted solid waste in an area sanitary landfill. The soil material is obtained offsite, transported to the landfill, and spread over the waste. The ratings in the table also apply to the final cover for a landfill. They are based on the soil properties that affect workability, the ease of digging, and the ease of moving and spreading the material over the refuse daily during wet and dry periods. These properties include soil texture, depth to a water table, ponding, rock fragments, slope, depth to bedrock, reaction, and content of salts, sodium, or lime.

Loamy or silty soils that are free of large stones and excess gravel are the best cover for a landfill. Clayey soils may be sticky and difficult to spread; sandy soils are subject to wind erosion.

Slope affects the ease of excavation and of moving the cover material. Also, it can influence runoff, erosion, and reclamation of the borrow area.

After soil material has been removed, the soil material remaining in the borrow area must be thick

enough over bedrock or the water table to permit revegetation. The soil material used as the final cover for a landfill should be suitable for plants. It should not have excess sodium, salts, or lime and should not be too acid.

#### **Construction Materials**

Table 17, parts I and II, give information about the soils as potential sources of gravel, sand, topsoil, reclamation material, and roadfill. Normal compaction, minor processing, and other standard construction practices are assumed.

The soils are rated *good, fair,* or *poor* as potential sources of topsoil, reclamation material, and roadfill. The features that limit the soils as sources of these materials are specified in the table. The numerical ratings given after the specified features indicate the degree to which the features limit the soils as sources of topsoil, reclamation material, or roadfill. The lower the number, the greater the limitation.

The soils are rated as a *probable* or *improbable* source of sand and gravel. A rating of *probable* means that the source material is likely to be in or below the soil. The numerical ratings in these columns indicate the degree of probability. The number 0.00 indicates that the soil is an improbable source. A number between 0.00 and 1.00 indicates the degree to which the soil is a probable source of sand or gravel.

Sand and gravel are natural aggregates suitable for commercial use with a minimum of processing. They are used in many kinds of construction. Specifications for each use vary widely. In table 17, only the probability of finding material in suitable quantity is evaluated. The suitability of the material for specific purposes is not evaluated, nor are factors that affect excavation of the material. The properties used to evaluate the soil as a source of sand or gravel are gradation of grain sizes (as indicated by the Unified classification of the soil), the thickness of suitable material, and the content of rock fragments. If the lowest layer of the soil contains sand or gravel, the soil is rated as a probable source regardless of thickness. The assumption is that the sand or gravel layer below the depth of observation exceeds the minimum thickness.

Reclamation material is used in areas that have been drastically disturbed by surface mining or similar activities. When these areas are reclaimed, layers of soil material or unconsolidated geological material, or both, are replaced in a vertical sequence. The reconstructed soil favors plant growth. The ratings in the table do not apply to quarries and other mined areas that require an offsite source of reconstruction material. The ratings are based on the soil properties

that affect erosion and stability of the surface and the productive potential of the reconstructed soil. These properties include the content of sodium, salts, and calcium carbonate; reaction; available water capacity; erodibility; texture; content of rock fragments; and content of organic matter and other features that affect fertility.

Roadfill is soil material that is excavated in one place and used in road embankments in another place. In this table, the soils are rated as a source of roadfill for low embankments, generally less than 6 feet high and less exacting in design than higher embankments.

The ratings are for the whole soil, from the surface to a depth of about 5 feet. It is assumed that soil layers will be mixed when the soil material is excavated and spread.

The ratings are based on the amount of suitable material and on soil properties that affect the ease of excavation and the performance of the material after it is in place. The thickness of the suitable material is a major consideration. The ease of excavation is affected by large stones, depth to a water table, and slope. How well the soil performs in place after it has been compacted and drained is determined by its strength (as inferred from the AASHTO classification of the soil) and linear extensibility (shrink-swell potential).

Topsoil is used to cover an area so that vegetation can be established and maintained. The upper 40 inches of a soil is evaluated for use as topsoil. Also evaluated is the reclamation potential of the borrow area. The ratings are based on the soil properties that affect plant growth; the ease of excavating, loading, and spreading the material; and reclamation of the borrow area. Toxic substances, soil reaction, and the properties that are inferred from soil texture, such as available water capacity and fertility, affect plant growth. The ease of excavating, loading, and spreading is affected by rock fragments, slope, depth to a water table, soil texture, and thickness of suitable material. Reclamation of the borrow area is affected by slope, depth to a water table, rock fragments, depth to bedrock, and toxic material.

The surface layer of most soils is generally preferred for topsoil because of its organic matter content. Organic matter greatly increases the absorption and retention of moisture and nutrients for plant growth.

#### **Water Management**

Table 18 gives information on the soil properties and site features that affect water management. The

degree and kind of soil limitations are given for pond reservoir areas; embankments, dikes, and levees; and aquifer-fed excavated ponds. The limitations are considered *slight* if soil properties and site features are generally favorable for the indicated use and limitations are minor and are easily overcome; *moderate* if soil properties or site features are not favorable for the indicated use and special planning, design, or maintenance is needed to overcome or minimize the limitations; and *severe* if soil properties or site features are so unfavorable or so difficult to overcome that special design, significant increase in construction costs, and possibly increased maintenance are required.

Pond reservoir areas hold water behind a dam or embankment. Soils best suited to this use have low seepage potential in the upper 60 inches. The seepage potential is determined by the permeability of the soil and the depth to fractured bedrock or other permeable material. Excessive slope can affect the storage capacity of the reservoir area.

Embankments, dikes, and levees are raised structures of soil material, generally less than 20 feet high, constructed to impound water or to protect land against overflow. In this table, the soils are rated as a source of material for embankment fill. The ratings apply to the soil material below the surface layer to a depth of about 5 feet. It is assumed that soil layers will be uniformly mixed and compacted during construction.

The ratings do not indicate the ability of the natural soil to support an embankment. Soil properties to a depth even greater than the height of the embankment can affect performance and safety of the embankment. Generally, deeper onsite investigation is needed to determine these properties.

Soil material in embankments must be resistant to seepage, piping, and erosion and have favorable compaction characteristics. Unfavorable features include less than 5 feet of suitable material and a high content of stones or boulders, organic matter, or salts or sodium. A high water table affects the amount of usable material. It also affects trafficability.

Aquifer-fed excavated ponds are pits or dugouts that extend to a ground-water aquifer or to a depth below a permanent water table. Excluded are ponds that are fed only by surface runoff and embankment ponds that impound water 3 feet or more above the original surface. Excavated ponds are affected by depth to a permanent water table, permeability of the aquifer, and quality of the water as inferred from the salinity of the soil. Depth to bedrock and the content of large stones affect the ease of excavation.

# Soil Properties

Data relating to soil properties are collected during the course of the soil survey. The data and the estimates of soil and water features, listed in the tables, are explained on the following pages.

Estimates of soil properties are based on field examinations, on laboratory tests of samples from the survey area, and on laboratory tests of samples of similar soils in nearby areas. Tests verify field observations, verify properties that cannot be estimated accurately by field observation, and help to characterize key soils.

The estimates of soil properties are shown in tables. They include engineering index properties, physical and chemical properties, and pertinent soil and water features.

# **Engineering Index Properties**

Table 19 gives the engineering classifications and the range of index properties for the layers of several soils in the survey area.

*Depth* to the upper and lower boundaries of each layer is indicated.

Texture is given in the standard terms used by the U.S. Department of Agriculture. These terms are defined according to percentages of sand, silt, and clay in the fraction of the soil that is less than 2 millimeters in diameter. "Loam," for example, is soil that is 7 to 27 percent clay, 28 to 50 percent silt, and less than 52 percent sand. If the content of particles coarser than sand is 15 percent or more, an appropriate modifier is added, for example, "gravelly." Textural terms are defined in the Glossary.

Classification of the soils is determined according to the Unified soil classification system (2) and the system adopted by the American Association of State Highway and Transportation Officials (1).

The Unified system classifies soils according to properties that affect their use as construction material. Soils are classified according to particle-size distribution of the fraction less than 3 inches in diameter and according to plasticity index, liquid limit,

and organic matter content. Sandy and gravelly soils are identified as GW, GP, GM, GC, SW, SP, SM, and SC; silty and clayey soils as ML, CL, OL, MH, CH, and OH; and highly organic soils as PT. Soils exhibiting engineering properties of two groups can have a dual classification, for example, CL-ML.

The AASHTO system classifies soils according to those properties that affect roadway construction and maintenance. In this system, the fraction of a mineral soil that is less than 3 inches in diameter is classified in one of seven groups from A-1 through A-7 on the basis of particle-size distribution, liquid limit, and plasticity index. Soils in group A-1 are coarse grained and low in content of fines (silt and clay). At the other extreme, soils in group A-7 are fine grained. Highly organic soils are classified in group A-8 on the basis of visual inspection.

Rock fragments larger than 10 inches in diameter and 3 to 10 inches in diameter are indicated as a percentage of the total soil on a dry-weight basis. The percentages are estimates determined mainly by converting volume percentage in the field to weight percentage.

Percentage (of soil particles) passing designated sieves is the percentage of the soil fraction less than 3 inches in diameter based on an ovendry weight. The sieves, numbers 4, 10, 40, and 200 (USA Standard Series), have openings of 4.76, 2.00, 0.420, and 0.074 millimeters, respectively. Estimates are based on laboratory tests of soils sampled in the survey area and in nearby areas and on estimates made in the field

Liquid limit and plasticity index (Atterberg limits) indicate the plasticity characteristics of a soil. The estimates are based on test data from the survey area or from nearby areas and on field examination.

The estimates of particle-size distribution, liquid limit, and plasticity index are generally rounded to the nearest 5 percent. Thus, if the ranges of gradation and Atterberg limits extend a marginal amount (1 or 2 percentage points) across classification boundaries, the classification in the marginal zone is generally omitted in the table.

# **Physical Properties**

Tables 20 and 21 show estimates of some physical characteristics and features that affect soil behavior. These estimates are given for the layers of each soil in the survey area. The estimates are based on field observations and on test data for these and similar soils.

*Depth* to the upper and lower boundaries of each layer is indicated.

Particle size is the effective diameter of a soil particle as measured by sedimentation, sieving, or micrometric methods. Particle sizes are expressed as classes with specific effective diameter class limits. The broad classes are sand, silt, and clay, ranging from the larger to the smaller.

Sand as a soil separate consists of mineral soil particles that are 0.05 millimeter to 2 millimeters in diameter.

*Silt* as a soil separate consists of mineral soil particles that are 0.002 to 0.05 millimeter in diameter.

Clay as a soil separate consists of mineral soil particles that are less than 0.002 millimeter in diameter. In tables 20 and 21, the estimated clay content of each soil layer is given as a percentage, by weight, of the soil material that is less than 2 millimeters in diameter.

The content of sand, silt, and clay affects the physical behavior of a soil. Particle size is important for engineering and agronomic interpretations, for determination of soil hydrologic qualities, and for soil classification.

The amount and kind of clay affect the fertility and physical condition of the soil and the ability of the soil to adsorb cations and to retain moisture. They influence shrink-swell potential, permeability, plasticity, the ease of soil dispersion, and other soil properties. The amount and kind of clay in a soil also affect tillage and earthmoving operations.

Moist bulk density is the weight of soil (ovendry) per unit volume. Volume is measured when the soil is at field moisture capacity, that is, the moisture content at 1/3- or 1/10-bar (33kPa or 10kPa) moisture tension. Weight is determined after the soil is dried at 105 degrees C. In the tables, the estimated moist bulk density of each soil horizon is expressed in grams per cubic centimeter of soil material that is less than 2 millimeters in diameter. Bulk density data are used to compute shrink-swell potential, available water capacity, total pore space, and other soil properties. The moist bulk density of a soil indicates the pore space available for water and roots. Depending on soil texture, a bulk density of more than 1.4 can restrict

water storage and root penetration. Moist bulk density is influenced by texture, kind of clay, content of organic matter, and soil structure.

Permeability ( $K_{sat}$ ) refers to the ability of a soil to transmit water or air. The term "permeability," as used in soil surveys, indicates saturated hydraulic conductivity ( $K_{sat}$ ). The estimates in the tables indicate the rate of water movement, in inches per hour, when the soil is saturated. They are based on soil characteristics observed in the field, particularly structure, porosity, and texture. Permeability is considered in the design of soil drainage systems and septic tank absorption fields.

Available water capacity refers to the quantity of water that the soil is capable of storing for use by plants. The capacity for water storage is given in inches of water per inch of soil for each soil layer. The capacity varies, depending on soil properties that affect retention of water. The most important properties are the content of organic matter, soil texture, bulk density, and soil structure. Available water capacity is an important factor in the choice of plants or crops to be grown and in the design and management of irrigation systems. Available water capacity is not an estimate of the quantity of water actually available to plants at any given time.

Linear extensibility refers to the change in length of an unconfined clod as moisture content is decreased from a moist to a dry state. It is an expression of the volume change between the water content of the clod at <sup>1</sup>/<sub>3</sub>- or <sup>1</sup>/<sub>10</sub>-bar tension (33kPa or 10kPa tension) and oven dryness. The volume change is reported in the tables as percent change for the whole soil. Volume change is influenced by the amount and type of clay minerals in the soil.

Linear extensibility is used to determine the shrink-swell potential of soils. The shrink-swell potential is low if the soil has a linear extensibility of less than 3 percent; moderate if 3 to 6 percent; high if 6 to 9 percent; and very high if more than 9 percent. If the linear extensibility is more than 3, shrinking and swelling can cause damage to buildings, roads, and other structures and to plant roots. Special design commonly is needed.

Organic matter is the plant and animal residue in the soil at various stages of decomposition. In tables 20 and 21, the estimated content of organic matter is expressed as a percentage, by weight, of the soil material that is less than 2 millimeters in diameter.

The content of organic matter in a soil can be maintained by returning crop residue to the soil.

Organic matter has a positive effect on available water capacity, water infiltration, soil organism activity, and

tilth. It is a source of nitrogen and other nutrients for crops and soil organisms.

Erosion factors are shown in tables 20 and 21 as the K factor (Kw and Kf) and the T factor. Erosion factor K indicates the susceptibility of a soil to sheet and rill erosion by water. Factor K is one of several factors used in the Universal Soil Loss Equation (USLE) and the Revised Universal Soil Loss Equation (RUSLE) to predict the average annual rate of soil loss by sheet and rill erosion in tons per acre per year. The estimates are based primarily on percentage of silt, sand, and organic matter and on soil structure and permeability. Values of K range from 0.02 to 0.69. Other factors being equal, the higher the value, the more susceptible the soil is to sheet and rill erosion by water.

*Erosion factor Kw* indicates the erodibility of the whole soil. The estimates are modified by the presence of rock fragments.

*Erosion factor Kf* indicates the erodibility of the fineearth fraction, or the material less than 2 millimeters in size.

Erosion factor *T* is an estimate of the maximum average annual rate of soil erosion by water that can occur without affecting crop productivity over a sustained period. The rate is in tons per acre per year.

# **Chemical Properties**

Table 22 shows estimates of some chemical characteristics and features that affect soil behavior. These estimates are given for the layers of several soils in the survey area. The estimates are based on field observations and on test data for these and similar soils.

*Depth* to the upper and lower boundaries of each layer is indicated.

Cation-exchange capacity is the total amount of extractable bases that can be held by the soil, expressed in terms of milliequivalents per 100 grams of soil at neutrality (pH 7.0) or at some other stated pH value. Soils having a low cation-exchange capacity hold fewer cations and may require more frequent applications of fertilizer than soils having a high cation-exchange capacity. The ability to retain cations reduces the hazard of ground-water pollution.

Effective cation-exchange capacity refers to the sum of extractable bases plus aluminum expressed in terms of milliequivalents per 100 grams of soil. It is determined for soils that have pH of less than 5.5.

Soil reaction is a measure of acidity or alkalinity. The pH of each soil horizon is based on many field tests. For many soils, values have been verified by

laboratory analyses. Soil reaction is important in selecting crops and other plants, in evaluating soil amendments for fertility and stabilization, and in determining the risk of corrosion.

#### Water Features

Table 23 gives estimates of various water features. The estimates are used in land use planning that involves engineering considerations.

Hydrologic soil groups are based on estimates of runoff potential. Soils are assigned to one of four groups according to the rate of water infiltration when the soils are not protected by vegetation, are thoroughly wet, and receive precipitation from long-duration storms.

The four hydrologic soil groups are:

Group A. Soils having a high infiltration rate (low runoff potential) when thoroughly wet. These consist mainly of deep, well drained to excessively drained sands or gravelly sands. These soils have a high rate of water transmission.

Group B. Soils having a moderate infiltration rate when thoroughly wet. These consist chiefly of moderately deep or deep, moderately well drained or well drained soils that have moderately fine texture to moderately coarse texture. These soils have a moderate rate of water transmission.

Group C. Soils having a slow infiltration rate when thoroughly wet. These consist chiefly of soils having a layer that impedes the downward movement of water or soils of moderately fine texture or fine texture. These soils have a slow rate of water transmission.

Group D. Soils having a very slow infiltration rate (high runoff potential) when thoroughly wet. These consist chiefly of clays that have a high shrink-swell potential, soils that have a high water table, soils that have a claypan or clay layer at or near the surface, and soils that are shallow over nearly impervious material. These soils have a very slow rate of water transmission.

The *months* in the table indicate the portion of the year in which the feature is most likely to be a concern.

Water table refers to a saturated zone in the soil. Table 23 indicates, by month, depth to the top (upper limit) of the saturated zone in most years. Estimates of the upper limits are based mainly on observations of the water table at selected sites and on evidence of a saturated zone, namely grayish colors or mottles (redoximorphic features) in the soil. A saturated zone that lasts for less than a month is not considered a water table.

Ponding is standing water in a closed depression. Unless a drainage system is installed, the water is removed only by percolation, transpiration, or evaporation. Table 23 indicates *surface water depth* and the duration and frequency of ponding. Duration is expressed as very brief if less than 2 days, brief if 2 to 7 days, *long* if 7 to 30 days, and *very long* if more than 30 days. Frequency is expressed as none, rare, occasional, and frequent. None means that ponding is not probable; rare that it is unlikely but possible under unusual weather conditions (the chance of ponding is nearly 0 percent to 5 percent in any year); occasional that it occurs, on the average, once or less in 2 years (the chance of ponding is 5 to 50 percent in any year); and *frequent* that it occurs, on the average, more than once in 2 years (the chance of ponding is more than 50 percent in any year).

Flooding is the temporary inundation of an area caused by overflowing streams or by runoff from adjacent slopes. Water standing for short periods after rainfall or snowmelt is not considered flooding, and water standing in swamps and marshes is considered ponding rather than flooding.

Duration and frequency are estimated. Duration is expressed as extremely brief (0.1 hour to 4 hours), very brief (4 hours to 2 days), brief (2 to 7 days), long (7 to 30 days), and very long (more than 30 days). Frequency is expressed as none, very rare, rare, occasional, frequent, and very frequent. None means that flooding is not probable; very rare that it is very unlikely but possible under extremely unusual weather conditions (the chance of flooding is less than 1 percent in any year); rare that it is unlikely but possible under unusual weather conditions (the chance of flooding is 1 to 5 percent in any year); occasional that it occurs infrequently under normal weather conditions (the chance of flooding is 5 to 50 percent in any year); frequent that it is likely to occur often under normal weather conditions (the chance of flooding is more than 50 percent in any year but is less than 50 percent in all months in any year); and very frequent that it is likely to occur very often under normal weather conditions (the chance of flooding is more than 50 percent in all months of any year).

The information is based on evidence in the soil profile, namely thin strata of gravel, sand, silt, or clay deposited by floodwater; irregular decrease in organic matter content with increasing depth; and little or no horizon development.

Also considered are local information about the extent and levels of flooding and the relation of each soil on the landscape to historic floods. Information on the extent of flooding based on soil data is less

specific than that provided by detailed engineering surveys that delineate flood-prone areas at specific flood frequency levels.

#### Soil Features

Tables 24 and 25 give estimates of various soil features. The estimates are used in land use planning that involves engineering considerations.

A restrictive layer is a nearly continuous layer that has one or more physical or chemical properties that significantly impede the movement of water and air through the soil or that restrict roots or otherwise provide an unfavorable root environment. Examples are hard bedrock, fragipans, and weathered bedrock. The tables indicate the hardness and thickness of the restrictive layer, both of which significantly affect the ease of excavation. Depth to top is the vertical distance from the soil surface to the upper boundary of the restrictive layer.

Potential for frost action is the likelihood of upward or lateral expansion of the soil caused by the formation of segregated ice lenses (frost heave) and the subsequent collapse of the soil and loss of strength on thawing. Frost action occurs when moisture moves into the freezing zone of the soil. Temperature, texture, density, permeability, content of organic matter, and depth to the water table are the most important factors considered in evaluating the potential for frost action. It is assumed that the soil is not insulated by vegetation or snow and is not artificially drained. Silty and highly structured, clayey soils that have a high water table in winter are the most susceptible to frost action. Well drained, very gravelly, or very sandy soils are the least susceptible. Frost heave and low soil strength during thawing cause damage to pavements and other rigid structures.

Risk of corrosion pertains to potential soil-induced electrochemical or chemical action that corrodes or weakens uncoated steel or concrete. The rate of corrosion of uncoated steel is related to such factors as soil moisture, particle-size distribution, acidity, and electrical conductivity of the soil. The rate of corrosion of concrete is based mainly on the sulfate and sodium content, texture, moisture content, and acidity of the soil. Special site examination and design may be needed if the combination of factors results in a severe hazard of corrosion. The steel or concrete in installations that intersect soil boundaries or soil layers is more susceptible to corrosion than the steel or concrete in installations that are entirely within one kind of soil or within one soil layer.

For uncoated steel, the risk of corrosion, expressed as *low, moderate*, or *high*, is based on soil drainage class, total acidity, electrical resistivity near field capacity, and electrical conductivity of the saturation extract.

For concrete, the risk of corrosion also is expressed as *low, moderate,* or *high*. It is based on soil texture, acidity, and amount of sulfates in the saturation extract.

# Classification of the Soils

The system of soil classification used by the National Cooperative Soil Survey has six categories (8, 9). Beginning with the broadest, these categories are the order, suborder, great group, subgroup, family, and series. Classification is based on soil properties observed in the field or inferred from those observations or from laboratory measurements. Table 26 shows the classification of the soils in the survey area. The categories are defined in the following paragraphs.

ORDER. Twelve soil orders are recognized. The differences among orders reflect the dominant soilforming processes and the degree of soil formation. Each order is identified by a word ending in sol. An example is Alfisol.

SUBORDER. Each order is divided into suborders primarily on the basis of properties that influence soil genesis and are important to plant growth or properties that reflect the most important variables within the orders. The last syllable in the name of a suborder indicates the order. An example is Udalf (Ud, meaning humid, plus alf, from Alfisol).

GREAT GROUP. Each suborder is divided into great groups on the basis of close similarities in kind, arrangement, and degree of development of pedogenic horizons; soil moisture and temperature regimes; type of saturation; and base status. Each great group is identified by the name of a suborder and by a prefix that indicates a property of the soil. An example is Hapludalfs (Hapl, meaning minimal horizonation, plus udalf, the suborder of the Alfisols that has a udic moisture regime).

SUBGROUP. Each great group has a typic subgroup. Other subgroups are intergrades or extragrades. The typic subgroup is the central concept of the great group; it is not necessarily the most extensive. Intergrades are transitions to other orders, suborders, or great groups. Extragrades have some properties that are not representative of the great group but do not indicate transitions to any other taxonomic class. Each subgroup is identified by one or more adjectives preceding the name of the great group. The adjective *Typic* identifies the subgroup that typifies the great group. An example is Typic Hapludalfs.

FAMILY. Families are established within a subgroup on the basis of physical and chemical properties and other characteristics that affect management. Generally, the properties are those of horizons below plow depth where there is much biological activity. Among the properties and characteristics considered are particle size, mineral content, soil temperature regime, soil depth, and reaction. A family name consists of the name of a subgroup preceded by terms that indicate soil properties. An example is fine, mixed, active, mesic Typic Hapludalfs.

SERIES. The series consists of soils within a family that have horizons similar in color, texture, structure, reaction, consistence, mineral and chemical composition, and arrangement in the profile.

# Soil Series and Their Morphology

In this section, each soil series recognized in the survey area is described. Characteristics of the soil and the material in which it formed are identified for each series. A pedon, a small three-dimensional area of soil, that is typical of the series in the survey area is described. The detailed description of each soil horizon follows standards in the "Soil Survey Manual" (6). Many of the technical terms used in the descriptions are defined in "Soil Taxonomy" (8) and in "Keys to Soil Taxonomy" (9). Unless otherwise indicated, colors in the descriptions are for moist soil. Following the pedon description is the range of important characteristics of the soils in the series.

#### Baxter Series

Depth class: Very deep Drainage class: Well drained Permeability: Moderately slow

Physiographic area: Highland Rim/Pennyroyal

Landform: Karst ridges and hillsides

Parent material: Gravelly limestone residuum

Slope: 2 to 30 percent

Taxonomic class: Fine, mixed, semiactive, mesic Typic

**Paleudalfs** 



Figure 10.—A profile of Baxter soils. These soils have a subsoil of cherty clay and are very deep over hard limestone bedrock.

# **Typical Pedon**

Baxter gravelly silt loam, 6 to 12 percent slopes; 2.75 miles east of Smiths Grove on Hays-Smith Grove Road, 100 yards north of the intersection of Interstate Highway 65 and Smith Grove Road, in a field; USGS Smith's Grove Quadrangle; lat. 37 degrees 2 minutes 44.2 seconds N. and long. 86 degrees 9 minutes 36.7 seconds W.

Ap—0 to 8 inches; brown (10YR 4/3) gravelly silt loam; weak very fine granular structure; very friable; common fine roots; 25 percent chert gravel; neutral; abrupt smooth boundary.

Bt1—8 to 15 inches; yellowish red (5YR 5/6) gravelly silty clay loam; weak medium subangular blocky structure; friable; common fine roots; few fine continuous pores; common fine distinct reddish brown (5YR 5/4) clay films on faces of peds; 15 percent chert gravel; very strongly acid; clear smooth boundary.

Bt2—15 to 49 inches; red (2.5YR 4/6) gravelly clay; few medium distinct (7.5YR 5/6) strong brown mottles; moderate fine and medium angular blocky structure parting to very fine angular blocky; very firm; few fine roots; few fine continuous pores; many fine prominent reddish brown (2.5YR 4/4) clay films on faces of peds; few fine discontinuous silt coatings between peds; 25 percent chert gravel and few cobbles; very strongly acid; gradual wavy boundary.

Bt3—49 to 61 inches; red (2.5YR 4/6) gravelly clay; common medium distinct strong brown (7.5YR 5/6) and common medium prominent very pale brown (10YR 7/3) mottles; moderate medium angular blocky structure parting to fine and very fine angular blocky; very firm; few fine roots; few fine continuous pores; many fine prominent reddish brown (2.5YR 4/4) clay films on faces of peds; 25 percent chert gravel and few cobbles; very strongly acid; gradual wavy boundary.

Bt4—61 to 81 inches; red (2.5YR 4/6) gravelly clay; common medium distinct (5YR 5/4) reddish brown mottles; moderate medium angular blocky structure parting to fine and very fine angular blocky; very firm; few fine continuous pores; many fine and medium prominent reddish brown (2.5YR 4/4) clay films on faces of peds; 20 percent chert gravel and few cobbles; very strongly acid.

### **Range in Characteristics**

Depth to bedrock: More than 60 inches
Kind of rock fragments: Subrounded chert (fig. 10)
Reaction: Strongly acid or very strongly acid, except in
limed areas

A or Ap horizon:

Hue—10YR or 7.5YR

Value—4 or 5

Chroma-2 to 4

Texture of the fine-earth fraction—silt loam or silty

Content of rock fragments—15 to 35 percent

#### Bt horizon:

Hue-5YR, 2.5YR, or 10R

Value—4 or 5 Chroma—4 to 6

Texture of the fine-earth fraction—silty clay or clay Content of rock fragments—5 to 45 percent

# Caneyville Series

Depth class: Moderately deep Drainage class: Well drained Permeability: Slow or very slow

Physiographic area: Highland Rim/Pennyroyal Landform: Undulating ridges and steep hillsides

Parent material: Residuum of limestone

Slope: 2 to 60 percent

Taxonomic class: Fine, mixed, active, mesic Typic

Hapludalfs

#### **Typical Pedon**

Caneyville silt loam, 2 to 6 percent slopes; 5.2 miles north of Bowling Green on Kentucky Highway 185, about 1.5 miles east on Kentucky Highway 526, about 0.6 mile south on Bill Ferguson Road, 500 feet north of a farmhouse, in pasture; USGS Bowling Green North Quadrangle; lat. 37 degrees 3 minutes 33.3 seconds N. and long. 86 degrees 25 minutes 2.7 seconds W.

Ap—0 to 6 inches; brown (10YR 4/3) silt loam; weak fine granular structure; friable; many fine roots; slightly acid; abrupt smooth boundary.

Bt1—6 to 11 inches; reddish brown (5YR 4/4) silty clay; moderate medium angular and subangular blocky structure; firm; slightly sticky; slightly plastic; common fine roots; many prominent reddish brown (5YR 4/3) clay films on faces of peds; moderately acid; clear smooth boundary.

Bt2—11 to 21 inches; yellowish red (5YR 4/6) clay; moderate medium angular blocky structure; very firm; moderately sticky; moderately plastic; common very fine roots; many prominent reddish brown (5YR 4/4) clay films on faces of peds; moderately acid; clear smooth boundary.

Bt3—21 to 27 inches; dark reddish brown (5YR 3/4) clay; moderate medium angular blocky structure; very firm; moderately sticky; moderately plastic; few very fine roots; many prominent reddish brown (5YR 4/4) clay films on faces of peds; few black (5YR 2.5/1) manganese concretions; few limestone gravel; slightly acid; abrupt smooth boundary.

R—27 inches; hard limestone bedrock.

# Range in Characteristics

Depth to bedrock: 20 to 40 inches

Kind of rock fragments: Subrounded chert

Reaction: Typically strongly acid or moderately acid;

the layer just above bedrock ranges from

moderately acid to neutral

A or Ap horizon:

Hue—10YR or 7.5YR

Value—4 or 5

Chroma-2 to 4

Texture of the fine-earth fraction—silt loam or silty

clay

Content of rock fragments—0 to 10 percent

Bt horizon:

Hue—2.5YR, 5YR, or 7.5YR

Value—4 or 5 Chroma—4 to 6

Texture of the fine-earth fraction—silty clay or clay

Content of rock fragments—0 to 10 percent

# Crider Series

Depth class: Very deep Drainage class: Well drained Permeability: Moderate

Physiographic area: Highland Rim/Pennyroyal

Landform: Undulating karst plains

Parent material: Loess and residuum from limestone

Slope: 2 to 12 percent

Taxonomic class: Fine-silty, mixed, active, mesic Typic

Paleudalfs

### **Typical Pedon**

Crider silt loam, 2 to 6 percent slopes; 3.2 miles northwest of Woodburn on Kentucky Highway 240, about 1.9 miles northwest of the intersection of U.S. Highway 31W and Kentucky Highway 240, about 1,248 feet northeast of the intersection of Kentucky Highway 240 and Old Downing Hanes Road, in a field; USGS Woodburn Quadrangle; lat. 36 degrees 52 minutes 9 seconds N. and long. 86 degrees 34 minutes 14 seconds W.

Ap—0 to 9 inches; brown (10YR 4/3) silt loam; weak fine granular structure; very friable; many fine roots; few continuous pores; neutral; clear smooth boundary.

Bt1—9 to 17 inches; strong brown (7.5YR 5/6) silty clay loam; moderate medium subangular blocky structure; friable; many fine roots; few fine pores; few faint strong brown clay films on faces of peds; neutral; gradual smooth boundary.

- Bt2—17 to 28 inches; yellowish red (5YR 5/6) silty clay loam; moderate medium subangular blocky structure; friable; few fine roots; few fine pores; common distinct reddish brown (5YR 5/4) clay films on faces of peds; moderately acid; gradual smooth boundary.
- 2Bt3—28 to 50 inches; red (2.5YR 4/6) silty clay loam; moderate medium subangular blocky structure; friable; few fine pores; common distinct reddish brown (2.5YR 4/4) clay films on faces of peds; few fine black (5YR 2.5/1) manganese concretions; strongly acid; clear smooth boundary.
- 2Bt4—50 to 80 inches; dark red (10R 3/6) clay; few fine prominent brown (7.5YR 5/4) and yellowish red (5YR 5/8) mottles; strong fine angular blocky structure; firm; moderately sticky; moderately plastic; common prominent dark red (2.5YR 3/6) clay films on faces of peds; common black (5YR 2.5/1) manganese concretions; strongly acid.

#### Range in Characteristics

Depth to bedrock: More than 60 inches
Kind of rock fragments: Subrounded chert
Reaction: Neutral to strongly acid in the A and Bt
horizons and moderately acid to very strongly acid
in the 2Bt horizon

A or Ap horizon:

Hue-10YR or 7.5YR

Value—4

Chroma-2 to 4

Texture of the fine-earth fraction—silt loam Content of rock fragments—0 to 2 percent

Bt horizon:

Hue-5YR, 7.5YR, or 10YR

Value—4 or 5

Chroma—4 to 8

Texture of the fine-earth fraction—silty clay loam or clay

Content of rock fragments—0 to 10 percent

2Bt horizon:

Hue—5YR, 2.5YR, or 10R

Value—3 to 5

Chroma—4 to 8

Texture of the fine-earth fraction—silty clay loam, silty clay, or clay

Content of rock fragments—0 to 35 percent

# **Dunning Series**

Depth class: Very deep

Drainage class: Poorly drained or very poorly drained

Permeability: Slow or very slow

Physiographic area: Highland Rim/Pennyroyal Landform: Upland depressions and flood plains Parent material: Fine textured alluvium

Slope: 0 to 2 percent

Taxonomic class: Fine, mixed, active, mesic

Fluvaquentic Endoaquolls

#### **Typical Pedon**

Dunning silty clay loam, ponded; 1.2 miles southwest of Rockfield, 0.5 mile northwest of the intersection of Bogle Road and Old Downing Hanes Lane, 400 feet northwest of the bridge on Brush Creek, in a field; USGS Rockfield Quadrangle; lat. 36 degrees 53 minutes 53 seconds N. and long. 86 degrees 34 minutes 54 seconds W.

- Ap—0 to 9 inches; very dark grayish brown (10YR 3/2) silty clay loam; moderate medium angular blocky structure; firm; many fine roots; neutral; gradual smooth boundary.
- Ag—9 to 16 inches; very dark gray (10YR 3/1) silty clay loam; moderate medium angular blocky structure; firm; common fine roots; few fine prominent dark yellowish brown (10YR 4/6) masses of iron accumulation; slightly alkaline; gradual smooth boundary.
- Bg1—16 to 25 inches; dark gray (10YR 4/1) silty clay; moderate medium subangular blocky structure; firm; common fine roots; few fine prominent dark yellowish brown (10YR 4/6) masses of iron accumulation; slightly alkaline; gradual smooth boundary.
- Bg2—25 to 43 inches; dark gray (10YR 4/1) clay; moderate medium subangular blocky structure; firm; few fine roots; common fine distinct brown (10YR 4/3) masses of iron accumulation; slightly alkaline; gradual smooth boundary.
- Cg—43 to 71 inches; dark gray (5Y 4/1) clay; massive; firm; moderately sticky; moderately plastic; common black (10YR 2/1) and dark brown (10YR 3/3) iron and manganese concretions; common medium prominent light olive brown (2.5Y 5/6) and brown (7.5YR 5/4) masses of iron accumulation; slightly alkaline.

# Range in Characteristics

Depth to bedrock: More than 60 inches Kind of rock fragments: Rounded gravel Reaction: Moderately acid to slightly alkaline

Ap and Ag horizons:

Hue—10YR to 5Y

Value—2 or 3

Chroma—1 or 2

Texture of the fine-earth fraction—silty clay loam Content of rock fragments—none

#### Bg horizon:

Hue—10YR to 5Y Value—3 to 5 Chroma—0 to 2

Texture of the fine-earth fraction—silty clay or clay Content of rock fragments—none

#### Cg horizon:

Hue—2.5Y or 5Y Value—3 to 5 Chroma—0 to 2

Texture of the fine-earth fraction—clay or silty clay Content of rock fragments—0 to 30 percent

### Elk Series

Depth class: Very deep Drainage class: Well drained Permeability: Moderate

Physiographic area: Highland Rim/Pennyroyal

Landform: Stream terraces Parent material: Alluvium Slope: 2 to 6 percent

Taxonomic class: Fine-silty, mixed, active, mesic Ultic

Hapludalfs

# **Typical Pedon**

Elk silt loam, 2 to 6 percent slopes, rarely flooded; 3.3 miles southeast of Bowling Green on U.S. Highway 231, about 3.2 miles southeast of the intersection of Interstate 65 and U.S. Highway 231, about 0.6 mile southeast of the intersection of Upton Road and U.S. Highway 231, about 1,655 feet northwest of the Drake's Creek Bridge, in a field; USGS Bowling Green South Quadrangle; lat. 36 degrees 53 minutes 55 seconds N. and long. 86 degrees 23 minutes 00 seconds W.

Ap—0 to 10 inches; brown (10YR 4/3) silt loam; weak fine granular structure; very friable; many fine roots; moderately acid; gradual smooth boundary.

Bt1—10 to 20 inches; brown (7.5YR 4/4) silt loam; moderate medium subangular blocky structure; friable; common fine roots; few faint clay films on faces of peds; moderately acid; gradual smooth boundary.

Bt2—20 to 32 inches; brown (7.5YR 4/4) silty clay loam; moderate medium subangular blocky structure; friable; common fine roots; few faint clay films on faces of peds; 2 percent rounded chert gravel; strongly acid; gradual smooth boundary.

Bt3—32 to 42 inches; strong brown (7.5YR 5/6) silty

clay loam; moderate medium subangular blocky structure; friable; few fine roots; few distinct brown (7.5YR 4/4) clay films on faces of peds; few black (10YR 2/1) manganese concretions; 2 percent rounded chert gravel; strongly acid; clear smooth boundary.

C—42 to 65 inches; yellowish brown (10YR 5/4) silty clay loam; common medium faint pale brown (10YR 6/3) and light yellowish brown (10YR 6/4) mottles; massive; firm; few black (10YR 2/1) manganese concretions; moderately acid.

### **Range in Characteristics**

Depth to bedrock: More than 60 inches Kind of rock fragments: Rounded chert

Reaction: Strongly acid or moderately acid, except in

limed areas

A or Ap horizon:

Hue—10YR or 7.5YR

Value—4 or 5

Chroma—3 or 4

Texture of the fine-earth fraction—silt loam Content of rock fragments—0 to 5 percent

#### Bt horizon:

Hue—10YR or 7.5YR

Value—4 or 5

Chroma—4 or 6

Texture of the fine-earth fraction—silt loam or silty

clay loam

Content of rock fragments—0 to 5 percent

#### C horizon:

Hue—10YR to 5YR

Value—4 or 5

Chroma—4 to 8

Texture of the fine-earth fraction—silt loam or silty

clay loam

Content of rock fragments—0 to 35 percent

# Epley Series

Depth class: Deep or very deep

Drainage class: Moderately well drained

Permeability: Slow or very slow

Physiographic area: Western Coal Fields

Landform: Upland ridges

Parent material: Silty alluvium and residuum of shale

Slope: 2 to 6 percent

Taxonomic class: Fine-silty, mixed, semiactive, mesic

Oxyaquic Hapludalfs

#### Typical Pedon

Epley silt loam, 2 to 6 percent slopes; about 17 miles

northeast of Lewisburg, 0.2 mile north of the intersection of Kentucky Highways 106 and 1153, about 875 feet north of the intersection of Kentucky Highway 1153 and Iron Mountain Road, in pasture; USGS Lewisburg Quadrangle; lat. 36 degrees 59 minutes 54.7 seconds N. and long. 86 degrees 55 minutes 24.9 seconds W.

Ap—0 to 9 inches; brown (10YR 4/3) silt loam; weak fine granular structure; very friable; few fine roots; common black (10YR 2/1) manganese concretions; slightly acid; gradual wavy boundary.

Bt1—9 to 17 inches; yellowish brown (10YR 5/4) silt loam; weak fine subangular blocky structure; friable; few fine roots; few faint clay films on faces of peds; few fine strong brown (7.5YR 5/6) iron concentrations; slightly acid; gradual wavy boundary.

Bt2—17 to 24 inches; yellowish brown (10YR 5/4) silt loam; weak medium subangular blocky structure; friable; few fine roots; common distinct brown (10YR 5/3) clay films on faces of peds; few light gray (10YR 7/2) silt coatings on faces of peds at horizon transition; common medium distinct strong brown (7.5YR 5/6) iron concentrations; very strongly acid; abrupt smooth boundary.

2Bt/E—24 to 29 inches; brown (7.5YR 4/4) silty clay; weak medium and coarse prismatic structure parting to moderate medium subangular blocky; firm; moderately sticky; moderately plastic; common prominent brown (7.5YR 4/3) clay films on faces of peds; common medium distinct grayish brown (10YR 5/2) silt coatings on prism faces; very strongly acid; abrupt smooth boundary.

2Bt—29 to 41 inches; dark yellowish brown (10YR 4/6) silty clay; weak coarse prismatic structure parting to moderate medium and coarse subangular blocky; very firm; very sticky; very plastic; common prominent dark yellowish brown (10YR 4/4) clay films and pressure faces on prism faces; few fine and medium pale brown (10YR 6/3) silt coatings on prism faces; common black (10YR 2/1) manganese concretions; common medium prominent light brownish gray (10YR 6/2) iron depletions; very strongly acid; gradual wavy boundary.

2C—41 to 65 inches; yellowish brown (10YR 5/4) clay; massive; very firm; very sticky; very plastic; common medium distinct grayish brown (10YR 5/2) silt coatings on faces of peds; few fine faint brown (10YR 5/3) iron depletions; slightly acid.

## **Range in Characteristics**

Depth to bedrock: More than 60 inches Kind of rock fragments: Limestone and shale

Reaction: Very strongly acid to moderately acid to a depth of 4 feet and moderately acid to neutral below this depth

#### A or Ap horizon:

Hue-2.5Y or 10YR

Value—4 or 5

Chroma-2 to 4

Texture of the fine-earth fraction—silt loam Content of rock fragments—none

#### Bt horizon:

Hue-2.5Y, 10YR, or 7.5YR

Value—4 to 6

Chroma—3 to 6

Texture of the fine-earth fraction—silt loam or silty clay loam

Content of rock fragments—none

#### 2Bt/E and 2Bt horizons:

Hue—10YR or 7.5YR

Value—4 to 7

Chroma—0 to 8

Texture of the fine-earth fraction—silty clay or clay Content of rock fragments—none

#### 2C horizon:

Hue—10YR or 7.5YR

Value—4 to 7

Chroma—0 to 8

Texture of the fine-earth fraction—clay Content of rock fragments—0 to 50 percent

#### Fredonia Series

Depth class: Moderately deep Drainage class: Well drained

Permeability: Moderately slow or slow

Physiographic area: Highland Rim/Pennyroyal

Landform: Undulating karst plains

Parent material: Residuum from limestone

Slope: 2 to 12 percent

Taxonomic class: Fine, mixed, active, mesic Typic

Hapludalfs

# **Typical Pedon**

Fredonia silt loam in an area of Fredonia-Vertrees complex, 6 to 12 percent slopes, very rocky; 0.3 mile north of Petros at the intersection of U.S. Highway 68 and Petros-Browning Road, 0.6 mile southeast of the intersection of Petros-Browning Road and Finney Road, 400 feet east of Petros-Browning Road, in pasture; USGS Rockfield Quadrangle; lat. 36 degrees 54 minutes 6 seconds N. and long. 86 degrees 35 minutes 59 seconds W.

- Ap—0 to 5 inches; brown (7.5YR 4/4) silt loam; moderate fine granular structure; friable; many fine roots; moderately acid; abrupt smooth boundary.
- Bt1—5 to 22 inches; dark red (2.5YR 3/6) silty clay; moderate fine and medium subangular blocky structure; firm; slightly sticky; slightly plastic; common fine roots; many distinct dark reddish brown (2.5YR 3/4) clay films on faces of peds; few fine black (10YR 2/1) manganese concretions; moderately acid; gradual smooth boundary.
- Bt2—22 to 37 inches; dusky red (10R 3/4) clay; moderate medium angular blocky structure; very firm; moderately sticky; moderately plastic; common fine roots; many dark reddish brown (2.5YR 3/4) clay films on faces of peds; few fine black (10YR 2/1) manganese concretions; 2 percent fragments of chert; slightly acid; abrupt wavy boundary.
- R-37 inches; hard limestone bedrock.

#### Range in Characteristics

Depth to bedrock: 20 to 40 inches

Kind of rock fragments: Subrounded chert

Reaction: Strongly acid to slightly acid in the upper layers and moderately acid to neutral in the Bt2 horizon

A or Ap horizon:

Hue-10YR or 7.5YR

Value—3 or 4

Chroma—2 to 4

Texture of the fine-earth fraction—silt loam Content of rock fragments—0 to 5 percent

Bt horizon:

Hue-2.5YR to 10R

Value—3 to 5

Chroma—4 to 6

Texture of the fine-earth fraction—silty clay or clay Content of rock fragments—0 to 5 percent

#### Frondorf Series

Depth class: Moderately deep Drainage class: Well drained

Permeability: Moderate or moderately rapid Physiographic area: Western Coal Fields Landform: Upland ridges and hillsides

Parent material: Loess and residuum of sandstone

and siltstone Slope: 6 to 20 percent

Taxonomic class: Fine-loamy, mixed, active, mesic

Ultic Hapludalfs

# **Typical Pedon**

Frondorf silt loam, 12 to 20 percent slopes; 1.3 miles north of Anna on Kentucky Highway 185, about 0.3 mile north of the intersection of Kentucky Highway 185 and Austin Raymer Road, 100 feet west of Kentucky Highway 185, in pasture; USGS Reedyville Quadrangle; lat. 37 degrees 8 minutes 9.4 seconds N. and long. 86 degrees 25 minutes 26.5 seconds W.

- Ap—0 to 5 inches; brown (10YR 4/3) silt loam; weak fine granular structure; very friable; many fine roots; few fine pores; slightly acid; clear smooth boundary.
- Bt1—5 to 11 inches; strong brown (7.5YR 5/6) silty clay loam; moderate fine subangular blocky structure; friable; common fine roots; few fine pores; few faint clay films on faces of peds; very strongly acid; clear smooth boundary.
- Bt2—11 to 18 inches; yellowish brown (10YR 5/6) silty clay loam; few fine distinct pale brown (10YR 6/3) mottles; moderate medium angular and subangular blocky structure; firm; common fine roots; few fine pores; common distinct yellowish brown (10YR 5/4) clay films on faces of peds; 2 percent channers of sandstone and shale; very strongly acid; clear smooth boundary.
- 2Bt3—18 to 26 inches; yellowish brown (10YR 5/6) very channery silty clay loam; few fine faint yellowish brown (10YR 5/8) mottles; weak medium angular blocky structure; firm; few fine pores; common distinct yellowish brown (10YR 5/4) clay films on faces of peds; 60 percent channers of sandstone and shale; very strongly acid; abrupt smooth boundary.
- R—26 inches; hard sandstone bedrock.

#### Range in Characteristics

Depth to bedrock: 20 to 40 inches

Kind of rock fragments: Channers of sandstone and

shale

Reaction: Strongly acid or very strongly acid, except in

limed areas

A or Ap horizon:

Hue—10YR

Value—3 to 5

Chroma-2 to 4

Texture of the fine-earth fraction—silt loam Content of rock fragments—0 to 5 percent

#### Bt horizon:

Hue—10YR or 7.5YR

Value—4 to 6

Chroma—4 to 8

Texture of the fine-earth fraction—silty clay loam or silt loam

Content of rock fragments—0 to 5 percent

2Bt horizon:

Hue—10YR or 7.5YR

Value—4 to 6 Chroma—4 to 8

Texture of the fine-earth fraction—silty clay loam,

silt loam, loam, or clay loam

Content of rock fragments—15 to 70 percent

# Grigsby Series

Depth class: Very deep Drainage class: Well drained

Permeability: Moderate or moderately rapid Physiographic area: Western Coal Fields

Landform: Flood plains of the Barren and Green

Rivers

Parent material: Alluvium Slope: 0 to 2 percent

Taxonomic class: Coarse-loamy, mixed, active, mesic

Dystric Fluventic Eutrudepts

# **Typical Pedon**

Grigsby sandy loam, frequently flooded; 6.6 miles north-northwest of Richardsville, 1.2 miles north of the intersection of Harry Cherry Road and Richardsville-Threlkel Ferry Road, 939 feet east of Threlkel Ferry Road, in a field adjacent to the Green River; USGS Reedyville Quadrangle; lat. 37 degrees 11 minutes 13.2 seconds N. and long. 86 degrees 29 minutes 41 seconds W.

Ap—0 to 9 inches; dark yellowish brown (10YR 4/4) sandy loam; weak fine granular structure; very friable; many fine roots; neutral; gradual smooth boundary.

Bw1—9 to 21 inches; dark yellowish brown (10YR 4/4) sandy loam; few fine faint brown (10YR 5/3) mottles; weak fine and medium subangular blocky structure; very friable; common fine roots; few fine pores and earthworm channels; neutral; gradual wavy boundary.

Bw2—21 to 26 inches; brown (10YR 5/3) sandy loam; few fine faint brown (10YR 4/3) mottles; weak fine subangular blocky structure; very friable; common fine roots; neutral; gradual wavy boundary.

Bw3—26 to 41 inches; yellowish brown (10YR 5/4) sandy loam; weak fine subangular blocky structure; very friable; common fine roots; neutral; gradual wavy boundary.

Bw4—41 to 80 inches; dark yellowish brown (10YR 4/4) loam; few fine faint yellowish brown (10YR

5/4) mottles; weak fine subangular blocky structure; very friable; few fine roots; neutral.

#### **Range in Characteristics**

Depth to bedrock: More than 60 inches

Kind of rock fragments: Rounded chert and sandstone

Reaction: Moderately acid to neutral

A or Ap horizon:

Hue—10YR

Value—4 or 5

Chroma—2 to 4

Texture of the fine-earth fraction—sandy loam Content of rock fragments—0 to 10 percent

Bw horizon:

Hue—10YR or 7.5YR

Value—4 or 5

Chroma—3 to 6

Texture of the fine-earth fraction—sandy loam or

loam

Content of rock fragments—0 to 10 percent

#### Hammack Series

Depth class: Very deep Drainage class: Well drained Permeability: Moderate

Permeability. Moderate

Physiographic area: Highland Rim/Pennyroyal

Landform: Undulating plains

Parent material: Loess and residuum of limestone

Slope: 2 to 6 percent

Taxonomic class: Fine-silty, mixed, semiactive, mesic

Glossic Paleudalfs

#### **Typical Pedon**

Hammack silt loam, 2 to 6 percent slopes; 0.7 mile northwest of Oakland, 0.5 mile northwest of the intersection of Oakland School Road and Oakland-31W Road, 0.3 mile southeast of the intersection of W.R. Wilson Road and Oakland-31W Road, 75 feet east of Oakland-31W Road, in a field; USGS Bristow Quadrangle; lat. 37 degrees 3 minutes 11.2 seconds N. and long. 86 degrees 15 minutes 39.4 seconds W.

Ap—0 to 9 inches; dark yellowish brown (10YR 4/4) silt loam; weak fine granular structure; very friable; many fine roots; slightly acid; clear smooth boundary.

Bt1—9 to 17 inches; brown (7.5YR 4/4) silt loam; moderate medium subangular blocky structure; friable; common fine roots; few fine black (10YR 2/1) manganese concretions; moderately acid; clear smooth boundary.

Bt2—17 to 30 inches; yellowish red (5YR 4/6) silty

clay loam; moderate medium subangular blocky structure; firm; common fine roots; few distinct reddish brown (5YR 5/4) clay films on faces of peds; common fine black (10YR 2/1) manganese concretions; moderately acid; abrupt wavy boundary.

- 2B/E—30 to 41 inches; 70 percent yellowish red (5YR 4/6) very gravelly silt loam; moderate medium subangular blocky structure; firm; few very fine roots; few distinct reddish brown (5YR 5/4) clay films on faces of peds; 30 percent light brownish gray (10YR 6/2) and pale brown (10YR 6/3) silt coatings on faces of peds and coating fragments; 60 percent angular fragments of chert; strongly acid; clear smooth boundary.
- 2Bt1—41 to 54 inches; dark red (2.5YR 3/6) gravelly clay; moderate medium subangular blocky structure; firm; common prominent dark reddish brown (2.5YR 3/4) clay films on faces of peds; common black (10YR 2/1) manganese concretions; 30 percent angular fragments of chert; strongly acid; clear smooth boundary.
- 2Bt2—54 to 84 inches; dark red (10R 3/6) clay; moderate medium subangular blocky structure; very firm; moderately sticky; moderately plastic; many prominent dark red (2.5YR 3/6) clay films on faces of peds; common black (10YR 2/1) manganese concretions; 10 percent angular fragments of chert; strongly acid.

#### Range in Characteristics

Depth to bedrock: More than 60 inches
Kind of rock fragments: Subrounded and angular chert
Reaction: Moderately acid to very strongly acid,
except in limed areas

A or Ap horizon:

Hue—10YR

Value-4 or 5

Chroma—3 or 4

Texture of the fine-earth fraction—silt loam Content of rock fragments—0 to 5 percent

Bt horizon:

Hue—5YR or 7.5YR

Value—4 or 5

Chroma—3 to 6

Texture of the fine-earth fraction—silty clay loam or silt loam

Content of rock fragments—0 to 5 percent

2B/E horizon:

Hue-5YR, 7.5YR, or 10YR

Value—4 or 5

Chroma-3 to 6

Texture of the fine-earth fraction—silty clay loam or silt loam

Content of rock fragments—15 to 70 percent

2Bt horizon:

Hue-5YR to 10R

Value—3 to 5

Chroma-4 or 6

Texture of the fine-earth fraction—silty clay or clay Content of rock fragments—10 to 75 percent

## Lawrence Series

Depth class: Very deep

Drainage class: Somewhat poorly drained

Permeability: Moderate above the fragipan and slow

or very slow in the fragipan

Physiographic area: Highland Rim/Pennyroyal Landform: Nearly level uplands and stream terraces Parent material: Loess or alluvium and residuum of limestone

Slope: 0 to 2 percent

Taxonomic class: Fine-silty, mixed, semiactive, mesic Aquic Fragiudalfs

#### **Typical Pedon**

Lawrence silt loam, rarely flooded; 0.6 mile northwest of Plano, 2,927 feet southwest of the intersection of Carter Sims Road and Kentucky Highway 622, about 3,069 feet northwest of the intersection of Baldock Road and the Plano-Richpond Road; USGS Bowling Green South Quadrangle; lat. 36 degrees 53 minutes 13 seconds N. and long. 86 degrees 25 minutes 36 seconds W.

- Ap—0 to 7 inches; grayish brown (10YR 5/2) silt loam; weak fine granular structure; very friable; common fine roots; few fine black (10YR 2/1) and dark brown (10YR 3/3) iron and manganese concretions; strongly acid; abrupt smooth boundary.
- Bt1—7 to 14 inches; yellowish brown (10YR 5/6) silty clay loam; moderate medium subangular blocky structure; friable; common fine roots; few faint clay films on faces of peds; common medium distinct light yellowish brown (2.5Y 6/4) iron depletions; very strongly acid; clear smooth boundary.
- Bt2—14 to 18 inches; yellowish brown (10YR 5/6) silty clay loam; moderate medium subangular blocky structure; friable; few faint clay films on faces of peds; few fine white (10YR 8/1) silt coatings on faces of peds; few fine black (10YR 2/1) and dark brown (10YR 3/3) iron and manganese concretions; common medium distinct very pale

brown (10YR 7/4) and common medium prominent light brownish gray (10YR 6/2) iron depletions; strongly acid; clear smooth boundary.

Btx1—18 to 40 inches; 50 percent gray (10YR 5/1) and 50 percent yellowish brown (10YR 5/6) silty clay loam; weak very coarse prismatic structure parting to weak medium subangular blocky; very firm; few very fine roots between prisms; common distinct yellowish brown (10YR 5/4) clay films on prism faces; few fine light gray (10YR 7/2) silt coatings on prism faces; brittle in 70 percent of the mass; strongly acid; gradual smooth boundary.

Btx2—40 to 65 inches; 50 percent gray (10YR 5/1) and 50 percent yellowish brown (10YR 5/6) silty clay loam; moderate very coarse prismatic structure parting to moderate medium subangular blocky; very firm; few very fine roots between prisms; few distinct yellowish brown (10YR 5/4) clay films on prism faces; few fine light brownish gray (10YR 6/2) silt coatings on prism faces; brittle in 90 percent of the mass; strongly acid.

#### Range in Characteristics

Depth to bedrock: More than 60 inches Kind of rock fragments: Subrounded chert

Reaction: Very strongly acid or strongly acid, except in

limed areas

A or Ap horizon:

Hue—10YR or 2.5Y

Value—4 or 5

Chroma—2 to 4

Texture of the fine-earth fraction—silt loam

Content of rock fragments—none

Bt horizon:

Hue-7.5YR to 2.5Y

Value—5 or 6

Chroma—4 or 6

Texture of the fine-earth fraction—silty clay loam or silt loam

Content of rock fragments—none

Btx horizon:

Hue-7.5YR to 2.5Y

Value—4 to 6

Chroma—1 to 6

Texture of the fine-earth fraction—silty clay loam

or silt loam

Content of rock fragments—0 to 5 percent

#### Lindside Series

Depth class: Very deep

Drainage class: Moderately well drained

Permeability: Moderate

Physiographic area: Highland Rim/Pennyroyal

Landform: Flood plains
Parent material: Alluvium
Slope: 0 to 2 percent

Taxonomic class: Fine-silty, mixed, active, mesic

Fluvaquentic Eutrudepts

## **Typical Pedon**

Lindside silt loam, frequently flooded; 2.4 miles northwest of Riverside, 1.0 mile north of the intersection of James Elkins Road and Joe Willis Road, 738 feet northwest of Joe Willis Road, in a field; USGS Riverside Quadrangle; lat. 37 degrees 10 minutes 30 seconds N. and long. 86 degrees 34 minutes 10 seconds W.

Ap—0 to 10 inches; brown (10YR 4/3) silt loam; moderate fine granular structure; friable; few fine roots; neutral; clear smooth boundary.

BA—10 to 16 inches; brown (10YR 4/3) silt loam; weak fine granular structure; friable; few fine roots; neutral; clear smooth boundary.

Bw1—16 to 22 inches; brown (10YR 4/3) silty clay loam; moderate medium subangular blocky structure; friable; few fine pores; few fine distinct light brownish gray (10YR 6/2) iron depletions; moderately acid; gradual wavy boundary.

Bw2—22 to 42 inches; brown (10YR 4/3) silty clay loam; moderate medium subangular blocky structure; friable; common fine pores; common fine prominent yellowish brown (10YR 5/8) masses of iron accumulation; common medium distinct light brownish gray (10YR 6/2) iron depletions; moderately acid; clear smooth boundary.

Cg—42 to 65 inches; 25 percent light brownish gray (10YR 6/2), 25 percent light gray (2.5Y 7/2), 25 percent dark brown (10YR 3/3), and 25 percent light yellowish brown (10YR 6/4) silt loam; massive; firm; few rounded chert gravel; moderately acid.

#### Range in Characteristics

Depth to bedrock: More than 60 inches Kind of rock fragments: Rounded chert

Reaction: Strongly acid or very strongly acid, except in

limed areas

A or Ap horizon:

Hue—10YR

Value—4 or 5

Chroma—2 or 3

Texture of the fine-earth fraction—silt loam Content of rock fragments—15 to 35 percent

#### BA and Bw horizons:

Hue—7.5YR to 2.5Y

Value—4 or 5

Chroma—3 to 6

Texture of the fine-earth fraction—silty clay loam

or silt loam

Content of rock fragments—0 to 5 percent

#### Cg horizon:

Hue-10YR or 2.5Y

Value—4 to 6

Chroma—1 to 4

Texture of the fine-earth fraction—silt loam or silty

clay loam

Content of rock fragments—0 to 35 percent

## Melvin Series

Depth class: Very deep

Drainage class: Poorly drained

Permeability: Moderate

Physiographic area: Highland Rim/Pennyroyal

Landform: Flood plains
Parent material: Alluvium
Slope: 0 to 2 percent

Taxonomic class: Fine-silty, mixed, active, nonacid,

mesic Fluvaquentic Endoaquepts

#### **Typical Pedon**

Melvin silt loam, frequently flooded; 6.0 miles northwest of Benleo on Kentucky Highway 263, about 1.2 miles northwest of the intersection of Amber White Road and Kentucky Highway 263, about 2,342 feet west on a dirt road off Kentucky Highway 263, about 1,006 feet northwest from the end of the road, in a field; USGS Riverside Quadrangle; lat. 37 degrees 9 minutes 30 seconds N. and long. 86 degrees 36 minutes 38 seconds W.

- Ap—0 to 9 inches; grayish brown (10YR 5/2) silt loam; weak fine granular structure; friable; common fine roots; few fine prominent yellowish brown (10YR 5/8) masses of iron accumulation; slightly alkaline; abrupt smooth boundary.
- Bg—9 to 33 inches; light brownish gray (10YR 6/2) silty clay loam; moderate medium subangular blocky structure; friable; few fine roots; common fine distinct yellowish brown (10YR 5/4) masses of iron accumulation; moderately alkaline; gradual smooth boundary.
- Cg—33 to 62 inches; light brownish gray (10YR 6/2) silty clay loam; massive; friable; few fine black (10YR 2/1) manganese concretions; few fine prominent yellowish brown (10YR 5/6) masses of iron accumulation; slightly alkaline.

# **Range in Characteristics**

Depth to bedrock: More than 60 inches Kind of rock fragments: Rounded chert

Reaction: Moderately acid to moderately alkaline

#### A or Ap horizon:

Hue-10YR to 5Y

Value—6 or 7

Chroma—1 or 2

Texture of the fine-earth fraction—silt loam

Content of rock fragments—none

#### Bg horizon:

Hue—10YR to 5Y

Value—5 to 7

Chroma—0 to 2

Texture of the fine-earth fraction—silty clay loam

or silt loam

Content of rock fragments—none

# Cg horizon:

Hue—10YR to 2.5Y

Value—4 to 6

Chroma—0 to 2

Texture of the fine-earth fraction—silty clay loam

or silt loam

Content of rock fragments—none

#### **Newark Series**

Depth class: Very deep

Drainage class: Somewhat poorly drained

Permeability: Moderate

Physiographic area: Highland Rim/Pennyroyal Landform: Flood plains and depressions

Parent material: Alluvium

Slope: 0 to 2 percent Taxonomic class: Fine-silty, mixed, active, nonacid,

mesic Fluventic Endoaquepts

#### **Typical Pedon**

Newark silt loam, frequently flooded; 1.0 mile northeast of Greenwood, 1.6 miles northwest of the intersection of Hunt Road and Middle Bridge Road, 1.5 miles northwest of the intersection of Roy Thomas Road and Middle Bridge Road, 400 feet east of Drake's Creek; USGS Bowling Green South Quadrangle; lat. 36 degrees 56 minutes 50.8 seconds N. and long. 86 degrees 24 minutes 18.7 seconds W.

- Ap—0 to 11 inches; brown (10YR 4/3) silt loam; weak fine granular structure; very friable; many fine roots; few fine pores; moderately alkaline; abrupt smooth boundary.
- Bw—11 to 18 inches; yellowish brown (10YR 5/4) silty clay loam; weak fine subangular blocky structure;

very friable; common fine roots; few fine and medium pores; many fine and medium light brownish gray (10YR 6/2) iron depletions; slightly acid; clear smooth boundary.

- Bg—18 to 28 inches; light brownish gray (10YR 6/2) silty clay loam; weak fine subangular blocky structure; friable; common fine pores; few fine black (10YR 2/1) manganese concretions; common medium distinct yellowish brown (10YR 5/4) masses of iron accumulation; slightly acid; clear smooth boundary.
- Cg—28 to 65 inches; light brownish gray (2.5Y 6/2) silty clay loam; massive; friable; few fine pores; common fine and medium black (10YR 2/1) manganese concretions; few medium distinct light yellowish brown (2.5Y 6/4) masses of iron accumulation; moderately acid.

# Range in Characteristics

Depth to bedrock: More than 60 inches Kind of rock fragments: Rounded chert Reaction: Moderately acid to slightly alkaline

A or Ap horizon:

Hue-10YR or 7.5YR

Value—4 or 5

Chroma—2 to 4

Texture of the fine-earth fraction—silt loam

Content of rock fragments—none

Bw horizon:

Hue—10YR or 2.5Y

Value—4 or 5

Chroma—3 to 6

Texture of the fine-earth fraction—silty clay loam Content of rock fragments—none

Ba horizon:

Hue-10YR or 2.5Y

Value—5 or 6

Chroma—0 to 2

Texture of the fine-earth fraction—silty clay loam Content of rock fragments—none

Cg horizon:

Hue-10YR or 2.5Y

Value—4 to 7

Chroma—0 to 2

Texture of the fine-earth fraction—silty clay loam

or silt loam

Content of rock fragments—none

#### Nicholson Series

Depth class: Very deep

Drainage class: Moderately well drained

Permeability: Moderate above the fragipan and slow or very slow in the fragipan

Physiographic area: Highland Rim/Pennyroyal Landform: Undulating or rolling ridges and side slopes Parent material: Loess and residuum of limestone Slope: 0 to 12 percent

Taxonomic class: Fine-silty, mixed, active, mesic Oxyaquic Fragiudalfs

#### **Typical Pedon**

Nicholson silt loam, 2 to 6 percent slopes; 0.7 mile northwest of Plano, 0.4 mile west of the intersection of Kentucky Highway 622 and Carter Sims Road, 1,122 feet south of Carter Sims Road; USGS Bowling Green South Quadrangle; lat. 36 degrees 53 minutes 18 seconds N. and long. 86 degrees 25 minutes 37 seconds W.

- Ap—0 to 6 inches; dark grayish brown (10YR 4/2) silt loam; weak fine granular structure; very friable; common fine roots; slightly acid; clear smooth boundary.
- Bt1—6 to 19 inches; yellowish brown (10YR 5/4) silty clay loam; moderate medium subangular blocky structure; friable; few fine roots; few faint clay films on faces of peds; slightly acid; gradual smooth boundary.
- Bt2—19 to 25 inches; yellowish brown (10YR 5/4) silty clay loam; moderate medium subangular blocky structure; friable; few fine roots; common distinct brown (10YR 5/3) clay films on faces of peds; few medium faint pale brown (10YR 6/3) iron depletions; few fine prominent red (2.5YR 4/6) iron concentrations; strongly acid; gradual wavy boundary.
- Btx—25 to 37 inches; yellowish brown (10YR 5/4) silt loam; strong very coarse prismatic structure parting to moderate medium angular blocky; very firm; few very fine roots between prisms; common distinct brown (10YR 5/3) clay films on prism faces; common black (10YR 2/1) manganese concretions; common medium distinct gray (10YR 6/1) iron depletions; brittle in 80 percent of the mass; strongly acid; gradual smooth boundary.
- 2Bt—37 to 57 inches; red (2.5YR 4/6) clay; moderate coarse angular blocky structure; firm; moderately sticky; moderately plastic; common prominent reddish brown (2.5YR 4/4) clay films on faces of peds; few black (10YR 2/1) manganese concretions; common medium prominent light brownish gray (10YR 6/2) iron depletions; strongly acid; gradual wavy boundary.
- 2C—57 to 62 inches; yellowish brown (10YR 5/6) clay; massive; very firm; very sticky; very plastic;

common medium prominent light brownish gray (10YR 6/2) iron depletions; moderately acid.

#### **Range in Characteristics**

Depth to bedrock: More than 60 inches Depth to fragipan: 18 to 30 inches

Reaction: Strongly acid to slightly acid, except in limed

areas

A or Ap horizon:

Hue—10YR or 7.5YR

Value—4 or 5 Chroma—2 to 4

Texture of the fine-earth fraction—silt loam

Content of rock fragments—none

Bt horizon:

Hue—10YR or 7.5YR

Value—4 or 5 Chroma—3 to 6

Texture of the fine-earth fraction—silty clay loam

or silt loam

Content of rock fragments—none

Btx horizon:

Hue-2.5Y to 7.5YR

Value—3 to 5

Chroma—4 to 8

Texture of the fine-earth fraction—silty clay loam

or silt loam

Content of rock fragments—none

2Bt and 2C horizons:

Hue—10YR to 2.5YR

Value—4 or 5

Chroma—4 or 6

Texture of the fine-earth fraction—silty clay or clay

Content of rock fragments—0 to 35 percent

#### **Nolin Series**

Depth class: Very deep Drainage class: Well drained Permeability: Moderate

Physiographic area: Highland Rim/Pennyroyal and

Western Coal Fields

Landform: Flood plains and depressions

Parent material: Alluvium Slope: 0 to 2 percent

Taxonomic class: Fine-silty, mixed, active, mesic

Dystric Fluventic Eutrudepts

### **Typical Pedon**

Nolin silt loam, frequently flooded; 7.65 miles northwest of Benleo, 1.65 miles northwest of the intersection of Richardsville-Morgantown Road and Old Kentucky Highway 263, about 1,765 feet northeast of the end of Richardsville-Morgantown Road and the Green River, in a field; USGS Riverside Quadrangle; lat. 37 degrees 10 minutes 52 seconds N. and long. 86 degrees 37 minutes 00 seconds W.

Ap—0 to 9 inches; brown (10YR 4/3) silt loam; weak fine granular structure; very friable; many fine roots; moderately acid; gradual smooth boundary.
 Bw—9 to 65 inches; dark yellowish brown (10YR 4/4) silt loam; weak fine subangular blocky structure;

friable; few fine black (10YR 2/1) manganese

concretions; moderately acid.

# **Range in Characteristics**

Depth to bedrock: More than 60 inches

Kind of rock fragments: Rounded chert and sandstone

Reaction: Strongly acid to moderately alkaline

A or Ap horizon:

Hue—10YR

Value—4 or 5

Chroma—2 to 4

Texture of the fine-earth fraction—silt loam

Content of rock fragments—0 to 5 percent

Bw horizon:

Hue—10YR or 7.5YR

Value—4 or 5

Chroma-3 to 6

Texture of the fine-earth fraction—silt loam or silty

clay loam

Content of rock fragments—0 to 5 percent

### **Otwood Series**

Depth class: Very deep

Drainage class: Moderately well drained

Permeability: Moderate above the fragipan and slow

or very slow in the fragipan

Physiographic area: Highland Rim/Pennyroyal and

Western Coal Fields Landform: Stream terraces Parent material: Alluvium Slope: 0 to 6 percent

Taxonomic class: Fine-silty, mixed, active, mesic

Oxyaquic Fragiudalfs

#### **Typical Pedon**

Otwood silt loam, 0 to 2 percent slopes, rarely flooded; in Bowling Green, 2.2 miles northeast of the intersection of Kentucky Highways 880 and 1435, about 1.4 miles northeast of the intersection of Kentucky Highway 1435 and McFarland Lane, 2,814 feet northwest at the end of McFarland Lane, in a field;

USGS Bowling Green North Quadrangle; lat. 37 degrees 2 minutes 5.8 seconds N. and long. 86 degrees 28 minutes 2.2 seconds W.

- Ap—0 to 6 inches; brown (10YR 5/3) silt loam; weak fine granular structure; very friable; many fine and medium roots; few fine black (10YR 2/1) manganese and iron concretions; slightly acid; gradual smooth boundary.
- BA—6 to 12 inches; yellowish brown (10YR 5/4) silt loam; weak fine subangular blocky structure; friable; common fine and very fine roots; common fine black (10YR 2/1) manganese concretions; common fine faint pale brown (10YR 6/3) iron depletions; slightly acid; gradual smooth boundary.
- Bt1—12 to 20 inches; brown (10YR 5/3) silt loam; weak medium subangular blocky structure; friable; common fine roots; few faint clay films on faces of peds; common fine distinct yellowish brown (10YR 5/6) masses of iron accumulation; slightly acid; gradual wavy boundary.
- Bt2—20 to 28 inches; pale brown (10YR 6/3) silt loam; weak medium subangular blocky structure; friable; few fine roots; few faint clay films on faces of peds; common fine black (10YR 2/1) and dark brown (10YR 3/3) manganese and iron concretions; common fine faint light brownish gray (10YR 6/2) iron depletions; common fine distinct yellowish brown (10YR 5/6) masses of iron accumulation; 2 percent rounded siltstone gravel; moderately acid; abrupt smooth boundary.
- Btx—28 to 37 inches; 60 percent light brownish gray (10YR 6/2) and 40 percent pale brown (10YR 6/3) silt loam; moderate to strong very coarse prismatic structure parting to moderate medium subangular blocky; very firm; few very fine roots between prisms; few fine distinct brown (10YR 5/3) clay films on prism faces; few fine pale brown (10YR 6/3) silt coatings on prism faces; few fine black (10YR 2/1) manganese concretions; common medium distinct yellowish brown (10YR 5/6) iron concentrations along faces of peds; brittle in 90 percent of the mass; moderately acid; abrupt wavy boundary.
- B't1—37 to 44 inches; light brownish gray (10YR 6/2) silt loam; weak fine subangular blocky structure; firm; few fine distinct brown (10YR 5/3) clay films on faces of peds; few fine distinct very pale brown (10YR 7/4) silt coatings on faces of peds; few black (10YR 2/1) and dark brown (10YR 3/3) manganese and iron concentrations; strongly acid; clear smooth boundary.
- B't2—44 to 80 inches; brown (7.5YR 4/4) silt loam; weak fine subangular blocky structure; firm; few fine faint clay films on faces of peds; few fine

distinct brown (10YR 5/3) silt coatings on faces of peds; common black (10YR 2/1) and dark brown (10YR 3/3) manganese and iron stains on faces of peds; very strongly acid.

#### **Range in Characteristics**

Depth to bedrock: More than 60 inches Depth to fragipan: 20 to 36 inches Kind of rock fragments: Rounded chert Reaction: Slightly acid to very strongly acid

#### A or Ap horizon:

Hue-10YR or 2.5Y

Value—4 or 5

Chroma-2 to 4

Texture of the fine-earth fraction—silt loam Content of rock fragments—0 to 5 percent

#### BA horizon:

Hue-10YR

Value—4 or 5

Chroma—3 or 4

Texture of the fine-earth fraction—silt loam Content of rock fragments—0 to 5 percent

#### Bt horizon:

Hue-7.5YR to 2.5Y

Value—4 to 6

Chroma—4 to 8

Texture of the fine-earth fraction—silt loam or silty clay loam

Content of rock fragments—0 to 5 percent

#### Btx horizon:

Hue-7.5YR to 2.5Y

Value—4 to 6

Chroma—1 to 8

Texture of the fine-earth fraction—silt loam or silty

Content of rock fragments—0 to 15 percent

#### B't horizon:

Hue—7.5YR to 2.5Y

Value—4 to 6

Chroma—1 to 8

Texture of the fine-earth fraction—silt loam or silty clay loam

Content of rock fragments—0 to 15 percent

#### Pembroke Series

Depth class: Very deep Drainage class: Well drained

Permeability: Moderate or moderately slow Physiographic area: Highland Rim/Pennyroyal

Landform: Nearly level karst plains

Parent material: Loess and alluvium or residuum of limestone

Slope: 0 to 2 percent

Taxonomic class: Fine-silty, mixed, active, mesic

Mollic Paleudalfs

#### **Typical Pedon**

Pembroke silt loam, 0 to 2 percent slopes; 0.8 mile southeast of Memphis Junction, 0.54 mile east of the intersection of U.S. Highway 31 and Bennett Road, 350 feet south of Bennett Road, in pasture; USGS Bowling Green South Quadrangle; lat. 36 degrees 56 minutes 13.1 seconds N. and long. 86 degrees 28 minutes 32.2 seconds W.

- Ap—0 to 9 inches; dark brown (7.5YR 3/3) silt loam; weak fine granular structure; friable; common fine roots; neutral; clear wavy boundary.
- Bt1—9 to 18 inches; reddish brown (5YR 4/4) silt loam; weak fine subangular blocky structure; friable; common fine and medium roots; common distinct reddish brown (5YR 4/3) clay films on faces of peds; common fine black (10YR 2/1) manganese stains and concretions throughout; neutral; gradual wavy boundary.
- Bt2—18 to 28 inches; yellowish red (5YR 4/6) silty clay loam; moderate medium subangular blocky structure; firm; slightly sticky; slightly plastic; common fine roots; common distinct reddish brown (5YR 5/4) clay films on faces of peds; common fine black (10YR 2/1) manganese stains and concretions; moderately acid; gradual wavy boundary.
- Bt3—28 to 35 inches; red (2.5YR 4/6) silty clay loam; moderate medium subangular blocky structure; firm; slightly sticky; slightly plastic; common very fine roots; common prominent reddish brown (2.5YR 4/4) clay films on faces of peds; common fine black (10YR 2/1) manganese stains and concretions; moderately acid; gradual wavy boundary.
- Bt4—35 to 62 inches; dark red (2.5YR 3/6) silty clay loam; moderate medium subangular blocky structure; firm; slightly sticky; slightly plastic; few very fine roots; common prominent reddish brown (2.5YR 4/4) clay films on faces of peds; few fine distinct yellowish red (5YR 4/6) silt coatings on faces of peds; common fine black (10YR 2/1) manganese concretions; strongly acid; gradual wavy boundary.
- Bt5—62 to 80 inches; dark red (2.5YR 3/6) silty clay; moderate medium subangular blocky structure; very firm; moderately sticky; moderately plastic; common prominent reddish brown (2.5YR 4/4) clay films on faces of peds; common fine black

(10YR 2/1) manganese concretions; 5 percent chert gravel; strongly acid.

#### Range in Characteristics

Depth to bedrock: More than 60 inches Kind of rock fragments: Subrounded chert Reaction: Moderately acid to very strongly acid,

except in limed areas

A or Ap horizon:

Hue-10YR to 5YR

Value—3

Chroma—2 or 3

Texture of the fine-earth fraction—silt loam Content of rock fragments—0 to 5 percent

Bt horizon:

Hue—5YR or 2.5YR

Value—4 or 5

Chroma—4 to 8

Texture of the fine-earth fraction—silty clay loam

or silty clay

Content of rock fragments—0 to 15 percent

# Ramsey Series

Depth class: Shallow

Drainage class: Somewhat excessively drained

Permeability: Rapid

Physiographic area: Western Coal Fields

Landform: Steep hillsides

Parent material: Residuum of sandstone

Slope: 20 to 60 percent

Taxonomic class: Loamy, siliceous, subactive, mesic

Lithic Dystrudepts

#### **Typical Pedon**

Ramsey loam in an area of Ramsey-Frondorf complex, 20 to 60 percent slopes; 2.81 miles south of Glenmore, 1.76 miles southeast of the intersection of Kentucky Highway 1748 and Lake Road, 1.03 miles east of the intersection of Lake Road and Shanty Hollow Road, 65 feet east of the road in woods; USGS Reedyville Quadrangle; lat. 37 degrees 2 minutes 44.2 seconds N. and long. 86 degrees 9 minutes 36.7 seconds W.

- A1—0 to 1 inch; very dark grayish brown (10YR 3/2) loam; weak fine granular structure; very friable; many fine roots; very strongly acid; clear smooth boundary.
- A2—1 to 4 inches; brown (10YR 4/3) channery loam; weak medium granular structure; very friable; many fine roots; 15 percent channers of sandstone; strongly acid; clear smooth boundary.

Bw1—4 to 12 inches; yellowish brown (10YR 5/4) channery loam; weak medium subangular blocky structure; very friable; common fine roots; 20 percent channers of sandstone; very strongly acid; abrupt smooth boundary.

Bw2—12 to 19 inches; light yellowish brown (10YR 6/4) channery loam; weak medium subangular blocky structure; very friable; common fine roots; 30 percent channers of sandstone; very strongly acid; very abrupt smooth boundary.

R—19 inches; hard sandstone bedrock.

### Range in Characteristics

Depth to bedrock: 7 to 20 inches

Kind of rock fragments: Channers of sandstone Reaction: Strongly acid or very strongly acid

#### A horizon:

Hue—10YR

Value—3 to 5

Chroma—2 to 4

Texture of the fine-earth fraction—loam or sandy

Content of rock fragments—0 to 35 percent

#### Bw horizon:

Hue-10YR or 7.5YR

Value—4 or 6

Chroma—3 to 8

Texture of the fine-earth fraction—loam or sandy

Content of rock fragments—5 to 35 percent

#### Robertsville Series

Depth class: Very deep

Drainage class: Poorly drained

Permeability: Moderate above the fragipan and slow

or very slow in the fragipan

Physiographic area: Highland Rim/Pennyroyal Landform: Nearly level stream terraces and upland

depressions

Parent material: Mixed alluvium and loess

Slope: 0 to 2 percent

Taxonomic class: Fine-silty, mixed, semiactive, mesic

Typic Fragiaqualfs

# **Typical Pedon**

Robertsville silt loam, ponded; 2.26 miles northwest of Plano, 1.3 miles west of the intersection of Kentucky Highway 522 and Collett Lane, 2,088 feet west of Dewey Lake Road and a farm road, in a field; USGS Bowling Green South Quadrangle; lat. 36 degrees 54 minutes 7.2 seconds N. and long. 86 degrees 25 minutes 52.2 seconds W.

Ap—0 to 10 inches; dark grayish brown (10YR 4/2) silt loam; weak fine granular structure; very friable; common fine roots; common medium prominent yellowish brown (10YR 5/6) masses of iron accumulation; slightly acid; abrupt smooth boundary.

Bg—10 to 28 inches; light gray (10YR 7/1) silt loam; moderate medium subangular blocky structure; friable; few fine black (10YR 2/1) manganese concretions; common medium prominent yellowish brown (10YR 5/6) masses of iron accumulation; very strongly acid; clear wavy boundary.

Btxg—28 to 40 inches; gray (10YR 6/1) silty clay loam; moderate very coarse prismatic structure parting to weak fine and medium subangular blocky; very firm; few fine faint clay films on faces of prisms; few light brownish gray (10YR 6/2) silt coatings on prism faces; few fine black (10YR 2/1) manganese concretions; many medium prominent yellowish brown (10YR 5/6) masses of iron accumulation; brittle in 90 percent of the mass; very strongly acid; gradual wavy boundary.

Cg—40 to 80 inches; 34 percent gray (10YR 5/1), 33 percent red (2.5YR 4/8), and 33 percent yellowish red (5YR 5/8) silty clay; massive; very firm; few fine black (10YR 2/1) manganese concretions; very strongly acid.

### **Range in Characteristics**

Depth to bedrock: More than 60 inches Depth to fragipan: 18 to 30 inches Kind of rock fragments: Rounded chert

Reaction: Strongly acid to extremely acid, except in

limed areas

A or Ap horizon:

Hue-10YR or 2.5Y

Value—4 to 6

Chroma—1 or 2

Texture of the fine-earth fraction—silt loam Content of rock fragments—0 to 5 percent

#### Bg horizon:

Hue-10YR to 5Y

Value—6 or 7

Chroma—1 or 2

Texture of the fine-earth fraction—silt loam or silty

ciay ioam

Content of rock fragments—0 to 5 percent

# Btxq horizon:

Hue—10YR to 5Y

Value—5 to 7

Chroma—1 or 2

Texture of the fine-earth fraction—silt loam or silty clay loam

Content of rock fragments—0 to 5 percent

# Cg horizon:

Hue—10YR to 5Y Value—5 to 7 Chroma—1 or 2

Texture of the fine-earth fraction—silt loam, silty

clay loam, or silty clay

Content of rock fragments—0 to 20 percent

# Sadler Series

Depth class: Very deep

Drainage class: Moderately well drained

Permeability: Moderate above the fragipan and slow

or very slow in the fragipan

Physiographic area: Western Coal Fields Landform: Nearly level or undulating ridges

Parent material: Loess and residuum of sandstone

Slope: 0 to 6 percent

Taxonomic class: Fine-silty, mixed, semiactive, mesic

Oxyaquic Fraglossudalfs

# **Typical Pedon**

Sadler silt loam, 2 to 6 percent slopes; 2.42 miles northwest of Richardsville on Kentucky Highway 263, about 0.74 mile northwest of the intersection of Ed Hudson Road and Kentucky Highway 263, about 844 feet northeast of Kentucky Highway 263, in a field; USGS Reedyville Quadrangle; lat. 37 degrees 7 minutes 48 seconds N. and long. 86 degrees 29 minutes 49 seconds W.

Ap—0 to 9 inches; brown (10YR 4/3) silt loam; weak fine granular structure; very friable; many fine roots; neutral; clear smooth boundary.

Bt—9 to 23 inches; brownish yellow (10YR 6/6) silty clay loam; weak medium angular and subangular blocky structure; friable; many fine roots; common distinct yellowish brown (10YR 5/4) clay films on faces of peds; few fine distinct strong brown (7.6YR 5/6) masses of iron accumulation; moderately acid; abrupt smooth boundary.

E/B—23 to 26 inches; 55 percent brown (10YR 5/3) silt loam (E part) and 45 percent brownish yellow (10YR 6/6) silt loam (B part); weak fine and medium subangular blocky structure in E part; moderate medium subangular blocky structure in B part; very friable in E part and firm in B part; few fine roots in E part; few fine distinct pale brown (10YR 6/3) and light brownish gray (10YR 6/2) silt coatings on faces of peds; few fine and medium black (10YR 2/1) manganese concretions; brittle

in less than 40 percent of the mass; very strongly acid; clear irregular boundary.

2Btx—26 to 56 inches; 34 percent brownish yellow (10YR 6/6), 33 percent grayish brown (10YR 5/2), and 33 percent yellowish brown (10YR 5/4) silty clay loam; strong very coarse prismatic structure parting to moderate medium angular blocky; very firm; common light yellowish brown (10YR 6/4) clay films on faces of prisms; few fine black (10YR 2/1) and dark brown (10YR 3/3) manganese and iron concretions; brittle in 90 percent of the mass; very strongly acid; clear wavy boundary.

2B't—56 to 65 inches; light brownish gray (10YR 6/2) silt loam; moderate medium subangular blocky structure; firm; common gray (10YR 6/1) clay films on faces of peds; few fine black (10YR 2/1) manganese concretions; common medium prominent yellowish brown (10YR 5/8) and strong brown (7.5YR 5/8) masses of iron accumulation; 5 percent channers of sandstone; very strongly acid; clear wavy boundary.

R—65 inches; hard sandstone bedrock.

# Range in Characteristics

Depth to bedrock: More than 60 inches Depth to fragipan: 18 to 32 inches (fig. 11) Kind of rock fragments: Channers of sandstone Reaction: Strongly acid or very strongly acid, except in

limed areas

A or Ap horizon:

Hue—10YR or 2.5Y

Value—4 or 5

Chroma-2 to 4

Texture of the fine-earth fraction—silt loam Content of rock fragments—0 to 5 percent

#### Bt horizon:

Hue-7.5YR to 2.5Y

Value—5 or 6

Chroma—4 or 6

Texture of the fine-earth fraction—silty clay loam or silt loam

Content of rock fragments—0 to 5 percent

#### E/B horizon:

Hue-10YR to 2.5Y

Value—4 to 6

Chroma-2 to 6

Texture of the fine-earth fraction—silty clay loam or silt loam

Content of rock fragments—0 to 5 percent

# 2Btx horizon:

Hue-7.5YR to 5Y

Value—3 to 6



Figure 11.—A profile of Sadler soils. A dense fragipan starting at a depth of 24 inches limits rooting depth and available water capacity.

Chroma—1 to 6

Texture of the fine-earth fraction—silty clay loam or silt loam

Content of rock fragments—0 to 15 percent

2B't horizon:

Hue-7.5YR to 2.5Y

Value—5 or 6

Chroma—4 to 6

Texture of the fine-earth fraction—silty clay loam or silt loam

Content of rock fragments—0 to 60 percent

# Vertrees Series

Depth class: Very deep Drainage class: Well drained

Permeability: Moderately slow or slow

Physiographic area: Highland Rim/Pennyroyal Landform: Undulating or rolling ridges and side slopes Parent material: Residuum from limestone

Slope: 2 to 12 percent

Taxonomic class: Fine, mixed, semiactive, mesic Typic Paleudalfs

oddano

# **Typical Pedon**

Vertrees silt loam in an area of Fredonia-Vertrees complex, 2 to 6 percent slopes, rocky; in Bowling Green, 0.4 mile southeast of Memphis Junction, 0.2 mile northeast of the intersection of U.S. Highway 31W and Elrod Road, 767 feet southeast of the intersection of Memphis Junction Road and U.S. Highway 31W; USGS Bowling Green South Quadrangle; lat. 36 degrees 56 minutes 15.4 seconds N. and long. 86 degrees 29 minutes 3.8 seconds W.

Ap—0 to 4 inches; brown (10YR 4/3) silt loam; weak fine granular structure; friable; common fine roots; neutral; abrupt smooth boundary.

E—4 to 6 inches; yellowish brown (10YR 5/4) silt loam; weak medium granular structure; common fine roots; neutral; abrupt wavy boundary.

Bt1—6 to 15 inches; red (2.5YR 4/6) silty clay; moderate medium subangular blocky structure; firm; slightly sticky; slightly plastic; common fine roots; common distinct reddish brown (2.5YR 4/4) clay films on faces of peds; common fine black (10YR 2/1) manganese concretions; slightly acid; gradual wavy boundary.

Bt2—15 to 27 inches; red (2.5YR 4/6) clay; moderate medium subangular blocky structure; firm; slightly sticky; slightly plastic; common fine roots; common prominent reddish brown (2.5YR 4/4) clay films on faces of peds; common fine black (10YR 2/1) manganese concretions; few fine chert gravel; moderately acid; gradual wavy boundary.

Bt3—27 to 80 inches; dark red (2.5YR 3/6) clay; few fine prominent dark yellowish brown (10YR 4/6) and strong brown (7.5YR 5/6) mottles; moderate medium subangular blocky structure; firm; moderately sticky; moderately plastic; few very fine and fine roots; common or many prominent red (2.5YR 4/6) clay films on faces of peds; slightly acid.

#### Range in Characteristics

Depth to bedrock: More than 60 inches
Kind of rock fragments: Subrounded and angular chert
Reaction: Strongly acid or moderately acid, except in
limed areas

A or Ap horizon:

Hue-10YR to 5YR

Value—4 or 5

Chroma—2 to 4

Texture of the fine-earth fraction—silt loam or silty clay loam

Content of rock fragments—0 to 10 percent

#### E horizon:

Hue-10YR or 7.5YR

Value—4 to 6

Chroma—3 or 4

Texture of the fine-earth fraction—silt loam Content of rock fragments—0 to 10 percent

#### Bt horizon:

Hue-5YR, 2.5YR, or 10R

Value—3 to 5

Chroma—4 to 8

Texture of the fine-earth fraction—silty clay or clay

Content of rock fragments—5 to 35 percent

# Wellston Series

Depth class: Deep

Drainage class: Well drained Permeability: Moderate

Physiographic area: Western Coal Fields Landform: Undulating or rolling ridges

Parent material: Loess and residuum of sandstone

Slope: 2 to 12 percent

Taxonomic class: Fine-silty, mixed, active, mesic Ultic

Hapludalfs

#### **Typical Pedon**

Wellston silt loam, 2 to 6 percent slopes; 2.74 miles northeast of Rockfield, 2.92 miles northwest of the intersection of U.S. Highway 68 and Kentucky Highway 1083, about 1.25 miles northeast of the intersection of Fuqua Road and Kentucky Highway 1083, about 2,972 feet east of the intersection of Fuqua Road and a farm path, in pasture; USGS Rockfield Quadrangle; lat. 36 degrees 56 minutes 55 seconds N. and long. 86 degrees 33 minutes 8.1 seconds W.

Ap—0 to 8 inches; brown (10YR 4/3) silt loam; weak fine granular structure; very friable; many fine roots; strongly acid; abrupt smooth boundary.

Bt1—8 to 13 inches; yellowish brown (10YR 5/6) silt loam; weak fine subangular blocky structure; friable; many fine roots; few faint clay films on faces of peds; few fine black (10YR 2/1) manganese concretions; very strongly acid; clear smooth boundary.

Bt2—13 to 30 inches; strong brown (7.5YR 5/6) silty

clay loam; moderate medium subangular blocky structure; firm; common fine roots; few distinct brown (7.5YR 5/4) clay films on faces of peds; few fine prominent pale brown (10YR 6/3) silt coatings on faces of peds; few fine black (10YR 2/1) manganese concretions; very strongly acid; abrupt smooth boundary.

2Bt3—30 to 46 inches; strong brown (7.5YR 5/6) gravelly clay loam; moderate medium angular and subangular blocky structure; firm; few fine roots; 20 percent channers of sandstone; very strongly acid; abrupt wavy boundary.

R—46 inches; hard sandstone bedrock.

# Range in Characteristics

Depth to bedrock: 40 to 60 inches

Kind of rock fragments: Channers of sandstone Reaction: Strongly acid or very strongly acid, except in

limed areas

A or Ap horizon:

Hue—10YR or 7.5YR

Value—4 or 5

Chroma—3 to 8

Texture of the fine-earth fraction—silt loam Content of rock fragments—0 to 10 percent

#### Bt horizon:

Hue-7.5YR or 10YR

Value—4 or 5

Chroma—4 to 8

Texture of the fine-earth fraction—silt loam or silty

clav loam

Content of rock fragments—5 to 15 percent

#### 2Bt horizon:

Hue-7.5YR or 10YR

Value—4 or 5

Chroma-3 to 8

Texture of the fine-earth fraction—silt loam, loam,

or clay loam

Content of rock fragments—5 to 45 percent

#### Zanesville Series

Depth class: Deep

Drainage class: Moderately well drained

Permeability: Moderate above the fragipan and slow

or very slow in the fragipan

Physiographic area: Western Coal Fields Landform: Undulating or rolling ridges

Parent material: Loess and residuum of sandstone

Slope: 2 to 12 percent

Taxonomic class: Fine-silty, mixed, active, mesic Typic

Fragiudalfs

# **Typical Pedon**

Zanesville silt loam, 2 to 6 percent slopes; 2.27 miles northwest of Richardsville, 1.0 mile northwest of the intersection of Kentucky Highways 2631 and 263, about 0.56 mile northwest of the intersection of Ed Hudson Road and Kentucky Highway 263, about 300 feet northeast of Kentucky Highway 263, in a field; USGS Reedyville Quadrangle; lat. 37 degrees 2 minutes 44.2 seconds N. and long. 86 degrees 9 minutes 36.7 seconds W.

Ap—0 to 8 inches; dark grayish brown (10YR 4/2) silt loam; weak fine granular structure; very friable; many fine roots; moderately alkaline; clear smooth boundary.

Bt1—8 to 16 inches; strong brown (7.5YR 5/6) silty clay loam; moderate medium subangular blocky structure; friable; many fine roots; few faint clay films on faces of peds; moderately acid; abrupt smooth boundary.

Bt2—16 to 23 inches; yellowish brown (10YR 5/6) silty clay loam; moderate medium subangular blocky structure; friable; few faint clay films on faces of peds; strongly acid; clear wavy boundary.

Btx1—23 to 35 inches; yellowish brown (10YR 5/6) silty clay loam; moderate very coarse prismatic structure parting to moderate medium subangular blocky; very firm; common distinct yellowish brown (10YR 5/4) clay films on prism faces; common fine prominent gray (10YR 6/1) silt coatings on prism faces; many medium prominent light brownish gray (10YR 6/2) iron depletions; brittle in 90 percent of the mass; strongly acid; clear wavy boundary.

Btx2—35 to 45 inches; yellowish brown (10YR 5/6) silty clay loam; moderate very coarse prismatic structure parting to moderate medium subangular blocky; very firm; common distinct yellowish brown (10YR 5/4) clay films on prism faces; common fine distinct brown (10YR 5/3) and common fine prominent light brownish gray (10YR 6/2) iron depletions; brittle in 90 percent of the mass; strongly acid; clear smooth boundary.

2C-45 to 56 inches; yellowish brown (10YR 5/6) clay

loam; weak medium and coarse platy structure parting to weak medium subangular blocky; firm; common medium prominent gray (10YR 6/1) and light brownish gray (2.5Y 6/2) iron depletions; 10 percent sandstone fragments; very strongly acid; clear smooth boundary.

R-56 inches; hard sandstone bedrock.

# **Range in Characteristics**

Depth to bedrock: 40 to 60 inches Depth to fragipan: 20 to 32 inches

Kind of rock fragments: Subrounded and angular

sandstone

Reaction: Strongly acid or very strongly acid, except in

limed areas

A or Ap horizon:

Hue—10YR

Value—4 or 5

Chroma-2 to 4

Texture of the fine-earth fraction—silt loam Content of rock fragments—0 to 5 percent

#### Bt horizon:

Hue-7.5YR or 10YR

Value—4 or 5

Chroma—4 to 6

Texture of the fine-earth fraction—silty clay loam or silt loam

Content of rock fragments—0 to 5 percent

#### Btx horizon:

Hue—7.5YR or 10YR

Value—4 or 5

Chroma—4 to 6

Texture of the fine-earth fraction—silty clay loam or silt loam

Content of rock fragments—0 to 5 percent

#### 2C horizon:

Hue—7.5YR or 10YR

Value—4 or 5

Chroma—4 to 6

Texture of the fine-earth fraction—clay loam, silty clay loam, or silt loam

Content of rock fragments—5 to 35 percent

# References

- American Association of State Highway and Transportation Officials (AASHTO). 1998. Standard specifications for transportation materials and methods of sampling and testing. 19th ed., 2 vol.
- (2) American Society for Testing and Materials (ASTM). 1998. Standard classification of soils for engineering purposes. ASTM Standard D 2487.
- (3) Baird, Nancy, and Carol Crowe-Carraco. History of Warren County, Kentucky. http://www.wku.edu/Library/200Years/cntyhist.htm.
- (4) United States Census Bureau QuickFact. http://quickfacts.census.gov/qfd/states.
- (5) United States Department of Agriculture. 1981. Soil survey of Warren County, Kentucky.
- (6) United States Department of Agriculture, Natural Resources Conservation Service. 1993. Soil survey manual. Soil Surv. Staff. U.S. Dep. Agric. Handb. 18.
- (7) United States Department of Agriculture, Natural Resources Conservation Service. 1998 (revised). National forestry manual. Soil Surv. Staff.
- (8) United States Department of Agriculture, Natural Resources Conservation Service. 1999. Soil taxonomy: A basic system of soil classification for making and interpreting soil surveys. 2nd edition. Soil Surv. Staff. U.S. Dep. Agric. Handb. 436.
- (9) United States Department of Agriculture, Natural Resources Conservation Service. 2003. Keys to soil taxonomy. 9th ed. Soil Surv. Staff.
- (10) United States Department of Agriculture, Soil Conservation Service. 1961. Land capability classification. U.S. Dep. Agric. Handb. 210.

# **Glossary**

- **Aggregate, soil.** Many fine particles held in a single mass or cluster. Natural soil aggregates, such as granules, blocks, or prisms, are called peds. Clods are aggregates produced by tillage or logging.
- **Alluvial fan.** The fanlike deposit of a stream where it issues from a gorge upon a plain or of a tributary stream near or at its junction with its main stream.
- **Alluvium.** Material, such as sand, silt, or clay, deposited on land by streams.
- Alpha,alpha-dipyridyl. A dye that when dissolved in 1N ammonium acetate is used to detect the presence of reduced iron (Fe II) in the soil. A positive reaction indicates a type of redoximorphic feature.
- Animal unit month (AUM). The amount of forage required by one mature cow of approximately 1,000 pounds weight, with or without a calf, for 1 month.
- **Aquic conditions.** Current soil wetness characterized by saturation, reduction, and redoximorphic features.
- **Argillic horizon.** A subsoil horizon characterized by an accumulation of illuvial clay.
- **Aspect.** The direction in which a slope faces.
- Available water capacity (available moisture capacity). The capacity of soils to hold water available for use by most plants. It is commonly defined as the difference between the amount of soil water at field moisture capacity and the amount at wilting point. It is commonly expressed as inches of water per inch of soil. The capacity, in inches, in a 40-inch profile or to a limiting layer is expressed as:

Very low	0 to 2
Low	2 to 4
Moderate	4 to 6
High	more than 6

- **Backslope.** The position that forms the steepest and generally linear, middle portion of a hillslope. In profile, backslopes are commonly bounded by a convex shoulder above and a concave footslope below.
- **Basal area.** The area of a cross section of a tree, generally referring to the section at breast height

- and measured outside the bark. It is a measure of stand density, commonly expressed in square feet
- Base saturation. The degree to which material having cation-exchange properties is saturated with exchangeable bases (sum of Ca, Mg, Na, and K), expressed as a percentage of the total cation-exchange capacity.
- **Bedding planes.** Fine strata, less than 5 millimeters thick, in unconsolidated alluvial, eolian, lacustrine, or marine sediment.
- **Bedrock.** The solid rock that underlies the soil and other unconsolidated material or that is exposed at the surface.
- **Bedrock-controlled topography.** A landscape where the configuration and relief of the landforms are determined or strongly influenced by the underlying bedrock.
- **Bottom land.** The normal flood plain of a stream, subject to flooding.
- **Boulders.** Rock fragments larger than 2 feet (60 centimeters) in diameter.
- **Breast height.** An average height of 4.5 feet above the ground surface; the point on a tree where diameter measurements are ordinarily taken.
- Brush management. Use of mechanical, chemical, or biological methods to make conditions favorable for reseeding or to reduce or eliminate competition from woody vegetation and thus allow understory grasses and forbs to recover. Brush management increases forage production and thus reduces the hazard of erosion. It can improve the habitat for some species of wildlife.
- Cable yarding. A method of moving felled trees to a nearby central area for transport to a processing facility. Most cable yarding systems involve use of a drum, a pole, and wire cables in an arrangement similar to that of a rod and reel used for fishing. To reduce friction and soil disturbance, felled trees generally are reeled in while one end is lifted or the entire log is suspended.
- **Canopy.** The leafy crown of trees or shrubs. (See Crown.)
- **Capillary water.** Water held as a film around soil particles and in tiny spaces between particles.

Surface tension is the adhesive force that holds capillary water in the soil.

- **Catena.** A sequence, or "chain," of soils on a landscape that formed in similar kinds of parent material but have different characteristics as a result of differences in relief and drainage.
- **Cation.** An ion carrying a positive charge of electricity. The common soil cations are calcium, potassium, magnesium, sodium, and hydrogen.
- Cation-exchange capacity. The total amount of exchangeable cations that can be held by the soil, expressed in terms of milliequivalents per 100 grams of soil at neutrality (pH 7.0) or at some other stated pH value. The term, as applied to soils, is synonymous with base-exchange capacity but is more precise in meaning.
- Channery soil material. Soil material that has, by volume, 15 to 35 percent thin, flat fragments of sandstone, shale, slate, limestone, or schist as much as 6 inches (15 centimeters) along the longest axis. A single piece is called a channer.
- **Chemical treatment.** Control of unwanted vegetation through the use of chemicals.
- Clay. As a soil separate, the mineral soil particles less than 0.002 millimeter in diameter. As a soil textural class, soil material that is 40 percent or more clay, less than 45 percent sand, and less than 40 percent silt.
- Clay depletions. Low-chroma zones having a low content of iron, manganese, and clay because of the chemical reduction of iron and manganese and the removal of iron, manganese, and clay. A type of redoximorphic depletion.
- **Clay film.** A thin coating of oriented clay on the surface of a soil aggregate or lining pores or root channels. Synonyms: clay coating, clay skin.
- Coarse textured soil. Sand or loamy sand.
- **Cobble (or cobblestone).** A rounded or partly rounded fragment of rock 3 to 10 inches (7.6 to 25 centimeters) in diameter.
- Cobbly soil material. Material that has 15 to 35 percent, by volume, rounded or partially rounded rock fragments 3 to 10 inches (7.6 to 25 centimeters) in diameter. Very cobbly soil material has 35 to 60 percent of these rock fragments, and extremely cobbly soil material has more than 60 percent.
- **COLE** (coefficient of linear extensibility). See Linear extensibility.
- **Colluvium.** Soil material or rock fragments, or both, moved by creep, slide, or local wash and deposited at the base of steep slopes.
- **Complex slope.** Irregular or variable slope. Planning or establishing terraces, diversions, and other

- water-control structures on a complex slope is difficult.
- Complex, soil. A map unit of two or more kinds of soil or miscellaneous areas in such an intricate pattern or so small in area that it is not practical to map them separately at the selected scale of mapping. The pattern and proportion of the soils or miscellaneous areas are somewhat similar in all areas
- Concretions. Cemented bodies with crude internal symmetry organized around a point, a line, or a plane. They typically take the form of concentric layers visible to the naked eye. Calcium carbonate, iron oxide, and manganese oxide are common compounds making up concretions. If formed in place, concretions of iron oxide or manganese oxide are generally considered a type of redoximorphic concentration.
- Conservation cropping system. Growing crops in combination with needed cultural and management practices. In a good conservation cropping system, the soil-improving crops and practices more than offset the effects of the soil-depleting crops and practices. Cropping systems are needed on all tilled soils. Soil-improving practices in a conservation cropping system include the use of rotations that contain grasses and legumes and the return of crop residue to the soil. Other practices include the use of green manure crops of grasses and legumes, proper tillage, adequate fertilization, and weed and pest control.
- **Conservation tillage.** A tillage system that does not invert the soil and that leaves a protective amount of crop residue on the surface throughout the year.
- Consistence, soil. Refers to the degree of cohesion and adhesion of soil material and its resistance to deformation when ruptured. Consistence includes resistance of soil material to rupture and to penetration; plasticity, toughness, and stickiness of puddled soil material; and the manner in which the soil material behaves when subject to compression. Terms describing consistence are defined in the "Soil Survey Manual."
- **Contour stripcropping.** Growing crops in strips that follow the contour. Strips of grass or close-growing crops are alternated with strips of clean-tilled crops or summer fallow.
- **Control section.** The part of the soil on which classification is based. The thickness varies among different kinds of soil, but for many it is that part of the soil profile between depths of 10 inches and 40 or 80 inches.

- **Corrosion.** Soil-induced electrochemical or chemical action that dissolves or weakens concrete or uncoated steel.
- **Cover crop.** A close-growing crop grown primarily to improve and protect the soil between periods of regular crop production, or a crop grown between trees and vines in orchards and vineyards.
- **Cropping system.** Growing crops according to a planned system of rotation and management practices.
- **Crop residue management.** Returning crop residue to the soil, which helps to maintain soil structure, organic matter content, and fertility and helps to control erosion.
- **Cross-slope farming.** Deliberately conducting farming operations on sloping farmland in such a way that tillage is across the general slope.
- **Crown.** The upper part of a tree or shrub, including the living branches and their foliage.
- Culmination of the mean annual increment (CMAI). The average annual increase per acre in the volume of a stand. Computed by dividing the total volume of the stand by its age. As the stand increases in age, the mean annual increment continues to increase until mortality begins to reduce the rate of increase. The point where the stand reaches its maximum annual rate of growth is called the culmination of the mean annual increment.
- **Deferred grazing.** Postponing grazing or resting grazing land for a prescribed period.
- Depth, soil. Generally, the thickness of the soil over bedrock. Very deep soils are more than 60 inches deep over bedrock; deep soils, 40 to 60 inches; moderately deep soils, 20 to 40 inches; shallow soils, 10 to 20 inches; and very shallow soils, less than 10 inches.
- **Diversion (or diversion terrace).** A ridge of earth, generally a terrace, built to protect downslope areas by diverting runoff from its natural course.
- Divided-slope farming. A form of field stripcropping in which crops are grown in a systematic arrangement of two strips, or bands, across the slope to reduce the hazard of water erosion. One strip is in a close-growing crop that provides protection from erosion, and the other strip is in a crop that provides less protection from erosion. This practice is used where slopes are not long enough to permit a full stripcropping pattern to be used.
- **Drainage class** (natural). Refers to the frequency and duration of wet periods under conditions similar to those under which the soil formed. Alterations of the water regime by human activities, either

- through drainage or irrigation, are not a consideration unless they have significantly changed the morphology of the soil. Seven classes of natural soil drainage are recognized—excessively drained, somewhat excessively drained, well drained, moderately well drained, somewhat poorly drained, poorly drained, and very poorly drained. These classes are defined in the "Soil Survey Manual."
- **Drainage, surface.** Runoff, or surface flow of water, from an area.
- **Duff.** A generally firm organic layer on the surface of mineral soils. It consists of fallen plant material that is in the process of decomposition and includes everything from the litter on the surface to underlying pure humus.
- **Eluviation.** The movement of material in true solution or colloidal suspension from one place to another within the soil. Soil horizons that have lost material through eluviation are eluvial; those that have received material are illuvial.
- **Endosaturation.** A type of saturation of the soil in which all horizons between the upper boundary of saturation and a depth of 2 meters are saturated.
- **Eolian soil material.** Earthy parent material accumulated through wind action; commonly refers to sandy material in dunes or to loess in blankets on the surface.
- **Ephemeral stream.** A stream, or reach of a stream, that flows only in direct response to precipitation. It receives no long-continued supply from melting snow or other source, and its channel is above the water table at all times.
- **Episaturation.** A type of saturation indicating a perched water table in a soil in which saturated layers are underlain by one or more unsaturated layers within 2 meters of the surface.
- **Erosion.** The wearing away of the land surface by water, wind, ice, or other geologic agents and by such processes as gravitational creep. *Erosion* (geologic). Erosion caused by geologic processes acting over long geologic periods and resulting in the wearing away of mountains and the building up of such landscape features as flood plains and coastal plains. Synonym: natural erosion.
  - Erosion (accelerated). Erosion much more rapid than geologic erosion, mainly as a result of human or animal activities or of a catastrophe in nature, such as a fire, that exposes the surface.
- **Escarpment.** A relatively continuous and steep slope or cliff breaking the general continuity of more gently sloping land surfaces and resulting from erosion or faulting. Synonym: scarp.

- **Fertility, soil.** The quality that enables a soil to provide plant nutrients, in adequate amounts and in proper balance, for the growth of specified plants when light, moisture, temperature, tilth, and other growth factors are favorable.
- Field moisture capacity. The moisture content of a soil, expressed as a percentage of the ovendry weight, after the gravitational, or free, water has drained away; the field moisture content 2 or 3 days after a soaking rain; also called normal field capacity, normal moisture capacity, or capillary capacity.
- **Fill slope.** A sloping surface consisting of excavated soil material from a road cut. It commonly is on the downhill side of the road.
- Fine textured soil. Sandy clay, silty clay, or clay.

  Firebreak. An area cleared of flammable material to stop or help control creeping or running fires. It also serves as a line from which to work and to facilitate the movement of firefighters and equipment. Designated roads also serve as firebreaks.
- **First bottom.** The normal flood plain of a stream, subject to frequent or occasional flooding.
- Flaggy soil material. Material that has, by volume, 15 to 35 percent flagstones. Very flaggy soil material has 35 to 60 percent flagstones, and extremely flaggy soil material has more than 60 percent flagstones.
- **Flagstone.** A thin fragment of sandstone, limestone, slate, shale, or (rarely) schist 6 to 15 inches (15 to 38 centimeters) long.
- **Flood plain.** A nearly level alluvial plain that borders a stream and is subject to flooding unless protected artificially.
- **Fluvial.** Of or pertaining to rivers; produced by river action, as a fluvial plain.
- **Footslope.** The position that forms the inner, gently inclined surface at the base of a hillslope. In profile, footslopes are commonly concave. A footslope is a transition zone between upslope sites of erosion and transport (shoulders and backslopes) and downslope sites of deposition (toeslopes).
- **Forb.** Any herbaceous plant not a grass or a sedge. **Forest cover.** All trees and other woody plants (underbrush) covering the ground in a forest.
- **Forest type.** A stand of trees similar in composition and development because of given physical and biological factors by which it may be differentiated from other stands.
- **Fragipan.** A loamy, brittle subsurface horizon low in porosity and content of organic matter and low or moderate in clay but high in silt or very fine sand.

- A fragipan appears cemented and restricts roots. When dry, it is hard or very hard and has a higher bulk density than the horizon or horizons above. When moist, it tends to rupture suddenly under pressure rather than to deform slowly.
- **Genesis, soil.** The mode of origin of the soil. Refers especially to the processes or soil-forming factors responsible for the formation of the solum, or true soil, from the unconsolidated parent material.
- **Gleyed soil.** Soil that formed under poor drainage, resulting in the reduction of iron and other elements in the profile and in gray colors.
- **Grassed waterway.** A natural or constructed waterway, typically broad and shallow, seeded to grass as protection against erosion. Conducts surface water away from cropland.
- **Gravel.** Rounded or angular fragments of rock as much as 3 inches (2 millimeters to 7.6 centimeters) in diameter. An individual piece is a pebble.
- Gravelly soil material. Material that has 15 to 35 percent, by volume, rounded or angular rock fragments, not prominently flattened, as much as 3 inches (7.6 centimeters) in diameter.
- **Green manure crop** (agronomy). A soil-improving crop grown to be plowed under in an early stage of maturity or soon after maturity.
- **Ground water.** Water filling all the unblocked pores of the material below the water table.
- **Gully.** A miniature valley with steep sides cut by running water and through which water ordinarily runs only after rainfall. The distinction between a gully and a rill is one of depth. A gully generally is an obstacle to farm machinery and is too deep to be obliterated by ordinary tillage; a rill is of lesser depth and can be smoothed over by ordinary tillage.
- **Hard bedrock.** Bedrock that cannot be excavated except by blasting or by the use of special equipment that is not commonly used in construction.
- **Head slope.** A geomorphic component of hills consisting of a laterally concave area of a hillside, especially at the head of a drainageway. The overland waterflow is converging.
- High-residue crops. Such crops as small grain and corn used for grain. If properly managed, residue from these crops can be used to control erosion until the next crop in the rotation is established. These crops return large amounts of organic matter to the soil.
- **Hill.** A natural elevation of the land surface, rising as much as 1,000 feet above surrounding lowlands, commonly of limited summit area and having a

- well defined outline; hillsides generally have slopes of more than 15 percent. The distinction between a hill and a mountain is arbitrary and is dependent on local usage.
- Horizon, soil. A layer of soil, approximately parallel to the surface, having distinct characteristics produced by soil-forming processes. In the identification of soil horizons, an uppercase letter represents the major horizons. Numbers or lowercase letters that follow represent subdivisions of the major horizons. An explanation of the subdivisions is given in the "Soil Survey Manual." The major horizons of mineral soil are as follows:
  - *O horizon.*—An organic layer of fresh and decaying plant residue.
  - A horizon.—The mineral horizon at or near the surface in which an accumulation of humified organic matter is mixed with the mineral material. Also, a plowed surface horizon, most of which was originally part of a B horizon.
  - *E horizon.*—The mineral horizon in which the main feature is loss of silicate clay, iron, aluminum, or some combination of these.
  - B horizon.—The mineral horizon below an A horizon. The B horizon is in part a layer of transition from the overlying A to the underlying C horizon. The B horizon also has distinctive characteristics, such as (1) accumulation of clay, sesquioxides, humus, or a combination of these; (2) prismatic or blocky structure; (3) redder or browner colors than those in the A horizon; or (4) a combination of these.
  - C horizon.—The mineral horizon or layer, excluding indurated bedrock, that is little affected by soil-forming processes and does not have the properties typical of the overlying soil material. The material of a C horizon may be either like or unlike that in which the solum formed. If the material is known to differ from that in the solum, an Arabic numeral, commonly a 2, precedes the letter C.
  - *Cr horizon.*—Soft, consolidated bedrock beneath the soil.
  - *R layer.*—Consolidated bedrock beneath the soil. The bedrock commonly underlies a C horizon, but it can be directly below an A or a B horizon.
- Hydrologic soil groups. Refers to soils grouped according to their runoff potential. The soil properties that influence this potential are those that affect the minimum rate of water infiltration on a bare soil during periods after prolonged wetting when the soil is not frozen. These properties are depth to a seasonal high water table, the

- infiltration rate and permeability after prolonged wetting, and depth to a very slowly permeable layer. The slope and the kind of plant cover are not considered but are separate factors in predicting runoff.
- **Illuviation.** The movement of soil material from one horizon to another in the soil profile. Generally, material is removed from an upper horizon and deposited in a lower horizon.
- **Impervious soil.** A soil through which water, air, or roots penetrate slowly or not at all. No soil is absolutely impervious to air and water all the time.
- **Infiltration.** The downward entry of water into the immediate surface of soil or other material, as contrasted with percolation, which is movement of water through soil layers or material.
- Infiltration rate. The rate at which water penetrates the surface of the soil at any given instant, usually expressed in inches per hour. The rate can be limited by the infiltration capacity of the soil or the rate at which water is applied at the surface.
- **Interfluve.** An elevated area between two drainageways that sheds water to those drainageways.
- Intermittent stream. A stream, or reach of a stream, that flows for prolonged periods only when it receives ground-water discharge or long, continued contributions from melting snow or other surface and shallow subsurface sources.
- Iron depletions. Low-chroma zones having a low content of iron and manganese oxide because of chemical reduction and removal, but having a clay content similar to that of the adjacent matrix. A type of redoximorphic depletion.
- **Karst** (topography). The relief of an area underlain by limestone that dissolves in differing degrees, thus forming numerous depressions or small basins.
- **Knoll.** A small, low, rounded hill rising above adjacent landforms.
- **K**<sub>sat</sub>. Saturated hydraulic conductivity. (See Permeability.)
- Landslide. The rapid downhill movement of a mass of soil and loose rock, generally when wet or saturated. The speed and distance of movement, as well as the amount of soil and rock material, vary greatly.
- **Leaching.** The removal of soluble material from soil or other material by percolating water.
- Linear extensibility. Refers to the change in length of an unconfined clod as moisture content is decreased from a moist to a dry state. Linear extensibility is used to determine the shrink-swell potential of soils. It is an expression of the volume change between the water content of the clod at

- 1/3- or 1/10-bar tension (33kPa or 10kPa tension) and oven dryness. Volume change is influenced by the amount and type of clay minerals in the soil. The volume change is the percent change for the whole soil. If it is expressed as a fraction, the resulting value is COLE, coefficient of linear extensibility.
- **Liquid limit.** The moisture content at which the soil passes from a plastic to a liquid state.
- **Loam.** Soil material that is 7 to 27 percent clay particles, 28 to 50 percent silt particles, and less than 52 percent sand particles.
- **Loess.** Fine-grained material, dominantly of silt-sized particles, deposited by wind.
- Low-residue crops. Such crops as corn used for silage, peas, beans, and potatoes. Residue from these crops is not adequate to control erosion until the next crop in the rotation is established. These crops return little organic matter to the soil.
- **Low strength.** The soil is not strong enough to support loads.
- Masses. Concentrations of substances in the soil matrix that do not have a clearly defined boundary with the surrounding soil material and cannot be removed as a discrete unit. Common compounds making up masses are calcium carbonate, gypsum or other soluble salts, iron oxide, and manganese oxide. Masses consisting of iron oxide or manganese oxide generally are considered a type of redoximorphic concentration.
- **Mechanical treatment.** Use of mechanical equipment for seeding, brush management, and other management practices.
- **Medium textured soil.** Very fine sandy loam, loam, silt loam, or silt.
- **Minimum tillage.** Only the tillage essential to crop production and prevention of soil damage.
- **Miscellaneous area.** An area that has little or no natural soil and supports little or no vegetation.
- **Moderately coarse textured soil.** Coarse sandy loam, sandy loam, or fine sandy loam.
- **Moderately fine textured soil.** Clay loam, sandy clay loam, or silty clay loam.
- **Mollic epipedon.** A thick, dark, humus-rich surface horizon (or horizons) that has high base saturation and pedogenic soil structure. It may include the upper part of the subsoil.
- **Morphology, soil.** The physical makeup of the soil, including the texture, structure, porosity, consistence, color, and other physical, mineral, and biological properties of the various horizons, and the thickness and arrangement of those horizons in the soil profile.

- Mottling, soil. Irregular spots of different colors that vary in number and size. Descriptive terms are as follows: abundance—few, common, and many; size—fine, medium, and coarse; and contrast—faint, distinct, and prominent. The size measurements are of the diameter along the greatest dimension. Fine indicates less than 5 millimeters (about 0.2 inch); medium, from 5 to 15 millimeters (about 0.2 to 0.6 inch); and coarse, more than 15 millimeters (about 0.6 inch).
- **Mudstone.** Sedimentary rock formed by induration of silt and clay in approximately equal amounts.
- **Munsell notation.** A designation of color by degrees of three simple variables—hue, value, and chroma. For example, a notation of 10YR 6/4 is a color with hue of 10YR, value of 6, and chroma of 4.
- **Natric horizon.** A special kind of argillic horizon that contains enough exchangeable sodium to have an adverse effect on the physical condition of the subsoil.
- **Neutral soil.** A soil having a pH value of 6.6 to 7.3. (See Reaction, soil.)
- Nodules. Cemented bodies lacking visible internal structure. Calcium carbonate, iron oxide, and manganese oxide are common compounds making up nodules. If formed in place, nodules of iron oxide or manganese oxide are considered types of redoximorphic concentrations.
- **Nose slope.** A geomorphic component of hills consisting of the projecting end (laterally convex area) of a hillside. The overland waterflow is predominantly divergent.
- Nutrient, plant. Any element taken in by a plant essential to its growth. Plant nutrients are mainly nitrogen, phosphorus, potassium, calcium, magnesium, sulfur, iron, manganese, copper, boron, and zinc obtained from the soil and carbon, hydrogen, and oxygen obtained from the air and water
- **Organic matter.** Plant and animal residue in the soil in various stages of decomposition. The content of organic matter in the surface layer is described as follows:

Very low	less than 0.5 percent
Low	0.5 to 1.0 percent
Moderately low	1.0 to 2.0 percent
Moderate	2.0 to 4.0 percent
High	4.0 to 8.0 percent
Very high	more than 8.0 percent

**Parent material.** The unconsolidated organic and mineral material in which soil forms.

- **Ped.** An individual natural soil aggregate, such as a granule, a prism, or a block.
- **Pedon.** The smallest volume that can be called "a soil." A pedon is three dimensional and large enough to permit study of all horizons. Its area ranges from about 10 to 100 square feet (1 square meter to 10 square meters), depending on the variability of the soil.

Percolation. The movement of water through the soil.

Permeability. The quality of the soil that enables water or air to move downward through the profile. The rate at which a saturated soil transmits water is accepted as a measure of this quality. In soil physics, the rate is referred to as "saturated hydraulic conductivity," which is defined in the "Soil Survey Manual." In line with conventional usage in the engineering profession and with traditional usage in published soil surveys, this rate of flow continues to be expressed as "permeability." Terms describing permeability, measured in inches per hour, are as follows:

Extremely slow	0.0 to 0.01 inch
Very slow	0.01 to 0.06 inch
Slow	0.06 to 0.2 inch
Moderately slow	0.2 to 0.6 inch
Moderate	0.6 inch to 2.0 inches
Moderately rapid	2.0 to 6.0 inches
Rapid	6.0 to 20 inches
Very rapid	more than 20 inches

- **Phase, soil.** A subdivision of a soil series based on features that affect its use and management, such as slope, stoniness, and flooding.
- **pH value.** A numerical designation of acidity and alkalinity in soil. (See Reaction, soil.)
- **Plasticity index.** The numerical difference between the liquid limit and the plastic limit; the range of moisture content within which the soil remains plastic.
- **Plastic limit.** The moisture content at which a soil changes from semisolid to plastic.
- **Plowpan.** A compacted layer formed in the soil directly below the plowed layer.
- **Ponding.** Standing water on soils in closed depressions. Unless the soils are artificially drained, the water can be removed only by percolation or evapotranspiration.
- **Poorly graded.** Refers to a coarse-grained soil or soil material consisting mainly of particles of nearly the same size. Because there is little difference in size of the particles, density can be increased only slightly by compaction.
- Potential rooting depth (effective rooting depth).

- Depth to which roots could penetrate if the content of moisture in the soil were adequate. The soil has no properties restricting the penetration of roots to this depth.
- **Prescribed burning.** Deliberately burning an area for specific management purposes, under the appropriate conditions of weather and soil moisture and at the proper time of day.
- **Productivity, soil.** The capability of a soil for producing a specified plant or sequence of plants under specific management.
- **Profile, soil.** A vertical section of the soil extending through all its horizons and into the parent material.
- Proper grazing use. Grazing at an intensity that maintains enough cover to protect the soil and maintain or improve the quantity and quality of the desirable vegetation. This practice increases the vigor and reproduction capacity of the key plants and promotes the accumulation of litter and mulch necessary to conserve soil and water.
- Reaction, soil. A measure of acidity or alkalinity of a soil, expressed in pH values. A soil that tests to pH 7.0 is described as precisely neutral in reaction because it is neither acid nor alkaline. The degrees of acidity or alkalinity, expressed as pH values, are:

Ultra acid	less than 3.5
Extremely acid	3.5 to 4.4
Very strongly acid	4.5 to 5.0
Strongly acid	5.1 to 5.5
Moderately acid	5.6 to 6.0
Slightly acid	6.1 to 6.5
Neutral	6.6 to 7.3
Slightly alkaline	7.4 to 7.8
Moderately alkaline	7.9 to 8.4
Strongly alkaline	8.5 to 9.0
Very strongly alkaline	9.1 and higher

# Redoximorphic concentrations. Nodules,

concretions, soft masses, pore linings, and other features resulting from the accumulation of iron or manganese oxide. An indication of chemical reduction and oxidation resulting from saturation.

- **Redoximorphic depletions.** Low-chroma zones from which iron and manganese oxide or a combination of iron and manganese oxide and clay has been removed. These zones are indications of the chemical reduction of iron resulting from saturation.
- Redoximorphic features. Redoximorphic concentrations, redoximorphic depletions, reduced matrices, a positive reaction to alpha,alpha-

dipyridyl, and other features indicating the chemical reduction and oxidation of iron and manganese compounds resulting from saturation.

- Reduced matrix. A soil matrix that has low chroma in situ because of chemically reduced iron (Fe II). The chemical reduction results from nearly continuous wetness. The matrix undergoes a change in hue or chroma within 30 minutes after exposure to air as the iron is oxidized (Fe III). A type of redoximorphic feature.
- **Relief.** The elevations or inequalities of a land surface, considered collectively.
- Residuum (residual soil material). Unconsolidated, weathered or partly weathered mineral material that accumulated as consolidated rock disintegrated in place.
- **Rill.** A steep-sided channel resulting from accelerated erosion. A rill generally is a few inches deep and not wide enough to be an obstacle to farm machinery.
- **Road cut.** A sloping surface produced by mechanical means during road construction. It is commonly on the uphill side of the road.
- **Rock fragments.** Rock or mineral fragments having a diameter of 2 millimeters or more; for example, pebbles, cobbles, stones, and boulders.
- **Root zone.** The part of the soil that can be penetrated by plant roots.
- Runoff. The precipitation discharged into stream channels from an area. The water that flows off the surface of the land without sinking into the soil is called surface runoff. Water that enters the soil before reaching surface streams is called groundwater runoff or seepage flow from ground water.
- **Sand.** As a soil separate, individual rock or mineral fragments ranging from 0.05 millimeter to 2.0 millimeters in diameter. Most sand grains consist of quartz. As a soil textural class, a soil that is 85 percent or more sand and not more than 10 percent clay.
- **Sandstone.** Sedimentary rock containing dominantly sand-sized particles.
- **Saprolite.** Unconsolidated residual material underlying the soil and grading to hard bedrock below.
- **Saturation.** Wetness characterized by zero or positive pressure of the soil water. Under conditions of saturation, the water will flow from the soil matrix into an unlined auger hole.
- **Scarification.** The act of abrading, scratching, loosening, crushing, or modifying the surface to increase water absorption or to provide a more tillable soil.

**Second bottom.** The first terrace above the normal flood plain (or first bottom) of a river.

- Sedimentary rock. Rock made up of particles deposited from suspension in water. The chief kinds of sedimentary rock are conglomerate, formed from gravel; sandstone, formed from sand; shale, formed from clay; and limestone, formed from soft masses of calcium carbonate. There are many intermediate types. Some wind-deposited sand is consolidated into sandstone.
- **Series, soil.** A group of soils that have profiles that are almost alike, except for differences in texture of the surface layer. All the soils of a series have horizons that are similar in composition, thickness, and arrangement.
- **Shale.** Sedimentary rock formed by the hardening of a clay deposit.
- **Sheet erosion.** The removal of a fairly uniform layer of soil material from the land surface by the action of rainfall and surface runoff.
- **Shoulder.** The position that forms the uppermost inclined surface near the top of a hillslope. It is a transition from backslope to summit. The surface is dominantly convex in profile and erosional in origin.
- **Side slope.** A geomorphic component of hills consisting of a laterally planar area of a hillside. The overland waterflow is predominantly parallel.
- Silt. As a soil separate, individual mineral particles that range in diameter from the upper limit of clay (0.002 millimeter) to the lower limit of very fine sand (0.05 millimeter). As a soil textural class, soil that is 80 percent or more silt and less than 12 percent clay.
- **Siltstone.** Sedimentary rock made up of dominantly silt-sized particles.
- Similar soils. Soils that share limits of diagnostic criteria, behave and perform in a similar manner, and have similar conservation needs or management requirements for the major land uses in the survey area.
- **Sinkhole.** A depression in the landscape where limestone has been dissolved.
- **Site index.** A designation of the quality of a forest site based on the height of the dominant stand at an arbitrarily chosen age. For example, if the average height attained by dominant and codominant trees in a fully stocked stand at the age of 50 years is 75 feet, the site index is 75.
- **Slickensides.** Polished and grooved surfaces produced by one mass sliding past another. In soils, slickensides may occur at the bases of slip surfaces on the steeper slopes; on faces of

- blocks, prisms, and columns; and in swelling clayey soils, where there is marked change in moisture content.
- Slope. The inclination of the land surface from the horizontal. Percentage of slope is the vertical distance divided by horizontal distance, then multiplied by 100. Thus, a slope of 20 percent is a drop of 20 feet in 100 feet of horizontal distance. In this survey, classes for simple slopes are as follows:

Level	0 to 1 percent
Nearly level	0 to 3 percent
Gently sloping	2 to 6 percent
Strongly sloping	6 to 12 percent
Moderately steep	12 to 20 percent
Steep	20 to 60 percent
Very steep	45 percent and higher

# Classes for complex slopes are as follows:

Level	0 to 1 percent
Nearly level	0 to 3 percent
Undulating	2 to 6 percent
Rolling	6 to 12 percent
Hilly	12 to 20 percent
Steep	20 to 60 percent
Very steep	45 percent and higher

- **Soft bedrock.** Bedrock that can be excavated with trenching machines, backhoes, small rippers, and other equipment commonly used in construction.
- Soil. A natural, three-dimensional body at the earth's surface. It is capable of supporting plants and has properties resulting from the integrated effect of climate and living matter acting on earthy parent material, as conditioned by relief over periods of time.
- **Soil separates.** Mineral particles less than 2 millimeters in equivalent diameter and ranging between specified size limits. The names and sizes, in millimeters, of separates recognized in the United States are as follows:

Very coarse sand	2.0 to 1.0
Coarse sand	1.0 to 0.5
Medium sand	0.5 to 0.25
Fine sand	0.25 to 0.10
Very fine sand	0.10 to 0.05
Silt	0.05 to 0.002
Clay	less than 0.002

**Solum.** The upper part of a soil profile, above the C horizon, in which the processes of soil formation are active. The solum in soil consists of the A, E, and B horizons. Generally, the characteristics of the material in these horizons are unlike those of

- the material below the solum. The living roots and plant and animal activities are largely confined to the solum.
- Stone line. A concentration of coarse fragments in a soil. Generally, it is indicative of an old weathered surface. In a cross section, the line may be one fragment or more thick. It generally overlies material that weathered in place and is overlain by recent sediment of variable thickness.
- Stones. Rock fragments 10 to 24 inches (25 to 60 centimeters) in diameter if rounded or 15 to 24 inches (38 to 60 centimeters) in length if flat.
- **Stony.** Refers to a soil containing stones in numbers that interfere with or prevent tillage.
- **Stripcropping.** Growing crops in a systematic arrangement of strips or bands that provide vegetative barriers to wind erosion and water erosion.
- **Structure, soil.** The arrangement of primary soil particles into compound particles or aggregates. The principal forms of soil structure are—platy (laminated), prismatic (vertical axis of aggregates longer than horizontal), columnar (prisms with rounded tops), blocky (angular or subangular), and granular. Structureless soils are either single grained (each grain by itself, as in dune sand) or massive (the particles adhering without any regular cleavage, as in many hardpans).
- Stubble mulch. Stubble or other crop residue left on the soil or partly worked into the soil. It protects the soil from wind erosion and water erosion after harvest, during preparation of a seedbed for the next crop, and during the early growing period of the new crop.
- Subsoil. Technically, the B horizon; roughly, the part of the solum below plow depth.
- Subsoiling. Tilling a soil below normal plow depth, ordinarily to shatter a hardpan or claypan.
- **Substratum.** The part of the soil below the solum. Subsurface layer. Any surface soil horizon (A, E, AB,
- or EB) below the surface layer.
- Surface layer. The soil ordinarily moved in tillage, or its equivalent in uncultivated soil, ranging in depth from 4 to 10 inches (10 to 25 centimeters). Frequently designated as the "plow layer," or the "Ap horizon."
- Surface soil. The A, E, AB, and EB horizons, considered collectively. It includes all subdivisions of these horizons.
- **Talus.** Fragments of rock and other soil material accumulated by gravity at the foot of cliffs or steep
- Terrace. An embankment, or ridge, constructed across sloping soils on the contour or at a slight

- angle to the contour. The terrace intercepts surface runoff so that water soaks into the soil or flows slowly to a prepared outlet. A terrace in a field generally is built so that the field can be farmed. A terrace intended mainly for drainage has a deep channel that is maintained in permanent sod.
- **Terrace** (geologic). An old alluvial plain, ordinarily flat or undulating, bordering a river, a lake, or the sea.
- **Texture, soil.** The relative proportions of sand, silt, and clay particles in a mass of soil. The basic textural classes, in order of increasing proportion of fine particles, are sand, loamy sand, sandy loam, loam, silt loam, silt, sandy clay loam, clay loam, silty clay loam, sandy clay, silty clay, and clay. The sand, loamy sand, and sandy loam classes may be further divided by specifying "coarse," "fine," or "very fine."
- **Tilth, soil.** The physical condition of the soil as related to tillage, seedbed preparation, seedling emergence, and root penetration.
- **Toeslope.** The position that forms the gently inclined surface at the base of a hillslope. Toeslopes in profile are commonly gentle and linear and are constructional surfaces forming the lower part of a hillslope continuum that grades to valley or closed-depression floors.
- **Topsoil.** The upper part of the soil, which is the most favorable material for plant growth. It is ordinarily rich in organic matter and is used to topdress roadbanks, lawns, and land affected by mining.
- **Trace elements.** Chemical elements, for example, zinc, cobalt, manganese, copper, and iron, in soils in extremely small amounts. They are essential to plant growth.

- **Upland.** Land at a higher elevation, in general, than the alluvial plain or stream terrace; land above the lowlands along streams.
- Valley fill. In glaciated regions, material deposited in stream valleys by glacial meltwater. In nonglaciated regions, alluvium deposited by heavily loaded streams.
- **Variegation.** Refers to patterns of contrasting colors assumed to be inherited from the parent material rather than to be the result of poor drainage.
- Water bars. Smooth, shallow ditches or depressional areas that are excavated at an angle across a sloping road. They are used to reduce the downward velocity of water and divert it off and away from the road surface. Water bars can easily be driven over if constructed properly.
- **Weathering.** All physical and chemical changes produced in rocks or other deposits at or near the earth's surface by atmospheric agents. These changes result in disintegration and decomposition of the material.
- **Well graded.** Refers to soil material consisting of coarse-grained particles that are well distributed over a wide range in size or diameter. Such soil normally can be easily increased in density and bearing properties by compaction. Contrasts with poorly graded soil.
- Wilting point (or permanent wilting point). The moisture content of soil, on an ovendry basis, at which a plant (specifically a sunflower) wilts so much that it does not recover when placed in a humid, dark chamber.
- **Windthrow.** The uprooting and tipping over of trees by the wind.

# **Tables**

Table 1.—Temperature and Precipitation

(Recorded in the period 1961-90 at Bowling Green, Kentucky)

	Temperature							Precipitation				
	2 years in							s in 10		Aver-		
				10 will	have	Average		will 1	nave	Average	age	
Month		Average	Average	Maximum	Minimum	number of	Average			number of		
	daily	_			temperature	, -	ļ	Less		days with		
	maximum	minimum		higher	lower	degree	ļ	than	than	0.10 inch		
				than	than	days*				or more		
	<u>°</u> F	° <sub>F</sub>	°F	<u>°F</u>	<u>°</u> F	<u>Units</u>	<u>In</u>	<u>In</u>	I <u>In</u>	 	<u>In</u>	
January	42.1	23.6	32.9	   69 	-8	   62 	3.83	1.85	5.54	   6 	5.2	
February-	47.1	27.1	37.1	   74 	0	   92 	4.13	2.20	   5.84 	   6 	3.9	
March	58.2	36.6	   47.4 	82	15	   274 	5.10	2.93	7.04	   8 	1.3	
April	   68.6	45.4	57.0	88	26	512	4.32	2.44	5.99	7	0.1	
May	77.3	54.3	65.8	92	35	800 	4.94	2.84	6.81	   8 	0.0	
June	85.5	62.8	74.1	97	47	1,024	4.17	2.16	5.92	   6 	0.0	
July	   88.6 	67.1	   77.9 	101	52	1,174	4.74	2.69	6.57	   6 	0.0	
August	87.2	65.4	76.3	99	51	1,125	3.52	1.87	4.96	5   5	0.0	
September	81.0	58.4	69.7	96	39	890	3.72	1.68	5.47	5   5	0.0	
October	70.2	45.4	57.8	87	27	552	3.02	1.30	4.49	5 	0.0	
November-	57.6	37.3	47.5	80	17	260	4.43	2.58	6.08	7	0.4	
December-	47.0	28.4	37.7	71	1	104 	5.03	2.62	7.13	7 	1.8 	
Yearly:	 	 	   			   	   	   	   	   	   	
Average-	67.5	46.0	   56.8 									
Extreme-	   107	-21		101	-10	ļ				 		
Total			 			   6,868 	   50.95 	  43.81 	  57.84 	   76 	12.8	

<sup>\*</sup> A growing degree day is a unit of heat available for plant growth. It can be calculated by adding the maximum and minimum daily temperatures, dividing the sum by 2, and subtracting the temperature below which growth is minimal for the principal crops in the area (40 degrees F).

Table 2.—Freeze Dates in Spring and Fall
(Recorded in the period 1961-90 at Bowling Green,
Kentucky)

	 		Temper	perature				
Probability	!	o <sub>F</sub> .ower	!	o <sub>F</sub>	   32 <sup>O</sup> F   or lower			
Last freezing temperature in spring:	     		     		     			
1 year in 10 later than	    Apr.	6	    Apr.	11	    Apr.	25		
2 years in 10 later than	    Mar.	30	    Apr.	7	    Apr.	20		
5 years in 10 later than	    Mar.	17	    Mar.	29	    Apr.	10		
First freezing temperature in fall:	     		     		     			
1 year in 10 earlier than	    Oct.	30	    Oct.	21	    Oct.	7		
2 years in 10 earlier than	    Nov.	4	    Oct.	26	    Oct.	12		
5 years in 10 earlier than	    Nov. 	16	    Nov.	5	    Oct. 	22		

Table 3.—Growing Season

(Recorded in the period 1961-90 at Bowling Green,
Kentucky)

Daily minimum temperature during growing season							
Probability	Higher than 24 <sup>O</sup> F	Higher than 28 <sup>O</sup> F	Higher than 32 <sup>O</sup> F				
	Days	Days	Days				
9 years in 10	218	   201	177				
8 years in 10	227	   208 	183				
5 years in 10	243	   220	194				
2 years in 10	259	232	206				
1 year in 10	267	   238 	211				

Table 4.—Acreage and Proportionate Extent of the Soils

Map symbol	Soil name	Acres	Percent 
BaB	  Baxter gravelly silt loam, 2 to 6 percent slopes	2,525	0.7
BaC	Baxter gravelly silt loam, 6 to 12 percent slopes	39,522	11.3
BaD	Baxter gravelly silt loam, 12 to 20 percent slopes	34,401	9.8
BaE	Baxter gravelly silt loam, 20 to 30 percent slopes	4,269	1.2
BbC3	Baxter gravelly silty clay loam, 6 to 12 percent slopes, severely eroded-	2,122	0.6
BbD3	Baxter gravelly silty clay loam, 12 to 20 percent slopes, severely eroded	725	0.2
BrB	Baxter-Urban land complex, 2 to 6 percent slopes	291	j *
BrC	Baxter-Urban land complex, 6 to 12 percent slopes	762	0.2
BrD	Baxter-Urban land complex, 12 to 20 percent slopes	372	0.1
CaB	Caneyville silt loam, 2 to 6 percent slopes	280	*
CaC	Caneyville silt loam, 6 to 12 percent slopes	1,177	0.3
CaC3	Caneyville silty clay, 6 to 12 percent slopes, severely eroded	396	0.1
CnD	Caneyville-Rock outcrop complex, 6 to 20 percent slopes	10,605	3.0
CnF	Caneyville-Rock outcrop complex, 20 to 60 percent slopes	19,601	5.6
CoD	Caneyville-Urban land-Rock outcrop complex, 6 to 20 percent slopes	219	*
CoE	Caneyville-Urban land-Rock outcrop complex, 20 to 30 percent slopes	118	!
CrB CrC	Crider silt loam, 2 to 6 percent slopes	50,827	14.5
CuB	Crider silt loam, 6 to 12 percent slopes   Crider-Urban land complex, 2 to 6 percent slopes	8,476 9,053	2.4
CuC	Crider-Urban land complex, 2 to 6 percent slopes	1,055	0.3
DAM	Dam, large	70	*
Du	Dunning silty clay loam, ponded	657	0.2
EkB	Elk silt loam, 2 to 6 percent slopes, rarely flooded	1,063	0.3
EpB	Epley silt loam, 2 to 6 percent slopes	335	*
FeB	Fredonia-Vertrees complex, 2 to 6 percent slopes, rocky	286	*
FeC	Fredonia-Vertrees complex, 6 to 12 percent slopes, very rocky	25,248	7.2
FnB	Fredonia-Vertrees-Urban land complex, 2 to 6 percent slopes, rocky	2,712	0.8
FnC	Fredonia-Vertrees-Urban land complex, 6 to 12 percent slopes, very rocky-	607	0.2
FnC2	Fredonia-Vertrees-Urban land complex, 6 to 12 percent slopes, eroded,		
	rocky	2,140	0.6
FrC	Frondorf silt loam, 6 to 12 percent slopes	7,148	2.0
FrD	Frondorf silt loam, 12 to 20 percent slopes	8,666	2.5
Gr	Grigsby sandy loam, frequently flooded	609	0.2
HaB -	Hammack silt loam, 2 to 6 percent slopes	4,616	1.3
La	Lawrence silt loam, rarely flooded	4,873	1.4
Ld	Lindside silt loam, frequently flooded	1,008	0.3
Me	Melvin silt loam, frequently flooded	1,143	0.3
Ne Nf	Newark silt loam, proded	3,904 332	*
NhA	Nicholson silt loam, 0 to 2 percent slopes	649	0.2
NhB	Nicholson silt loam, 2 to 6 percent slopes	8,254	2.4
NhC	Nicholson silt loam, 6 to 12 percent slopes	172	*
No	Nolin silt loam, frequently flooded	13,685	3.9
Np	Nolin silt loam, ponded	1,675	0.5
OtA	Otwood silt loam, 0 to 2 percent slopes, rarely flooded	48	*
OtB	Otwood silt loam, 2 to 6 percent slopes, rarely flooded	256	j *
PbA	Pembroke silt loam, 0 to 2 percent slopes	4,696	1.3
PeA	Pembroke-Urban land complex, 0 to 2 percent slopes	107	*
Pm	Pits, loamy, frequently flooded	22	*
Pq	Pits, quarry	361	0.1
RaF	Ramsey-Frondorf complex, 20 to 60 percent slopes	21,786	6.2
Ro	Robertsville silt loam, ponded	1,246	0.4
RxF	Rock outcrop-Caneyville complex, 20 to 60 percent slopes	6,382	1.8
SaA	Sadler silt loam, 0 to 2 percent slopes	475	0.1
SaB	Sadler silt loam, 2 to 6 percent slopes	2,611	0.7
UaC	Udorthents, 0 to 20 percent slopes	165	*
UaD	Udorthents, refuse substratum, 0 to 25 percent slopes	132	*
Ub	Urban land-Udorthents complex, 0 to 12 percent slopes	1,991	0.6
Uc	Urban land-Udorthents complex, clayey substratum, hard bedrock 0-5 feet,   0 to 12 percent slopes	705	
	A CO IN DELCHIC STONES	785	0.2

See footnote at end of table.

Table 4.—Acreage and Proportionate Extent of the Soils—Continued

Map symbol	   Soil name 	Acres	  Percent 
Ud	Urban land-Udorthents complex, clayey substratum, hard bedrock >5 feet, 0 to 12 percent slopes	2,017	0.6
Us	Urban land-Udorthents complex, smoothed, 0 to 15 percent slopes	2,412	0.7
VrC3	Vertrees silty clay loam, 6 to 12 percent slopes, severely eroded	1,893	0.5
VtC3	Vertrees-Urban land complex, 6 to 12 percent slopes, severely eroded	193	*
W	Water	3,650	1.0
WeB	Wellston silt loam, 2 to 6 percent slopes	624	0.2
WeC2	Wellston silt loam, 6 to 12 percent slopes, eroded	1,915	0.5
ZaB	Zanesville silt loam, 2 to 6 percent slopes	14,380	4.1
ZaC2	Zanesville silt loam, 6 to 12 percent slopes, eroded	5,579	1.6
ZuB	Zanesville-Urban land complex, 2 to 6 percent slopes	122	*
	   Total  	350,496	100.0

<sup>\*</sup> Less than 0.1 percent.

Table 5.-Land Capability and Yields per Acre of Crops

(Yields are those that can be expected under a high level of management. They are for nonirrigated areas. Absence of a yield indicates that the soil is not suited to the crop or the crop generally is not grown on the soil. Map units that have Urban land as a major component were not rated and are not included in this table)

Map symbol and soil name	Land capability	Corn	   Soybeans 	Tobacco	   Wheat 
		Bu	<u>Bu</u>	Lbs	<u>Bu</u>
BaB Baxter	2e	100.00	   35.00 	3,000.00	   45.00 
BaC Baxter	3e	90.00	33.00	2,600.00	40.00
BaD Baxter	4e	75.00	25.00	1,600.00	30.00
BaE Baxter	6e				
BbC3 Baxter	4e	75.00	23.00	1,500.00	28.00
BbD3 Baxter	6e				
CaB Caneyville	3e	85.00	30.00	2,500.00	
CaC Caneyville	4e	70.00	25.00	2,200.00	
CaC3 Caneyville	бе				
CnD Caneyville-Rock outcrop	6s				   
CnF Caneyville-Rock outcrop	7s				
CrB Crider	2e	125.00	50.00	3,400.00	50.00
CrC Crider	3e	110.00	40.00	2,900.00	45.00
DAM. Dam, large					
Du Dunning	4w				
EkB Elk	2e	125.00	50.00	3,200.00	   45.00 
EpB  Epley	2e	95.00	   35.00 		

Table 5.-Land Capability and Yields per Acre of Crops-Continued

Map symbol and soil name	Land capability	   Corn 	   Soybeans 	Tobacco	   Wheat 
		Bu	Bu	Lbs	<u>Bu</u>
FeB Fredonia-Vertrees	3e	   	   28.00 	   1500.00 	   
FeCFredonia-Vertrees	<b>4</b> e				   
FrC Frondorf	3e	   85.00 	30.00		   35.00 
FrD Frondorf	4e	   80.00 	   25.00 		   30.00 
Gr Grigsby	2w		   35.00 	2,900.00	   
HaB Hammack	2e	   120.00 	   40.00 	3,100.00	   50.00 
La Lawrence	3w	   85.00 	   40.00 	1,700.00	   
Ld Lindside	3w		   45.00 	2,800.00	   
Me Melvin	4w				   
Ne Newark	3w		35.00		   
Nf Newark	4w		30.00		   
NhA Nicholson	2w	125.00	45.00	2,500.00	   40.00 
NhB Nicholson	2e	120.00	45.00	3,000.00	   40.00 
NhC Nicholson	3e	110.00	30.00	2,200.00	35.00
No Nolin	2w		45.00	3,300.00	   
Np Nolin	3w	   	35.00		   
OtAOtwood	2w	   110.00 	   40.00 	2,600.00	   45.00 
OtBOtwood	2e	105.00	   40.00 	2,550.00	   40.00 
PbA Pembroke	1	   130.00 	   50.00 	3,400.00	   50.00 
	•			•	•

Table 5.—Land Capability and Yields per Acre of Crops—Continued

Map symbol   Land and soil name   capability		Corn	   Soybeans 	   Tobacco 	   Wheat 
		Bu	<u>Bu</u>	Lbs	Bu
Pm. Pits, loamy, frequently flooded					
Pq. Pits, quarry			   		   
RaF Ramsey-Frondorf	7s		 		 
Ro Robertsville	4w				 
RxF Rock outcrop-Caneyville	7s				 
SaA Sadler	2w	110.00	   45.00 	2,600.00	   40.00 
SaB Sadler	2e	105.00	   40.00 	2,550.00	   40.00 
VrC3 Vertrees	4e	75.00	   25.00 	1,700.00	   30.00 
W. Water			 		   
WeB Wellston	2e	125.00	   45.00 	3,000.00	   45.00 
WeC2 Wellston	3e	115.00	   40.00 	   2,800.00 	   40.00 
ZaB Zanesville	2e	110.00	   40.00 	   2,800.00 	   40.00 
ZaC2 Zanesville	3e	100.00	   35.00 	   2,550.00 	   35.00 

Table 6.-Land Capability and Yields per Acre of Pasture and Hay

(Yields are those that can be expected under a high level of management. They are for nonirrigated areas. Absence of a yield indicates that the soil is not suited to pasture or hay crops or those crops generally are not grown on the soil. Map units that have Urban land as a major component were not rated and are not included in this table)

				<u> </u>	 	
Map symbol and soil name	Land capability	Alfalfa hay   	Corn silage   	Grass-legume   hay	ladino	
		Tons	Tons	Tons	AUM*	
BaB Baxter	2e	   3.50 	   18.00 	   4.50 	   9.00 	
BaCBaxter	3e	3.00	17.00	   4.50 	   9.00 	
BaDBaxter	4e	2.50	15.00	3.50	7.00	
BaE Baxter	6e		 		4.00 	
BbC3 Baxter	4e	2.50	15.00	3.50	7.00	
BbD3Baxter	6e	   	 	3.00	6.00	
CaB Caneyville	3e	   	   16.00 	4.00	8.00	
CaC Caneyville	4e	   	   15.00 	3.50	   7.00 	
CaC3Caneyville	6e	   	 	 	   5.50 	
CnDCaneyville-Rock outcrop	6s	 	 	 	   	
CnFCaneyville-Rock outcrop	7s				   	
CrB Crider	2e	5.00	23.00	5.00	   10.00 	
CrCCrider	3e	4.50	18.00	4.50	9.00	
DAM. Dam, large		 	 	 		
Du Dunning	4w	   	 	4.00	   6.00 	
EkB Elk	2e	   5.00 	23.00	   4.50 	   9.00 	
EpB Epley	2e	   	   16.00 	   4.00 	   7.00 	

See footnote at end of table.

Table 6.-Land Capability and Yields per Acre of Pasture and Hay-Continued

Map symbol and soil name	   Land   capability 	  Alfalfa hay   	  Corn silage   	  Grass-legume   hay 	  Tall fescue-   ladino 
		Tons	Tons	Tons	AUM*
FeB Fredonia-Vertrees	   3e 	   	   	   3.80 	   7.50 
FeCFredonia-Vertrees	   4e 	   	   	   3.50 	   7.00 
FrC Frondorf	   3e 	   	   16.00 	3.00	   6.00 
FrD Frondorf	   4e 	   	   15.00 	   2.50 	   5.00 
Gr Grigsby	2w	   	   17.00 	3.00	   6.00 
HaB Hammack	   2e 	3.00	   23.00 	   5.00 	   10.00 
La Lawrence	3w	   	   16.00 	3.00	   5.50 
Ld Lindside	3w	   	   23.00 	   3.50 	   7.00 
Me Melvin	   4w 	   	 	   3.50 	   5.50 
Ne Newark	3w	   	 	   4.50 	   8.50 
Nf Newark	4w	   	 	   3.50 	   7.50 
NhA Nicholson	2w	   	   23.00 	   3.50 	   7.00 
NhB Nicholson	   2e 	   	   24.00 	   3.50 	   6.50 
NhC Nicholson	   3e 	   	   20.00 	3.00	   6.00 
No Nolin	2w	   	   24.00 	   4.50 	   9.00 
Np Nolin	   3w 	   	   	   4.00 	   8.00 
OtAOtwood	   2w 	   	   18.00 	   3.80 	   7.50 
OtBOtwood	2e	   	   19.00 	   3.50 	   7.00 
PbA Pembroke	   1 	   5.00 	   24.00 	   5.00 	   10.00 

See footnote at end of table.

Table 6.—Land Capability and Yields per Acre of Pasture and Hay—Continued

		I	1	I	I	
Map symbol and soil name	Land capability	Alfalfa hay	Corn silage	  Grass-legume   hay	  Tall fescue   ladino 	
		Tons	Tons	Tons	AUM*	
Pm. Pits, loamy, frequently flooded		 	 	 		
Pq. Pits, quarry		   	   	 	 	
RaF Ramsey-Frondorf	7s	   	   	 		
Ro Robertsville	4w	   	   	3.00	   5.50 	
RxF Rock outcrop-Caneyville	7s	   	   	   	 	
SaA Sadler	2w	   	   18.00 	   3.80 	   7.50 	
SaB Sadler	2e	   	   19.00 	   3.50 	   7.00 	
VrC3 Vertrees	4e	   2.50 	   	   3.00 	   6.00 	
W. Water		 	   	   		
WeB Wellston	2e	   4.00 	   23.00 	   4.00 	   7.50 	
WeC2 Wellston	3e	   3.50 	   22.00 	   4.00 	   7.00 	
ZaB Zanesville	2e	   	   20.00 	   4.00 	   7.50 	
ZaC2 Zanesville	3e	   	   18.00 	   3.50 	   7.00 	

<sup>\*</sup> Animal unit month: The amount of forage or feed required to feed one animal unit (one cow, one horse, one sheep, or five goats) for 30 days.

#### Table 7.—Prime Farmland

(Only the soils considered prime farmland are listed. Urban or built-up areas of the soils listed are not considered prime farmland. If a soil is prime farmland only under certain conditions, the conditions are specified in parentheses after the soil name)

Map symbol	Soil name 
BaB	  Baxter gravelly silt loam, 2 to 6 percent slopes
CaB	Caneyville silt loam, 2 to 6 percent slopes
CrB	Crider silt loam, 2 to 6 percent slopes
EkB	Elk silt loam, 2 to 6 percent slopes, rarely flooded
ЕрВ	Epley silt loam, 2 to 6 percent slopes
Gr	Grigsby sandy loam, frequently flooded (if protected from flooding or not frequently flooded during the growing season)
HaB	Hammack silt loam, 2 to 6 percent slopes
La	Lawrence silt loam, rarely flooded (if drained)
Ld	Lindside silt loam, frequently flooded (if protected from flooding or not frequently flooded   during the growing season)
Ne	Newark silt loam, frequently flooded (if drained and either protected from flooding or not frequently flooded during the growing season)
NhA	Nicholson silt loam, 0 to 2 percent slopes
NhB	Nicholson silt loam, 2 to 6 percent slopes
No	Nolin silt loam, frequently flooded (if protected from flooding or not frequently flooded   during the growing season)
OtA	Otwood silt loam, 0 to 2 percent slopes, rarely flooded
OtB	Otwood silt loam, 2 to 6 percent slopes, rarely flooded
PbA	Pembroke silt loam, 0 to 2 percent slopes
SaA	Sadler silt loam, 0 to 2 percent slopes
SaB	Sadler silt loam, 2 to 6 percent slopes
WeB	Wellston silt loam, 2 to 6 percent slopes

Table 8.—Forest Productivity

(Map units that have Urban land as a major component were not rated and are not included in this table)

	Potential produ	uctivit	су	.[	
Map symbol and		Site	Volume	Trees to manage	
soil name	Common trees	index	of wood		
			fiber		
	l		cu ft/ac		
		ļ			
BaB, BaC, BaD, BaE, BbC3, BbD3:	į	 			
Baxter	black oak	80	57	black oak, northerr	
	northern red oak	85	62	red oak, white	
	white oak   yellow-poplar	75   92	57   90	oak, yellow-poplar 	
	 	72			
CaB, CaC, CaC3:	İ	İ			
Caneyville	black oak	75	62	black oak, eastern	
	eastern redcedar	45	43	redcedar, northerr	
	northern red oak	70	52	red oak, scarlet	
	scarlet oak	70	52	oak, white oak	
	white oak	70	52		
Can Care				İ	
CnD, CnF: Caneyville	  black oak	l I 75	l   62	  black oak, eastern	
34.107 1 = = 3	eastern redcedar		43	redcedar, northern	
	northern red oak	70	52	red oak, scarlet	
	scarlet oak	70	52	oak, white oak	
	white oak	70	52	,,	
Dogle out anon			 		
Rock outcrop.		! !	<u> </u>		
CrB, CrC:	İ	i			
Crider	black oak	85	62	black oak, black	
	black walnut	85	62	walnut, northern	
	northern red oak	85	62	red oak, white	
	white ash	85	62	ash, white oak,	
	white oak	75	57	yellow-poplar	
	yellow-poplar	95	98		
DAM:	 		 		
Dam, large		i	! 		
	İ	j			
Du:					
Dunning	American sycamore	:	62	American sycamore,	
	green ash	60   75	52   57	green ash, pin oak, sweetgum,	
	sweetgum	75   85	57   70	willow oak	
	willow oak	65   75	70   52	WIIIOW Oak	
	WIIIOW Oak	/3 	52	] 	
EkB:	İ	İ			
Elk	black walnut	85	62	black walnut,	
	cherrybark oak		62	cherrybark oak,	
	white ash	80	62	white ash, white	
	white oak	85	62	oak, yellow-poplar	
	yellow-poplar	100	107		
EnR.	 		 	[ ]	
Epley	  black oak	l I 70	   57	  black oak,	
	cherrybark oak	70   70	57   57	cherrybark oak,	
		70   75	57   52	green ash,	
	largen sch				
	green ash	!	!		
	green ash  sweetgum  white oak	73   80   70	86   57	sweetgum, white oak	

Table 8.-Forest Productivity-Continued

	Potential produ	ıctivi	tv	l
Map symbol and	F_00		Volume	Trees to manage
soil name	Common trees	!	of wood	11002 00
			fiber	İ
			cu ft/ac	
		i		İ
FeB, FeC:		İ	İ	
Fredonia	eastern redcedar	45	40	black oak, eastern
	black oak	80	57	redcedar, northern
	northern red oak	70	52	red oak, scarlet
	scarlet oak	70	52	oak
		ļ		
Vertrees	eastern redcedar	!	40	black oak, eastern
	black oak	80	57	redcedar, northern
	northern red oak	70	52	red oak, scarlet
	scarlet oak	70	52	oak
FrC, FrD:		l i	l I	 
Frondorf	chestnut oak	l l 65	l l 57	chestnut oak,
riondori	northern red oak	l 55	57   57	northern red oak,
	Virginia pine	l 60	l 90	Virginia pine
	VIIgImia pine	00 	]	VIIgIIIIA PING
Gr:		i	İ	İ
Grigsby	American sycamore	80	62	American sycamore,
	black walnut	85	62	black walnut,
	cherrybark oak	90	72	cherrybark oak,
	sweetgum	100	107	sweetgum, white
	white oak	90	72	oak, yellow-poplar
	yellow-poplar	110	129	
HaB:				
Hammack	northern red oak	85	62	northern red oak,
	white oak	80	62	white oak, yellow-
	yellow-poplar	90	86	poplar
La:	<u> </u>	l I	l I	 
Lawrence	green ash	l l 75	l l 57	green ash, pin oak,
nami circo	pin oak	95	72	sweetgum, white
	sweetgum	90	l 85	oak, willow oak,
	white oak	85	57	yellow-poplar
	willow oak	90	72	
	yellow-poplar	90	95	İ
		j	İ	1
Ld:			ļ	
Lindside	cherrybark oak	86	72	cherrybark oak,
	pin oak	90	72	white ash, white
	sweetgum	95	95	oak, willow oak,
	white ash	85	72	yellow-poplar
	yellow-poplar	98	100	] 
Mo		l i	l I	 
Me: Melvin	  American sycamore	l l 85	l   62	  American sycamore,
Met vili	green ash	l 85	62   57	green ash, pin
	pin oak	85   95	l 90	oak, sweetgum,
	sweetgum	95   90	90   85	willow oak
	willow oak	85	62	
	== <b>==                           </b>	55	į	
Ne:		j	j	
Newark	American sycamore	85	62	American sycamore,
	green ash	85	62	green ash, pin
	pin oak	98	95	oak, sweetgum,
	sweetgum	95	90	willow oak
	willow oak	90	62	
			l	I

Table 8.-Forest Productivity-Continued

	Potential produ	uctivi	ty	
Map symbol and		Site	Volume	Trees to manage
soil name	Common trees	index	of wood	
	1	<u> </u>	fiber cu ft/ac	İ
	! !	l I	l cu It/ac	 
Nf:	i	i	 	
Newark	American sycamore	85	62	American sycamore,
	green ash	85	62	green ash, pin
	pin oak	95	90	oak, sweetgum,
	sweetgum   willow_oak	95   85	90   62	willow oak
	Ulifow Gar	05	02	
NhA, NhB, NhC:	į	j	İ	
Nicholson	black oak	82	57	black oak,
	cherrybark oak	85	62	cherrybark oak,
	northern red oak	85   75	57   52	northern red oak, white oak, yellow-
	yellow-poplar	75   95	l 98	poplar
		į		
No:		ļ	ļ	
Nolin	American sycamore	!	62	American sycamore,
	cherrybark oak	90   92	72   98	cherrybark oak, sweetgum, white
	white oak	75	62	oak, yellow-poplar
	yellow-poplar	98	107	
	į	į	ĺ	
Np:	<u> </u> .			
Nolin	American sycamore	•	57   57	American sycamore, cherrybark oak,
	sweetgum	!	l 90	sweetgum, white
	white oak	75	52	oak, yellow-poplar
	yellow-poplar	j 90	92	
		ļ		
OtA, OtB: Otwood	cherrybark oak	l l 85	   62	  cherrybark oak, pin
0tw00d	pin oak	85   95	l 98	oak, sweetgum,
	sweetgum	90	92	white oak, yellow-
	white oak	85	62	poplar
	yellow-poplar	95	98	
PbA:			 	]
Pembroke	  black oak	l I 85	l   72	  black oak, black
	black walnut	80	62	walnut, northern
	northern red oak	85	72	red oak, white
	white ash	85	62	ash, yellow-poplar
	yellow-poplar	95 	98 	
Pm. Pits, loamy, frequently flooded		     	     	
Pq. Pits, quarry		   	 	
RaF:	 		 	
Ramsey	chestnut oak	   75	!   57	chestnut oak,
-	eastern redcedar	45	45	eastern redcedar,
	Virginia pine	60	53	Virginia pine,
	white oak	70	52	white oak
Frondorf	  chestnut oak	l l 75	   57	chestnut oak,
110114011	eastern redcedar	75   45	37   45	eastern redcedar,
	Virginia pine	60	53	Virginia pine,
	white oak	70	52	white oak
			I	

Table 8.-Forest Productivity-Continued

Potential productivity						
Map symbol and	İ	Site	Volume	Trees to manage		
soil name	Common trees	index	of wood	_		
	<u> </u>	İ	fiber	<u></u>		
	I	ĺ	cu ft/ac			
	İ	İ	i	İ		
Ro:	į	İ	İ			
Robertsville	American sycamore	85	62	American sycamore,		
	green ash	60	52	green ash, pin		
	pin oak	75	57	oak, sweetgum,		
	sweetgum	85	70	willow oak		
	willow oak	75	52			
RxF:	ļ					
Rock outcrop.		ļ	ļ			
Caneyville	black oak	75	62	black oak, eastern		
	eastern redcedar	!	43	redcedar, northern		
	northern red oak	70   70	52   52	red oak, scarlet oak, white oak		
	scarret oak	70   70	52   52	Oak, white Oak		
	white Oak	, , o	52 			
SaA, SaB:		i	i			
Sadler	cherrybark oak	75	57	cherrybark oak,		
	northern red oak	75	57	northern red oak,		
	white oak	70	57	white oak, yellow-		
	yellow-poplar	90	90	poplar		
VrC3:	ļ	ļ				
Vertrees	black oak	80	57	black oak, northern		
	northern red oak		62	red oak, scarlet		
	scarlet oak	!	57	oak, white oak		
	white oak	80	57			
	yellow-poplar	90	90	<u> </u>		
W.		l I	l I			
Water	İ	i	i			
	İ	İ	İ			
WeB, WeC2:	İ	İ	İ			
Wellston	yellow-poplar	93	100	chestnut oak,		
	northern red oak	82	57	northern red oak,		
	chestnut oak	78	57	white ash, white		
	white ash	75	57	oak, yellow-poplar		
	white oak	74	57			
7-P 7-02.				l I		
ZaB, ZaC2: Zanesville	  black_oak	l I 77	l l 57	  black oak, chestnut		
201169 ATTT6	chestnut oak	!	57   57	oak, northern red		
	northern red oak	!	57   62	oak, white oak,		
	white oak	03   70	62   57	yellow-poplar		
	yellow-poplar	l 88	l 90	10110" POP101		
	•			•		

#### Table 9.-Forestland Management, Part I

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table. Map units that have Urban land as a major component were not rated and are not included in this table)

		Limitations affect	ting			 I	
	Pct.	construction of haul roads and		Suitability for log landings		Soil rutting	
Map symbol	of					hazard	
and soil name	map  unit 	log landings Rating class and limiting features		Rating class and limiting features	:	Rating class and limiting features	Value
D-D			!				
BaB: Baxter	   90 	  Moderate   Strength	    0.50	  Moderately suited   Strength	0.50	  Severe   Strength	1.00
BaC: Baxter	     85   	  Moderate   Strength	      0.50	  Moderately suited   Slope   Strength	    0.50  0.50	  Severe   Strength	1.00
BaD: Baxter	     85   	  Moderate   Slope   Strength	    0.50  0.50	! -	    1.00  0.50	  Severe   Strength	1.00
BaE: Baxter	     80 	  Moderate   Slope   Strength	      0.50  0.50	! -	    1.00  0.50	  Severe   Strength	1.00
BbC3: Baxter	     85   	  Moderate   Strength	      0.50	  Moderately suited   Slope   Strength	    0.50  0.50	Severe   Strength	1.00
BbD3: Baxter	     85 	   Moderate   Slope   Strength	      0.50  0.50	! -	      1.00  0.50	Severe   Strength	1.00
CaB: Caneyville	     85 	  Moderate   Strength   Restrictive layer	      0.50  0.50	    Moderately suited   Strength	      0.50	  Severe   Strength	1.00
CaC: Caneyville	     85   		      0.50  0.50	. –	      0.50  0.50	Severe   Strength	1.00
CaC3: Caneyville	     85   	   Moderate   Stickiness/slope   Strength   Restrictive layer	0.50	  Moderately suited   Slope   Strength   Stickiness	    0.50  0.50  0.50	Severe   Strength	1.00
CnD: Caneyville	     65 	   Moderate   Restrictive layer   Strength	      0.50  0.50	  Poorly suited   Slope   Strength	    1.00  0.50	Severe   Strength	1.00
Rock outcrop	   25	  Not rated	 	  Not rated		  Not rated	

Table 9.-Forestland Management, Part I-Continued

Map symbol and soil name	Pct. of map unit	Limitations affecting construction of haul roads and log landings		   Suitability for   log landings		   Soil rutting   hazard	
		Rating class and limiting features	Value	Rating class and limiting features	!	Rating class and limiting features	Value
CnF: Caneyville	     65   	  Severe   Slope   Stoniness   Strength	    1.00  1.00  0.50	Rock fragments	    1.00  1.00  0.50	    Severe   Strength 	1.00
Rock outcrop	25	  Not rated 	   	  Not rated 	   	  Not rated 	
CrB: Crider	     90 	  Moderate   Strength	    0.50	    Moderately suited   Strength 	      0.50	  Severe   Strength	1.00
CrC: Crider	   85   	  Moderate   Strength 	    0.50 	  Moderately suited   Slope   Strength	    0.50  0.50	  Severe   Strength 	    1.00 
DAM: Dam, large	100	  Not rated	 	  Not rated	 	  Not rated	<u> </u> 
Du: Dunning	   85     	  Moderate   Strength	    0.50 	  Poorly suited   Ponding   Wetness   Strength	  1.00  1.00  0.50	  Severe   Strength	1.00
EkB: Elk	     80 	    Moderate   Strength 	      0.50	    Moderately suited   Strength 	      0.50	    Severe   Strength 	1.00
EpB: Epley	   85     	  Moderate   Strength 	    0.50 	  Moderately suited   Strength   Wetness	    0.50  0.50	  Severe   Strength	    1.00 
FeB: Fredonia	   50   	  Moderate   Strength   Stickiness/slope   Restrictive layer		  Moderately suited   Rock fragments   Strength	    0.50  0.50	  Severe   Strength 	1.00
Vertrees	   35   	   Moderate   Strength   Stickiness/slope	    0.50  0.50	  Moderately suited   Strength	    0.50 	  Severe   Strength	1.00
FeC: Fredonia	   50     	  Moderate   Strength   Stoniness   Stickiness/slope   Restrictive layer	    0.50  0.50  0.50	  Poorly suited   Rock fragments   Slope   Strength	    1.00  0.50  0.50	  Severe   Strength   	1.00
Vertrees	   30     	  Moderate   Strength   Stoniness   Stickiness/slope	  0.50  0.50  0.50	  Poorly suited   Rock fragments   Slope   Strength	  1.00  0.50  0.50	  Severe   Strength   	1.00

Table 9.—Forestland Management, Part I—Continued

Map symbol and soil name	  Pct.   of  map	Limitations affecting construction of haul roads and log landings		Suitability for log landings		Soil rutting   hazard	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
FrC: Frondorf	     85   	   Moderate   Strength	      0.50 	  Moderately suited   Slope   Strength	      0.50  0.50	    Severe   Strength 	1.00
FrD: Frondorf	   85       	  Severe   Landslides   Slope   Strength	    1.00  0.50  0.50	  Poorly suited   Landslides   Slope   Strength	    1.00  1.00  0.50	  Severe   Strength 	1.00
Gr: Grigsby	   90 	  Severe   Flooding	    1.00	  Poorly suited   Flooding	    1.00	  Moderate   Strength	0.50
HaB: Hammack	   85 	  Moderate   Strength	    0.50	  Moderately suited   Strength	    0.50	  Severe   Strength	1.00
La: Lawrence	     90   	  Moderate   Strength	      0.50	  Moderately suited   Strength   Wetness	    0.50  0.50	  Severe   Strength	1.00
Ld: Lindside	     90   	  Severe   Flooding   Strength	    1.00  0.50	  Poorly suited   Flooding   Strength   Wetness	    1.00  0.50  0.50	  Severe   Strength	1.00
Me: Melvin	     80   	  Severe   Flooding   Strength	    1.00  0.50	  Poorly suited   Flooding   Wetness   Strength	    1.00  1.00  0.50	  Severe   Strength 	1.00
Ne: Newark	   90     	  Severe   Flooding   Strength	    1.00  0.50 	  Poorly suited   Flooding   Strength   Wetness	    1.00  0.50  0.50	  Severe   Strength 	1.00
Nf: Newark	   90     	  Moderate   Strength 	    0.50 	  Poorly suited   Ponding   Strength   Wetness	    1.00  0.50  0.50	  Severe   Strength 	1.00
NhA, NhB: Nicholson	   80   	  Moderate   Strength 	    0.50 	  Moderately suited   Strength   Wetness	    0.50  0.50	  Severe   Strength 	1.00
NhC: Nicholson	   85       	  Moderate   Strength 	    0.50   	  Moderately suited   Slope   Strength   Wetness	  0.50  0.50  0.50	  Severe   Strength 	1.00

Table 9.-Forestland Management, Part I-Continued

Map symbol and soil name	Pct. of	Limitations affecting   construction of   haul roads and   log landings		   Suitability for   log landings		   Soil rutting   hazard	
	unit		Value	Rating class and limiting features	Value	Rating class and limiting features	Value
No: Nolin	     90   	    Severe   Flooding   Strength	      1.00  0.50	    Poorly suited   Flooding   Strength	      1.00  0.50	    Severe   Strength 	1.00
Np: Nolin	     90   	  Moderate   Strength	      0.50	  Poorly suited   Ponding   Strength	      1.00  0.50	  Severe   Strength	1.00
OtA, OtB: Otwood	     90   	  Moderate   Strength 	      0.50	  Moderately suited   Strength   Wetness	      0.50  0.50	  Severe   Strength	1.00
PbA: Pembroke	     90 	  Moderate   Strength	      0.50	  Moderately suited   Strength	      0.50	    Severe   Strength	1.00
Pm: Pits, loamy, frequently flooded-	       95	      Not rated	       	    Not rated 	     	      Not rated	     
Pq: Pits, quarry	   90 	  Not rated 	j   	  Not rated 	į Į	  Not rated 	
RaF: Ramsey	   75     	  Severe   Landslides   Slope	    1.00  1.00	  Poorly suited   Slope   Landslides   Strength	  1.00  1.00  0.50	  Severe   Strength 	1.00
Frondorf	   20     	   Severe   Landslides   Slope   Strength	  1.00  1.00  0.50	  Poorly suited   Slope   Landslides   Strength	  1.00  1.00  0.50	   Severe   Strength   	1.00
Ro: Robertsville	   90         	   Moderate   Flooding   Strength 	  0.50  0.50 	  Poorly suited   Ponding   Wetness   Flooding   Strength	  1.00  1.00  0.50  0.50	  Severe   Strength 	1.00
RxF: Rock outcrop	55	  Not rated		  Not rated		  Not rated	
Caneyville	   33   	  Severe   Slope   Strength	    1.00  0.50	  Poorly suited   Slope   Strength	  1.00  0.50	  Severe   Strength 	1.00
SaA, SaB: Sadler	     85   	  Moderate   Strength 	      0.50	  Moderately suited   Strength   Wetness	    0.50  0.50	  Severe   Strength 	1.00
VrC3: Vertrees	   85     	  Moderate   Strength   Stickiness/slope	    0.50  0.50	  Moderately suited   Slope   Strength	    0.50  0.50	  Severe   Strength 	1.00

Table 9.—Forestland Management, Part I—Continued

		Limitations affec	ting				
	Pct.	construction o	f	Suitability fo	r	Soil rutting	
Map symbol	of	haul roads and		log landings		hazard	
and soil name	map	log landings					
	unit	Rating class and	Value	Rating class and	Value	Rating class and	Value
	<u> </u>	limiting features	<u> </u>	limiting features	<u> </u>	limiting features	<u> </u>
W:		 		 		 	!
Water	100	  Not rated	<u> </u>	  Not rated	1	  Not rated	1
Nacci	1 -00		i		i		i
WeB:	j	İ	j	İ	İ	İ	j
Wellston	90	Moderate		Moderately suited		Severe	
		Strength	0.50	Strength	0.50	Strength	1.00
WeC2:		 		 		 	-
Wellston	85	Moderate	i	  Moderately suited	i	Severe	i
	İ	Strength	0.50	Slope	0.50	Strength	1.00
	į		į	Strength	0.50		į
ZaB:		 		l I		 	-
Zanesville	85	  Moderate	1	  Moderately suited	1	  Severe	1
	"	Strength	0.50	Strength	0.50	Strength	1.00
				Wetness	0.50		
ZaC2:		 		 		 	
Zanesville	l   80	  Moderate		  Moderately suited	1	  Severe	1
201162 ATTT6	1 30	Strength	0.50	Slope	0.50	Strength	1.00
	1	Perenden	10.50	Strength	0.50	Screnach	1 - 00
				Strength   Wetness	0.50		1
	!	] 		Meriiess	10.50	 	1

# Table 9.-Forestland Management, Part II

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table. Map units that have Urban land as a major component were not rated and are not included in this table)

Map symbol and soil name	Pct. of	Hazard of off-road or off-trail eros:		Hazard of erosic		Suitability for roads (natural surface)		
	unit 	Rating class and limiting features	Value	Rating class and   limiting features	Value 	Rating class and limiting features	Value	
BaB: Baxter	     90 	    Slight 	     	    Moderate   Slope/erodibility 	      0.50	    Moderately suited   Strength	      0.50	
BaC: Baxter	   85   	  Slight   	     	  Severe   Slope/erodibility 	    0.95 	Moderately suited   Slope   Strength	    0.50  0.50	
BaD: Baxter	   85   	  Moderate   Slope/erodibility	    0.50 	  Severe   Slope/erodibility 	    0.95 	  Poorly suited   Slope   Strength	  1.00  0.50	
BaE: Baxter	   80 	  Moderate   Slope/erodibility	      0.50	  Severe   Slope/erodibility 	      0.95 	  Poorly suited   Slope   Strength	  1.00  0.50	
BbC3: Baxter	   85   	Slight	       	  Severe   Slope/erodibility 	      0.95 	  Moderately suited   Slope   Strength	0.50	
BbD3: Baxter	     85   	  Moderate   Slope/erodibility	      0.50	  Severe   Slope/erodibility 	      0.95 	  Poorly suited   Slope   Strength	    1.00  0.50	
CaB: Caneyville	     85 	  Slight 	     	    Moderate   Slope/erodibility 	      0.50	    Moderately suited   Strength 	0.50	
CaC: Caneyville	   85 	  Slight 	     	  Severe   Slope/erodibility 	    0.95 	  Moderately suited   Slope   Strength	0.50	
CaC3: Caneyville	     85     	  slight 	         	  Severe   Slope/erodibility   	      0.95   	  Moderately suited   Slope   Strength   Stickiness	    0.50  0.50  0.50	
CnD: Caneyville	     65 	  Moderate   Slope/erodibility	      0.50	    Severe   Slope/erodibility 	      0.95	  Poorly suited   Slope   Strength	    1.00  0.50	
Rock outcrop	   25 	  Not rated 	   	  Not rated 	   	  Not rated 	   	

Table 9.-Forestland Management, Part II-Continued

Map symbol and soil name	Pct. of map	Hazard of off-roated of off-roated by the Hazard of off-trail eros:		Hazard of erosion on roads and tra		Suitability for r natural surfac	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
CnF: Caneyville	     65     	     Severe   Slope/erodibility 	    0.75 	    Severe   Slope/erodibility   	    0.95 	Poorly suited Slope Rock fragments Strength	    1.00  1.00  0.50
Rock outcrop	   25 	  Not rated 	   	  Not rated 	   	  Not rated 	
CrB: Crider	   90 	  Slight 		  Moderate   Slope/erodibility 	!	Moderately suited Strength	    0.50
CrC: Crider	   85   	  Slight 		  Severe   Slope/erodibility 	!	  Moderately suited   Slope   Strength	    0.50  0.50
DAM: Dam, large	  100	  Not rated 		    Not rated 		Not rated	
Du: Dunning	   85     	  Slight 		  Slight     		Poorly suited Ponding Wetness Strength	  1.00  1.00  0.50
EkB: Elk	   80 	  Slight 		  Moderate   Slope/erodibility	!	  Moderately suited   Strength	    0.50
EpB: Epley	     85   	  Slight 		  Moderate   Slope/erodibility 		   Moderately suited   Strength   Wetness	    0.50  0.50
FeB: Fredonia	   50 	  Slight 		  Moderate   Slope/erodibility 		Moderately suited Rock fragments Strength	    0.50  0.50
Vertrees	   35 	  Slight 		  Moderate   Slope/erodibility		  Moderately suited   Strength	0.50
FeC: Fredonia	     50   	  Slight   		  Severe   Slope/erodibility   	    0.95 	Poorly suited Rock fragments Slope Strength	    1.00  0.50  0.50
Vertrees	   30       	  Slight     		  Severe   Slope/erodibility   		Poorly suited Rock fragments Slope Strength	  1.00  0.50  0.50
FrC: Frondorf	   85     	  Slight     		  Severe   Slope/erodibility   		Moderately suited Slope Strength	    0.50  0.50

Table 9.—Forestland Management, Part II—Continued

Map symbol and soil name	Pct. of map	Hazard of off-road or off-road or off-trail eros:		Hazard of erosion on roads and train		Suitability for roads (natural surface)		
		Rating class and limiting features	Value	Rating class and   limiting features	Value	Rating class and limiting features	Value	
FrD: Frondorf	     85     	    Moderate   Slope/erodibility   	      0.50   	    Severe   Slope/erodibility   	      0.95   	  Poorly suited   Landslides   Slope   Strength	  1.00  1.00  0.50	
Gr: Grigsby	     90 	    Slight 	     	    Slight 	     	  Poorly suited   Flooding	1.00	
HaB: Hammack	     85 	    Slight 	       	    Moderate   Slope/erodibility 	      0.50	    Moderately suited   Strength 	0.50	
La: Lawrence	   90 	  Slight   	     	  Slight   	     	  Moderately suited   Strength   Wetness	0.50	
Ld: Lindside	     90     	  Slight     	         	  Slight     	         	  Poorly suited   Flooding   Strength   Wetness	  1.00  0.50  0.50	
Me: Melvin	   80   	  Slight   		  Slight   	       	  Poorly suited   Flooding   Wetness   Strength	  1.00  1.00  0.50	
Ne: Newark	     90   	  Slight   	       	  Slight   	         	  Poorly suited   Flooding   Strength   Wetness	  1.00  0.50  0.50	
Nf: Newark	     90   	  Slight   	       	  Slight   	         	  Poorly suited   Ponding   Strength   Wetness	  1.00  0.50  0.50	
Nha: Nicholson	     80   	    slight   	       	    Slight   	         	  Moderately suited   Strength   Wetness	0.50	
NhB: Nicholson	   80   	  Slight   	     	  Moderate   Slope/erodibility   	    0.50 	  Moderately suited   Strength   Wetness	0.50	
NhC: Nicholson	   85     	  Slight         	 	  Severe   Slope/erodibility     	    0.95   	  Moderately suited   Slope   Strength   Wetness	  0.50  0.50  0.50	

Table 9.-Forestland Management, Part II-Continued

Map symbol and soil name	Pct. of map			Hazard of erosion on roads and tra		Suitability for roads   (natural surface)		
and soff name		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value	
No: Nolin	     90   	    Slight   	         	    Slight   	       	Poorly suited Flooding Strength	1.00	
Np: Nolin	     90   	  Slight   	       	  Slight   	       	  Poorly suited   Ponding   Strength	1.00	
OtA: Otwood	   90   	  Slight   	       	  Slight   	     	Moderately suited Strength Wetness	0.50	
OtB: Otwood	   90   	  Slight   	       	  Moderate   Slope/erodibility 	!	Moderately suited Strength Wetness	0.50	
PbA: Pembroke	   90 	  Slight 	   	  Slight 	   	  Moderately suited   Strength	0.50	
Pm: Pits, loamy, frequently flooded-	       95 	    Not rated 	       	    Not rated 	     	      Not rated 		
Pq: Pits, quarry	   90 	  Not rated 	   	  Not rated 	   	  Not rated 		
RaF: Ramsey	   75   	  Severe   Slope/erodibility   	    0.75 	  Severe   Slope/erodibility   	!	Poorly suited Slope Landslides Strength	  1.00  1.00  0.50	
Frondorf	   20     	  Severe   Slope/erodibility   	    0.75   	  Severe   Slope/erodibility   	    0.95   	Poorly suited Slope Landslides Strength	  1.00  1.00  0.50	
Ro: Robertsville	   90       	  Slight       	           	  Slight       	 	Poorly suited Ponding Wetness Flooding Strength	  1.00  1.00  0.50  0.50	
RxF: Rock outcrop	     55	  Not rated	į Į	  Not rated	<u> </u>	Not rated		
Caneyville	   33     	  Severe   Slope/erodibility 	    0.75 	  Severe   Slope/erodibility 	!	  Poorly suited   Slope   Strength	  1.00  0.50	
SaA: Sadler	   85     	  Slight   	       	  slight   		Moderately suited Strength Wetness	0.50	

Table 9.—Forestland Management, Part II—Continued

Map symbol and soil name	Pct. of	Hazard of off-road or off-trail eros:		Hazard of erosion on roads and train		Suitability for roads (natural surface)		
	unit	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value	
SaB: Sadler	     85   	  Slight 	       	    Moderate   Slope/erodibility 	      0.50 	  Moderately suited   Strength   Wetness	0.50	
VrC3: Vertrees	   85   	  Slight 	     	  Severe   Slope/erodibility	    0.95 	   Moderately suited   Slope   Strength	0.50	
W: Water	100	Not rated		  Not rated		  Not rated		
WeB: Wellston	     90 	  Slight 	       	    Moderate   Slope/erodibility	      0.50	    Moderately suited   Strength	0.50	
WeC2: Wellston	   85   	Slight  -		  Severe   Slope/erodibility	    0.95 	  Moderately suited   Slope   Strength	0.50	
ZaB: Zanesville	     85   	Slight	       	  Moderate   Slope/erodibility	      0.50 	  Moderately suited   Strength   Wetness	0.50	
ZaC2: Zanesville	     80     	  Slight   	         	  Severe   Slope/erodibility 	      0.95 	  Moderately suited   Slope   Strength   Wetness	0.50	

# Table 9.—Forestland Management, Part III

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table. Map units that have Urban land as a major component were not rated and are not included in this table)

				<u> </u>		<u> </u>	
Map symbol and soil name	Pct. of map	Suitability for hand planting		Suitability fo mechanical plant		Suitability for us   harvesting equipm 	
	! -	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
BaB: Baxter	     90 	  Well suited 	       	    Well suited   	     	    Moderately suited   Strength	      0.50
BaC: Baxter	   85 	  Well suited 	   	  Moderately suited   Slope	    0.50	  Moderately suited   Strength	0.50
BaD: Baxter	     85 	    Well suited 	       	  -  Poorly suited   Slope 	      0.75	    Moderately suited   Strength	0.50
BaE: Baxter	   80 	  Well suited  -	     	  Poorly suited   Slope 	    0.75	Moderately suited Strength Slope	0.50
BbC3: Baxter	     85   	Moderately suited Stickiness	      0.50 	  Moderately suited   Stickiness   Slope   Rock fragments	    0.50  0.50  0.50	   Moderately suited   Strength	0.50
BbD3: Baxter	     85     	  Moderately suited   Stickiness 	      0.50   	   Poorly suited   Slope   Stickiness   Rock fragments	    0.75  0.50  0.50	  Moderately suited   Strength 	0.50
CaB: Caneyville	     85 	  Poorly suited   Stickiness	      0.75	  Poorly suited   Stickiness	      0.75	  Moderately suited   Strength	0.50
CaC: Caneyville	     85   	Poorly suited Stickiness	      0.75 	  Poorly suited   Stickiness   Slope	    0.75  0.50	  Moderately suited   Strength	0.50
CaC3: Caneyville	     85   	  Poorly suited   Stickiness	      0.75 	  Poorly suited   Stickiness   Slope	    0.75  0.50	  Moderately suited   Strength   Stickiness	0.50
CnD: Caneyville	     65 	  Poorly suited   Stickiness	      0.75	  Poorly suited   Stickiness   Slope	    0.75  0.50	  Moderately suited   Strength	0.50
Rock outcrop	   25 	  Not rated 	   	  Not rated 	   	  Not rated 	   

Table 9.-Forestland Management, Part III-Continued

Map symbol	Pct.	Suitability for hand planting		Suitability for mechanical plant		   Suitability for use of   harvesting equipment		
and soll name	map  unit 	Rating class and limiting features	Value	Rating class and   limiting features	Value	Rating class and limiting features	Value	
CnF: Caneyville	     65     	Poorly suited   Stickiness   Rock fragments   Slope	    0.75  0.75  0.50	Unsuited Slope Rock fragments Stickiness	    1.00  1.00  0.75	  Poorly suited   Rock fragments   Slope   Strength	    1.00  1.00  0.50	
Rock outcrop	   25	  Not rated 	   	  Not rated 	   	  Not rated 		
CrB: Crider	     90 	    Well suited 	       	    Well suited 	       	    Moderately suited   Strength 	0.50	
CrC: Crider	   85 	  Well suited 	     	  Moderately suited   Slope 	    0.50	  Moderately suited   Strength	0.50	
DAM: Dam, large	  100 	  Not rated 	i   	  Not rated 	i   	  Not rated 	   	
Du: Dunning	   85 	  Moderately suited   Stickiness	    0.50	  Moderately suited   Stickiness	    0.50	  Moderately suited   Strength	0.50	
EkB: Elk	   80 	    Well suited 	   	    Well suited 	     	  Moderately suited   Strength	0.50	
EpB: Epley	     85 	    Well suited 	     	    Well suited 	     	    Moderately suited   Strength	0.50	
FeB: Fredonia	     50 	  Poorly suited   Stickiness	      0.75	  Poorly suited   Stickiness   Rock fragments	      0.75  0.50	  Moderately suited   Rock fragments   Strength	0.50	
Vertrees	   35 	  Poorly suited   Stickiness	    0.75	  Poorly suited   Stickiness	    0.75	  Moderately suited   Strength	0.50	
FeC: Fredonia	   50   	  Poorly suited   Stickiness   Rock fragments	    0.75  0.50	  Poorly suited   Stickiness   Rock fragments   Slope	  0.75  0.75  0.50	Poorly suited Rock fragments Strength	    1.00  0.50	
Vertrees	   30       	  Poorly suited   Stickiness   Rock fragments 	    0.75  0.50 	  Poorly suited   Stickiness   Rock fragments   Slope	    0.75  0.75  0.50	  Poorly suited   Rock fragments   Strength 	  1.00  0.50 	
FrC: Frondorf	   85 	  Well suited 	     	  Moderately suited   Slope 	    0.50	Moderately suited Strength	0.50	
FrD: Frondorf	   85 	  Well suited   	     	  Poorly suited   Slope 	    0.75 	  Moderately suited   Strength 	0.50	

Table 9.-Forestland Management, Part III-Continued

Map symbol and soil name	Pct. of map	Suitability for hand planting	r	Suitability fo mechanical plant		Suitability for use of   harvesting equipment 	
		Rating class and limiting features	Value	Rating class and   limiting features	Value	Rating class and limiting features	Value
Gr: Grigsby	     90 	    Well suited 	     	    Well suited 	     	    Well suited 	     
Hammack	   85 	  Well suited 	     	  Well suited 	     	Moderately suited Strength	0.50
La: Lawrence	     90 	  Well suited	     	  Well suited 	   	  Moderately suited   Strength	0.50
Ld: Lindside	     90 	  Well suited	     	    Well suited 	     	  Moderately suited   Strength	0.50
Me: Melvin	     80 	  Well suited	     	    Well suited 	     	  Moderately suited   Strength	0.50
Ne, Nf: Newark	     90 	  Well suited	     	    Well suited 	     	Moderately suited Strength	0.50
NhA, NhB: Nicholson	     80 	  Well suited	     	    Well suited 	     	Moderately suited Strength	0.50
NhC: Nicholson	     85 	    Well suited 	     	    Moderately suited   Slope	      0.50	     Moderately suited   Strength	0.50
No, Np: Nolin	     90 	    Well suited 	     	    Well suited 	     	    Moderately suited   Strength	      0.50
OtA, OtB: Otwood	     90 	    Well suited 	     	    Well suited 	     	    Moderately suited   Strength	      0.50
PbA: Pembroke	     90 	    Well suited 	     	    Well suited 	     	    Moderately suited   Strength	      0.50
Pm: Pits, loamy, frequently flooded-	       95	Not rated	     	      Not rated	     	Not rated	     
Pq: Pits, quarry	     90	    Not rated	   	    Not rated		Not rated	   
RaF: Ramsey	     75 	     Moderately suited   Slope 	      0.50	    Unsuited   Slope 	      1.00	  Poorly suited   Slope   Strength	    1.00  0.50
Frondorf	   20 	  Moderately suited   Slope 	    0.50 	  Unsuited   Slope 	    1.00	  Poorly suited   Slope   Strength	  1.00  0.50

Table 9.—Forestland Management, Part III—Continued

Map symbol contact map and soil name map		   Suitability fo:   hand planting 		   Suitability fo   mechanical plant 		   Suitability for use of   harvesting equipment 		
	unit	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value	
Ro: Robertsville	     90 	  Well suited 	     	    Well suited   	     	    Moderately suited   Strength	0.50	
RxF: Rock outcrop	     55	  Not rated	 	    Not rated		    Not rated		
Caneyville	   33   	Poorly suited Stickiness Slope	    0.75  0.50	  Unsuited   Slope   Stickiness	  1.00  0.75	  Poorly suited   Slope   Strength	  1.00  0.50	
SaA, SaB: Sadler	     85 	  Well suited	     	    Well suited 	     	  Moderately suited   Strength	0.50	
VrC3: Vertrees	     85 	    Poorly suited   Stickiness	      0.75	    Poorly suited   Stickiness   Slope	      0.75  0.50	    Moderately suited   Strength 	0.50	
W: Water	    100	    Not rated	   	    Not rated 		    Not rated	   	
WeB: Wellston	     90 	  Well suited 	     	    Well suited 	     	  Moderately suited   Strength	0.50	
WeC2: Wellston	     85 	  Well suited	     	  Moderately suited   Slope	      0.50	  Moderately suited   Strength	0.50	
ZaB: Zanesville	     85 	  Well suited 	     	  Well suited 	     	  Moderately suited   Strength	0.50	
ZaC2: Zanesville	     80 	  Well suited 	       	    Moderately suited   Slope 	      0.50	    Moderately suited   Strength 	0.50	

Table 9.-Forestland Management, Part IV

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table. Map units that have Urban land as a major component were not rated and are not included in this table)

Map symbol	Pct. of	·		Suitability for mechanical site	
and soil name		preparation (surfa		preparation (deep	
		Rating class and limiting features	Value		
BaB: Baxter	90	    Well suited	     	    Well suited	     
BaC: Baxter	   85 	  Well suited 	   	  Well suited 	j   
BaD: Baxter	     85 	  Poorly suited   Slope	    0.50	  Poorly suited   Slope	    0.50
BaE: Baxter	   80 	Poorly suited   Slope	    0.50	Poorly suited   Slope	    0.50
BbC3: Baxter	   85 	  Well suited 	   	  Well suited 	   
BbD3: Baxter	   85 	  Poorly suited   Slope	    0.50	  Poorly suited   Slope	    0.50
CaB, CaC, CaC3: Caneyville	     85 	  Poorly suited   Stickiness	      0.50	  Poorly suited   Restrictive layer	    0.50
CnD: Caneyville	     65 	. –	      0.50	  Poorly suited   Restrictive layer	    0.50
Rock outcrop	25	  Not rated		  Not rated 	į
CnF: Caneyville	   65     	Slope	  1.00  1.00  0.50	! -	  1.00  1.00  0.50
Rock outcrop	25	  Not rated 	   	  Not rated 	   
CrB:	     90	    Well suited 	     	    Well suited 	     
CrC: Crider	     85	    Well suited 	   	    Well suited 	   
DAM: Dam, large	  100 	  Not rated 	   	  Not rated 	   
Du: Dunning	     85 	  Poorly suited   Stickiness	    0.50	  Well suited 	     

Table 9.-Forestland Management, Part IV-Continued

	Pct.			Suitability for	r
Map symbol	of	mechanical site	9	mechanical site	9
and soil name	map	preparation (surfa	ace)	preparation (deep	o)
	unit	Rating class and	Value	Rating class and	Value
	<u> </u>	limiting features	<u> </u>	limiting features	<u> </u>
EkB:			ĺ	ĺ	ĺ
Elk	80	Well suited		Well suited	
EpB:					
Epley	85	Well suited		Well suited	
				ļ	
FeB:	ļ		!	ļ	!
Fredonia	50			Well suited	!
	ļ		0.50		!
	ļ	Stickiness	0.50		ļ
			ļ		ļ
Vertrees	35	. –	!	Well suited	ļ
	!	Stickiness	0.50		!
_ ~	ļ	 	!		!
FeC:		 	!	 	!
Fredonia	] 50 	!	:	Poorly suited	 
	!		1.00  0.50	Rock fragments	0.50
	ļ	SCICKINESS	0.50 	 	l i
Vertrees	   30	l   Imguited	! !	  Poorly suited	! !
VELCICEB	30	!	1.00	:	0.50
	i	:	0.50	l moon fragmence	<b>0.</b> 50
	i	= ===================================		İ	i
FrC:	i		i	İ	i
Frondorf	l 85	  Well suited	i	Unsuited	i
	i	İ	İ	Restrictive layer	1.00
	i	İ	İ	į	İ
FrD:	İ	]	İ	İ	İ
Frondorf	85	Poorly suited	İ	Unsuited	İ
	İ	Slope	0.50	Restrictive layer	1.00
				Slope	0.50
Gr:	ļ		!	ļ	!
Grigsby	90	Well suited	!	Well suited	!
	ļ		!		!
HaB:			ļ	<u> </u>	ļ
Hammack	85	Well suited	!	Well suited	!
_	!		!		!
La:		 		 	
Lawrence	J 90	Well Suited	!	Well suited	!
Ld:	ļ	 	l I	 	l i
Lindside	l I an	  Well suited	 	  Well suited	! !
HINGBIGE	30	Well Bulled 	! !	Well Bulled 	! !
Me:	¦	 	! !	l I	! !
Melvin	80	  Well suited	i	  Well suited	i
	"		i		i
Ne, Nf:	i		i	İ	i
Newark	90	  Well suited	i	  Well suited	i
	i		i		i
NhA, NhB:	İ		İ	j	İ
Nicholson	80	Well suited	İ	Well suited	İ
	İ	İ	İ	İ	İ
NhC:		1		l	
Nicholson	85	Well suited		Well suited	
				l	
No, Np:			ļ	ļ	ļ
Nolin	90	Well suited	!	Well suited	!
	l	I	l	l	

Table 9.-Forestland Management, Part IV-Continued

Map		Pct.	·		Suitability for	
Unit   Rating class and   Value   Rating class and   Inmiting features   Value   Cota, OtB:   Otwood		!	:		!	
OtA, OtB:         Otwood		i		!	-	i varac
Description   Part   Prondorf   Part		i .				<u> </u>
Description   Part   Prondorf   Part	Ota. Ota.	i i	] 	l I	! 	l I
PbA:         Pembroke		90	  Well suited	i	  Well suited	i
Pembroke	00,000	50	l	i	l	i
Pembroke	PhA:	i	1	i	! 	i
Pm:         Pits, loamy, frequently flooded-         95         Not rated         Not rated         Not rated           Pq:         Pits, quarry         90         Not rated         Not rated         Not rated           RaF:         75         Unsuited Slope         1.00         Slope Slope         1.00           Frondorf		90	  Well suited	i	  Well suited	i
Pits, loamy, frequently flooded- PG: Pits, quarry 90 Not rated         Not rated         Not rated           RaF: Ramsey 75 Unsuited Slope	1 01101 0710	50	l	i	l	i
Pits, loamy, frequently flooded- PG: Pits, quarry 90 Not rated         Not rated         Not rated           RaF: Ramsey 75 Unsuited Slope	Pm:	l		i	! ]	i
Pq:		i		i		i
Pq:         Pits, quarry         90         Not rated         Not rated           RaF:         Ramsey         75         Unsuited         1.00         Slope         1.00           Frondorf		95	Not rated	i	Not rated	i
Pits, quarry	irequenci, irecueu	]		i		i
Pits, quarry	Pa:	i	1	i	! 	i
RaF:       Ramsey	_	90	  Not rated	i	  Not_rated	i
Ramsey	iiob, quaii,	50		i		i
Ramsey	RaF:	i	1	i	! 	i
Slope   1.00   Restrictive layer   1.00   Restrictive layer   1.00   Restrictive layer   1.00   Restrictive layer   1.00   Restrictive layer   0.50   Robertsville   90   Well suited   Well s		75	  Unsuited	i	  Unsuited	i
Restrictive layer   1.00	11011110 0 2	'	!	!	!	1
Frondorf		i	22070		! <del>-</del>	!
Slope   1.00   Slope   1.00   Restrictive layer   0.50		i		i		
Slope   1.00   Slope   1.00   Restrictive layer   0.50	Frondorf	20	  Unsuited	i	  Unsuited	i
Restrictive layer   0.50			!	!	!	1
Ro:       Robertsville		i	22070		! <del>-</del>	!
RxF:         Rock outcrop		i		i		
RxF:         Rock outcrop	Ro:	i		i		i
RxF:       Rock outcrop       55       Not rated       Not rated         Caneyville		90	  Well suited	i	  Well suited	i
Rock outcrop         55         Not rated         Not rated           Caneyville		i		i		i
Caneyville	RxF:	i	İ	i	İ	i
Caneyville	Rock outcrop	55	Not rated	i	Not rated	i
Slope   1.00   Slope   1.00   Slope   0.50	-	İ	İ	İ	İ	İ
Stickiness   0.50   Restrictive layer   0.50	Caneyville	33	Unsuited	İ	Unsuited	İ
SaA, SaB: Sadler		İ	Slope	1.00	Slope	1.00
Sadler		İ	Stickiness	0.50	Restrictive layer	0.50
Sadler		İ		İ		İ
VrC3:       Vertrees	SaA, SaB:	İ		İ	1	İ
Vertrees	Sadler	85	Well suited		Well suited	ĺ
Vertrees		İ		İ	1	İ
W:       0.50         Water	VrC3:	ĺ				ĺ
W:       Water	Vertrees	85	Poorly suited		Well suited	ĺ
Water		ĺ	Stickiness	0.50		ĺ
Water						
WeB:       Wellston	W:					
Wellston       90       Well suited       Well suited         WeC2:       Wellston	Water	100	Not rated		Not rated	
Wellston       90       Well suited       Well suited         WeC2:       Wellston						
WeC2: Wellston	WeB:					
Wellston	Wellston	90	Well suited		Well suited	
Wellston						
ZaB: Zanesville						
Zanesville 85 Well suited Well suited ZaC2:	Wellston	85	Well suited		Well suited	
Zanesville 85 Well suited Well suited ZaC2:		ļ				!
zaC2:						
!!!!!!!!!!!!	Zanesville	85	Well suited		Well suited	!
!!!!!!!!!!!!		!				!
Zanesville 80   Well suited   Well suited		!				!
	Zanesville	80	Well suited		Well suited	!
		L	<u> </u>	l	<u> </u>	L

Table 9.-Forestland Management, Part V

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table. Map units that have Urban land as a major component were not rated and are not included in this table)

Map symbol	Pct. of	Potential for dama to soil by fire		Potential for seedling mortali	
and soil name	map	ļ			
	unit 	Rating class and   limiting features	:	Rating class and   limiting features	Value
	İ		İ		İ
BaB: Baxter	   90   	Low Texture/coarse fragments	    0.10 	Low	
BaC, BaD:	i	! 	i		1
Baxter	85     	Low   Texture/coarse   fragments	  0.10 	Low	
BaE:	İ		İ		İ
Baxter	80     	!	  0.10 	Low   	
BbC3, BbD3:	İ		İ		İ
Baxter	85	Low		Low	!
CaB, CaC: Caneyville	     85 	•		  Moderate  Droughty	0.5
	ļ		į		ļ
CaC3: Caneyville	   85     			Moderate   Droughty 	    0.75   
CnD:		 	 	[ ]	
Caneyville	65   	•		Moderate   Droughty 	0.75
Rock outcrop	25	  Not rated		  Not rated	
CnF: Caneyville	     65 	Low	     	High Droughty	1.00
Rock outcrop	25	  Not rated	 	  Not rated	
CrB: Crider	     90   	  Low   Texture/coarse   fragments	      0.10 	Low	
CrC: Crider	     85   	  Low   Texture/coarse   fragments	      0.10 	Low	

Table 9.—Forestland Management, Part V—Continued

Map symbol and soil name	Pct. of	to soil by fire		Potential for seedling mortali	
and soll name	map  unit 	   Rating class and   limiting features		Rating class and   limiting features	Value
DAM: Dam, large	    100	    Not rated 	     	    Not rated 	
Du: Dunning	   85 	  Low 	   	  High   Wetness	1.00
EkB: Elk	     80   	  Moderate   Texture/coarse   fragments	      0.50 	Low	
EpB: Epley	   85     	•	    0.10 	Low    -	
FeB: Fredonia	   50 	  Low   Texture/coarse   fragments	    0.10 	  Low   	
Vertrees	35 35	  Low   Texture/coarse   fragments	  0.10 	Low	
FeC: Fredonia	   50 	  Low   Texture/coarse   fragments		  Moderate   Droughty	0.5
Vertrees	   30   			  Moderate   Droughty	0.5
FrC, FrD: Frondorf	     85   	  Low   Texture/coarse   fragments	      0.10 	  Low   	
Gr: Grigsby	   90   	  Low   Texture/coarse   fragments		Low   Low 	
HaB: Hammack	   85     	Low Texture/coarse fragments	    0.10 	Low	
La: Lawrence	   90   	Low Texture/coarse fragments	    0.10 	  Moderate   Wetness 	    0.5
Ld: Lindside	   90   	Low Texture/coarse fragments	    0.10 	Low	

Table 9.-Forestland Management, Part V-Continued

Map symbol	Pct. of	:		Potential for seedling mortali	
and soil name	map  unit	Rating class and	Value	Rating class and	Value
Me:	       80	limiting features   		limiting features        High	     
Ne:	     	Texture/coarse fragments	0.50   	Wetness    -	1.00
Newark	   90     	!	  0.10 	Moderate   Wetness 	  0.5 
Nf: Newark	   90   	!	    0.10 	  High   Wetness 	    1.00 
NhA, NhB: Nicholson	   80   	!	    0.10 	Low	       
NhC: Nicholson	   85     	1	    0.10 	Low	     
No: Nolin	   90   	!	    0.10 	Low	     
Np: Nolin	   90   	!	:	  Moderate   Wetness 	    0.25 
OtA, OtB: Otwood	   90   	  Moderate   Texture/coarse   fragments	    0.50 	Low	       
PbA: Pembroke	   90   	  Low   Texture/coarse   fragments	    0.10 	Low	       
Pm: Pits, loamy, frequently flooded-	     95 	    Not rated 	     	    Not rated	     
Pq: Pits, quarry	   90 	  Not rated 	   	  Not rated 	
RaF: Ramsey	   75     	!	0.50	High Droughty	    1.00   

Table 9.—Forestland Management, Part V—Continued

Map symbol and soil name	Pct. of map	to soil by fire	_	Potential for seedling mortality		
		!		Rating class and limiting features	Value	
RaF: Frondorf	     20   	Low Texture/coarse fragments	      0.10 	  High   Droughty 	      1.00	
Ro: Robertsville	   90   	!	    0.10 	  High   Wetness	1.00	
RxF: Rock outcrop	     55	    Not rated	   	  Not rated		
Caneyville	   33   	! -	  0.1 	  High   Droughty 	1.00	
SaA, SaB: Sadler	     85   	!	      0.50	Low	       	
VrC3: Vertrees	     85	    Low	   	    Low		
W: Water	    100	    Not rated 	     	    Not rated 		
WeB: Wellston	   90 	!	    0.10 	Low	     	
WeC2: Wellston	     85   	!	      0.10	Low	       	
ZaB: Zanesville	     85   	:	      0.50	Low	       	
ZaC2: Zanesville	     80   	!	      0.50 	Low	       	

## Table 10.-Recreation, Part I

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table. See table 11, part I, for ratings for map units that have Urban land as a major component)

Map symbol and soil name	Pct. of map	      Camp areas 		 		   Playgrounds 	
	unit	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
BaB: Baxter	   90           	   Somewhat limited   Restricted   permeability   Gravel content	    0.26    0.11 	  Somewhat limited   Restricted   permeability   Gravel content	    0.26    0.11	Very limited   Gravel content   Slope   Restricted   permeability   Content of large   stones	    1.00  0.50  0.26    0.01
BaC: Baxter	   85           	Somewhat limited   Restricted   permeability   Gravel content   Slope	  0.26    0.11  0.04	   Somewhat limited   Restricted   permeability   Gravel content   Slope	  0.26    0.11  0.04	Gravel content	  1.00  1.00  0.26    0.01
BaD: Baxter	   85           	  Very limited   Slope   Restricted   permeability   Gravel content	  1.00  0.26    0.11	  Very limited   Slope   Restricted   permeability   Gravel content	  1.00  0.26    0.11	  Very limited   Slope   Gravel content   Restricted   permeability   Content of large   stones	  1.00  1.00  0.26    0.01
BaE: Baxter	   80           	   Very limited   Slope   Restricted   permeability   Gravel content	  1.00  0.26    0.11	  Very limited   Slope   Restricted   permeability   Gravel content	  1.00  0.26    0.11	Very limited   Slope   Gravel content   Restricted   permeability   Content of large   stones	  1.00  1.00  0.26    0.01
BbC3: Baxter	   85           	   Somewhat limited   Restricted   permeability   Gravel content   Slope	  0.26    0.22  0.04	  Somewhat limited   Restricted   permeability   Gravel content   Slope	  0.26    0.22  0.04	Very limited   Slope   Gravel content   Restricted   permeability   Content of large   stones	  1.00  1.00  0.26    0.01
BbD3: Baxter	   85           	   Very limited   Slope   Restricted   permeability   Gravel content	  1.00  0.26    0.22	   Very limited   Slope   Restricted   permeability   Gravel content	  1.00  0.26    0.22	Very limited   Slope   Gravel content   Restricted   permeability   Content of large   stones	  1.00  1.00  0.26    0.01

Table 10.-Recreation, Part I-Continued

Map symbol and soil name	Pct.	       Camp areas		   Picnic areas		   Playgrounds	
and soll name	map  unit 	   Rating class and   limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
CaB: Caneyville	     85       	  Somewhat limited   Restricted   permeability	      0.99     	  Somewhat limited   Restricted   permeability 	      0.99     	  Somewhat limited   Restricted   permeability   Depth to bedrock   Slope	    0.99    0.71  0.50
CaC: Caneyville	   85       	  Somewhat limited   Restricted   permeability   Slope	    0.99    0.04	  Somewhat limited   Restricted   permeability   Slope	  0.99    0.04	  Very limited   Slope   Restricted   permeability   Depth to bedrock	  1.00  0.99    0.71
CaC3: Caneyville	   85         	Very limited Too clayey Restricted permeability Slope	  1.00  0.99    0.04	  Very limited   Too clayey   Restricted   permeability   Slope	  1.00  0.99    0.04	Very limited Slope Too clayey Restricted permeability Depth to bedrock	  1.00  1.00  0.99    0.71
CnD: Caneyville	   65       	  Somewhat limited   Restricted   permeability   Slope	    0.99    0.84	  Somewhat limited   Restricted   permeability   Slope	    0.99    0.84	   Very limited   Slope   Restricted   permeability   Depth to bedrock	  1.00  0.99    0.71
Rock outcrop	   25 	  Not rated 		  Not rated 		  Not rated 	
CnF: Caneyville	   65       	   Very limited   Slope   Too stony   Restricted   permeability	  1.00  1.00  0.99	  Very limited   Slope   Too stony   Restricted   permeability	  1.00  1.00  0.99	Very limited Slope Too stony Restricted permeability Depth to bedrock	  1.00  1.00  0.99 
Rock outcrop	   25 	  Not rated 		  Not rated 	   	  Not rated 	   
CrB: Crider	   90 	  Not limited 	     	  Not limited 	     	  Somewhat limited   Slope	0.50
CrC: Crider	     85   	    Somewhat limited   Slope 	      0.04	    Somewhat limited   Slope 	      0.04	    Very limited   Slope 	1.00
DAM: Dam, large	  100	  Not rated	 	    Not rated 	 	  Not rated	
Du: Dunning	   85         	Very limited Depth to saturated zone Ponding Restricted permeability	  1.00    1.00  0.96	   Very limited   Ponding   Depth to   saturated zone   Restricted   permeability	  1.00  1.00    0.96	Very limited   Depth to   saturated zone   Ponding   Restricted   permeability	  1.00    1.00  0.96

Table 10.-Recreation, Part I-Continued

Map symbol and soil name	Pct.   of  map	   Camp areas 		   Picnic areas 		   Playgrounds 	
	unit	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
EkB: Elk	     80 	    Very limited   Flooding	      1.00	    Not limited 	       	    Somewhat limited   Slope	0.50
EpB: Epley	   85     	Somewhat limited   Restricted   permeability   Depth to   saturated zone	    0.99    0.88	Somewhat limited   Restricted   permeability   Depth to   saturated zone	    0.99    0.56		0.99
FeB: Fredonia	     50       	  Somewhat limited   Restricted   permeability   Too stony	        0.96    0.19	  Somewhat limited   Restricted   permeability   Too stony	      0.96    0.19	Slope 	0.50     0.96   0.50   0.19   0.03
Vertrees	   35     	   Somewhat limited   Restricted   permeability	    0.96   	  Somewhat limited   Restricted   permeability	    0.96   	   Somewhat limited   Restricted   permeability   Slope	0.96
FeC: Fredonia	   50       	   Very limited   Too stony   Restricted   permeability   Slope	  1.00  0.96    0.04	  Very limited   Too stony   Restricted   permeability   Slope	  1.00  0.96    0.04	Very limited   Slope   Too stony   Restricted   permeability   Depth to bedrock	  1.00  1.00  0.96 
Vertrees	   30       	  Very limited   Too stony   Restricted   permeability   Slope	  1.00  0.96    0.04	  Very limited   Too stony   Restricted   permeability   Slope	  1.00  0.96    0.04	  Very limited   Slope   Too stony   Restricted   permeability	  1.00  1.00  0.96
FrC: Frondorf	   85   	  Somewhat limited   Slope 	    0.04 	  Somewhat limited   Slope 	    0.04 	  Very limited   Slope   Depth to bedrock	  1.00  0.80
FrD: Frondorf	   85     	  Very limited   Slope 	    1.00 	  Very limited   Slope 	    1.00 	  Very limited   Slope   Depth to bedrock	1.00
Gr: Grigsby	   90 	  Very limited   Flooding 	    1.00	  Somewhat limited   Flooding	    0.40	  Very limited   Flooding 	    1.00
HaB: Hammack	   85   	  Not limited   	     	  Not limited   	     	  Somewhat limited   Slope 	    0.50

Table 10.-Recreation, Part I-Continued

Map symbol and soil name	Pct. of map	   Camp areas 		   Picnic areas 		   Playgrounds 	
	unit	Rating class and limiting features	Value	Rating class and limiting features	Value 	Rating class and limiting features	Value
La: Lawrence	     90     	  Very limited   Depth to   saturated zone   Flooding   Restricted   permeability	    1.00    1.00  0.99	  Somewhat limited   Restricted   permeability   Depth to   saturated zone	    0.99    0.94	Very limited Depth to saturated zone Restricted permeability	1.00
Ld: Lindside	     90     	Very limited Flooding Depth to saturated zone	    1.00  0.88	  Somewhat limited   Depth to   saturated zone   Flooding	    0.56    0.40	  Very limited   Flooding   Depth to   saturated zone	    1.00  0.88
Me: Melvin	   80     	   Very limited   Depth to   saturated zone   Flooding	    1.00    1.00	  Very limited   Depth to   saturated zone   Flooding	    1.00    0.40	  Very limited   Depth to   saturated zone   Flooding	1.00
Ne: Newark	   90     	  Very limited   Depth to   saturated zone   Flooding	    1.00    1.00	  Somewhat limited   Depth to   saturated zone   Flooding	    0.94    0.40	  Very limited   Depth to   saturated zone   Flooding	  1.00    1.00
Nf: Newark	   90     	  Very limited   Depth to   saturated zone   Ponding	    1.00    1.00	  Very limited   Ponding   Depth to   saturated zone	    1.00  0.94	  Very limited   Depth to   saturated zone   Ponding	1.00
NhA: Nicholson	   80       	Somewhat limited   Restricted   permeability   Depth to   saturated zone	    0.99    0.88	  Somewhat limited   Restricted   permeability   Depth to   saturated zone	    0.99    0.56	  Somewhat limited   Restricted   permeability   Depth to   saturated zone	0.99
NhB: Nicholson	   80         	  Somewhat limited   Restricted   permeability   Depth to   saturated zone	    0.99    0.88	  Somewhat limited   Restricted   permeability   Depth to   saturated zone	    0.99    0.56	Somewhat limited   Restricted   permeability   Depth to   saturated zone   Slope	0.99
NhC: Nicholson	   85           	  Somewhat limited   Restricted   permeability   Depth to   saturated zone   Slope	    0.99    0.88    0.04	  Somewhat limited   Restricted   permeability   Depth to   saturated zone   Slope	    0.99    0.56    0.04	  Very limited   Slope   Restricted   permeability   Depth to   saturated zone	  1.00  0.99    0.88
No: Nolin	     90 	  Very limited   Flooding	    1.00	  Somewhat limited   Flooding	      0.40	  Very limited   Flooding	1.00

Table 10.-Recreation, Part I-Continued

Map symbol and soil name	Pct. of map	   Camp areas 		   Picnic areas		   Playgrounds	
	unit	Rating class and   limiting features	Value	Rating class and   limiting features	Value	Rating class and   limiting features	Value
Np: Nolin	     90 	    Very limited   Ponding	      1.00	    Very limited   Ponding	      1.00	    Very limited   Ponding	1.00
OtA: Otwood	   90         	  Very limited   Flooding   Restricted   permeability   Depth to   saturated zone	  1.00  0.99    0.77	  Somewhat limited   Restricted   permeability   Depth to   saturated zone	    0.99    0.43 	  Somewhat limited   Restricted   permeability   Depth to   saturated zone	    0.99    0.77 
OtB: Otwood	   90         	  Very limited   Flooding   Restricted   permeability   Depth to   saturated zone	  1.00  0.99    0.77	Somewhat limited   Restricted   permeability   Depth to   saturated zone	    0.99    0.43 	Somewhat limited   Restricted   permeability   Depth to   saturated zone   Slope	  0.99    0.77    0.50
PbA: Pembroke	90	    Not limited	İ	    Not limited		    Not limited	 
Pm: Pits, loamy, frequently flooded-	       95	      Not rated 	       	      Not rated 		      Not rated 	
Pq: Pits, quarry	   90 	  Not rated 	   	  Not rated 		  Not rated 	į Į
RaF: Ramsey	   75         	  Very limited   Slope   Depth to bedrock 	1.00	  Very limited   Slope   Depth to bedrock 	  1.00  1.00 	   Very limited   Slope   Depth to bedrock   Gravel content   Content of large   stones	0.16
Frondorf	   20   	  Very limited   Slope 	    1.00 	  Very limited   Slope 	1.00	  Very limited   Slope   Depth to bedrock	    1.00  0.80
Ro: Robertsville	   90             	Very limited Depth to saturated zone Flooding Ponding Restricted permeability	   1.00   1.00   1.00   1.00   0.99	   Very limited   Ponding   Depth to   saturated zone   Restricted   permeability	  1.00  1.00    0.99	   Very limited   Depth to   saturated zone   Ponding   Restricted   permeability   Flooding	  1.00  1.00  0.99    0.60
RxF: Rock outcrop	     55	    Not rated 	     	    Not rated 		    Not rated 	
Caneyville	   33       	  Very limited   Slope   Restricted   permeability 	  1.00  0.99 	  Very limited   Slope   Restricted   permeability 	  1.00  0.99 	   Very limited   Slope   Restricted   permeability   Depth to bedrock	  1.00  0.99    0.71

Table 10.-Recreation, Part I-Continued

Map symbol	Pct. of	   Camp areas		   Picnic areas		   Playgrounds	
and soil name	map						
	unit 	Rating class and limiting features	Value 	Rating class and   limiting features	Value 	Rating class and limiting features	Value
SaA:							
Sadler	   85       	Somewhat limited Restricted permeability Depth to saturated zone	  0.99    0.77	Somewhat limited   Restricted   permeability   Depth to   saturated zone	  0.99    0.43	Somewhat limited   Restricted   permeability   Depth to   saturated zone	0.99
SaB:				 		 	
Sadler	65         	Restricted permeability Depth to saturated zone	  0.99    0.77 	Somewhat limited   Restricted   permeability   Depth to   saturated zone	  0.99    0.43 	Somewhat limited   Restricted   permeability   Depth to   saturated zone   Slope	0.99
VrC3: Vertrees	     85     	  Somewhat limited   Restricted   permeability   Slope	    0.96    0.04	  Somewhat limited   Restricted   permeability   Slope	    0.96    0.04	  Very limited   Slope   Restricted   permeability	  1.00  0.96
W: Water	    100	    Not rated	   	    Not rated		    Not rated	
WeB: Wellston	     90 	    Not limited 	       	    Not limited   	     	    Somewhat limited   Slope	0.50
WeC2: Wellston	     85 	  Somewhat limited   Slope	    0.04	  Somewhat limited   Slope	    0.04	  Very limited   Slope	1.00
ZaB: Zanesville	   85           	  Somewhat limited   Restricted   permeability   Depth to   saturated zone	    0.99    0.77 	  Somewhat limited   Restricted   permeability   Depth to   saturated zone	    0.99    0.43 	  Somewhat limited   Restricted   permeability   Depth to   saturated zone   Slope	0.99
ZaC2: Zanesville	   80       	Somewhat limited Restricted permeability Depth to saturated zone Slope	    0.99    0.77    0.04	Somewhat limited   Restricted   permeability   Depth to   saturated zone   Slope	0.99	   Very limited   Slope   Restricted   permeability   Depth to   saturated zone	  1.00  0.99    0.77

## Table 10.-Recreation, Part II

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table. See table 11, part II, for ratings for map units that have Urban land as a major component)

Map symbol	Pct.	      Paths and trail:	s	Off-road	1-	   Golf fairways	ŀ
and soil name	map  unit 	   Rating class and   limiting features	Value	motorcycle trai Rating class and limiting features	<u>is</u>  Value 	   Rating class and   limiting features	Value
BaB: Baxter	     90   	   	 	    Not limited   		Somewhat limited   Gravel content   Content of large   stones	0.11
BaC: Baxter	   85         	  Not limited       	           	  Not limited       		  Somewhat limited   Gravel content   Slope   Content of large   stones	  0.11  0.04  0.01
BaD: Baxter	   85       	  Somewhat limited   Slope 	    0.02   	  Not limited     	         	   Very limited   Slope   Gravel content   Content of large   stones	  1.00  0.11  0.01
BaE: Baxter	   80       	  Very limited   Slope 	    1.00   	  Not limited    -	         	   Very limited   Slope   Gravel content   Content of large   stones	  1.00  0.11  0.01
BbC3: Baxter	   85         	  Not limited     	 	  Not limited     	           	Somewhat limited   Gravel content   Slope   Content of large   stones	  0.22  0.04  0.01
BbD3: Baxter	   85         	  Somewhat limited   Slope 	    0.02     	  Not limited     	         	Very limited   Slope   Gravel content   Content of large   stones	  1.00  0.22  0.01
CaB: Caneyville	   85     	  Not limited   	       	  Not limited   	       	   Somewhat limited   Depth to bedrock   Droughty	0.71
CaC: Caneyville	   85     	  Very limited   Water erosion   	    1.00   	  Very limited   Water erosion   	    1.00   	   Somewhat limited   Depth to bedrock   Droughty   Slope	  0.71  0.14  0.04

Table 10.-Recreation, Part II-Continued

Map symbol and soil name	Pct. of	   Paths and trail 	s	   Off-road   motorcycle trai	ls	   Golf fairways 	
	unit	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
CaC3: Caneyville	   85       		      1.00   	    Very limited	      1.00   	Very limited Too clayey Depth to bedrock Droughty Slope	  1.00  0.71  0.23  0.04
CnD: Caneyville	   65     	  Very limited   Water erosion 	    1.00 	  Very limited   Water erosion 	    1.00 	Somewhat limited   Slope   Depth to bedrock   Droughty	  0.84  0.71  0.14
Rock outcrop	   25 	  Not rated 	   	  Not rated 	   	  Not rated 	
CnF: Caneyville	   65     	  Very limited   Water erosion   Too stony   Slope	  1.00  1.00  1.00	  Very limited   Water erosion   Too stony   Slope	  1.00  1.00  1.00	Depth to bedrock	  1.00  0.71  0.14
Rock outcrop	   25 	  Not rated 		  Not rated 		  Not rated 	
CrB: Crider	     90	    Not limited 	     	    Not limited 	     	    Not limited 	
CrC: Crider	   85 	  Not limited 	   	  Not limited 	   	  Somewhat limited   Slope	    0.04
DAM: Dam, large	    100 	    Not rated 	     	    Not rated 	     	    Not rated 	     
Du: Dunning	   85     	  Very limited   Depth to   saturated zone   Ponding	    1.00    1.00	  Very limited   Depth to   saturated zone   Ponding	    1.00    1.00	  Very limited   Ponding   Depth to   saturated zone	  1.00  1.00
EkB: Elk	   80 	    Not limited 	     	    Not limited 	   	    Not limited 	
EpB: Epley	   85     	  Somewhat limited   Depth to   saturated zone	    0.18   	  Somewhat limited   Depth to   saturated zone	    0.18   	  Somewhat limited   Depth to   saturated zone	    0.56 
FeB: Fredonia	   50 	  Somewhat limited   Too stony	    0.19	  Somewhat limited   Too stony	    0.19	  Somewhat limited   Depth to bedrock	0.03
Vertrees	   35 	  Not limited 		  Not limited 		  Not limited 	
FeC: Fredonia	     50   	  Very limited   Too stony   Water erosion	      1.00  1.00	  Very limited   Too stony   Water erosion	      1.00  1.00	  Somewhat limited   Slope   Depth to bedrock	    0.04  0.03

Table 10.-Recreation, Part II-Continued

Map symbol and soil name	Pct.   of  map	      Paths and trail: 	s	   Off-road   motorcycle trai	ls	   Golf fairways 		
		Rating class and limiting features	Value	<del></del>	Value	Rating class and limiting features	Value	
FeC: Vertrees	     30 	Very limited Too stony Water erosion	      1.00  1.00	! -	    1.00  1.00	    Somewhat limited   Slope 	0.04	
FrC: Frondorf	     85   	  Very limited   Water erosion	      1.00	    Very limited   Water erosion   	    1.00	  Somewhat limited   Droughty   Slope	0.10	
FrD: Frondorf	   85   	  Very limited   Water erosion   Slope	    1.00  0.02	  Very limited   Water erosion   	    1.00 	  Very limited   Slope   Depth to bedrock   Droughty	  1.00  0.80  0.10	
Gr: Grigsby	     90 	  Somewhat limited   Flooding	      0.40	    Somewhat limited   Flooding 	      0.40	    Very limited   Flooding 	1.00	
HaB: Hammack	   85	Not limited	<u> </u> 	  Not limited	<u> </u> 	  Not limited	į Į	
La: Lawrence	     90 	Somewhat limited Depth to saturated zone	      0.86	  Somewhat limited   Depth to   saturated zone	    0.86	  Somewhat limited   Depth to   saturated zone	0.94	
Ld: Lindside	     90   	  Somewhat limited   Flooding   Depth to   saturated zone	    0.40  0.18	  Somewhat limited   Flooding   Depth to   saturated zone	    0.40  0.18	  Very limited   Flooding   Depth to   saturated zone	1.00	
Me: Melvin	   80   	Very limited Depth to saturated zone Flooding	    1.00    0.40	saturated zone	    1.00    0.40	   Very limited   Flooding   Depth to   saturated zone	1.00	
Ne: Newark	90   90 	Somewhat limited Depth to saturated zone Flooding	    0.86    0.40	  Somewhat limited   Depth to   saturated zone   Flooding	    0.86    0.40	   Very limited   Flooding   Depth to   saturated zone	1.00	
Nf: Newark	     90     	Very limited Ponding Depth to saturated zone	    1.00  0.86	Very limited Ponding Depth to saturated zone	    1.00  0.86	  Very limited   Ponding   Depth to   saturated zone	1.00	
NhA, NhB: Nicholson	   80   	Somewhat limited Depth to saturated zone	      0.18 	  Somewhat limited   Depth to   saturated zone	      0.18 	  Somewhat limited   Depth to   saturated zone	    0.56 	

Table 10.-Recreation, Part II-Continued

Map symbol and soil name	Pct. of map	   Paths and trail 	s	   Off-road   motorcycle trai	ls	   Golf fairways 	
	unit	Rating class and limiting features	Value	Rating class and limiting features		Rating class and limiting features	Value
NhC: Nicholson	     85     	 	    1.00  0.18	  Very limited   Water erosion   Depth to   saturated zone	[ 	  Somewhat limited   Depth to	0.56
No: Nolin	     90 	  Somewhat limited   Flooding	0.40	  Somewhat limited   Flooding	      0.40	  Very limited   Flooding	1.00
Np: Nolin	     90 	  Very limited   Ponding	1.00	! -		  Very limited   Ponding	1.00
OtA, OtB: Otwood	     90   	  Somewhat limited   Depth to   saturated zone	      0.08	  Somewhat limited   Depth to   saturated zone	      0.08 	  Somewhat limited   Depth to   saturated zone	0.43
PbA: Pembroke	     90	    Not limited 		    Not limited 	     	    Not limited 	
Pm: Pits, loamy, frequently flooded-	     95	Not rated	     	    Not rated	     	    Not rated	
Pq: Pits, quarry	90	  Not rated	<u> </u> 	  Not rated 	<u> </u> 	  Not rated 	į į
RaF: Ramsey	   75         	  Very limited   Slope     	    1.00     	  Very limited   Slope   	    1.00     	   Very limited   Depth to bedrock   Slope   Droughty   Content of large   stones	1.00
Frondorf	   20   	  Very limited   Water erosion   Slope	  1.00  1.00	  Very limited   Water erosion   Slope	    1.00  1.00	! -	  1.00  0.80
Ro: Robertsville	Ro: Robertsville 90		  1.00    1.00	  Very limited   Depth to   saturated zone   Ponding	    1.00    1.00	  Very limited   Ponding   Depth to   saturated zone   Flooding	1.00
RxF: Rock outcrop	55	    Not rated		    Not rated	<u> </u> 	    Not rated	
Caneyville	neyville 33   Very limited   Water erosic   Slope		    1.00  1.00	  Very limited   Water erosion   Slope 	    1.00  1.00 	   Very limited   Slope   Depth to bedrock   Droughty	  1.00  0.71  0.14
SaA, SaB: Sadler	SaB: er		      0.08 	  Somewhat limited   Depth to   saturated zone	      0.08 	  Somewhat limited   Depth to   saturated zone	0.43

Table 10.-Recreation, Part II-Continued

	Pct.						
Map symbol	of	Paths and trail	s	Off-road		Golf fairways	3
and soil name	map		motorcycle trai	ls			
	unit	Rating class and	Value	Rating class and	Value	Rating class and	Value
		limiting features		limiting features		limiting features	<u> </u>
VrC3:	 			 		 	-
Vertrees	85	Not limited	i	Not limited	i	  Somewhat limited	i
	į		į	į	į	Slope	0.04
W:	 			 		[ [	
Water	100	Not rated	į	Not rated	į	Not rated	į
WeB:	 		 	 	 	 	
Wellston	90	Not limited	İ	Not limited	į	Not limited	ļ
WeC2:	 		 	 	 	 	
Wellston	85	Very limited	İ	Very limited	İ	Somewhat limited	İ
		Water erosion	1.00	Water erosion	1.00	Slope	0.04
ZaB:				 			
Zanesville	85	Somewhat limited		Somewhat limited		Somewhat limited	
	ļ	Depth to	0.08	Depth to	0.08	Depth to	0.43
	 	saturated zone		saturated zone	l i	saturated zone	!
ZaC2:				 		 	
Zanesville	80	Very limited		Very limited		Somewhat limited	
		Water erosion	1.00	Water erosion	1.00	Depth to	0.43
	[	Depth to	0.08	Depth to	0.08	saturated zone	ļ
	ļ	saturated zone	ļ	saturated zone		Slope	0.04

Table 11.—Recreation Interpretations for Urban Areas, Part I

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table)

Map symbol and soil name	Pct.	   Camp areas 		   Picnic areas 		   Playgrounds 	
	map unit	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
BrB: Baxter	     60         	Somewhat limited   Restricted   permeability   Gravel content	    0.26    0.11 	   Somewhat limited   Restricted   permeability   Gravel content	    0.26    0.11 	Very limited   Gravel content   Slope   Restricted   permeability   Content of large   stones	    1.00  0.50  0.26    0.01
Urban land	30	  Not rated 		  Not rated 		  Not rated 	
BrC: Baxter	   55           	  Somewhat limited   Restricted   permeability   Gravel content   Slope	  0.26    0.11  0.04	  Somewhat limited   Restricted   permeability   Gravel content   Slope	  0.26    0.11  0.04	   Very limited   Slope   Gravel content   Restricted   permeability   Content of large   stones	  1.00  1.00  0.26    0.01
Urban land	30	  Not rated 		  Not rated 		  Not rated 	
BrD: Baxter	   60         	   Very limited   Slope   Restricted   permeability   Gravel content	  1.00  0.26    0.11	  Very limited   Slope   Restricted   permeability   Gravel content	  1.00  0.26    0.11	Very limited   Slope   Gravel content   Restricted   permeability   Content of large   stones	  1.00  1.00  0.26    0.01
Urban land	25	  Not rated 		  Not rated 		  Not rated 	
CoD: Caneyville	   40     	  Somewhat limited   Restricted   permeability   Slope	    0.99    0.84	  Somewhat limited   Restricted   permeability   Slope	    0.99    0.84	  Very limited   Slope   Restricted   permeability   Depth to bedrock	  1.00  0.99 
Urban land	   25	  Not rated	ļ ļ	  Not rated	 	  Not rated	
Rock outcrop	20	  Not rated		  Not rated		  Not rated	
CoE: Caneyville	     40       	  Very limited   Slope   Restricted   permeability	      1.00  0.99 	  Very limited   Slope   Restricted   permeability	      1.00  0.99 	  Very limited   Slope   Restricted   permeability   Depth to bedrock	    1.00  0.99    0.71
Urban land	   25 	  Not rated 		  Not rated 		  Not rated 	
Rock outcrop	20	  Not rated		  Not rated		  Not rated	

Table 11.—Recreation Interpretations for Urban Areas, Part I—Continued

Map symbol and soil name	Pct. of	!      Camp areas 		   Picnic areas 		   Playgrounds 	
	map unit	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
CuB: Crider	     55 	  Not limited	     	  Not limited 	     	  Somewhat limited   Slope	0.50
Urban land	   35 	  Not rated 	   	  Not rated 	   	  Not rated 	   
CuC: Crider	     55 	  Somewhat limited   Slope	0.04	  Somewhat limited   Slope	      0.04	  Very limited   Slope	1.00
Urban land	d 35   Not rated			  Not rated		  Not rated 	
FnB: Fredonia	·		  1.00  0.96 	  Very limited   Too stony   Restricted   permeability	    1.00  0.96   	   Very limited   Slope   Too stony   Restricted   permeability   Depth to bedrock	  1.00  1.00  0.96
Vertrees	   30     	   Somewhat limited   Restricted   permeability	    0.96   	Somewhat limited   Restricted   permeability	    0.96   	   Somewhat limited   Restricted   permeability   Slope	0.96
Urban land  25		  Not rated 	   	  Not rated 	   	  Not rated 	   
FnC: Fredonia	   37       	Very limited Too stony Restricted permeability Slope	  1.00  0.96    0.04	  Very limited   Too stony   Restricted   permeability   Slope	  1.00  0.96    0.04	   Very limited   Slope   Too stony   Restricted   permeability   Depth to bedrock	  1.00  1.00  0.96 
Vertrees	   27   	  Somewhat limited   Restricted   permeability   Slope	    0.96    0.04	  Somewhat limited   Restricted   permeability   Slope	    0.96    0.04	   Very limited   Slope   Restricted   permeability	  1.00  0.96
Urban land	   25 	  Not rated 		  Not rated 		  Not rated 	
FnC2: Fredonia	   37       	Somewhat limited   Restricted   permeability   Too stony   Slope	  0.96    0.76  0.04	  Somewhat limited   Restricted   permeability   Too stony   Slope	  0.96    0.76  0.04	   Very limited   Slope   Restricted   permeability   Too stony   Depth to bedrock	  1.00  0.96    0.76  0.03
Vertrees	   30   	  Somewhat limited   Restricted   permeability   Slope	    0.96    0.04	  Somewhat limited   Restricted   permeability   Slope	    0.96    0.04	  Very limited   Slope   Restricted   permeability	  1.00  0.96
Urban land	   25	  Not rated 		  Not rated 		  Not rated 	[
PeA: Pembroke	     65	    Not limited		    Not limited	     	    Not limited	
Urban land	   25 	  Not rated 		  Not rated 		  Not rated 	

Table 11.—Recreation Interpretations for Urban Areas, Part I—Continued

Map symbol and soil name	  Pct.   of	 		 		   Playgrounds 	
	map unit	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
UaC: Udorthents	     95   	   Not rated   Onsite   investigation   needed	         	  Not rated   Onsite   investigation   needed	         	Not rated Onsite investigation needed	
UaD: Udorthents, refuse substratum	       95     	  Not rated   Onsite   investigation   needed	             	  Not rated   Onsite   investigation   needed	           	  Not rated   Onsite   investigation   needed	
Ub:	į		İ		İ	_	İ
Urban land	75 	Not rated 		Not rated 		Not rated 	
Udorthents	22       	Not rated   Onsite   investigation   needed	     	Not rated   Onsite   investigation   needed	     	Not rated Onsite investigation needed	     
Uc:	ļ	ļ	į	ļ	į		
Urban land	50 	Not rated 		Not rated 		Not rated 	
Udorthents, clayey substratum, hard bedrock 0-5 feet	     30       	  Very limited   Too clayey   Restricted   permeability	    1.00  0.99 	  Very limited   Too clayey   Restricted   permeability	    1.00  0.99 	  Very limited   Slope   Too clayey   Restricted   permeability	    1.00  1.00  0.99
Ud:		_		_		_	
Urban land Udorthents, clayey substratum, hard	75     	Not rated      -	     	Not rated     	     	Not rated     	     
bedrock >5 feet	20         	Very limited   Too clayey   Restricted   permeability	  1.00  0.99   	Very limited   Too clayey   Restricted   permeability 	  1.00  0.99 	Very limited   Slope   Too clayey   Restricted   permeability	  1.00  1.00  0.99
Us: Urban land	60	    Not rated		    Not rated		    Not rated	
Udorthents, smoothed	40	  Impractical		  Impractical		  Impractical	
VtC3: Vertrees	     60   	  Somewhat limited   Restricted   permeability  Slope	    0.96    0.04	  Somewhat limited   Restricted   permeability  Slope	    0.96    0.04	   Very limited   Slope   Restricted   permeability	1.00
Urban land	   25 	  Not rated 		  Not rated 		  Not rated 	   

Table 11.—Recreation Interpretations for Urban Areas, Part I—Continued

Map symbol and soil name	Pct. of	Camp areas		Picnic areas		Playgrounds		
	map  unit	Rating class and limiting features	Value 	Rating class and limiting features	Value	Rating class and limiting features	Value	
ZuB:	 		 	 		 		
Zanesville	65   	Somewhat limited   Restricted   permeability	  0.99 	Somewhat limited   Restricted   permeability	  0.99 	Somewhat limited   Restricted   permeability	  0.99 	
	   	Depth to saturated zone	0.77   	Depth to saturated zone	0.43	Depth to saturated zone	0.77	
Urban land	   25 	  Not rated 	   	    Not rated 		    Not rated 		

Table 11.-Recreation Interpretations for Urban Areas, Part II

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table)

Map symbol and soil name	  Pct.   of	      Paths and trail 	s	Off-road   motorcycle trai	ls	Golf fairways		
	map unit	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value	
BrB: Baxter	     60   	    Not limited   	         	    Not limited   	         	  Somewhat limited   Gravel content   Content of large   stones	0.11	
Urban land	   30 	  Not rated 		  Not rated 		  Not rated 		
BrC: Baxter	   55       	  Not limited     	         	  Not limited     	         	Somewhat limited   Gravel content   Slope   Content of large   stones	  0.11  0.04  0.01	
Urban land	   30	  Not rated 		  Not rated 	 	  Not rated 		
BrD: Baxter	   60     	  Somewhat limited   Slope 	    0.02   	  Not limited   	         	Very limited   Slope   Gravel content   Content of large   stones	  1.00  0.11  0.01	
Urban land	25	  Not rated 		  Not rated 		  Not rated 		
CoD: Caneyville	     40   	  Very limited   Water erosion 	    1.00 	  Very limited   Water erosion 	      1.00 	  Somewhat limited   Slope   Depth to bedrock   Droughty	  0.84  0.71  0.14	
Urban land	   25	  Not rated		  Not rated		  Not rated		
Rock outcrop	   20	  Not rated 		  Not rated 	 	  Not rated 		
CoE: Caneyville	     40   	   Very limited   Water erosion   Slope	    1.00  1.00	  Very limited   Water erosion 	    1.00 	   Very limited   Slope   Depth to bedrock   Droughty	  1.00  0.71  0.14	
Urban land	   25	  Not rated		  Not rated		  Not rated		
Rock outcrop	   20 	  Not rated 		  Not rated 	   	  Not rated 	   	
CuB: Crider	     55	    Not limited		    Not limited 	<u> </u> 	    Not limited 		
Urban land	35 	  Not rated 		  Not rated 	 	  Not rated 	 	

Table 11.—Recreation Interpretations for Urban Areas, Part II—Continued

Map symbol and soil name	Pct. of	      Paths and trail 	s	   Off-road   motorcycle trai	ls_	   Golf fairways 		
	map unit	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value	
CuC: Crider	     55 	    Not limited 	     	    Not limited 	     	    Somewhat limited   Slope	      0.04	
Urban land	   35 	  Not rated 	   	  Not rated 		  Not rated 	   	
FnB: Fredonia	   37 	  Very limited   Too stony   Water erosion	    1.00  1.00	· -	    1.00  1.00	  Somewhat limited   Slope   Depth to bedrock	0.04	
Vertrees	30	  Not limited	   	  Not limited		  Not limited		
Urban land	25	  Not rated 	   	  Not rated 		  Not rated 	   	
FnC: Fredonia	   37 	  Very limited   Too stony   Water erosion	    1.00  1.00	  Very limited   Too stony   Water erosion	    1.00  1.00	  Somewhat limited   Slope   Depth to bedrock	0.04	
Vertrees	   27 	  Very limited   Water erosion	1.00	  Very limited   Water erosion	1.00	  Somewhat limited   Slope	0.04	
Urban land	25	  Not rated	   	  Not rated 		  Not rated		
FnC2: Fredonia	     37 	  Very limited   Water erosion   Too stony	      1.00  0.76	!	    1.00  0.76	  Somewhat limited   Slope   Depth to bedrock	0.04	
Vertrees	   30 	  Very limited   Water erosion	!	  Very limited   Water erosion	1.00	  Somewhat limited   Slope	0.04	
Urban land	   25	  Not rated	   	  Not rated 		  Not rated		
PeA: Pembroke	65	    Not limited	į Į	  Not limited		    Not limited		
Urban land	   25	  Not rated 	   	  Not rated 		  Not rated 		
UaC: Udorthents	     95	    Not rated 	     	    Not rated 		    Not rated 		
UaD: Udorthents, refuse substratum	     95	    Not rated	     	    Not rated 	     	    Not rated	     	
Ub: Urban land	75	  Not rated	 	  Not rated		  Not rated		
Udorthents	22	  Not rated 		  Not rated 		  Not rated 		
Uc: Urban land	     50	    Not rated 	i I	    Not rated 		    Not rated		
Udorthents, clayey substratum, hard bedrock 0-5 feet	       30	    Not rated 	       	    Not rated 	       	    Not rated 		

Table 11.—Recreation Interpretations for Urban Areas, Part II—Continued

Map symbol	Pct.	Paths and trails	3	Off-road	_	Golf fairway:	5
and soil name	of			motorcycle trai			
	map	Rating class and	Value	1	Value		Value
	unit	limiting features	<u> </u>	limiting features		limiting features	+
Ud:		] ]	ļ i	 		] ]	
Urban land	   75	  Not rated	l I	  Not rated	1	  Not rated	
010011 10110	'		i		i		i
Udorthents, clayey	j	İ	j	İ	İ		j
substratum, hard			ļ	ļ			[
bedrock >5 feet	20	Not rated	ļ	Not rated		Not rated	!
Us:	!	] ]				İ	-
Urban land	l l 60	  Not rated	 	  Not rated		  Not rated	-
orban rana	00	 	ľ	l	l		1
Udorthents, smoothed	40	Not rated	İ	Not rated	İ	Not rated	i
	İ	ĺ	İ	İ	İ		İ
VtC3:			ļ		ļ		ļ
Vertrees	60	Not limited		Not limited		Somewhat limited	0.04
		<u> </u> 	l i	 		Slope	10.04
Urban land	l l 25	  Not rated	! !	  Not rated	ł	  Not rated	
			i		i		i
ZuB:	j	1	j	İ	İ		j
Zanesville	65	Somewhat limited	ļ	Somewhat limited		Somewhat limited	[
	ļ	Depth to	0.08	Depth to	0.08	Depth to	0.43
		saturated zone		saturated zone		saturated zone	
Urban land	   25	  Not rated	l I	  Not rated		  Not rated	-
orban rand	23	l	! !	HOC 14064		l	-

### Table 12.-Wildlife Habitat

(See text for definitions of terms used in this table. Absence of an entry indicates that no rating is applicable. Map units that have Urban land as a major component were not rated and are not included in this table)

	<u> </u>	Pote		or habit	at eleme	nts		:		bitat for
Map symbol	Grain		Wild					Open-	Wood-	Wetland
and soil name	and	Grasses		Hard-	Conif-	!	Shallow	!	land	wild-
	seed	and	ceous	wood	erous	plants	water	wild-	wild-	life
	crops	legumes	plants	trees	plants	<u> </u>	areas	life	life	
BaB:	 		 	 			 	 		
Baxter	l Good	Good	l Good	Good	Fair	Poor	  Very	  Good	Good	Very
Darcel							poor		Good	poor
BaC:	 		 				 	 		
Baxter	Fair	Good	Good	Good	Fair	Very	Very	Good	Good	Very
						poor	poor			poor
BaD:	 		! 	 			 	! 		
Baxter	Poor	Fair	Good	Good	Fair	Very	Very	Fair	Good	Very
	į	į	į	į	į	poor	poor	į	į	poor
BaE:	i i		 				 	! 		
Baxter	Very	Fair	Good	Good	Fair	Very	Very	Fair	Good	Very
	poor					poor	poor			poor
BbC3:	İ		 				 	 		
Baxter	Fair	Good	Good	Good	Fair	Very	Very	Good	Good	Very
						poor	poor			poor
BbD3:	¦		! 				! 	! 		
Baxter	Poor	Fair	Good	Good	Fair	Very	Very	Fair	Good	Very
						poor	poor			poor
laB:	 		! 				 	! 		
Caneyville	Fair	Good	Good	Good	Fair	Poor	Very	Good	Good	Very
							poor			poor
CaC:	¦		! 				! 	! 		
Caneyville	Fair	Good	Good	Good	Fair	Very	Very	Good	Good	Very
						poor	poor			poor
CaC3:	! 		 				 	 		
Caneyville	Fair	Good	Good	Fair	Fair	Very	Very	Good	Good	Very
						poor	poor			poor
CnD:	! 		 				 	 		
Caneyville	Fair	Good	Good	Fair	Fair	Very	Very	Good	Good	Very
						poor	poor			poor
Rock outcrop.	 		! 	 			 	! 		
	ĺ	İ	ĺ				İ	ĺ		
Carourillo	170~~	  Pai=	l Cood	  Pai∽	  Pain	170	17027	  Pai∽	Cood	170222
Caneyville	very   poor	Fair	Good	Fair	Fair	Very   poor	Very   poor	Fair	Good	Very   poor
	10001		! 			10001	1001	! 	i	10001
Rock outcrop.	į	İ	İ	İ	İ	İ	j I	ĺ		
CrB:	 		 				 	 		
Crider	Good	Good	Good	Good	Fair	Poor	Very	Good	Good	Very
	į	İ	ĺ	İ	İ	İ	poor	ĺ	İ	poor
CrC:	 		 				 	 		
Crider	Fair	Good	Good	Good	Fair	Very	Very	Good	Good	Very
	i	i			İ	poor	poor		1	poor
	i	i	i	i	i	i - '	i	i	i	i

Table 12.-Wildlife Habitat-Continued

Potential for habitat elements   Potential as habitat for-										
Man gembal		ı		I Habit	I ereme	l I		:		
Map symbol	Grain		Wild	!				Open-	Wood-	Wetland
and soil name	and	Grasses	!	Hard-	Conif-	Wetland		!	land	wild-
	seed	and	ceous	wood	erous	plants	water	wild-	wild-	life
	crops	legumes	plants	trees	plants		areas	life	life	
DAM.	İ	İ	İ	İ	İ	İ	İ	İ	İ	
Dam, large	İ	İ	İ	İ	İ	İ	İ	İ	İ	į
	i	i	i	i	i	i	i	i	i	
Du:	i	i	i	i	i	i		i	i	+
Dunning	170277	Poor	Poor	Poor	Poor	Good	Good	Poor	Poor	Good
Duming		FOOL	1	1	1	1 0000	i Good	1	1 - 001	i Good
	poor	!	!	!	!	!		!	!	
_1 _	!	!	!	!	!	!		!	!	
EkB:	ļ <u>.</u>				!					
Elk	Good	Good	Good	Good	Fair	Poor	Very	Good	Good	Very
							poor			poor
EpB:	ĺ		l	ĺ	l			l	İ	
Epley	Good	Good	Good	Good	Fair	Poor	Poor	Good	Good	Poor
	i	i	i	i	i	i		i	i	
FeB, FeC:	i	i	i	i	i	i	i	i	i	i
Fredonia	  Fair	Good	Good	Good	  Fair	Poor	Very	Good	Good	Very
riedollia	Fall	JGOOG	i Good	i Good	Fall	IFOOL	-	i Good	i Good	-
	!	!	!	!	!	!	poor	!	!	poor
	ļ <u>.</u>				!	ļ				
Vertrees	Good	Good	Good	Good	Fair	Poor	Very	Good	Good	Very
	ļ	ļ	ļ	ļ	ļ		poor	ļ	ļ	poor
FrC, FrD:										
Frondorf	Fair	Good	Good	Good	Fair	Very	Very	Good	Good	Very
	İ	İ	İ	İ	İ	poor	poor	İ	İ	poor
	i	i	i	i	i			i	i	
Gr:	i	i	i	i	i	i		i	i	1
Grigsby	Good	Good	Good	Good	Good	Poor	Very	Good	Good	Very
GI IGSDY	1	Jugoda	l GOOG	1 3000	l GOOG	1 001	-	l GOOG	l Good	-
	!	!	!	!	!	!	poor	!	!	poor
	!	!	!	!	!	!		!	!	
HaB:	ļ <u>.</u>				!					
Hammack	Good	Good	Good	Good	Fair	Poor	Very	Good	Good	Very
							poor			poor
	1								1	
La:	ĺ		l	ĺ	l			l	İ	
Lawrence	Fair	Good	Good	Good	Poor	Fair	Fair	Good	Good	Fair
	i	i	i	i	i	i		i	i	
Ld:	i	i	i	i	i	i	i	i	i	i
Lindside	Good	Good	Good	Good	  Fair	Poor	Poor	Good	Good	Poor
HIHABIAC	1 3000	10000	i dood	1 3000	I	1 001	1 001	i dood	1 3000	1 001
We -	!	!	!	!	!	1		!	!	
Me:	!_	!	!	!				!_	!_	
Melvin	Poor	Fair	Fair	Fair	Very	Good	Good	Poor	Poor	Good
	ļ	ļ	ļ	ļ	poor	ļ		ļ	ļ	
	ļ		ļ	ļ	ļ	ļ		ļ	ļ	
Ne:										
Newark	Poor	Fair	Fair	Fair	Poor	Fair	Fair	Fair	Fair	Fair
	ĺ		l	ĺ	l			l	İ	
Nf:	İ	İ	İ	İ	İ	İ	İ	İ	İ	į
Newark	Poor	Fair	Fair	Fair	Poor	Good	Fair	Fair	Fair	Good
	i	i	i	i	i	i		i	i	
NhA:	i	i	i	i	i	i		i	i	+
Nicholson	l land	Cood	l  Good	l l	l I Doom	l Doom	l Doom	l  Good	  Good	Doom
MICHOIDOIL	1 3000	Good	i good	Good	Poor	Poor	Poor	i good	1 3000	Poor
37- D	!			!		!			!	
NhB:	ļ				!	ļ	ļ			
Nicholson	Good	Good	Good	Good	Poor	Poor	Very	Good	Good	Very
							poor		1	poor
	1			1					1	
NhC:	İ	İ	İ	İ	İ	İ	İ	İ	İ	
Nicholson	Fair	Good	Good	Good	Poor	Very	Very	Good	Good	Very
	i	i	i	i	i	poor	poor	i	i	poor
	i	i	i	i	i			i	i	
	ı	ı	ı	ı	ı	ı	1	ı	ı	ı

Table 12.-Wildlife Habitat-Continued

	I	Pot	ential fo	or habit	at eleme	nts		Potenti	al as hai	bitat for
Map symbol	Grain		Wild	 			l I	Open-	Wood-	Wetland
and soil name	and	Grasses	!	Hard-	Conif-	Wetland	Shallow		land	wild-
	seed	and	ceous	wood	erous	plants	water	wild-	wild-	life
	crops	legumes	!	trees	plants	1	areas	life	life	İ
	i	İ	i	i	i	i	İ	i		İ
No:	i	i	i	i	i	i	i	i	i	i
Nolin	Good	Good	Good	Good	Fair	Poor	Very	Good	Good	Very
	İ	İ	İ	İ	İ	İ	poor	İ	İ	poor
	İ	İ	İ	İ	İ	İ	į	İ	İ	į
Np:			I	I			ĺ			ĺ
Nolin	Good	Good	Good	Fair	Poor	Poor	Very	Good	Good	Very
							poor			poor
OtA:	ļ	ļ	!	!	ļ	!	ļ	ļ	ļ	ļ
Otwood	Poor	Fair	Fair	Fair	Poor	Poor	Very	Fair	Good	Very
	ļ	ļ	ļ	ļ	ļ	!	poor	ļ	ļ	poor
	ļ	ļ	ļ	ļ	ļ	!	ļ	ļ	ļ	!
OtB:	! .	! .	! .	!	ļ		!	! .	ļ	!
Otwood	Fair	Fair	Fair	Fair	Poor	Fair	Poor	Fair	Good	Poor
_	ļ	ļ	!	!	ļ	!	ļ	!	ļ	!
PbA:					<u> </u> .	!_				
Pembroke	Good	Good	Good	Good	Fair	Poor	Very	Good	Good	Very
	!	!	!	!		!	poor	!	!	poor
P	!	!	!	!	!	!	!	!	!	!
Pm.	!	ļ	!	!	!	!	!	!	!	!
Pits, loamy,	1	1			1	-	 	ļ	1	 
frequently flooded	1	1			1	-	 	ļ	1	 
Pa	1	1	!	!	1	1	!	!	1	!
Pq. Pits, quarry	1	1	<b>!</b>	<u> </u>	-	1	<u> </u>	<b>!</b>	1	<u> </u>
Fics, quality	1	1	<b>!</b>	<u> </u>	-	1	<u> </u>	<b>!</b>	1	<u> </u>
RaF:	ł	1	ł	¦	ł	1	ł	ł	ŀ	¦
Ramsey	  Verv	Poor	Poor	  Very	Very	Very	  Very	  Very	Poor	  Very
rampo <sub>j</sub>	poor	1	1	poor	poor	poor	poor	poor	1	poor
		i	i	1					i	
Frondorf	Very	Fair	Good	Fair	Fair	Very	Very	Poor	Good	Very
	poor	İ	i	i	i	poor	poor	i		poor
	i -	i	i	i	i	i -	i <sup>-</sup>	i	i	i <sup>-</sup>
Ro:	i	i	i	i	i	i	i	i	i	i
Robertsville	Poor	Poor	Fair	Fair	Fair	Good	Good	Poor	Fair	Good
	İ	İ	İ	İ	İ	İ	İ	İ	İ	İ
RxF:	İ	İ	İ	İ	İ	İ	İ	İ	İ	İ
Rock outcrop.										
Caneyville	Very	Fair	Good	Fair	Fair	Very	Very	Fair	Good	Very
	poor	l	ļ	Į.	ļ	poor	poor		l	poor
	!		!	!		!	ļ	ļ		!
SaA:	!	ļ	!	! _	ļ	ļ	!	ļ _	ļ	!
Sadler	Good	Good	Good	Good	Poor	Poor	Poor	Good	Good	Poor
	!	!	!	!		!	!	!	!	
SaB:							 			 
Sadler	Good	Good	Good	Good	Poor	Poor	Very	Good	Good	Very
	1	1			1	-	poor	ļ	1	poor
VrC3:	1	1	!	!	1	1	!	!	1	!
Vertrees	  Pair	  Good	l  Good	  Good	  Fair	  Very	  Verv	  Good	  Good	  Very
AGT CT 660	1.077	3000	300a 	<del>3</del> 000	1.077	Very   poor	Very   poor	l 3000		Very   poor
			¦			5001	2001	ľ		1001
W.				İ		1	İ	i		l
Water	i		i	i		i	i	i		i
	i	i	i	i	İ	i	İ	İ	i	i
WeB:	i	i	i	i	İ	i	İ	İ	i	i
Wellston	Good	Good	Good	Good	Fair	Poor	Very	Good	Good	Very
	İ	İ	İ	İ	İ	i	poor	İ	İ	poor
	İ	į	İ	İ	İ	İ	j	İ	į	İ
	-	-	-	-	-	-	-	-	-	-

Table 12.-Wildlife Habitat-Continued

	l	Pote	ential fo	or habit	at eleme	nts		Potenti	al as ha	bitat for
Map symbol	Grain	I	Wild	1		1		Open-	Wood-	Wetland
and soil name	and	Grasses	herba-	Hard-	Conif-	Wetland	Shallow	land	land	wild-
	seed	and	ceous	wood	erous	plants	water	wild-	wild-	life
	crops	legumes	plants	trees	plants	L	areas	life	life	
WeC2: Wellston	    Fair 	    Good 	    Good 	    Good 	    Fair 	    Very   poor	  Very   poor	    Good 	    Good 	    Very   poor
ZaB: Zanesville	    Good 	    Good 	    Good 	    Good 	    Poor 	  Poor 	  Very   poor	    Good 	    Good 	  Very   poor
ZaC2: Zanesville	  Fair 	  Good 	  Good 	  Good 	  Poor 	  Very   poor	  Very   poor	  Good 	  Good 	  Very   poor

Table 13.—Building Site Development, Part I

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table. See table 14, part I, for ratings for map units that have Urban land as a major component)

Map symbol and soil name	Pct. of map	basements	ut	Dwellings with basements		Small commercial   buildings		
	unit 	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value	
BaB: Baxter	     90 	  Somewhat limited  Shrink-swell	      0.50	  Somewhat limited   Shrink-swell	      0.50	  Somewhat limited  Shrink-swell	0.50	
BaC: Baxter	     85   	  Somewhat limited   Shrink-swell   Slope	    0.50  0.04	  Somewhat limited   Shrink-swell   Slope	    0.50  0.04	   Very limited   Slope   Shrink-swell	    1.00  0.50	
BaD: Baxter	     85   	  Very limited   Slope   Shrink-swell	    1.00  0.50	  Very limited   Slope   Shrink-swell	    1.00  0.50	   Very limited   Slope   Shrink-swell	    1.00  0.50	
BaE: Baxter	   80   	  Very limited   Slope   Shrink-swell	    1.00  0.50	  Very limited   Slope   Shrink-swell	    1.00  0.50	  Very limited   Slope   Shrink-swell	    1.00  0.50	
BbC3: Baxter	     85   	  Somewhat limited   Shrink-swell   Slope	    0.50  0.04	  Somewhat limited   Shrink-swell   Slope	    0.50  0.04	   Very limited   Slope   Shrink-swell	    1.00  0.50	
BbD3: Baxter	     85   	  Very limited   Slope   Shrink-swell	    1.00  0.50	  Very limited   Slope   Shrink-swell	    1.00  0.50	  Very limited   Slope   Shrink-swell	    1.00  0.50	
CaB: Caneyville	     85     	  Somewhat limited   Shrink-swell   Depth to hard   bedrock	    1.00  0.71	  Very limited   Depth to hard   bedrock   Shrink-swell	    1.00    1.00	   Very limited   Shrink-swell   Depth to hard   bedrock	  1.00  0.71	
CaC, CaC3: Caneyville	   85       	Somewhat limited   Shrink-swell   Depth to hard   bedrock   Slope	  1.00  0.71    0.04	  Very limited   Depth to hard   bedrock   Shrink-swell   Slope	  1.00    1.00  0.04	   Very limited   Slope   Shrink-swell   Depth to hard   bedrock	  1.00  1.00  0.71	
CnD: Caneyville	   65       	Somewhat limited   Shrink-swell   Slope   Depth to hard   bedrock	  1.00  0.84  0.71	  Very limited   Depth to hard   bedrock   Shrink-swell   Slope	  1.00    1.00  0.84	Very limited   Slope   Shrink-swell   Depth to hard   bedrock	  1.00  1.00  0.71	
Rock outcrop	   25 	  Not rated 	   	  Not rated 	   	  Not rated 		

Table 13.—Building Site Development, Part I—Continued

Map symbol and soil name	Pct. of map	   Dwellings witho   basements	ut	   Dwellings with   basements		   Small commercial   buildings		
	unit	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value	
CnF: Caneyville	     65       	   Very limited   Slope   Shrink-swell   Depth to hard   bedrock	    1.00  1.00  0.71	   Very limited   Slope   Depth to hard   bedrock   Shrink-swell	    1.00  1.00 	   Very limited   Slope   Shrink-swell   Depth to hard   bedrock	  1.00  1.00  0.71	
Rock outcrop	   25 	  Not rated 	   	  Not rated 	   	  Not rated 		
CrB: Crider	   90 	  Not limited 	   	  Somewhat limited   Shrink-swell	    0.50	  Not limited 		
CrC: Crider	     85   	  Somewhat limited   Slope 	      0.04	  Somewhat limited   Shrink-swell   Slope	      0.50  0.04	  Very limited   Slope 	1.00	
DAM: Dam, large	  100 	    Not rated 	     	    Not rated 	   	    Not rated 	   	
Du: Dunning	   85     	  Very limited   Ponding   Depth to   saturated zone   Shrink-swell	  1.00  1.00    0.50	  Very limited   Ponding   Depth to   saturated zone   Shrink-swell	  1.00  1.00    0.50	  Very limited   Ponding   Depth to   saturated zone   Shrink-swell	  1.00  1.00    0.50	
EkB: Elk	   80 	  Very limited   Flooding	1.00	  Very limited   Flooding	      1.00	  Very limited   Flooding	1.00	
EpB: Epley	     85     	  Somewhat limited   Depth to   saturated zone   Shrink-swell	    0.88    0.50	  Very limited   Depth to   saturated zone   Shrink-swell	    1.00    0.50	  Somewhat limited   Depth to   saturated zone   Shrink-swell	0.88	
FeB: Fredonia	     50   	  Somewhat limited   Shrink-swell   Depth to hard   bedrock	    0.50  0.03	  Very limited   Depth to hard   bedrock   Shrink-swell	    1.00    0.50	  Somewhat limited   Shrink-swell   Depth to hard   bedrock	0.50	
Vertrees	   35 	  Somewhat limited   Shrink-swell	0.50	  Somewhat limited   Shrink-swell	0.50	  Somewhat limited   Shrink-swell	0.50	
FeC: Fredonia	     50     	  Somewhat limited   Shrink-swell   Slope   Depth to hard   bedrock	    0.50  0.04  0.03	   Very limited   Depth to hard   bedrock   Shrink-swell   Slope	    1.00    0.50  0.04	  Very limited   Slope   Shrink-swell   Depth to hard   bedrock	  1.00  0.50  0.03	
Vertrees	   30   	  Somewhat limited   Shrink-swell   Slope 	    0.50  0.04	  Somewhat limited   Shrink-swell   Slope 	    0.50  0.04	  Very limited   Slope   Shrink-swell 	  1.00  0.50	

Table 13.—Building Site Development, Part I-Continued

Map symbol and soil name	Pct. of	Dwellings witho basements	ut	Dwellings with basements		Small commercia   buildings	1
	unit	Rating class and limiting features	Value	Rating class and   limiting features	Value	Rating class and   limiting features	Value
FrC: Frondorf	     85   	  Somewhat limited   Slope   	      0.04 	  Somewhat limited   Depth to soft   bedrock   Slope	    0.79    0.04	  Very limited   Slope 	1.00
FrD: Frondorf	   85     	  Very limited   Slope   	    1.00   	  Very limited   Slope   Depth to soft   bedrock	    1.00  0.79	  Very limited   Slope 	1.00
Gr: Grigsby	   90     	  Very limited   Flooding 	    1.00   	  Very limited   Flooding   Depth to   saturated zone	    1.00  0.15 	  Very limited   Flooding 	1.00
HaB: Hammack	   85 	  Not limited   	     	  Somewhat limited   Shrink-swell	    0.50	  Not limited   	     
La: Lawrence	   90   	  Very limited   Flooding   Depth to   saturated zone	    1.00  1.00	  Very limited   Flooding   Depth to   saturated zone	    1.00  1.00	  Very limited   Flooding   Depth to   saturated zone	1.00
Ld: Lindside	     90   	  Very limited   Flooding   Depth to   saturated zone	    1.00  0.88	  Very limited   Flooding   Depth to   saturated zone	    1.00  1.00	  Very limited   Flooding   Depth to   saturated zone	1.00
Me: Melvin	   80   	  Very limited   Flooding   Depth to   saturated zone	    1.00  1.00	  Very limited   Flooding   Depth to   saturated zone	    1.00  1.00	  Very limited   Flooding   Depth to   saturated zone	1.00
Ne: Newark	   90     	  Very limited   Flooding   Depth to   saturated zone	    1.00  1.00	  Very limited   Flooding   Depth to   saturated zone	    1.00  1.00	  Very limited   Flooding   Depth to   saturated zone	1.00
Nf: Newark	   90   	  Very limited   Ponding   Depth to   saturated zone	    1.00  1.00	  Very limited   Ponding   Depth to   saturated zone	    1.00  1.00	  Very limited   Ponding   Depth to   saturated zone	1.00
NhA, NhB: Nicholson	   80       	  Somewhat limited   Depth to   saturated zone	    0.88   	  Very limited   Depth to   saturated zone   Shrink-swell	    1.00    0.50	  Somewhat limited   Depth to   saturated zone	0.88

Table 13.—Building Site Development, Part I—Continued

Map symbol and soil name	Pct. of	Dwellings witho basements	ut	Dwellings with basements		Small commercia   buildings	al
and soff name	map  unit 	Rating class and limiting features	Value	Rating class and   limiting features	Value	Rating class and limiting features	Value
NhC: Nicholson	   85       	  Somewhat limited   Depth to   saturated zone   Slope	      0.88    0.04	  Very limited   Depth to   saturated zone   Shrink-swell   Slope	    1.00    0.50  0.04	Very limited Slope Depth to saturated zone	    1.00  0.88
No: Nolin	     90 	  Very limited   Flooding	    1.00	  Very limited   Flooding	    1.00	  Very limited   Flooding	1.00
Np: Nolin	     90 	  Very limited   Ponding	    1.00	  Very limited   Ponding	    1.00	  Very limited   Ponding	1.00
OtA, OtB: Otwood	   90       	Very limited Flooding Depth to saturated zone Shrink-swell	  1.00  0.77    0.50	  Very limited   Flooding   Depth to   saturated zone   Shrink-swell	  1.00  1.00    0.50	Very limited Flooding Depth to saturated zone Shrink-swell	1.00
PbA: Pembroke	     90 	  Somewhat limited   Shrink-swell	      0.50	  Somewhat limited   Shrink-swell	      0.50	    Somewhat limited   Shrink-swell	0.50
Pm: Pits, loamy, frequently flooded-	       95 	    Not rated	     	      Not rated	     	    Not rated 	     
Pq: Pits, quarry	   90 	  Not rated 	   	  Not rated 	   	  Not rated 	
RaF: Ramsey	   75   	  Very limited   Slope   Depth to hard   bedrock	    1.00  1.00	  Very limited   Slope   Depth to hard   bedrock	    1.00  1.00	  Very limited   Slope   Depth to hard   bedrock	1.00
Frondorf	   20     	  Very limited   Slope   	    1.00   	  Very limited   Slope   Depth to soft   bedrock	    1.00  0.79 	  Very limited   Slope   	1.00
Ro: Robertsville	   90       	   Very limited   Ponding   Flooding   Depth to   saturated zone	  1.00  1.00  1.00	  Very limited   Ponding   Flooding   Depth to   saturated zone	  1.00  1.00  1.00	   Very limited   Ponding   Flooding   Depth to   saturated zone	  1.00  1.00  1.00
RxF: Rock outcrop	     55	Not rated	 	    Not rated	 	    Not rated	
Caneyville	   33       	   Very limited   Slope   Depth to hard   bedrock   Shrink-swell	  1.00  0.71    0.50	   Very limited   Slope   Depth to hard   bedrock   Shrink-swell	  1.00  1.00    0.50	   Very limited   Slope   Depth to hard   bedrock   Shrink-swell	  1.00  0.71    0.50

Table 13.—Building Site Development, Part I—Continued

Map symbol and soil name	Pct. of map	Dwellings witho basements	ut	   Dwellings with   basements		   Small commercial   buildings 		
	unit	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value	
SaA, SaB: Sadler	     85   	  Somewhat limited   Depth to   saturated zone	      0.77 	  Very limited   Depth to   saturated zone	      1.00	  Somewhat limited   Depth to   saturated zone	0.77	
VrC3: Vertrees	     85   	  Somewhat limited   Shrink-swell   Slope	    0.50  0.04	  Somewhat limited   Shrink-swell   Slope	    0.50  0.04		1.00	
W: Water	100	  Not rated	 	  Not rated	 	  Not rated		
WeB: Wellston	     90   	  Not limited 	       	  Somewhat limited   Depth to hard   bedrock	      0.77	  Not limited 		
WeC2: Wellston	     85   	  Somewhat limited   Slope 	      0.04 	  Somewhat limited   Depth to hard   bedrock   Slope	    0.77    0.04	  Very limited   Slope 	1.00	
ZaB: Zanesville	   85       	  Somewhat limited   Depth to   saturated zone	    0.77   	  Very limited   Depth to   saturated zone   Depth to hard   bedrock	  1.00    0.05	  Somewhat limited   Depth to   saturated zone	0.77	
ZaC2: Zanesville	   80         	  Somewhat limited   Depth to   saturated zone   Slope	    0.77    0.04 	saturated zone	  1.00    0.05    0.04	Depth to	  1.00  0.77 	

## Table 13.-Building Site Development, Part II

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table. See table 14, part II, for ratings for map units that have Urban land as a major component)

Map symbol	Pct. of	Local roads an	đ	   Shallow excavati 	ons	Lawns and landscaping		
and soil name	map  unit 	   Rating class and   limiting features	Value	   Rating class and   limiting features	Value	   Rating class and   limiting features	Value	
BaB: Baxter	     90   	     Low strength   Shrink-swell	      1.00  0.50	    Very limited   Cutbanks cave   Too clayey 	      1.00  0.50	  Somewhat limited   Gravel content   Content of large   stones	0.11	
BaC: Baxter	   85       	   Very limited   Low strength   Shrink-swell   Slope	  1.00  0.50  0.04	  Very limited   Cutbanks cave   Too clayey   Slope	  1.00  0.50  0.04	Somewhat limited   Gravel content   Slope   Content of large   stones	0.11	
BaD: Baxter	   85       	  Very limited   Slope   Low strength   Shrink-swell	  1.00  1.00  0.50	  Very limited   Cutbanks cave   Slope   Too clayey	  1.00  1.00  0.50	  Very limited   Slope   Gravel content   Content of large   stones	  1.00  0.11  0.01	
BaE: Baxter	   80       	   Very limited   Slope   Low strength   Shrink-swell	  1.00  1.00  0.50	   Very limited   Slope   Cutbanks cave   Too clayey	  1.00  1.00  0.50	Very limited   Slope   Gravel content   Content of large   stones	  1.00  0.11  0.01	
BbC3: Baxter	     85       	  Very limited   Low strength   Shrink-swell   Slope	    1.00  0.50  0.04	  Very limited   Cutbanks cave   Too clayey   Slope 	    1.00  0.50  0.04	  Somewhat limited   Gravel content   Slope   Content of large   stones	    0.22  0.04  0.01	
BbD3: Baxter	   85       	  Very limited   Slope   Low strength   Shrink-swell	  1.00  1.00  0.50	  Very limited   Cutbanks cave   Slope   Too clayey	  1.00  1.00  0.50	  Very limited   Slope   Gravel content   Content of large   stones	  1.00  0.22  0.01	
CaB: Caneyville	   85         	  Very limited   Low strength   Shrink-swell   Depth to hard   bedrock	    1.00  1.00  0.71 	  Very limited   Depth to hard   bedrock   Too clayey   Cutbanks cave	    1.00    0.50  0.10	  Somewhat limited   Depth to bedrock   Droughty 	    0.71  0.14 	

Table 13.—Building Site Development, Part II—Continued

Map symbol and soil name	  Pct.   of  map	   Local roads and   streets	d	   Shallow excavati   	ons	Lawns and landscaping		
		Rating class and limiting features	Value	Rating class and limiting features		Rating class and limiting features	Value	
CaC: Caneyville	   85         	Very limited Low strength Shrink-swell Depth to hard bedrock Slope	    1.00  1.00  0.71    0.04	bedrock Too clayey Cutbanks cave	    1.00    0.50  0.10  0.04	Droughty	    0.71  0.14  0.04	
CaC3: Caneyville	   85         	   Very limited   Low strength   Shrink-swell   Depth to hard   bedrock   Slope	  1.00  1.00  0.71 	bedrock   Too clayey   Cutbanks cave	  1.00    0.50  0.10  0.04	Depth to bedrock Droughty	  1.00  0.71  0.23  0.04	
CnD: Caneyville	   65         	   Very limited   Low strength   Shrink-swell   Slope   Depth to hard   bedrock		Slope	  1.00    0.84  0.50  0.10	Depth to bedrock	  0.84  0.71  0.14	
Rock outcrop	25	  Not rated	 	  Not rated		  Not rated		
CnF: Caneyville	   65       	  Very limited   Slope   Low strength   Shrink-swell   Depth to hard   bedrock	    1.00  1.00  1.00  0.71	bedrock Slope	    1.00    1.00  0.50  0.10	Depth to bedrock	  1.00  0.71  0.14	
Rock outcrop	   25	  Not rated 	   	  Not rated 		  Not rated 		
Crider	   90   	  Very limited   Low strength	    1.00 	  Somewhat limited   Too clayey   Cutbanks cave	    0.12  0.10	  Not limited   		
CrC: Crider	   85       	   Very limited   Low strength   Slope	    1.00  0.04 	  Somewhat limited   Too clayey   Cutbanks cave   Slope	  0.12  0.10  0.04	  Somewhat limited   Slope 	0.04	
DAM: Dam, large	100	Not rated	<u> </u>	  Not rated	<u> </u>	  Not rated	į Į	
Du: Dunning	   85   85       	   Very limited   Ponding   Depth to   saturated zone   Low strength   Shrink-swell	    1.00  1.00    1.00  0.50	  Very limited   Ponding   Depth to   saturated zone   Too clayey   Cutbanks cave	  1.00  1.00    0.50  0.10	  Very limited   Ponding   Depth to   saturated zone	    1.00  1.00 	

Table 13.—Building Site Development, Part II—Continued

Map symbol and soil name	Pct. of map	   Local roads and   streets	d	   Shallow excavati   	ons	Lawns and landscaping		
		Rating class and limiting features	Value 	Rating class and limiting features	Value	Rating class and limiting features	Value	
EkB: Elk	     80   	   Very limited   Low strength   Flooding	      1.00  0.40	    Somewhat limited   Cutbanks cave 	      0.10 	  Not limited   	       	
EpB: Epley	   85       	Very limited Low strength Depth to saturated zone Shrink-swell	  1.00  0.56    0.50	  Very limited   Depth to   saturated zone   Too clayey   Cutbanks cave	  1.00    0.98  0.10	  Somewhat limited   Depth to   saturated zone	    0.56   	
FeB: Fredonia	   50     	Very limited Low strength Shrink-swell Depth to hard bedrock	  1.00  0.50  0.03	  Very limited   Depth to hard   bedrock   Too clayey   Cutbanks cave	  1.00    0.50  0.10	   Somewhat limited   Depth to bedrock   	    0.03   	
Vertrees	   35   	   Very limited   Low strength   Shrink-swell	    1.00  0.50	  Somewhat limited   Too clayey   Cutbanks cave	    0.98  0.10	  Not limited 	     	
FeC: Fredonia	   50       	   Very limited   Low strength   Shrink-swell   Slope   Depth to hard   bedrock	    1.00  0.50  0.04  0.03	!	    1.00    0.50  0.10  0.04	  Somewhat limited   Slope   Depth to bedrock 	0.04	
Vertrees	   30     	   Very limited   Low strength   Shrink-swell   Slope	  1.00  0.50  0.04	  Somewhat limited   Too clayey   Cutbanks cave   Slope	  0.98  0.10  0.04	  Somewhat limited   Slope   	0.04	
FrC: Frondorf	   85         	Somewhat limited   Slope 	    0.04   	Somewhat limited   Depth to soft   bedrock   Cutbanks cave   Slope	    0.79    0.10  0.04	  Somewhat limited   Depth to bedrock   Droughty   Slope	  0.80  0.10  0.04	
FrD: Frondorf	   85       	  Very limited   Slope 	    1.00   	  Very limited   Slope   Depth to soft   bedrock   Cutbanks cave	  1.00  0.79    0.10	  Very limited   Slope   Depth to bedrock   Droughty	  1.00  0.80  0.10	
Gr: Grigsby	   90         	Very limited Flooding	    1.00     	  Somewhat limited   Flooding   Depth to   saturated zone   Cutbanks cave	  0.80  0.15    0.10	  Very limited   Flooding 	    1.00     	

Table 13.—Building Site Development, Part II—Continued

Map symbol and soil name	Pct. of	Local roads an	d.	   Shallow excavati 	ons	   Lawns and landscaping   		
	unit	Rating class and limiting features	Value	Rating class and limiting features	!	Rating class and limiting features	Value	
HaB: Hammack	     85   	    Very limited   Low strength	      1.00	  Very limited   Cutbanks cave   Too clayey	      1.00  0.50	  Not limited   		
La: Lawrence	   90       	Very limited Low strength Depth to saturated zone Flooding	  1.00  0.94    0.40	  Very limited   Depth to   saturated zone   Cutbanks cave	  1.00    0.10	  Somewhat limited   Depth to   saturated zone	  0.94   	
Ld: Lindside	   90       	  Very limited   Flooding   Low strength   Depth to   saturated zone	  1.00  1.00  0.56	  Very limited   Depth to   saturated zone   Flooding   Cutbanks cave	  1.00    0.80  0.10	  Very limited   Flooding   Depth to   saturated zone	  1.00  0.56	
Me: Melvin	   80       	  Very limited   Depth to   saturated zone   Flooding   Low strength	  1.00    1.00  1.00	  Very limited   Depth to   saturated zone   Flooding   Cutbanks cave	  1.00    0.80  0.10	  Very limited   Flooding   Depth to   saturated zone	1.00	
Ne: Newark	   90       	  Very limited   Flooding   Low strength   Depth to   saturated zone	  1.00  1.00  0.94	saturated zone	  1.00    0.80  0.10	  Very limited   Flooding   Depth to   saturated zone	  1.00  0.94 	
Nf: Newark	   90       	   Very limited   Ponding   Low strength   Depth to   saturated zone	  1.00  1.00  0.94	!	  1.00  1.00    0.10	   Very limited   Ponding   Depth to   saturated zone	  1.00  0.94	
NhA, NhB: Nicholson	   80       	  Very limited   Low strength   Depth to   saturated zone	    1.00  0.56 	  Very limited   Depth to   saturated zone   Too clayey   Cutbanks cave	  1.00    0.28  0.10	  Somewhat limited   Depth to   saturated zone	  0.56   	
NhC: Nicholson	   85         	  Very limited   Low strength   Depth to   saturated zone   Slope	  1.00  0.56    0.04	  Very limited   Depth to   saturated zone   Too clayey   Cutbanks cave   Slope	  1.00    0.28  0.10  0.04	  Somewhat limited   Depth to   saturated zone   Slope	  0.56    0.04	
No: Nolin	   90     	  Very limited   Flooding   Low strength	    1.00  1.00	  Somewhat limited   Flooding   Cutbanks cave	    0.80  0.10	  Very limited   Flooding 	1.00	

Table 13.—Building Site Development, Part II—Continued

Map symbol and soil name	Pct. of	Local roads and streets	đ	   Shallow excavati   	ons	Lawns and landsca	Lawns and landscaping		
	! -	Rating class and limiting features	Value	Rating class and limiting features		Rating class and limiting features	Value		
Np: Nolin	90	   Very limited   Ponding   Low strength	      1.00  1.00	  Very limited   Ponding   Cutbanks cave	      1.00  0.10	  Very limited   Ponding	1.00		
OtA, OtB: Otwood	   90       	   Very limited   Low strength   Shrink-swell   Depth to   saturated zone   Flooding	  1.00  0.50  0.43 	  Very limited   Depth to   saturated zone   Cutbanks cave	  1.00    0.10	  Somewhat limited   Depth to   saturated zone	0.43		
PbA: Pembroke	90	  Very limited   Low strength   Shrink-swell	      1.00  0.50	  Somewhat limited   Too clayey   Cutbanks cave	      0.50  0.10	  Not limited 			
Pm: Pits, loamy, frequently flooded-	95	      Not rated	       	      Not rated	     	      Not rated	     		
Pq: Pits, quarry	90	    Not rated 	   	    Not rated		    Not rated	     		
RaF: Ramsey	   75       	   Very limited   Depth to hard   bedrock   Slope	  1.00    1.00	  Very limited   Depth to hard   bedrock   Slope   Cutbanks cave	  1.00    1.00  0.10	Slope Droughty	1.00		
Frondorf	20	   Very limited   Slope   Low strength	    1.00  0.22 	. –	  1.00  0.79    0.10	  Very limited   Slope   Depth to bedrock	1.00		
Ro: Robertsville	   90           	   Very limited   Ponding   Depth to   saturated zone   Flooding   Low strength	  1.00  1.00    1.00  1.00	  Very limited   Ponding   Depth to   saturated zone   Flooding   Cutbanks cave   Too clayey		  Very limited   Ponding   Depth to   saturated zone   Flooding	  1.00  1.00      0.60		
RxF: Rock outcrop	55	  Not rated		  Not rated		  Not rated			
Caneyville	   33       	   Very limited   Slope   Low strength   Depth to hard   bedrock   Shrink-swell	  1.00  1.00  0.71    0.50	   Very limited   Depth to hard   bedrock   Slope   Too clayey   Cutbanks cave	  1.00    1.00  0.50  0.10	  Very limited   Slope   Depth to bedrock   Droughty 	  1.00  0.71  0.14		

Table 13.—Building Site Development, Part II—Continued

Map symbol and soil name	Pct. of	Local roads and streets	d	   Shallow excavati 	ons	Lawns and landsca	ping
and soff name		Rating class and limiting features		Rating class and limiting features		Rating class and limiting features	Value
SaA, SaB: Sadler	   85       	   Very limited   Low strength   Depth to   saturated zone	      1.00  0.43 		      1.00    0.10	   Somewhat limited   Depth to   saturated zone	0.43
VrC3: Vertrees	   85     	  Very limited   Low strength   Shrink-swell   Slope	    1.00  0.50  0.04	Cutbanks cave	    0.50  0.10  0.04	  Somewhat limited   Slope 	0.04
W: Water	    100	    Not rated	   	    Not rated	   	  Not rated	
WeB: Wellston	     90   	  Somewhat limited   Low strength 	      0.22 	Very limited Cutbanks cave Depth to hard bedrock	    1.00  0.77	  Not limited   	
WeC2: Wellston	     85       	  Very limited   Low strength   Slope	    1.00  0.04		    1.00  0.77    0.04	  Somewhat limited   Slope 	0.04
ZaB: Zanesville	   85           	  Somewhat limited   Low strength   Depth to   saturated zone	    0.78  0.43   	   Very limited   Depth to   saturated zone   Cutbanks cave   Depth to hard   bedrock	    1.00    0.10  0.05	  Somewhat limited   Depth to   saturated zone 	0.43
ZaC2: Zanesville	   80           	Somewhat limited   Low strength   Depth to   saturated zone   Slope	  0.78  0.43    0.04	saturated zone Cutbanks cave	   1.00   0.10   0.05   0.04	   Somewhat limited   Depth to   saturated zone   Slope	0.43

Table 14.—Building Site Interpretations for Urban Areas, Part I

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table)

Map symbol and soil name	Pct. of	Dwellings without basements	ut	Dwellings with basements		Small commercia buildings	.1
	map unit	Rating class and limiting features	Value 	Rating class and limiting features	Value	Rating class and limiting features	Value
BrB: Baxter	     60 	    Somewhat limited   Shrink-swell	      0.50	  Somewhat limited   Shrink-swell	      0.50	    Somewhat limited   Shrink-swell	      0.50
Urban land	   30	  Not rated	 	  Not rated	 	  Not rated	
BrC:	<u> </u>	 	<u> </u>		}	 	1
Baxter	   55   	Somewhat limited   Shrink-swell   Slope	  0.50  0.04	Somewhat limited Shrink-swell Slope	  0.50  0.04	Very limited   Slope   Shrink-swell	1.00
Urban land	   30 	  Not rated 	   	  Not rated 	   	  Not rated 	   
BrD: Baxter	   60   	  Very limited   Slope   Shrink-swell	    1.00  0.50	  Very limited   Slope   Shrink-swell	    1.00  0.50	  Very limited   Slope   Shrink-swell	  1.00  0.50
Urban land	25	  Not rated		Not rated		  Not rated	
CoD: Caneyville	   40       	   Somewhat limited   Shrink-swell   Slope   Depth to hard   bedrock	    1.00  0.84  0.71	Very limited  Depth to hard  bedrock  Shrink-swell  Slope	  1.00    1.00  0.84	   Very limited   Slope   Shrink-swell   Depth to hard   bedrock	  1.00  1.00  0.71
Urban land	   25	  Not rated 	   	  Not rated 		  Not rated 	
Rock outcrop	20	  Not rated 		Not rated		  Not rated 	
CoE: Caneyville	   40     	Very limited Slope Shrink-swell Depth to hard bedrock	    1.00  1.00  0.71	Very limited Slope Depth to hard bedrock Shrink-swell	  1.00  1.00 	   Very limited   Slope   Shrink-swell   Depth to hard   bedrock	  1.00  1.00  0.71
Urban land	   25	  Not rated	   	  Not rated		  Not rated 	
Rock outcrop	20	  Not rated 	   	  Not rated 		  Not rated 	
CuB: Crider	     55 	    Not limited 	     	  Somewhat limited   Shrink-swell	      0.50	    Not limited 	   
Urban land	   35	  Not rated 	   	Not rated		  Not rated 	
CuC: Crider	     55 	    Somewhat limited   Slope 	      0.04 	  Somewhat limited   Shrink-swell   Slope	      0.50  0.04	    Very limited   Slope 	1.00
Urban land	   35	  Not rated	 	Not rated	 	  Not rated	

Table 14.—Building Site Interpretations for Urban Areas, Part I—Continued

Map symbol and soil name	Pct. of	Dwellings witho	ut	Dwellings with basements		Small commercia   buildings	.1
	  map  unit	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and	Value
			<del>                                     </del>		<u> </u>		1
FnB: Fredonia	   37     	Somewhat limited   Shrink-swell   Depth to hard   bedrock	    0.50  0.03	  Very limited   Depth to hard   bedrock   Shrink-swell	    1.00    0.50	  Very limited   Shrink-swell   Depth to hard   bedrock	  0.50  0.03
Vertrees	   30 	  Somewhat limited   Shrink-swell	0.50	  Somewhat limited   Shrink-swell	0.50	  Somewhat limited   Shrink-swell	0.50
Urban land	   25 	  Not rated 		  Not rated 		  Not rated 	
FnC: Fredonia	   37     	   Somewhat limited   Shrink-swell   Slope   Depth to hard   bedrock	  0.50  0.04  0.03	Very limited Depth to hard bedrock Shrink-swell Slope	  1.00    0.50  0.04	   Very limited   Slope   Shrink-swell   Depth to hard   bedrock	  1.00  0.50  0.03
Vertrees	   27   	  Somewhat limited   Shrink-swell   Slope	0.50	  Somewhat limited   Shrink-swell   Slope	    0.50  0.04	  Very limited   Slope   Shrink-swell	1.00
Urban land	25	  Not rated 		  Not rated 		  Not rated 	
FnC2: Fredonia	   37       	  Somewhat limited   Shrink-swell   Slope   Depth to hard   bedrock	  0.50  0.04  0.03	   Very limited   Depth to hard   bedrock   Shrink-swell   Slope	    1.00    0.50  0.04	  Very limited   Slope   Shrink-swell   Depth to hard   bedrock	  1.00  0.50  0.03
Vertrees	   30 	  Somewhat limited   Shrink-swell   Slope	0.50	  Somewhat limited   Shrink-swell   Slope	    0.50  0.04	  Very limited   Slope   Shrink-swell	  1.00  0.50
Urban land	25	  Not rated 		  Not rated 		  Not rated 	
PeA: Pembroke	     65 	  Somewhat limited   Shrink-swell	0.50	  Somewhat limited   Shrink-swell	0.50	  Somewhat limited   Shrink-swell	0.50
Urban land	25	  Not rated 		  Not rated 		  Not rated 	
UaC: Udorthents	     95   	Onsite   Investigation   needed		Onsite   Onsite   investigation   needed		Onsite   Investigation   needed	     
UaD: Udorthents, refuse substratum	       95   	Onsite   onsite   investigation   needed		Onsite   onsite   investigation   needed	         	Onsite investigation needed	
Ub: Urban land	     75	    Not rated		    Not rated		    Not rated	
Udorthents	22	Onsite  investigation  needed		Onsite investigation needed	     	Onsite investigation needed	

Table 14.—Building Site Interpretations for Urban Areas, Part I—Continued

Map symbol and soil name	Pct. of	Dwellings without basements	ut	Dwellings with basements		Small commercia buildings	.1
	map  unit	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Uc: Urban land	     50 	    Not rated 	     	    Not rated 	     	    Not rated 	     
Udorthents, clayey substratum, hard bedrock 0-5 feet	     30       	  Somewhat limited   Depth to hard   bedrock  Shrink-swell	      0.90    0.50	  Very limited   Depth to hard   bedrock   Shrink-swell	      1.00    0.50	  Somewhat limited   Depth to hard   bedrock   Slope   Shrink-swell	      0.90    0.50  0.50
Ud: Urban land	   75 	  Not rated 	   	  Not rated 	   	  Not rated 	
Udorthents, clayey substratum, hard bedrock >5 feet	     20   	    Somewhat limited   Shrink-swell 	      0.50 	    Somewhat limited   Shrink-swell 	      0.50 	  Somewhat limited   Slope   Shrink-swell	    0.50  0.50
Us: Urban land	60	  Not rated	<u> </u>	  Not rated	<u> </u> 	  Not rated	į Į
Udorthents, smoothed	40	  Impractical 	 	  Impractical 		  Impractical 	
VtC3: Vertrees	   60 	  Somewhat limited   Shrink-swell   Slope	    0.50  0.04	  Somewhat limited   Shrink-swell   Slope	    0.50  0.04	  Very limited   Slope   Shrink-swell	  1.00  0.50
Urban land	25	  Not rated		  Not rated 		  Not rated 	
ZuB: Zanesville	     65     	  Somewhat limited   Depth to   saturated zone 	      0.77   	  Very limited   Depth to   saturated zone   Depth to hard   bedrock	    1.00    0.05	  Somewhat limited   Depth to   saturated zone 	      0.77   
Urban land	   25 	  Not rated 	   	  Not rated 	   	  Not rated 	

Table 14.—Building Site Interpretations for Urban Areas, Part II

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table)

Map symbol and soil name	Pct.	   Local roads an   streets	d	   Shallow excavati 	ons	Lawns and landscaping		
and soll name	map	Rating class and	Value	Rating class and	Value	Rating class and	Value	
	unit	limiting features	-	limiting features	<del> </del>	limiting features	-	
BrB: Baxter	     60 	    Very limited   Low strength   Shrink-swell	    1.00  0.50	    Very limited   Cutbanks cave   Too clayey	    1.00  0.50	    Somewhat limited   Gravel content   Content of large	    0.11  0.01	
		SHITHK-SWEIT		100 Clayey   		stones		
Urban land	30	  Not rated 		  Not rated 		  Not rated 		
BrC:	i		i	 	i	 	i	
Baxter	55         	Very limited Low strength Shrink-swell Slope	  1.00  0.50  0.04	Too clayey	  1.00  0.50  0.04	Slope	  0.11  0.04  0.01	
Urban land	30	  Not rated		  Not rated 		  Not rated 		
BrD: Baxter	     60     	   Very limited   Slope   Low strength   Shrink-swell	    1.00  1.00  0.50	  Very limited   Cutbanks cave   Slope   Too clayey	  1.00  1.00  0.50	Gravel content	  1.00  0.11  0.01	
Urban land	   25	  Not rated 		  Not rated		  Not rated		
CoD: Caneyville	   40         	  Very limited   Low strength   Shrink-swell   Slope   Depth to hard   bedrock	    1.00  1.00  0.84  0.71	  Very limited   Depth to hard   bedrock   Slope   Too clayey   Cutbanks cave	    1.00    0.84  0.50  0.10	Depth to bedrock	  0.84  0.71  0.14	
Urban land	25	  Not rated		  Not rated		  Not rated		
Rock outcrop	20	  Not rated		  Not rated		  Not rated		
CoE: Caneyville	   40   40     	   Very limited   Slope   Low strength   Shrink-swell   Depth to hard   bedrock	    1.00  1.00  1.00  0.71	bedrock Slope	    1.00    1.00  0.50  0.10	Depth to bedrock	  1.00  0.71  0.14	
Urban land	25	  Not rated 		  Not rated 		  Not rated 		
Rock outcrop	20	  Not rated		  Not rated		  Not rated		

Table 14.—Building Site Interpretations for Urban Areas, Part II—Continued

Map symbol and soil name	Pct.	   Local roads and  streets	đ	   Shallow excavation 	ons	Lawns and landsca	ping
	map unit	Rating class and limiting features	Value 	Rating class and limiting features	Value	Rating class and limiting features	Value
CuB: Crider	     55 	    Very limited   Low strength	      1.00	    Somewhat limited   Too clayey   Cutbanks cave	    0.12  0.10	    Not limited 	
Urban land	   35 	  Not rated 	   	  Not rated 	   	  Not rated 	
CuC: Crider	   55   	   Very limited   Low strength   Slope	    1.00  0.04		  0.12  0.10  0.04	  Somewhat limited   Slope	    0.04 
Urban land	   35 	  Not rated 	   	  Not rated 	   	  Not rated 	
FnB: Fredonia	37   	Very limited Low strength Shrink-swell Depth to hard bedrock	  1.00  0.50  0.03	bedrock	  1.00    0.50  0.10	   Somewhat limited   Depth to bedrock	0.03
Vertrees	   30 	Very limited Low strength Shrink-swell	    1.00  0.50	  Somewhat limited   Too clayey   Cutbanks cave	    0.98  0.10	Not limited	
Urban land	   25 	  Not rated 	   	  Not rated 	   	  Not rated 	
FnC: Fredonia	   37     	Very limited Low strength Shrink-swell Slope Depth to hard bedrock	  1.00  0.50  0.04  0.03	bedrock Too clayey	  1.00    0.50  0.10  0.04	Somewhat limited   Slope   Depth to bedrock	0.04
Vertrees	   27   	Very limited Low strength Shrink-swell Slope	  1.00  0.50  0.04	Cutbanks cave	  0.98  0.10  0.04	Somewhat limited	  0.04   
Urban land	   25 	  Not rated 	   	  Not rated 	   	  Not rated 	
FnC2: Fredonia	   37   	Very limited Low strength Shrink-swell Slope Depth to hard bedrock	  1.00  0.50  0.04  0.03	  Very limited   Depth to hard   bedrock   Too clayey   Cutbanks cave   Slope	  1.00    0.50  0.10  0.04	  Somewhat limited   Slope   Depth to bedrock	  0.04  0.03 
Vertrees	   30   	Very limited Low strength Shrink-swell Slope	  1.00  0.50  0.04	  Somewhat limited   Too clayey   Cutbanks cave   Slope	  0.50  0.10  0.04	  Somewhat limited   Slope 	    0.04 
Urban land	   25 	  Not rated 	   	  Not rated 	   	  Not rated 	

Table 14.—Building Site Interpretations for Urban Areas, Part II—Continued

Map symbol and soil name	  Pct.   of	   Local roads and  streets	d	   Shallow excavation 	ons	Lawns and landscaping		
	map unit	Rating class and limiting features	Value 	Rating class and limiting features	Value 	Rating class and limiting features	Value	
UaC: Udorthents	     95   	  Onsite  investigation  needed	 	  Onsite  investigation  needed	       	    Soil test needed   		
UaD: Udorthents, refuse substratum	     95   	  Onsite  investigation  needed 	         	  Onsite  investigation  needed 	         	  Soil test needed   		
Ub: Urban land	   75	  Not rated	 	  Not rated	 	  Not rated	İ	
Udorthents	22	  Not rated 		  Not rated 		  Not rated 		
Uc: Urban land	     50	    Not rated 	     	    Not rated 	     	    Not rated 		
Udorthents, clayey substratum, hard bedrock 0-5 feet	     30 	Onsite  investigation  needed	       	Onsite  investigation  needed	       	  Soil test needed		
Ud: Urban land	     75	    Not rated	     	    Not rated	   	    Not rated		
Udorthents, clayey substratum, hard bedrock >5 feet	       30 	Onsite  investigation  needed	         	Onsite  investigation  needed	         	    Soil test needed		
Us: Urban land	     60	    Not rated	   	    Not rated	   	    Not rated		
Udorthents, smoothed	   40 	Onsite investigation needed	     	Onsite investigation needed	     	  Soil test needed 		
VtC3: Vertrees	     60   	  Very limited   Low strength   Shrink-swell   Slope	    1.00  0.50  0.04	  Somewhat limited   Too clayey   Cutbanks cave   Slope	    0.50  0.10  0.04	  Somewhat limited   Slope 	0.04	
Urban land	   25	  Not rated	 	  Not rated	 	  Not rated		
ZuB: Zanesville	     65       	  Somewhat limited   Low strength   Depth to   saturated zone	      0.78  0.43 	   Very limited   Depth to   saturated zone   Cutbanks cave   Depth to hard   bedrock	      1.00    0.10  0.05	  Somewhat limited   Depth to   saturated zone	    0.43     	
Urban land	   25 	  Not rated 	   	  Not rated 		  Not rated		

## Table 15.-Sanitary Facilities, Part I

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table. See table 16 for ratings for map units that have Urban land as a major component)

Map symbol	Pct.	!		Sewage lagoons	
and soil name	of	!——— <del>-</del> ————			
		Rating class and limiting features	Value	Rating class and limiting features	Value
			1		<del>                                     </del>
BaB: Baxter	   90 	  Very limited   Restricted   permeability	    1.00 	  Somewhat limited   Seepage   Slope	0.53
BaC:	 	] 		] ]	1
Baxter	85     	Very limited Restricted permeability Slope	  1.00    0.04	Very limited   Slope   Seepage	  1.00  0.53 
BaD:	¦				i
Baxter	85       	Very limited Restricted permeability Slope	  1.00    1.00	Very limited Slope Seepage	1.00
BaE: Baxter	   80   	   Very limited   Slope   Restricted   permeability	    1.00  1.00	  Very limited   Slope   Seepage	  1.00  0.53
BbC3: Baxter	     85   	  Very limited   Restricted   permeability   Slope	1.00	  Very limited   Slope 	1.00
BbD3: Baxter	     85     	  Very limited   Restricted   permeability   Slope	    1.00    1.00	  Very limited   Slope 	1.00
CaB: Caneyville	   85   	   Very limited   Restricted   permeability   Depth to bedrock	1.00	  Very limited   Depth to hard   bedrock   Slope	1.00
CaC, CaC3: Caneyville	     85       	  Very limited   Restricted   permeability   Depth to bedrock   Slope	      1.00    1.00  0.04	  Very limited   Depth to hard   bedrock   Slope	      1.00    1.00

Table 15.—Sanitary Facilities, Part I—Continued

Map symbol and soil name	  Pct.   of	· -	is	   Sewage lagoons 	
		Rating class and limiting features	Value	Rating class and limiting features	Value
CnD: Caneyville	     65     	! <del>-</del>	1.00	  Very limited   Depth to hard   bedrock   Slope	    1.00    1.00
Rock outcrop	   25 	  Not rated 	   	  Not rated 	   
CnF: Caneyville	   65     	Restricted permeability Depth to bedrock	1.00	  Very limited   Depth to hard   bedrock   Slope	    1.00    1.00
Rock outcrop	   25	  Not rated 	   	  Not rated	
CrB: Crider	     90   	  Very limited   Restricted   permeability	      1.00 	  Somewhat limited   Seepage   Slope	0.53
CrC: Crider	   85     	   Very limited   Restricted   permeability   Slope	  1.00    0.04	  Very limited   Slope   Seepage	    1.00  0.53
DAM: Dam, large	100	    Not rated	 	    Not rated	
Du: Dunning	   85         	Very limited Restricted permeability Ponding Depth to saturated zone	    1.00    1.00  1.00	  Very limited   Ponding   Depth to   saturated zone	  1.00  1.00 
EkB: Elk	     80     	  Somewhat limited   Restricted   permeability   Flooding	    0.46    0.40	  Somewhat limited   Seepage   Flooding   Slope	    0.53  0.40  0.32
EpB: Epley	   85           	Very limited   Restricted   permeability   Depth to   saturated zone   Depth to bedrock	  1.00    1.00    0.09	  Somewhat limited   Depth to   saturated zone   Seepage   Slope	  0.96    0.53  0.32
FeB: Fredonia	   50     	   Very limited   Restricted   permeability   Depth to bedrock	  1.00    1.00	  Very limited   Depth to hard   bedrock   Slope	    1.00    0.32

Table 15.—Sanitary Facilities, Part I—Continued

Map symbol and soil name	Pct.	! -	ds	   Sewage lagoons 	
	map unit	Rating class and limiting features	Value 	Rating class and limiting features	Value
FeB: Vertrees	     35   	     Very limited   Restricted   permeability	      1.00 	    Somewhat limited   Slope 	      0.32
FeC: Fredonia	   50     	  Very limited   Restricted   permeability   Depth to bedrock   Slope	1.00	Very limited Depth to hard bedrock Slope	  1.00    1.00
Vertrees	   30     	   Very limited   Restricted   permeability   Slope	 	   Very limited   Slope   	    1.00   
FrC: Frondorf	   85           	   Very limited   Depth to bedrock   Restricted   permeability   Slope	!	Very limited Depth to soft bedrock Slope Seepage Content of large stones	  1.00    1.00  0.53  0.02
FrD: Frondorf	   85         	Very limited   Depth to bedrock   Slope   Restricted   permeability	!	Very limited Depth to soft bedrock Slope Seepage Content of large stones	  1.00    1.00  0.53  0.02
Gr: Grigsby	     90     	Very limited Flooding Depth to saturated zone	    1.00  0.40 	  Very limited   Flooding   Seepage 	    1.00  1.00
HaB: Hammack	   85     	   Very limited   Restricted   permeability	    1.00 	   Somewhat limited   Seepage   Slope	    0.53  0.32
La: Lawrence	   90         	  Very limited   Restricted   permeability   Depth to   saturated zone   Flooding	    1.00    1.00    0.40	  Very limited   Depth to   saturated zone   Seepage   Flooding	  1.00    0.53  0.40
Ld: Lindside	   90         	Very limited Flooding Depth to saturated zone Restricted permeability	  1.00  1.00    0.46	Very limited Flooding Depth to saturated zone Seepage	  1.00  1.00    0.53

Table 15.—Sanitary Facilities, Part I—Continued

Map symbol and soil name	Pct.	   Septic tank   absorption fiel	ds	   Sewage lagoons 	
	  map  unit	Rating class and	Value	Rating class and limiting features	Value
Me: Melvin	     80     	Very limited   Flooding   Depth to   saturated zone   Restricted   permeability	    1.00  1.00    0.46	   Very limited   Flooding   Depth to   saturated zone   Seepage	  1.00  1.00    0.53
Ne: Newark	   90         	  Very limited   Flooding   Depth to   saturated zone   Restricted   permeability	  1.00  1.00      0.46	   Very limited   Flooding   Depth to   saturated zone   Seepage	  1.00  1.00    0.53
Nf: Newark	   90         	   Very limited   Ponding   Depth to   saturated zone   Restricted   permeability	  1.00  1.00      0.46	   Very limited   Ponding   Depth to   saturated zone   Seepage	  1.00  1.00      0.53
NhA: Nicholson	   80       	  Very limited   Restricted   permeability   Depth to   saturated zone	  1.00    1.00	  Somewhat limited   Depth to   saturated zone   Seepage	  0.96    0.53
NhB: Nicholson	   80       	  Very limited   Restricted   permeability   Depth to   saturated zone	  1.00    1.00	Somewhat limited   Depth to   saturated zone   Seepage   Slope	  0.96    0.53  0.32
NhC: Nicholson	   85         	  Very limited   Restricted   permeability   Depth to   saturated zone   Slope	  1.00    1.00    0.04	   Very limited   Slope   Depth to   saturated zone   Seepage	  1.00  0.96    0.53
No: Nolin	     90     	  Very limited   Flooding   Restricted   permeability	    1.00  0.46	  Very limited   Flooding   Seepage 	  1.00  0.53
Np: Nolin	   90       	  Very limited   Ponding   Restricted   permeability	    1.00  0.46 	   Very limited   Ponding   Seepage 	  1.00  0.53

Table 15.—Sanitary Facilities, Part I—Continued

Map symbol and soil name	Pct.	· -	ds	   Sewage lagoons 	
		Rating class and limiting features	Value	Rating class and limiting features	Value
OtA: Otwood	     90       	   Very limited   Restricted   permeability   Depth to   saturated zone   Flooding	    1.00    1.00    0.40	  Somewhat limited   Depth to   saturated zone   Seepage   Flooding	    0.92    0.53  0.40
OtB: Otwood	   90       	Very limited   Restricted   permeability   Depth to   saturated zone   Flooding	  1.00    1.00    0.40	Somewhat limited   Depth to   saturated zone   Seepage   Flooding   Slope	  0.92    0.53  0.40  0.32
PbA: Pembroke	     90   	  Very limited   Restricted   permeability	      1.00	  Somewhat limited   Seepage	0.53
Pm: Pits, loamy, frequently flooded-	       95	      Not rated	       	    Not rated	     
Pq: Pits, quarry	   90	  Not rated	 	  Not rated	
RaF: Ramsey	   75     	  Very limited   Depth to bedrock   Slope 	!	Very limited Depth to hard bedrock Slope Seepage	  1.00    1.00  1.00
Frondorf	   20       	  Very limited   Depth to bedrock   Slope   Restricted   permeability	  1.00  1.00  0.46	   Very limited   Depth to soft   bedrock   Slope   Seepage	  1.00    1.00  0.53
Ro: Robertsville	   90         	Very limited   Flooding   Restricted   permeability   Ponding   Depth to   saturated zone	  1.00  1.00    1.00  1.00	Very limited Ponding Flooding Depth to saturated zone Seepage	  1.00  1.00  1.00    0.53
RxF: Rock outcrop	     55	    Not rated	   	    Not rated	
Caneyville	   33       	  Very limited   Restricted   permeability   Depth to bedrock   Slope	  1.00    1.00  1.00	  Very limited   Depth to hard   bedrock   Slope 	  1.00    1.00

Table 15.—Sanitary Facilities, Part I—Continued

Map symbol and soil name	  Pct.   of	· -	ds	   Sewage lagoons 	
		!	Value	Rating class and limiting features	Value
SaA: Sadler	     85         	permeability	1.00    1.00 	  Somewhat limited   Depth to   saturated zone   Seepage	      0.92    0.53
SaB: Sadler	   85       	permeability	  1.00    1.00    0.09	saturated zone	  0.92    0.53  0.32
VrC3: Vertrees	     85     	  Very limited   Restricted   permeability   Slope	    1.00    0.04	  Very limited   Slope   	    1.00 
W: Water	  100	    Not rated 	   	    Not rated 	
WeB: Wellston	   90     	  Somewhat limited   Depth to bedrock   Restricted   permeability	!	Somewhat limited   Depth to hard   bedrock   Seepage   Slope	  0.77    0.53  0.32
WeC2: Wellston	   85         	  Somewhat limited   Depth to bedrock   Restricted   permeability   Slope	!	  Very limited   Slope   Depth to hard   bedrock   Seepage	    1.00  0.77    0.53
ZaB: Zanesville	   85         	Restricted permeability Depth to saturated zone	  1.00    1.00    0.47	Somewhat limited   Depth to   saturated zone   Seepage   Slope   Depth to hard   bedrock	  0.92    0.53  0.32  0.05
ZaC2: Zanesville	   80         	Very limited Restricted permeability Depth to saturated zone Depth to bedrock Slope	  1.00    1.00    0.47  0.04	Very limited Slope Depth to saturated zone Seepage Depth to hard bedrock	  1.00  0.92    0.53  0.05

## Table 15.-Sanitary Facilities, Part II

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table. Map units that have Urban land as a major component were not rated and are not included in this table)

Map symbol and soil name	Pct. of	Trench sanitary		Area sanitary   landfill		Daily cover fo	r
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
BaB: Baxter	     90     	  Very limited   Too clayey	      1.00   	  Not limited   	         	  Very limited   Too clayey   Hard to compact   Gravel content	  1.00  1.00  0.19
BaC: Baxter	   85       	   Very limited   Too clayey   Slope 	  1.00  0.04 	  Somewhat limited   Slope 	    0.04     	Very limited Too clayey Hard to compact Gravel content Slope	  1.00  1.00  0.19  0.04
BaD: Baxter	   85       	Very limited Too clayey Slope	  1.00  1.00 	  Very limited   Slope 	    1.00     	Very limited Too clayey Hard to compact Slope Gravel content	  1.00  1.00  1.00  0.19
BaE: Baxter	   80       	  Very limited   Slope   Too clayey 	    1.00  1.00 	  Very limited   Slope     	    1.00     	   Very limited   Slope   Too clayey   Hard to compact   Gravel content	  1.00  1.00  1.00  0.19
BbC3: Baxter	   85       	   Very limited   Too clayey   Slope	    1.00  0.04 	  Somewhat limited   Slope 	    0.04   	Very limited Too clayey Hard to compact Gravel content Slope	  1.00  1.00  0.22  0.04
BbD3: Baxter	   85       	  Very limited   Too clayey   Slope 	  1.00  1.00 	  Very limited   Slope 	    1.00   	   Very limited   Too clayey   Hard to compact   Slope   Gravel content	  1.00  1.00  1.00  0.22
CaB: Caneyville	   85     	Very limited Depth to bedrock Too clayey	    1.00  1.00 	  Very limited   Depth to bedrock 	:	Very limited  Depth to bedrock  Too clayey  Hard to compact	  1.00  1.00  1.00
CaC, CaC3: Caneyville	   85       	Very limited Depth to bedrock Too clayey Slope	  1.00  1.00  0.04	  Very limited   Depth to bedrock   Slope 	:	Very limited Depth to bedrock Too clayey Hard to compact Slope	  1.00  1.00  1.00  0.04

Table 15.—Sanitary Facilities, Part II—Continued

Map symbol and soil name	Pct. of map	   Trench sanitar   landfill	У	   Area sanitary   landfill		Daily cover for landfill		
and soil name	unit	Rating class and limiting features	Value	Rating class and   limiting features	Value	Rating class and   limiting features	Value	
CnD: Caneyville	     65       	   Very limited   Depth to bedrock   Too clayey   Slope	    1.00  1.00  0.84	  Very limited   Depth to bedrock   Slope	    1.00  0.84 	   Very limited   Depth to bedrock   Too clayey   Hard to compact   Slope	  1.00  1.00  1.00  0.84	
Rock outcrop	   25 	  Not rated 		  Not rated 		  Not rated 	   	
CnF: Caneyville	   65     	  Very limited   Slope   Depth to bedrock   Too clayey	  1.00  1.00  1.00	  Very limited   Slope   Depth to bedrock 	    1.00  1.00 	  Very limited   Depth to bedrock   Slope   Too clayey   Hard to compact	  1.00  1.00  1.00	
Rock outcrop	   25 	  Not rated 		  Not rated 		  Not rated 		
CrB: Crider	   90 	  Somewhat limited   Too clayey	    0.50	  Not limited 	     	  Somewhat limited   Too clayey	0.50	
CrC: Crider	   85   	  Somewhat limited   Too clayey   Slope	    0.50  0.04	  Somewhat limited   Slope 	    0.04 	  Somewhat limited   Too clayey   Slope	0.50	
DAM: Dam, large	  100	  Not rated		  Not rated 		    Not rated 		
Du: Dunning	   85       	Very limited Depth to saturated zone Ponding Too clayey	  1.00    1.00  1.00	  Very limited   Ponding   Depth to   saturated zone	  1.00  1.00 	Very limited	  1.00  1.00    1.00  1.00	
EkB: Elk	     80   	  Somewhat limited   Too clayey   Flooding	    0.50  0.40	  Somewhat limited   Flooding	      0.40	  Somewhat limited   Too clayey	0.50	
EpB: Epley	   85       	   Very limited   Depth to   saturated zone   Depth to bedrock   Too clayey	  1.00    1.00  1.00	  Somewhat limited   Depth to   saturated zone	    0.96     	   Very limited   Too clayey   Hard to compact   Depth to   saturated zone	  1.00  1.00  0.98	
FeB: Fredonia	   50   	   Very limited   Depth to bedrock   Too clayey	    1.00  1.00	  Very limited   Depth to bedrock   	    1.00 	  Very limited   Depth to bedrock   Too clayey   Hard to compact	  1.00  1.00  1.00	
Vertrees	   35     	  Very limited   Too clayey   	    1.00 	  Not limited     	       	  Very limited   Too clayey   Hard to compact 	  1.00  1.00	

Table 15.—Sanitary Facilities, Part II—Continued

Map symbol	Pct. of			   Area sanitary   landfill		Daily cover for landfill		
	! -	Rating class and limiting features	Value	Rating class and   limiting features	Value	Rating class and limiting features	Value	
FeC: Fredonia	     50     	Depth to bedrock	    1.00  1.00  0.04	  Very limited   Depth to bedrock   Slope 		! -	1.00	
Vertrees	   30     	   Very limited   Too clayey   Slope	    1.00  0.04	  Somewhat limited   Slope 	    0.04 		  1.00  1.00  0.04	
FrC: Frondorf	   85       	  Very limited   Depth to bedrock   Too clayey   Slope		  Very limited   Depth to bedrock   Slope 		! -	    1.00  0.50  0.04	
FrD: Frondorf	   85     	Depth to bedrock		  Very limited   Depth to bedrock   Slope			  1.00  1.00  0.50	
Gr: Grigsby	   90       	  Very limited   Flooding   Depth to   saturated zone   Seepage	1.00	  Very limited   Flooding   Depth to   saturated zone   Seepage	  1.00  1.00    1.00	  Somewhat limited   Seepage 	    0.52     	
HaB: Hammack	     85 	    Very limited   Too clayey	      1.00	    Not limited 	       	  Not limited 	     	
La: Lawrence	   90       	  Very limited   Depth to   saturated zone   Too clayey   Flooding	1.00 	  Very limited   Depth to   saturated zone   Flooding	    1.00    0.40 	saturated zone	  1.00    0.50	
Ld: Lindside	   90         	Very limited Flooding Depth to saturated zone Too clayey	  1.00  1.00      0.50	  Very limited   Flooding   Depth to   saturated zone	  1.00  1.00 	Somewhat limited Depth to saturated zone Too clayey	    0.98    0.50	
Me: Melvin	   80       	   Very limited   Flooding   Depth to   saturated zone   Too clayey	  1.00  1.00    0.50	  Very limited   Flooding   Depth to   saturated zone	    1.00  1.00   	Very limited Depth to saturated zone Too clayey	    1.00    0.50 	

Table 15.—Sanitary Facilities, Part II—Continued

Map symbol and soil name	Pct. of	Trench sanitar	У	Area sanitary		Daily cover fo	or
	unit	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Ne: Newark	     90     	   Very limited   Flooding   Depth to   saturated zone	    1.00  1.00	   Very limited   Flooding   Depth to   saturated zone	    1.00  1.00	     Very limited   Depth to   saturated zone	1.00
Nf: Newark	     90     	  Very limited   Depth to   saturated zone   Ponding	    1.00    1.00	  Very limited   Ponding   Depth to   saturated zone	    1.00  1.00	  Very limited   Ponding   Depth to   saturated zone	1.00
NhA, NhB: Nicholson	   80       	  Very limited   Depth to   saturated zone   Too clayey	  1.00    1.00	  Somewhat limited   Depth to   saturated zone 	    0.96     	  Very limited   Too clayey   Hard to compact   Depth to   saturated zone	  1.00  1.00  0.98
NhC: Nicholson	   85         	   Very limited   Depth to   saturated zone   Too clayey   Slope	  1.00    1.00  0.04	  Somewhat limited   Depth to   saturated zone   Slope 	  0.96    0.04 	Very limited   Too clayey   Hard to compact   Depth to   saturated zone   Slope	  1.00  1.00  0.98 
No: Nolin	   90 	  Very limited   Flooding	    1.00	  Very limited   Flooding	    1.00	  Not limited   	     
Np: Nolin	   90 	  Very limited   Ponding	    1.00	  Very limited   Ponding	    1.00	  Very limited   Ponding	1.00
OtA, OtB: Otwood	   90     	  Very limited   Depth to   saturated zone   Flooding	    1.00    0.40	Somewhat limited   Depth to   saturated zone   Flooding	    0.92    0.40	  Somewhat limited   Depth to   saturated zone	0.95
PbA: Pembroke	     90   	  Somewhat limited   Too clayey	      0.50	  Not limited   	       	  Very limited   Hard to compact   Too clayey	1.00
Pm: Pits, loamy, frequently flooded-	     95	    Not rated	     	      Not rated	     	      Not rated 	
Pq: Pits, quarry	90	  Not rated	 	    Not rated 		    Not rated 	
RaF: Ramsey	   75       	    Very limited   Slope   Depth to bedrock   Seepage	    1.00  1.00  1.00	  Very limited   Slope   Depth to bedrock 	    1.00  1.00	  Very limited   Depth to bedrock   Slope   Seepage	  1.00  1.00  1.00

Table 15.—Sanitary Facilities, Part II—Continued

Map symbol and soil name	Pct. of	Trench sanitar	У	Area sanitary		Daily cover fo	r
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
RaF: Frondorf	     20   	  Very limited   Slope   Depth to bedrock	      1.00  1.00	  Very limited   Slope   Depth to bedrock	1.00	  Very limited   Depth to bedrock   Slope	    1.00  1.00
Ro: Robertsville	   90         	Very limited Flooding Depth to saturated zone Ponding Too clayey	  1.00  1.00    1.00  1.00	  Very limited   Flooding   Ponding   Depth to   saturated zone	  1.00  1.00  1.00 	Very limited Ponding Depth to saturated zone Too clayey	  1.00  1.00    1.00
RxF: Rock outcrop	   55	  Not rated	 	  Not rated	 	  Not rated	
Caneyville	į	Very limited Slope Depth to bedrock Too clayey	  1.00  1.00  1.00	  Very limited   Slope   Depth to bedrock	    1.00  1.00 	Very limited Depth to bedrock Slope Too clayey Hard to compact	  1.00  1.00  1.00  1.00
SaA, SaB: Sadler	   85     	  Very limited   Depth to   saturated zone   Depth to bedrock   Too clayey	  1.00    1.00  0.50	  Somewhat limited   Depth to   saturated zone 	    0.92   	  Somewhat limited   Depth to   saturated zone   Too clayey	    0.95    0.50
VrC3: Vertrees	     85     	  Very limited   Too clayey   Slope	    1.00  0.04	  Somewhat limited   Slope 	    0.04 	   Very limited   Too clayey   Hard to compact   Slope	  1.00  1.00  0.04
W: Water	    100	    Not rated 	     	    Not rated	     	    Not rated	
WeB: Wellston	     90   	  Very limited   Depth to bedrock   Too clayey	    1.00  0.50	  Somewhat limited   Depth to bedrock	    0.77 	  Somewhat limited   Depth to bedrock   Too clayey	    0.77  0.50
WeC2: Wellston	     85   	  Very limited   Depth to bedrock   Slope	    1.00  0.04	  Somewhat limited   Depth to bedrock   Slope	      0.77  0.04	  Somewhat limited   Depth to bedrock   Slope	    0.77  0.04
ZaB: Zanesville	   85         	  Very limited   Depth to   saturated zone   Depth to bedrock   Too clayey	    1.00    1.00  0.50	  Somewhat limited   Depth to   saturated zone   Depth to bedrock	    0.92    0.05	   Somewhat limited   Depth to   saturated zone   Too clayey   Depth to bedrock	  0.95    0.50  0.05

Table 15.—Sanitary Facilities, Part II—Continued

Map symbol and soil name	Pct. of map	   Trench sanitar   landfill 	У	   Area sanitary   landfill 		Daily cover for landfill		
	unit	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value	
ZaC2:	 	 		 		 		
Zanesville	80   	Very limited   Depth to   saturated zone	1.00	Somewhat limited   Depth to   saturated zone	0.92	Somewhat limited   Depth to   saturated zone	  0.95 	
	   	Depth to bedrock Too clayey Slope	1.00  0.50  0.04	Depth to bedrock   Slope	0.05	Too clayey Depth to bedrock Slope	0.50  0.05  0.04	

Table 16.—Sanitary Interpretations for Urban Areas

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table)

Map symbol	  Pct.	· -	_	   Sewage lagoons	
and soil name	of	absorption field	ds		
		Rating class and   limiting features	Value 	Rating class and   limiting features	Value
BrB:	İ				
Baxter	   60   	  Very limited   Restricted   permeability	    1.00 	  Somewhat limited   Seepage   Slope	0.53
Urban land	30   30	  Not rated 	   	  Not rated 	
BrC: Baxter	   55     	  Very limited   Restricted   permeability   Slope	    1.00    0.04	  Very limited   Slope   Seepage	    1.00  0.53
Urban land	30	  Not rated 	   	  Not rated 	
BrD: Baxter	     60   	  Very limited   Restricted   permeability   Slope	    1.00    1.00	  Very limited   Slope   Seepage	    1.00  0.53
Urban land	25	  Not rated 	   	  Not rated 	
CoD: Caneyville	   40       	   Very limited   Restricted   permeability   Depth to bedrock   Slope	1.00	   Very limited   Depth to hard   bedrock   Slope	  1.00    1.00
Urban land	   25	  Not rated 	   	  Not rated 	
Rock outcrop	20	  Not rated 	   	  Not rated 	į
CoE: Caneyville	   40       	! -	  1.00    1.00  1.00	  Very limited   Depth to hard   bedrock   Slope	  1.00    1.00
Urban land	25	  Not rated 		  Not rated 	
Rock outcrop	20	  Not rated 		  Not rated 	
CuB: Crider	   55 	  Very limited   Restricted   permeability	    1.00	  Somewhat limited   Seepage   Slope	    0.53  0.32
Urban land	   35 	  Not rated 	   	  Not rated 	

Table 16.—Sanitary Interpretations for Urban Areas—Continued

Map symbol and soil name	Pct.	· -	ds	   Sewage lagoons		
		!	Value	Rating class and limiting features	Value	
CuC: Crider	     55   	  Very limited   Restricted   permeability   Slope	    1.00    0.04	    Very limited   Slope   Seepage 	    1.00  0.53	
Urban land	   35 	  Not rated 	   	  Not rated 		
FnB: Fredonia	   37     	! -	1.00	bedrock	  1.00    0.32	
Vertrees	   30   		    1.00	  Somewhat limited   Slope 	0.32	
Urban land	   25 	  Not rated 	   	  Not rated 		
FnC: Fredonia	   37   		1.00	bedrock	    1.00    1.00	
Vertrees	   27     	Very limited Restricted permeability Slope	 	  Very limited   Slope 	    1.00 	
Urban land	   25	  Not rated 	 	  Not rated 		
FnC2: Fredonia	     37     	   Very limited   Restricted   permeability   Depth to bedrock   Slope	1.00 	  Very limited   Depth to hard   bedrock   Slope	    1.00    1.00	
Vertrees	   30   	   Very limited   Restricted   permeability   Slope	    1.00    0.04	  Very limited   Slope 	    1.00 	
Urban land	   25	  Not rated 	   	  Not rated 		
PeA: Pembroke	     65   	  Very limited   Restricted   permeability	      1.00	  Somewhat limited   Seepage	      0.53	
Urban land	   25 	  Not rated 	   	  Not rated 	   	
UaC: Udorthents	     95 	    Not rated 	   	    Not rated 	   	

Table 16.—Sanitary Interpretations for Urban Areas—Continued

	Pct.	! -	de	   Sewage lagoons 	
and porr name		!		Rating class and	Value
		limiting features		limiting features	<u> </u>
UaD: Udorthents, refuse substratum	       95	    Not rated	       	      Not rated	
Ub: Urban land	75	  Not rated	 	  Not rated	
Udorthents	   22   	  Onsite  investigation  needed	     	  Onsite  investigation  needed	     
Uc: Urban land	     50	    Not rated	   	    Not rated	
Udorthents, clayey substratum, hard bedrock 0-5 feet	       30	      Not rated	     	      Not rated	
Ud: Urban land	     75	    Not rated	   	    Not rated	
Udorthents, clayey substratum, hard bedrock >5 feet	       20	Not rated	     	      Not rated	
Us: Urban land	     60	    Not rated	 	    Not rated	
Udorthents, smoothed	40	  Not rated		  Impractical	
VtC3: Vertrees	     60   	   Very limited   Restricted   permeability   Slope	    1.00    0.04	  Very limited   Slope 	    1.00 
Urban land	   25	  Not rated	 	  Not rated	
ZuB: Zanesville	     65         	  Very limited   Restricted   permeability   Depth to   saturated zone   Depth to bedrock	1.00    1.00	saturated zone Seepage Slope	    0.92    0.53  0.32  0.05
Urban land	   25 	  Not rated 		  Not rated 	

Table 17.—Construction Materials, Part I

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The ratings given for the thickest layer are for the thickest layer above and excluding the bottom layer. The numbers in the value columns range from 0.00 to 0.99. The greater the value, the greater the likelihood that the bottom layer or thickest layer of the soil is a source of sand or gravel. See text for further explanation of ratings in this table. Map units that have Urban land as a major component were not rated and are not included in this table)

Map symbol and soil name	Pct. of map	!	of	Potential source sand	of
	unit	Rating class	Value	Rating class	Value
BaB: Baxter	     90 	  Poor   Bottom layer	    0.00  0.00	  Poor   Bottom layer	    0.00  0.00
BaC, BaD: Baxter	     85   	:	      0.00  0.00		    0.00  0.00
BaE: Baxter	   80   	! -	    0.00  0.00	· -	    0.00  0.00
BbC3, BbD3: Baxter	   85   	! -	    0.00  0.00	! -	    0.00  0.00
CaB, CaC, CaC3: Caneyville	     85   	! -	    0.00  0.00	! -	    0.00  0.00
CnD, CnF: Caneyville	     65   		    0.00  0.00		    0.00  0.00
Rock outcrop	25	  Not rated	ļ !	Not rated	
CrB: Crider	     90   	  Poor   Bottom layer   Thickest layer	      0.00  0.00		      0.00  0.00
CrC: Crider	     85   	! -	      0.00  0.00	! -	      0.00  0.00
DAM: Dam, large	  100 	  Not rated 	   	    Not rated 	   
Du: Dunning	   85   	Bottom layer	    0.00  0.00 	! -	    0.00  0.00

Table 17.—Construction Materials, Part I—Continued

Map symbol and soil name	Pct. of map	Potential source	of	Potential source	e of
	map  unit	Rating class	Value	Rating class	Value
EkB: Elk	İ	  Poor   Bottom layer   Thickest layer	0.00	    Poor	0.00
EpB: Epley	     85   	  Poor   Bottom layer   Thickest layer	      0.00  0.00	!	0.00
FeB: Fredonia	     50   	  Poor   Bottom layer   Thickest layer	    0.00  0.00	  Poor   Bottom layer   Thickest layer	0.00
Vertrees	   35   	  Poor   Bottom layer   Thickest layer 	0.00	· -	0.00
FeC: Fredonia	   50 	  Poor   Bottom layer   Thickest layer	0.00	!	0.00
Vertrees	   30   	  Poor   Bottom layer   Thickest layer 	  0.00  0.00	!	0.00
FrC, FrD: Frondorf	   85   	  Poor   Bottom layer   Thickest layer	    0.00  0.00	  Poor   Bottom layer   Thickest layer	0.00
Gr: Grigsby	   90   	  Poor   Bottom layer   Thickest layer	    0.00  0.00	  Fair   Bottom layer   Thickest layer	0.00
HaB: Hammack	   85     	  Poor   Thickest layer   Bottom layer	    0.00  0.00	  Poor   Bottom layer   Thickest layer	0.00
La: Lawrence	   90   	  Poor   Bottom layer   Thickest layer	    0.00  0.00	  Poor   Bottom layer   Thickest layer	0.00
Ld: Lindside	   90     	  Poor   Bottom layer   Thickest layer	    0.00  0.00	  Poor   Bottom layer   Thickest layer	0.00
Me: Melvin	   80     	  Poor   Bottom layer   Thickest layer	    0.00  0.00	  Poor   Bottom layer   Thickest layer	0.00

Table 17.—Construction Materials, Part I—Continued

Map symbol and soil name	Pct. of map	Potential source gravel	of	Potential source	of
	unit	Rating class	Value	Rating class	Value
Ne, Nf: Newark	İ	Poor   Bottom layer   Thickest layer		Poor   Bottom layer   Thickest layer	0.00
NhA, NhB: Nicholson	     80   	  Poor   Bottom layer   Thickest layer	    0.00  0.00	  Poor   Bottom layer   Thickest layer	0.00
NhC: Nicholson	     85   	  Poor   Bottom layer   Thickest layer	    0.00  0.00	  Poor   Bottom layer   Thickest layer	0.00
No, Np: Nolin	   90   	  Poor   Bottom layer   Thickest layer	    0.00  0.00	·	0.00
Ota, OtB: Otwood	   90   	  Poor   Bottom layer   Thickest layer	    0.00  0.00	  Poor   Bottom layer   Thickest layer	0.00
PbA: Pembroke	   90   	  Poor   Bottom layer   Thickest layer	0.00	  Poor   Bottom layer   Thickest layer	0.00
Pm: Pits, loamy, frequently flooded-	       95	    Not rated 		    Not rated	
Pq: Pits, quarry	   90 	  Not rated 	   	  Not rated 	   
Raf: Ramsey	   75   	  Poor   Bottom layer   Thickest layer	0.00	  Poor   Bottom layer   Thickest layer	  0.00  0.00
Frondorf	   20   	  Poor   Bottom layer   Thickest layer 	0.00	  Poor   Bottom layer   Thickest layer 	0.00
Ro: Robertsville	   90     	   Poor   Bottom layer   Thickest layer	    0.00  0.00	  Poor   Bottom layer   Thickest layer	0.00
RxF: Rock outcrop	   55	  Not rated		  Not rated	j 
Caneyville	   33     	  Poor   Bottom layer   Thickest layer 	0.00	  Poor   Bottom layer   Thickest layer 	0.00

Table 17.—Construction Materials, Part I—Continued

Map symbol and soil name	Pct. of	Potential source gravel	of	Potential source sand	of
	map  unit	Rating class	Value	Rating class	Value
SaA, SaB: Sadler	     85	Poor		Poor	
	   	Bottom layer   Thickest layer	0.00	Bottom layer Thickest layer	0.00
VrC3: Vertrees	     85   	Poor Bottom layer Thickest layer	    0.00  0.00	  Poor   Bottom layer   Thickest layer	    0.00  0.00
W: Water	    100	    Not rated	     	    Not rated 	
WeB: Wellston	     90 	Poor Bottom layer Thickest layer	    0.00  0.00	  Poor   Bottom layer   Thickest layer	0.00
WeC2: Wellston	     85   	Poor Bottom layer Thickest layer	      0.00  0.00	  Poor   Bottom layer   Thickest layer	    0.00  0.00
ZaB: Zanesville	     85   	Poor   Bottom layer   Thickest layer	      0.00  0.00	  Poor   Bottom layer   Thickest layer	    0.00  0.00
ZaC2: Zanesville	     80   	Poor   Bottom layer   Thickest layer	      0.00  0.00	  Poor   Bottom layer   Thickest layer	    0.00  0.00

Table 17.-Construction Materials, Part II

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.00 to 0.99. The smaller the value, the greater the limitation. See text for further explanation of ratings in this table. Map units that have Urban land as a major component were not rated and are not included in this table)

Map symbol and soil name	Pct. of map	Potential source of   reclamation material 		Potential source of roadfill		Potential source of   topsoil	
	unit	Rating class and limiting features	Value	Rating class and limiting features		Rating class and limiting features	Value
BaB: Baxter	90	  Poor   Too clayey   Too acid	      0.00  0.32	1	    0.00  0.87	  Poor   Too clayey   Rock fragments	    0.00  0.00
	   	Low content of organic matter	0.50   	 	   	Hard to reclaim   Too acid 	0.68
BaC: Baxter	   85       	Poor   Too clayey   Too acid   Low content of   organic matter	  0.00  0.32  0.50	  Poor   Low strength   Shrink-swell 	    0.00  0.87 	   Poor   Too clayey   Rock fragments   Hard to reclaim   Too acid   Slope	  0.00  0.00  0.68  0.88
BaD:		      Poor		      Poor		Blope      Poor	
Barcer		Too clayey Too acid Low content of organic matter	0.00  0.32  0.50 	Low strength Shrink-swell	0.00  0.87  0.98 	Too clayey   Slope   Rock fragments   Hard to reclaim   Too acid	0.00   0.00   0.00   0.68   0.88
BaE: Baxter	   80         	   Too clayey   Too acid   Low content of   organic matter	  0.00  0.32  0.50	  Poor   Low strength   Slope   Shrink-swell	    0.00  0.00  0.87	   Slope   Too clayey   Rock fragments   Hard to reclaim   Too acid	  0.00  0.00  0.00  0.68  0.88
BbC3: Baxter	   85       	Poor Too clayey Low content of organic matter Too acid	  0.00  0.12    0.32	!	    0.00  0.87 	Poor Too clayey Rock fragments Hard to reclaim Too acid Slope	  0.00  0.00  0.68  0.88
BbD3: Baxter	     85     	   Poor   Too clayey   Low content of   organic matter   Too acid	    0.00  0.12    0.32	!	      0.00  0.87  0.98	Poor Too clayey Slope Rock fragments Hard to reclaim	      0.00  0.00  0.00  0.68

Table 17.—Construction Materials, Part II—Continued

Map symbol and soil name	Pct. of	Potential source reclamation mater		Potential source roadfill	of	Potential source topsoil	of
did boll name		Rating class and limiting features	Value	Rating class and   limiting features	Value	Rating class and limiting features	Value
CaB: Caneyville	05	  Poor		  Poor		  Poor	!
caneyviiie	03	Too clayey	0.00	Depth to bedrock	!	Too clayey	0.00
	i	Droughty	0.05	Low strength	0.00	Depth to bedrock	
	i	Depth to bedrock	0.29	Shrink-swell	0.56		i
	İ	Low content of	0.50	İ	İ	İ	j
	ļ	organic matter	ļ	ļ	ļ	ļ	ļ
	!	Too acid	0.74	!	!		!
		Water erosion	0.90	 	!	 	!
CaC:		] 		 		 	1
Caneyville	85	Poor	İ	Poor	İ	Poor	į
	ļ	Too clayey	0.00	Depth to bedrock	!	Too clayey	0.00
		Droughty	0.05	Low strength	0.00	Depth to bedrock	!
		Depth to bedrock Low content of	0.29	Shrink-swell	0.56	Slope	0.96
	-	organic matter	10.50		}	 	1
	i	Too acid	0.74	i	i	 	i
	i	Water erosion	0.90	İ	İ		i
	ļ		ļ		ļ		ļ
CaC3: Caneyville	05	  Poor		  Poor		  Poor	
Caneyviiie	65	Too clayey	0.00	Depth to bedrock	0.00	!	0.00
	i	Droughty	0.03	Low strength	0.00	Depth to bedrock	!
	İ	Low content of	0.12	Shrink-swell	0.53	Slope	0.96
		organic matter	[	ļ		ļ	
	!	Depth to bedrock	0.29		!		!
	-	Too acid	0.74	 		 	}
CnD:	i		i		i		i
Caneyville	65	Poor	ļ	Poor	İ	Poor	İ
		Too clayey	0.00	Depth to bedrock	!	Too clayey	0.00
		Droughty Depth to bedrock	0.05	Low strength Shrink-swell	0.00	Slope Depth to bedrock	0.16
	1	Low content of	0.50	SHITHK-SWEIL	10.30	Depth to bedrock	10.29
	i	organic matter		İ	i	 	i
	İ	Too acid	0.74	İ	j	İ	j
	ļ	Water erosion	0.90		ļ		ļ
Rock outcrop	25	  Not rated		  Not rated	ļ	  Not rated	
NOON OUGGEOP	= 3		i		i		i
CnF:	į		į	İ	į		į
Caneyville	65	Poor		Poor		Poor	
		Too clayey	0.00	Depth to bedrock	0.00	Slope   Too clayey	0.00
	-	Droughty Depth to bedrock	0.05	Low strength Slope	10.00	Depth to bedrock	0.29
	i	Low content of	0.50	Shrink-swell	0.56	Depon to Dearoun	
	İ	organic matter	İ	j	İ		į
	ļ	Too acid	0.74	!	ļ		
		Water erosion	0.90	 		 	!
Rock outcrop	25	  Not rated		  Not rated		  Not rated	
CrB:		 		 		 	-
Crider	90	  Fair	i	Poor	i	  Good	i
	İ	Low content of	0.50	Low strength	0.00	ĺ	İ
	į	organic matter Too acid	  0.54	Shrink-swell	0.99		!

Table 17.—Construction Materials, Part II—Continued

Map symbol and soil name	Pct. of map	Potential source reclamation mater		Potential source roadfill	of	Potential source topsoil	of
	! -	Rating class and limiting features	Value	Rating class and   limiting features		Rating class and limiting features	Value
CrC: Crider	     85     	  Fair   Low content of   organic matter   Too acid	    0.50    0.54	Shrink-swell	      0.00  0.99	  Fair   Slope   	      0.96   
DAM: Dam, large	  100	  Not rated 	   	  Not rated 		  Not rated 	
Du: Dunning	   85       	Poor   Too clayey   Low content of   organic matter	    0.00  0.12 	Poor   Depth to   saturated zone   Low strength   Shrink-swell	  0.00    0.00  0.87	  Poor   Depth to   saturated zone   Too clayey	0.00
EkB: Elk	   80     	   Fair   Low content of   organic matter   Too acid   Water erosion	!	  Poor   Low strength 	    0.00   	  Good       	         
EpB: Epley	   85         	Poor   Too clayey   Low content of   organic matter   Too acid   Water erosion	    0.00  0.12    0.54  0.90	saturated zone	    0.00  0.24    0.98	!	    0.00  0.24    0.88  0.98
FeB: Fredonia	   50   51   1   1	Poor   Too clayey   Low content of   organic matter   Too acid   Depth to bedrock   Water erosion	0.00  0.50    0.84	  Poor   Depth to bedrock   Low strength   Shrink-swell	    0.00  0.00  0.87 		    0.00  0.97   
Vertrees	   35       	Poor Too clayey Low content of organic matter Too acid Water erosion	  0.00  0.12    0.54  0.99	   Low strength   Shrink-swell	  0.00  0.87 	Poor   Too clayey   Rock fragments	    0.00  0.97   
FeC: Fredonia	   50   50       	Poor   Too clayey   Low content of   organic matter   Too acid   Depth to bedrock   Water erosion	    0.00  0.50    0.74  0.97  0.99	  Poor   Depth to bedrock   Low strength   Shrink-swell	    0.00  0.00  0.87 	  Poor   Too clayey   Slope   Depth to bedrock	    0.00  0.96  0.97 

Table 17.—Construction Materials, Part II—Continued

Map symbol and soil name	Pct. of map	   Potential source   reclamation mater 		   Potential source   roadfill	of	   Potential source   topsoil 	of
	! -	Rating class and limiting features	Value	Rating class and   limiting features	Value	Rating class and   limiting features	Value
FeC: Vertrees	     30       	  Poor   Too clayey   Low content of   organic matter   Too acid   Water erosion	    0.00  0.12    0.54  0.99	  Poor   Low strength   Shrink-swell	0.00	  Poor   Too clayey   Slope   Rock fragments	    0.00  0.96  0.97
FrC: Frondorf	   85           	  Fair   Droughty   Depth to bedrock   Too acid   Low content of   organic matter   Water erosion	  0.08  0.21  0.50  0.50 	  Poor   Depth to bedrock   Low strength   Cobble content	!	Depth to bedrock	  0.00  0.21  0.88  0.96
FrD: Frondorf	   85           	Fair   Droughty   Depth to bedrock   Too acid   Low content of   organic matter   Water erosion	  0.08  0.21  0.50  0.50 	  Poor   Depth to bedrock   Low strength   Cobble content   Slope		Rock fragments Depth to bedrock	  0.00  0.00  0.21  0.88
Gr: Grigsby	   90   	  Fair   Low content of   organic matter	    0.12 	  Poor   Low strength 	    0.00 	  Good 	     
HaB: Hammack	   85       	  Fair   Low content of   organic matter   Too acid   Water erosion	    0.12    0.54  0.99	  Poor   Low strength   	    0.00     	  Poor   Hard to reclaim   	0.00
La: Lawrence	   90       	  Fair   Low content of   organic matter   Too acid   Water erosion	    0.12    0.50  0.90	  Poor   Low strength   Depth to   saturated zone	    0.00  0.04 	! -	  0.04    0.88
Ld: Lindside	   90     	  Fair   Low content of   organic matter   Water erosion	    0.50    0.99	  Poor   Low strength   Depth to   saturated zone	    0.00  0.24 	  Fair   Depth to   saturated zone 	    0.24   
Me: Melvin	   80     	  Fair   Low content of   organic matter   Water erosion	    0.50    0.90	  Poor   Depth to   saturated zone   Low strength	    0.00    0.00	  Poor   Depth to   saturated zone 	0.00

Table 17.—Construction Materials, Part II—Continued

Map symbol and soil name	Pct. of map			Potential source roadfill	of	Potential source topsoil	of
	! -	Rating class and limiting features	Value	Rating class and limiting features		Rating class and limiting features	•
Ne, Nf: Newark	     90   	Fair Low content of organic matter Water erosion	      0.50    0.90	Depth to	    0.00  0.04	! -	0.04
NhA, NhB: Nicholson	   80       	  Fair   Low content of   organic matter   Too acid   Water erosion	    0.12    0.68  0.90	Depth to	    0.00  0.24 	! -	    0.24   
NhC: Nicholson	   85       	Fair   Low content of   organic matter   Too acid   Water erosion	  0.12    0.68  0.90	Depth to	    0.00  0.24 	! -	0.24
No, Np: Nolin	     90   	  Fair   Low content of   organic matter   Water erosion	!	  Poor   Low strength 	    0.00 	  Good   	
OtA, OtB: Otwood	     90     	Fair Low content of organic matter Too acid Water erosion	      0.12    0.50  0.90	Depth to saturated zone	    0.00  0.32    0.87	saturated zone Too acid	    0.32    0.88
PbA: Pembroke	     90       	  Fair   Too clayey   Low content of   organic matter   Too acid	      0.08  0.12    0.54	Shrink-swell	    0.00  0.94 	!	      0.05  0.97  0.98
Pm: Pits, loamy, frequently flooded-	     95	    Not rated 	     	    Not rated 	     	    Not rated 	     
Pq: Pits, quarry	90	    Not rated 	 	    Not rated 		    Not rated 	   
Raf: Ramsey	   75           	   Poor   Droughty   Depth to bedrock   Low content of   organic matter   Too acid	   0.00   0.00   0.12   0.50	  Poor   Depth to bedrock   Low strength   Slope 	0.00	  Poor   Slope   Depth to bedrock   Rock fragments   Too acid	    0.00  0.00  0.88  0.88

Table 17.—Construction Materials, Part II—Continued

Map symbol and soil name	Pct. of map	Potential source reclamation mater		Potential source roadfill	of	Potential source topsoil	of
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Raf: Frondorf	   20   20   	   Fair   Depth to bedrock   Too acid   Droughty   Water erosion	    0.21  0.50  0.59  0.99	   Poor   Depth to bedrock   Low strength   Slope	      0.00  0.00  0.00	  Poor   Slope   Depth to bedrock   Too acid	    0.00  0.21  0.88
Ro: Robertsville	   90       	  Fair   Low content of   organic matter   Too acid   Water erosion	  0.12    0.32  0.90	   Poor   Depth to   saturated zone   Low strength	    0.00    0.00	  Poor   Depth to   saturated zone   Too acid	    0.00    0.88
RxF: Rock outcrop	55	  Not rated	<u> </u> 	  Not rated	į Į	  Not rated	į Į
Caneyville	   33           	Poor Too clayey Droughty Low content of organic matter Depth to bedrock Too acid Water erosion	  0.00  0.05  0.12    0.29  0.74  0.90	   Poor   Depth to bedrock   Low strength   Slope   Shrink-swell	  0.00  0.00  0.00  0.87 	Too clayey	0.00
SaA, SaB: Sadler	   85       	  Fair   Low content of   organic matter   Too acid   Water erosion	    0.12    0.32  0.90	  Poor   Low strength   Depth to   saturated zone	    0.00  0.32 	  Fair   Depth to   saturated zone   Too acid	    0.32    0.88
VrC3: Vertrees	   85       	Poor Too clayey Low content of organic matter Too acid	  0.00  0.12    0.54	  Poor   Low strength   Shrink-swell	    0.00  0.87 	   Poor   Too clayey   Slope   Rock fragments	  0.00  0.96  0.97
W: Water	100	    Not rated 	     	    Not rated 	     	    Not rated 	   
WeB: Wellston	   90       	  Fair   Low content of   organic matter   Too acid   Water erosion	    0.50    0.54  0.99	  Poor   Low strength   Depth to bedrock 	0.00	  Fair   Rock fragments   Too acid 	    0.88  0.98 
WeC2: Wellston	   85       	   Fair   Low content of   organic matter   Too acid   Water erosion	  0.50    0.54  0.99	  Poor   Low strength   Depth to bedrock 	  0.00  0.23 	  Fair   Rock fragments   Slope   Too acid	  0.88  0.96  0.98

Table 17.—Construction Materials, Part II—Continued

Map symbol and soil name	Pct. of map	Potential source reclamation mater		Potential source roadfill	Potential source of topsoil		
	unit	Rating class and	Value	Rating class and	Value	Rating class and	Value
		limiting features		limiting features	<u> </u>	limiting features	
ZaB:		  -  -	ļ ļ	  -	ļ ļ	 	
Zanesville	85   	Fair   Low content of   organic matter	0.12	Poor   Low strength   Depth to	  0.00  0.32	Fair   Depth to   saturated zone	0.32
	   	Too acid   Water erosion 	0.32  0.90	saturated zone Depth to bedrock	  0.95 	Too acid Hard to reclaim	0.88
ZaC2:	İ		İ	ĺ	İ	ĺ	İ
Zanesville	80   	Fair Low content of organic matter	0.12	Poor Low strength Depth to	0.00	Fair Depth to saturated zone	0.32
	   	Too acid   Water erosion 	0.32	saturated zone Depth to bedrock	0.95	Too acid   Slope   Hard to reclaim	0.88  0.96  0.98

## Table 18.-Water Management

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table. Map units that have Urban land as a major component were not rated and are not included in this table)

Map symbol and soil name	Pct.	Pond reservoir ar	eas	   Embankments, dikes   levees	, and	Aquifer-fed excavated pond	ls
	map  unit	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
BaB: Baxter	     90 	  Somewhat limited   Seepage	      0.03	    Not limited   		    Very limited   Depth to water	1.00
BaC: Baxter	   85 	  Somewhat limited   Seepage	    0.03	  Not limited 		  Very limited   Depth to water	1.00
BaD: Baxter	   85   	Somewhat limited   Slope   Seepage	    0.04  0.03	  Not limited   		  Very limited   Depth to water	1.00
BaE: Baxter	     80   	  Somewhat limited   Slope   Seepage	    0.28  0.03	  Not limited 	       	  Very limited   Depth to water	1.00
BbC3: Baxter	     85 	  Somewhat limited   Seepage	      0.03	  Somewhat limited   Hard to pack	0.26	  Very limited   Depth to water	1.00
BbD3: Baxter	     85   	  Somewhat limited   Slope   Seepage	    0.04  0.03	  Somewhat limited   Hard to pack	    0.26	  Very limited   Depth to water	1.00
CaB, CaC: Caneyville	     85 	  Somewhat limited   Depth to bedrock	      0.93	  Somewhat limited   Thin layer   Hard to pack	    0.93  0.51	  Very limited   Depth to water	1.00
CaC3: Caneyville	     85 	  Somewhat limited   Depth to bedrock	      0.93	  Somewhat limited   Hard to pack   Thin layer	      0.96  0.93	  Very limited   Depth to water	1.00
CnD: Caneyville	     65 	  Somewhat limited   Depth to bedrock   Slope		  Somewhat limited   Thin layer   Hard to pack	    0.93  0.51	  Very limited   Depth to water	1.00
Rock outcrop	   25   	Very limited Depth to bedrock Slope	!	  Not rated 		  Not rated 	     
CnF: Caneyville	     65 	Somewhat limited Depth to bedrock Slope	      0.93  0.88	  Somewhat limited   Thin layer   Hard to pack	      0.93  0.51	  Very limited   Depth to water	1.00
Rock outcrop	   25 	  Very limited   Depth to bedrock   Slope	    1.00  0.88	  Not rated   		  Not rated   	     

Table 18.-Water Management-Continued

Map symbol and soil name	Pct. of	Pond reservoir ar	eas	   Embankments, dikes   levees	, and	Aquifer-fed excavated pond	ls
	map  unit	Rating class and limiting features	Value 	Rating class and   limiting features	Value 	Rating class and limiting features	Value
CrB: Crider	     90 	    Somewhat limited   Seepage	      0.72	    Not limited   	       	    Very limited   Depth to water	1.00
CrC: Crider	   85 	  Somewhat limited   Seepage	    0.72	  Not limited 	     	  Very limited   Depth to water 	1.00
DAM: Dam, large	  100 	  Not rated 	;   	  Not rated 	j   	  Not rated 	j   
Du: Dunning	   85       	  Not limited   	           	  Very limited   Ponding   Depth to   saturated zone   Hard to pack	  1.00  1.00      0.36	  Somewhat limited   Slow refill   Cutbanks cave 	0.28
EkB: Elk	   80 	  Somewhat limited   Seepage	    0.72	  Very limited   Piping	1.00	  Very limited   Depth to water	1.00
EpB: Epley	   85     	  Somewhat limited   Seepage 	    0.72 	  Very limited   Depth to   saturated zone	    1.00 	  Very limited   Depth to water 	1.00
FeB: Fredonia	   50 	Somewhat limited   Depth to bedrock   Seepage	!	  Somewhat limited   Thin layer   Hard to pack	    0.61  0.49	  Very limited   Depth to water	1.00
Vertrees	   35 	  Not limited   	     	  Somewhat limited   Hard to pack 	0.77	  Very limited   Depth to water 	1.00
FeC: Fredonia	   50 	  Somewhat limited   Depth to bedrock   Seepage	!	  Somewhat limited   Thin layer   Hard to pack	    0.61  0.49	  Very limited   Depth to water 	1.00
Vertrees	   30 	  Not limited   	     	  Somewhat limited   Hard to pack	0.77	  Very limited   Depth to water	1.00
FrC: Frondorf	     85   	  Somewhat limited   Seepage   Depth to bedrock	    0.72  0.23	  Somewhat limited   Thin layer   Piping	    0.95  0.95	  Very limited   Depth to water 	1.00
FrD: Frondorf	   85     	  Somewhat limited   Seepage   Depth to bedrock   Slope	  0.72  0.23  0.04	  Somewhat limited   Thin layer   Piping 	    0.95  0.95 	  Very limited   Depth to water 	1.00
Gr: Grigsby	   90     	  Very limited   Seepage 	    1.00 	  Very limited   Piping   Seepage	    1.00  0.03	  Very limited   Depth to water 	1.00

Table 18.-Water Management-Continued

Map symbol and soil name	  Pct.   of	   Pond reservoir ar 	eas	   Embankments, dikes   levees	, and	Aquifer-fed excavated pond	ls
	  map  unit	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
HaB: Hammack	     85 	    Somewhat limited   Seepage	      0.72	    Not limited 		    Very limited   Depth to water	1.00
La: Lawrence	   90   	  Not limited     	       	  Very limited   Depth to   saturated zone   Piping	  1.00    0.94	  Very limited   Depth to water 	1.00
Ld: Lindside	     90     	  Somewhat limited   Seepage   	      0.72   	  Very limited   Depth to   saturated zone   Piping	    1.00    0.99	  Somewhat limited   Slow refill   Cutbanks cave	  0.28  0.10
Me: Melvin	   80     	  Somewhat limited   Seepage   	    0.72   	  Very limited   Depth to   saturated zone   Piping	    1.00    0.95	  Somewhat limited   Slow refill   Cutbanks cave	  0.28  0.10
Ne: Newark	   90     	  Somewhat limited   Seepage 	    0.72 	  Very limited   Depth to   saturated zone   Piping	  1.00    1.00	  Somewhat limited   Slow refill   Cutbanks cave	0.28
Nf: Newark	   90       	  Somewhat limited   Seepage   	      0.72   	  Very limited   Ponding   Depth to   saturated zone   Piping	  1.00  1.00    1.00	  Somewhat limited   Slow refill   Cutbanks cave 	  0.28  0.10
NhA, NhB: Nicholson	     80     	  Somewhat limited   Seepage   	      0.72   	  Very limited   Depth to   saturated zone   Piping	    1.00    0.06	  Very limited   Depth to water 	    1.00 
NhC: Nicholson	   85       	  Somewhat limited   Seepage   	    0.72   	  Very limited   Depth to   saturated zone   Piping	  1.00    0.06	  Very limited   Depth to water 	1.00
No: Nolin	   90 	  Somewhat limited   Seepage 	    0.72	  Somewhat limited   Piping	0.80	  Very limited   Depth to water	1.00
Np: Nolin	     90   	  Somewhat limited   Seepage 	    0.72	  Very limited   Ponding   Piping	    1.00  0.80	  Very limited   Depth to water	1.00
OtA, OtB: Otwood	     90     	  Somewhat limited   Seepage   	      0.72   	  Very limited   Depth to   saturated zone   Piping	    1.00    0.57	  Very limited   Depth to water   	1.00

Table 18.-Water Management-Continued

Map symbol and soil name	  Pct.   of	   Pond reservoir ar 	eas	   Embankments, dikes   levees	, and	Aquifer-fed excavated pond	ls
	map  unit	Rating class and limiting features	Value 	Rating class and limiting features	Value 	Rating class and limiting features	Value
PbA: Pembroke	     90 	  Somewhat limited   Seepage	      0.72	    Somewhat limited   Hard to pack	      0.31	    Very limited   Depth to water	1.00
Pm: Pits, loamy, frequently flooded-	     95	    Not rated	     	    Not rated	     	    Not rated 	     
Pq: Pits, quarry	   90 	  Not rated 	   	  Not rated 	   	  Not rated 	   
RaF: Ramsey	   75 	  Very limited   Depth to bedrock   Slope	    1.00  0.88	  Very limited   Thin layer   Piping	    1.00  1.00	  Very limited   Depth to water	1.00
Frondorf	   20     	   Somewhat limited   Slope   Seepage   Depth to bedrock	  0.88  0.72  0.23	  Very limited   Piping   Thin layer 	    1.00  0.95 	  Very limited   Depth to water   	1.00
Ro: Robertsville	   90         	  Somewhat limited   Seepage 	    0.72     	   Very limited   Ponding   Depth to   saturated zone   Piping	  1.00  1.00    0.53	  Somewhat limited   Slow refill   Cutbanks cave	0.28
RxF: Rock outcrop	   55   	  Very limited   Depth to bedrock   Slope	!	  Not rated   	     	  Not rated   	     
Caneyville	   33   	  Somewhat limited   Depth to bedrock   Slope	    0.93  0.88	  Somewhat limited   Thin layer   Hard to pack	    0.93  0.51	  Very limited   Depth to water 	1.00
SaA, SaB: Sadler	   85     	  Somewhat limited   Seepage 	    0.72 	  Very limited   Depth to   saturated zone   Piping	    1.00    0.98	  Very limited   Depth to water 	1.00
VrC3: Vertrees	     85 	  Somewhat limited   Seepage	    0.04	  Somewhat limited   Hard to pack	    0.83	  Very limited   Depth to water	1.00
W: Water	    100	    Not rated	   	    Not rated	į Į	    Not rated	
WeB: Wellston	     90   	  Somewhat limited   Seepage   Depth to bedrock	      0.72  0.22	  Somewhat limited   Piping   Thin layer	      0.98  0.22	  Very limited   Depth to water 	1.00
WeC2: Wellston	     85   	  Somewhat limited   Seepage   Depth to bedrock	    0.72  0.22	  Somewhat limited   Piping   Thin layer	    0.99  0.22	  Very limited   Depth to water	1.00

Table 18.-Water Management-Continued

Map symbol and soil name	Pct.	Pond reservoir ard	eas	   Embankments, dikes   levees	, and	Aquifer-fed excavated pond	ls
	map unit	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
ZaB: Zanesville	     85     	  Somewhat limited   Seepage   Depth to bedrock	    0.72  0.01	  Very limited   Depth to   saturated zone   Piping	      1.00    0.99	  Very limited   Depth to water	1.00
ZaC2: Zanesville	     80     	  Somewhat limited   Seepage   Depth to bedrock 	    0.72  0.01 	  Very limited   Depth to   saturated zone   Piping	    1.00    0.99	  Very limited   Depth to water   	1.00

Table 19.-Engineering Index Properties

(Absence of an entry indicates that the data were not estimated. Map units that have Urban land as a major component were not rated and are not included in this table)

Map symbol	Depth	USDA texture	Classification	cation	Fragments	ents	Per	Percentage passing sieve number	passir	JG T	Liquid	Plas-
and soil name			Unified	AASHTO	>10 inches	3-10	4	10	40	200	limit	ticity
	티				Pct	Pat					Pat	
BaB, BaC, BaD, BaE:												
Baxter	8-0	Gravelly silt	MIL, GC-GM,	A-4	0	0-10	06-09	55-80	45-70	45-70	25-35	4-10
		loam	MI									
	8-15	Gravelly silty clay loam,	CL, CL-ML,	A-4, A-6		0-10	06-09	55-80	55-80	45-80	25-40	5-20
		gravelly silt										
	15-61	Gravelly clay,	CH, CL, GC	A-7	0	0-10	55-90	45-85	45-85	45-80	40-60	20-35
		clay										
	61-81		CH, CL, GC	A-7	0	0-10	55-90	45-85	45-85	45-80	40-60	20-35
		silty clay										
BbC3, BbD3:												
Baxter	e-0 	Gravelly silty	턴_	A-6	 o	0-10	60-85	55-75	55-75	55-75	30-40	15-22
	3-61	Gravelly silty clay, gravelly	CH, CL, GC	A-7	0	0-10	55-90	45-85	45-85	45-80	40-60	20-35
		clay		1								
	18-19	Very gravelly	CH, CL, GC	A-7	 -	01-0	55-90	45-85	45-85	45-80	40-60	20-35
		silty clay										
CaB, CaC:												
Caneyville	9-0	Silt loam	CL, CL-ML, ML A-4,	A-4, A-6	0	0-3	90-100	85-100	75-100	60-95		2-12
	6-11	Silty clay,   clay, silty		A-7	 o	0-3	90-100	85-100	75-100	75-100 65-100	42-70	20-45
		clay loam			_							
	11-27	Clay, silty	<u> </u>	A-7	 o	0-3	90-100	85-100	75-100	65-100	50-75	30-45
	27-29	Unweathered	- -	;	 ¦	-	;	 ¦	-			;
		bedrock										

Table 19.-Engineering Index Properties-Continued

Map symbol	Depth	USDA texture	Classification	ication	Fragments	nents	Per	rcentage sieve nu	Percentage passing sieve number		Liquid	Plas-
and soil name	•		Unified	AASHTO	>10 inches	3-10 inches	4		40	200		ticity index
	띠				Pct	Pct					Pct	
CaC3: Caneyville	0-3	G.	GH, CL	A-7	0	0-3				75-100	45-65	25-45
	3-27	Clay, silty clay	<b>8</b>	A-7	 o	0-3	90-100	85-100	75-100   6 	55-100		30-45
	27-31	Unweathered   bedrock					:		 			:
CnD, CnF: Caneyville	9-0	  Silt loam	CL, CL-ML, ML		0	0-3	90-100	85-100	75-100   6		20-35	2-12
	6-11	Silty clay,   clay, silty	년 <b>,</b> 면,	A-7		0-3	90-100	85-100		65-100 , 		20-45
	11-27	clay loam	8_	A-7	0	0-3	90-100	85-100	75-100   6	65-100	50-75	30-45
	27-31	Clay  Unweathered   bedrock				-	 ¦		 ¦		 ¦	:
Rock outcrop.												
CrB, CrC: Crider	0 9 - 0 82 - 0	Silt loam	CL, CL-ML	A-4, A-6 A-4, A-6, A-7	00	00	100	95-100	90-100 8	85-100	25-35	4-12
		loam, silt		;		· <del>_</del>						<u> </u>
	28-50	Silty clay   loam, silty	면, 단	A-6, A-7	o 	0-5	85-100	75-100	70-100   6	60-100	35-65	15-40
	50-80	clay, clay Clay, silty clay, silty clay loam	CH, CL	A-6, A-7	o 	0 - 5	85-100	75-100	70-100 60-100		35-65	15-40
DAM. Dam, large						<u>-</u>						
Du: Dunning	0-9 9-25	Silty clay loam Silty clay, clay, silty	1 GH, GE	A-6, A-7 A-7	0 0	0 0	100	95-100	90-100 8	85-95	34-42 45-70	15-22 20-40
	25-71	clay loam Clay, silty clay, silty clay loam	С <b>Н</b> , СІ.	A-7	0	0	95-100	95-100	95-100 90-100 85-100		45-70	20-40

Table 19.-Engineering Index Properties-Continued

			Classification	cation	Fragments	ents	Per	Percentage passing	passin	מ		
Map symbol	Depth	USDA texture			-		α -	sieve number-	mper		_ 	Plas-
and soil name			Unified	AASHTO	>10  inches	3-10 inches	4	10	40	200	limit 	ticity index
	티				Pct	Pat					Pct	
EkB: Elk	0-10	Silt loam	ML	A-4	0	0	95-100	95-100	85-100	70-95	25-35	3-10
	10-20	Silt loam,	, CL-ML	A-4, A-6	0	0	95-100		85-100		25-40	5-15
	20-65	loam Silt loam, silty clay loam	CI, CI-MI	A-4, A-6	0	0	95-100	90-100	85-100 75-100		25-40	5-15
EpB: Epley	6-0	Silt loam		A-4	0	0	95-100	95-100	90-100	80-100	25-35	3-10
	9-24	Silt loam,   silty clay	CL, CL-ML	A-4, A-6	 •	o •	95-100	95-100 	90-100 	80-100 	25-40   	5-20
	24-41	loam  Silty clay,	CH, CL	A-6, A-7	 o	o	95-100	95-100	90-100	85-100	35-65	20-35
	41-65	Silty clay, clay, channery clay	CH, CL, GC,	A-7	0	0-20	60-100	40-100	40-100	40-95	40-70	20-40
FeB, FeC:	ر ا ا			8 - 4 9 - 4		ر ا ا	و 1	001-06	7001	75-100	05-40	00
	5-22	Silty clay,	CH, CL	A-7	· · ·	0-0	95-100		85-100	80-100	45-75	20-45
	22-37	Silty clay,	CH, CL	A-7	0	0-5	95-100	90-100	85-100	80-100	45-75	20-45
	37-39	Unweathered bedrock		-								
Vertrees	0-6	Silt loam Silty clay loam, silty	CL, CL-ML, ML	ML   A-4, A-6   A-7	o o	00	85-100 85-100	80-100 75-100	70-95	55-90	20-40   41-70	3-20 25-45
	15-80	clay Silty clay, gravelly clay	 	A-7	0	0-10	75-100	75-100	70-90	65-80	50-70	25-45

Table 19.-Engineering Index Properties-Continued

Map symbol	Depth	USDA texture	Classification	ication	Fragi	Fragments	Peı	Percentage passing sieve number	passii mber	bu	Liquid	Plas-
and soil name					>10						limit	ticity
			Unified	AASHTO	inches	inches	4	10	40	200		index
	H				Pct	Pct					Pat	
FrC, FrD:												
Frondorf	0-5	Silt loam  Channery silty	CL, CL-ML	A-4  A-2   A-4	0 10	0-5	90-100   55-90	90-100	85-100	75-100	25-35     15-45	5-10 NP-25
	0 1 0	clav loam,	3	A-6. A-7	 	P 		0	0			74
		silty clay		: : :								
		loam, channery										
		silt loam,										
		channery loam										
	18-26	Very channery	턴	A-2, A-4,	0-5 -0	10-40	55-90	- 28-05	40-80	30-75	15-45	NP-25
		Silty Clay		A-6, A-7								
		silt loam,										
		channery loam										
	26-30	Weathered	:	;	!	-	-	:	-	-	-	1
		bedrock 										
Gr:												
Grigsby	6-0	Sandy loam			_ _	0-2	80-100	80-100	20-02		15-20	NP-5
	9-41	Sandy loam,	SC-SM, SM	A-2, A-4	0	0-2	80-100	80-100	70-100	30-70		NP-5
		Ilne sandy										
	41-80	roam   Fine sandy	CL-ML, ML,	A-4	0	0	80-100	70-100 40-80	40-80	40-75	0-35	NP-15
			SC-SM, CL		_	_	_				_	
		sandy clay										
		loam 										
HaB:												
Hammack	6-0	Silt loam	CL-ML, ML	,	_ ·	0	100	95-100	90-100	85-100	25-35	4-10
	9-30	Silt loam,	CT, ML	A-4, A-6, A-7		o 	001	00T-56	001-06	- c6-c8	30-45	9-20
		Siley Ciay   loam										
	30-41	Very gravelly	CL, GC, GM,		0	15-35	25-80	22-75	22-75	18-70	30-45	6-20
		silt loam,	TW -	A-6, A-7								
		very graverry   silty clay										
		loam			_	_						
	41-84	7 11	GH, CL, GC	A-2, A-7	o 	10-40	40-75	30-75	30-70	25-70	45-70	20-40
		clay, very   gravelly silty										
		clay, clay				_						
					_	_	_	_	_	_	_	

Table 19.-Engineering Index Properties-Continued

Plas-	ticity  index		2-10	5-20	2-15	2-20		NP-10 3-20	5-10	5-20	16-40
Liquid	limit	Pct	25-35	25-42	20-35	25-40	25-35	15-32	25-35	25-45	34-70
61	200		80-100	80-100	55-90 70-95	55-95	80-95 80-95	55-95 70-100	80-95 80-100	75-100	55-100
passing	40		90-100	90-100	80-100	80-100	80-100	80-100	85-100 85-100	80-100	60-100
Percentage passi sieve number	10		95-100	95-100	95-100	95-100	90-100	90-100	95-100 85-100	90-100	70-100 60-100
Per	4		100	100	100	100	95-100	95-100	95-100 95-100	95-100	80-100
nents	3-10 inches	Pat	0 0	0	0 0	0	00	00	00	0	0-10
Fragments	>10   3-10 inches inches	Pct	0 0	0	0 0	0	o o	o o	0 0	0	0
			A-7	A-7				A-7	A-7	A-7	
ű	AASHTO		A-6,	A-6,	A-6 A-6	A-6	A-6	A-6,	A-6,	A-6,	A-7
Classification	*		A-4 A-4,	A-4,	A-4, A-4,	A-4,	A-4 A-4,	A-4 A-4,	A-4 A-4,	A-4,	A-6,
ssifi					MI	Ä		M K	¥		
Clas	Unified		CL-ML	CL-ML	CL-ML,	CL-ML,	CL-ML	CL-ML,	CL-ML, CL-ML	CL-ML	Ŋ
			필 년	_ <u>ਚੇ</u>	<u>- ਜ਼੍ਰੇ ਜ਼੍ਰੇ</u>	_ਜੁ	<u>ਬੇ</u> ਈ	<u> ਈਂ ਈਂ</u>	<u>ಕೆ ಕೆ</u>	_ <u>ਰੇ</u>	_ <del>[</del>
USDA texture			Silt loam Silty clay loam, silt	Loam Silty clay loam, silt loam	Silt loam Silty clay loam, silt	Loam Silt loam, Silty clay loam	Silt loam Silty clay loam, silt	Silt loam Silt loam, silty clay	Silt loam Silty clay loam, silt	loam Silt loam, silty clay	loam Clay, silty clay, gravelly silty clay
Depth		티	0-7	18-65	0-10	42-65	0 - 9 9 - 62	0-11	0 - 6 - 25	25-37	37-62
Map symbol	and soil name		Lawrence		Ld: Lindside		Melvin	Ne, Nf: Newark	Nha, NhB, NhC: Nicholson		

Table 19.-Engineering Index Properties-Continued

Map symbol	Depth	USDA texture		Classification	catio	ď	Fragments	lents	Per	rcentage pass sieve number-	Percentage passing sieve number	מ	Liquid	Plas-
and soil name				Unified	AA	AASHTO	>10 inches	3-10 inches	4	10	40	200	limit	ticity index
	티						Pct	Pct					Pat	
No, Np: Nolin		Silt loam	<u> </u>	CI-MI	A-4,	N-6	0	0	100	95-100	90-100	80-100	25-40	5-18
	9-65	Silt loam,   silty clay   loam		CL-ML		A-6, A-7		0	100	95-100	85-100	75-100	25-46	5-23
Ota, OtB:	9-0	  Silt loam	_ <u></u>	CI-MI	A-4	A-6	0	0	100	100	90-100	70-95	25-35	5-15
	6-28	silt loam,				A-6	0	0	100	100	90-100	70-95	25-40	5-20
		Silty Clay   loam												
	28-37	Silt loam,	번_		A-6,	A-7	 •	0	95-100	95-100	85-100 65-90	65-90	35-50	15-30
	37-80		년_		A-6,	A-7	0	0	95-100	75-100	95-100 75-100 75-100	65-95	35-50	15-30
PbA:														
Pembroke	0-9	Silt loam  Silt loam,	<u>ਜ਼੍ਹੇ</u> ਜ਼		A-4,	A-6	 • •	o o	95-100	90-100	80-100   70-100     85-100   75-100	70-100 75-100	25-40    30-45	3-16
		silty clay												
	18-62	Silty clay   loam, silty	<u> </u>	 5	A-6,	A-7	0	0	90-100	75-100	90-100 75-100 75-100 65-100	65-100	35-65	20-45
	62-80	. 0		 CI	A-7		0	0	85-100		75-100 70-100	60-95	45-70	20-45
		clay												
Pm. Pits, loamy, frequently flooded														
Pq. Pits, quarry														
RaF: Ramsey	0-4	Loam	<u> </u>	Tr-Mr,	A-2,	A-4	0	0-10	85-100 75-95	75-95	60-75	34-70	15-25	2 1 8
	4-19	Channery loam,   sandy loam,	CL-MI	ML, M	A-2,	A-4	0	0-10	85-100	75-95	60-75	30-70	15-25	NP-8
<b>-</b>	19-20													

Table 19.-Engineering Index Properties-Continued

	Depth	USDA texture	Classification	cation	Fragi	Fragments	Per	Percentage passing sieve number	passin	<u>ნ</u>	Liquid	Plas-
and soil name	ı				>10	3-10						ticity
			Unified	AASHTO	inches	inches	4	10	40	200		index
	η				Pct	Pct					Pct	
RaF: Frondorf	0-18	Silt loam	CL-ML, ML, CL	CI.   A-4	0	0 - 5	90-100	90-100	85-100	75-100	25-35	5-10
	18-26	Very channery		A-4, A-6,	0-5	10-40	25-90	50-85			15-45	NP-25
		silty clay   loam, channery	MI	A-7, A-2								
		channery loam										
	26-30	Unweathered	:	-		-		-		-	-	1
		bedrock										
									_			
Robertsville	0-10	Silt loam			0	0	95-100	001-56	85-100	75-100	25-35	2-10
	10-28		CI, MI	A-4, A-6	0	0	95-100	95-100	001-06	80-100	25-45	3-20
		silty clay										
		Loam										
	28-40	U	CL, ML	A-4, A-6	0	0	95-100	95-100	95-100   90-100   80-100		25-45	3-20
		loam, silt										
	1		ŧ			L	0	00 100 45 100 40 100 25 70	7			1
	40-70		CH, CL, CL-ML	CL-ML A-4, A-6, A-/		n    -	     	001-6/	     		72-60	U - C
		clay, silt					_	_	_	_	_	
		loam										
RxF:												
Rock outcrop.												
Caneyville	9-0	Silt loam	CL, CL-ML, ML A-4,	A-4, A-6	0	0-3	90-100		75-100	60-95		2-12
	6-11	Silty clay,	GH, CL	A-7	0	0-3	001-06	85-100	85-100 75-100 65-100	65-100	42-70	20-45
		clay, silty										
	11-27	Clay, silty	8	A-7	0	0-3	90-100	85-100	75-100	65-100	50-75	30-45
	27-29	Unweathered	:	-	-	-	 ¦	<u> </u>				-
		Dedrock										

Table 19.-Engineering Index Properties-Continued

Codmin	5 5 7	4 6001	Classification	cation	Fragments	ents	Per	Percentage passing	passin	<u></u>		ָרָ ק
and soil name	; h	נ	Unified	AASHTO	>10 inches	3-10 inches	4.	10	40	200		ticity index
	티				Pat	Pct					Pct	
Sad, SaB: Sadler	0-9 9-26	oam, oam,	CL-ML, ML	A-4, A-6	0 0	0 0	95-100	95-100	85-100 85-100	80-100 75-100	25-35	4-10 5-20
	26-56	clay	CL, CL-ML, ML	A-4, A-6	0	0-10	85-100	80-100	70-100	55-95	20-40	2-20
	56-65	loam, loam Loam, silty clay loam,	CL, GM, ML,	A-4, A-6, A-7	0	0-20	65-100	60-95	50-95	36-90	20-50	2-30
	65-67	1 4 6										
VrC3: Vertrees	0-3 3-20	clay loam silty	GF, GF	A-6 A-7	00	0 0	85-100			65-95 65-95		12-20 25-45
	20-80	Clay, gravelly   clay	CH.	A-7	0	0-10	75-100	75-100		65-80	50-70	25-45
W. Water												
Wellston	0-8 8-13 13-30 30-46	Silt loam Silt loam Silty clay loam Gravelly clay loam, loam,	ML CL, CL-ML CL, CL-ML CL, CL-ML, SC, SC-SM	A-4 A-4, A-6 A-4, A-6 A-4, A-6	0000	0 0 0-10	95-100 75-100 75-100 65-90	90-100 70-100 70-100 65-90	85-100 60-95 60-95 60-90	70-95 60-90 60-90 40-65	25-35 25-40 25-40 25-40	3-10 5-20 5-20 5-15
	46-48	silt loam Unweathered bedrock				1						
WeC2: Wellston	0-5	oam oam, clay	ML CL, CL-ML	A-4 A-4, A-6	00	0 0	95-100	90-100	85-100 60-95	70-95	25-35	3-10
	30-46	.ly loam, silt	CL, CL-ML, SC, SC-SM	A-4, A-6	0	0-10	65-90	65-90	06-09	40-65	20-35	5-15
	46-50	loam Unweathered bedrock										

Table 19.-Engineering Index Properties-Continued

Map symbol	Depth	USDA texture		Classification	cation	Fragi	Fragments	Per	rcentage passi sieve number	Percentage passing sieve number		Liquid	Plas-
and soil name			_			>10	3-10					limit	ticity
			$\rfloor$	Unified	AASHTO	inches	inches	4	10	40	200		index
	티					Pct	Pct					Pct	
ZaB:													
Zanesville	0-8	Silt loam	년	CI-MI	A-4, A-6	0	0	95-100	95-100	90-100	80-100	25-40	4-15
	8-23	Silt loam,	<u>ਜ</u> ੍ਹੇ_	CI-MI	A-4, A-6	0	0	95-100	95-100	95-100   90-100   80-100	80-100	25-40	5-20
	23-45	Silt loam,	<u>f</u>	CL-ML, ML A-4,	A-4, A-6	0	0-3	90-100	85-100	80-100	60-100	20-40	2-20
		silty clay	_	_						_			
			_			_		_	_	_		_	
	45-56		<u>Ę</u>	GM, SC,	A-1-b, A-2,	_ _	0-10	65-100   50-95	_	40-95	20-85	20-40	2-20
			SM		A-4, A-6					_			
			_					_		_			
			_			_		_		_		_	
		loam, silty	_	_		_	_	_	_	_	_		
_		clay loam	_	_	_	_	_	_	_	_	_	_	
_	26-58	Unweathered	_	-	-	_ ¦ _	-	_ ¦ _	-	-	-	-	1
		bedrock											
ZaC2:													
Zanesville	0-5	Silt loam	<u>ਰ</u>	CL-ML	A-4, A-6	0	0	95-100	95-100	90-100	80-100	25-40	4-15
	5-20	Silt loam,	<u>f</u>	CI-MI	A-4, A-6	0	0	95-100	95-100	90-100	80-100	25-40	5-20
		silty clay				_		_	_			_	
		loam	_	_		_	_	_	_	_	_	_	
	20-45	U	<u>ਜੁ</u>	CL-ML,	ML   A-4, A-6	- •	0-3	90-100	85-100	80-100	60-100	20-40	2-20
		silty clay	_			_		_		_		_	
		loam	_	_				_	_	_	_	_	
	45-56	Sandy clay	<u>ŋ</u>	GM, SC,	A-1-b, A-2,	_ 。 _	0-10	62-100	20-95	40-95	20-85	20-40	2-20
		loam, clay	SM	_	A-4, A-6								
		loam, channery	<u>.</u>		_	_		_	_	_	_	_	
			_	_		_	_	_	_	_	_	_	
		loam, silty	_	_		_	_	_	_	_	_		
_		clay loam	_	_		_	_	_	_	_	_	_	
	26-58	Unweathered		-	-	_    -	-	_    -		-		-	1
		bedrock											

Table 20.-Physical Properties of the Soils

(Entries under "Erosion factors--T" apply to the entire profile. Absence of an entry indicates that data were not estimated. See table 21 for ratings for map units that have Urban land as a major component)

			-	-						0 0	400	100
Map symbol	Depth	Sand	Silt	Clay	Moist	Permea-	Available	Linear	Organic			
and soil name	ı 				bulk density	bility (Ksat)	water	extensi- bility	matter	Kw	Κ Ψ	H
	티	Pat	Pat	Pat	<u>a/cc</u>	In/hr	In/in	Pct	Pct			
BaB, BaC, BaD, BaE:												
Baxter	0-8	-5	50-80		1.20-1.40		0.14-0.18	0.0-2.9	2.0-4.0	- 28	.37	2
	15-61	0 - L	40-73	18-40 40-60	1.30-1.55	20-2-00	0.14-0.18	3.0-0.6	0.0-C-C-C-C-C-C-C-C-C-C-C-C-C-C-C-C-C-C-	42.	ئ ا ا	
	61-81	0-45	0 - 3		1.30-1.55		0.10-0.14	3.0-5.9	0.0-0.0	2. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4.	2 8 8	
BbC3, BbD3:												
Baxter	0-3	0-19	40-73		1.20-1.45	0.60-2.00	0.12-0.18	0.0-2.9	0.5-3.0	.24	.32	2
	3-61	0-19	40-60	40-60	1.30 - 1.55	0.20-0.57	0.10-0.14	3.0-5.9	8-0-0-0	24.	2 28	
CaB, CaC:												
Caneyville	9-0	-5	20-80	_	1.20-1.40	0.60-2.00	0.15-0.22	0.0-2.9	2.0-4.0	.43	.43	м
	6-11	0-19	40-60	_		0.06-0.20	0.12-0.18	3.0-5.9	0.1-0.0	- 28	- 28	
	7	0-44	0-39	40-60	1.35-1.60	0.00-0.20	0.12-0.18	3.0-8.9	0.0-0.0	- 28	- 28	
	27-29		-	-	-	00.0-00.0	-	!	:	-	-	
CaC3:	,, I	0 1 0	40-60	40-60	1 30-1 55	06-0-90	0 1 3 - 0 1 8	9 7 9	0 2 - 2	32	32	c
		1 4	68-0		1.35-1.60	0-00	0.12-0.18		0.0-0.0	2 2	2 0	1
	27-31	-	:		-	.00-0	;	;	- !			
1												
Canb, cnr:	1	101	ם מ	10-27	1 20-1 40	00 6-09	0.15-0.22	0-0	0-4-0	43	4.3	~
	6-1	01-01	40-60		1.35-1.60	0.06-0-20	0.12-0.18	0 0		200	0 00	ו
	11-27	0-44	0-39		1,35-1,60	0.00-0.20	0.12-0.18	0.8-0.8	0.0-0.8	7 7 8 7 8 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9	7 8 8	
	27-31	-	- 1			00.0-00.0	!	-				
Rock outcrop.												
CrB, CrC:												
Crider	0-0	10-50	50-80		1.20-1.40	0.60-2.00	0.19-0.23	0.0-2.9	0.0-4.0	. 32	32	വ
	28-50	0-19	40-73	28-40	1.20-1.55	.60-2.00	0.12-0.18	3.0-5.9	0.0-0.8	. 28	7 7 8 8	
	20-80	4-	0-39		1.20-1.55	.20-0.57	0.12-0.18	3.0-5.9	0.0-0.8	.28	.28	
DAM.												
ì												
Dunning	6-0	0-19	40-73		1.20-1.40	0.60-2.00	0.19-0.23	3.0-5.9	1.0-4.0	.32	.32	2
	9-25	0-19	40-60	35-60	1.40-1.65   1.40-1.65	0.06-0.20	0.14-0.18   0.14-0.18	3.0-5.9	0.2-1.0	7 7 8 8 8 8	7 7 8	
_									_	_	_	

Table 20.-Physical Properties of the Soils-Continued

										Erosion	n factor	ors
Map symbol and soil name	Depth	Sand	Silt	Clay	Moist bulk density	Permea- bility (Ksat)	Available water capacity	Linear extensi- bility	Organic matter	Kw	1 24	EH
	ᄪ	Pct	Pct	Pct	g/cc	In/hr	In/in	Pct	Pct			
EkB: Elk	0-10 10-20 20-65	10-50 0-50 0-19	50-80 50-80 40-73	10-27 18-34 18-34	1.20-1.40 1.20-1.50 1.20-1.50	0.60-2.00 0.60-2.00 0.60-2.00	0.19-0.23 0.18-0.22 0.18-0.22	0.0-2.9	0.5-3.0	.28	288	Ŋ
Epley	0-9 9-24 24-41 41-65	5-50 0-19 0-19	50-80 40-73 40-60 0-39	12-27 18-40 40-60	1.20-1.40 1.20-1.45 1.30-1.55 1.35-1.60	0.60-2.00 0.60-2.00 0.00-0.20 0.00-0.20	0.19-0.23 0.18-0.22 0.13-0.18	0.00-12 0.00-12 3.00-15.9	2.0-4.0 0.0-1.0 0.0-0.8	. 43	. 43 . 37 . 28	m
FeB, FeC: Fredonia	0-5 5-22 22-37 37-39	10-50 0-19 0-44	50-80 40-60 0-39	15-27 40-60 40-60	1.30-1.50	0.60-2.00 0.06-0.60 0.06-0.20	0.18-0.22 0.13-0.18 0.13-0.18	0.00-2 3.00-2 3.00-5.9	0.00-0.8		1 2 2 3	м
Vertrees	0-6 6-15 15-80			15-27 35-60 40-60	1.20-1.40 1.40-1.65 1.45-1.65	0.60-2.00 0.20-0.60 0.06-0.20	0.18-0.22 0.14-0.18 0.10-0.16	0.0-2.9 3.0-5.9 3.0-5.9	1.0-3.0	.28	.28	Ŋ
FrC, FrD:	0-5 5-18 18-26 26-30	10-50 0-19 0-19	50-80 40-73 40-73	18-27 18-35 18-35	1.20-1.40 1.20-1.45 1.20-1.45 	0.60-2.00 0.60-2.00 0.60-2.00 0.00-0.06	0.18-0.22 0.08-0.16 0.08-0.16	0.00	0.010.8	.37	2.2.3	м
Gr: Grigsby	0 - 9 - 1 -	43-85 23-52	0-49 0-49 28-50	5-10 5-18 10-35	1.20-1.50 1.20-1.50 1.20-1.50	0.9-00.	0.14-0.18 0.12-0.16 0.12-0.16	0.0-2.9	1.0-4.0	7 7 7 8 8 8	3 3 2 8	rv
Нав: Наптаск	0-9 9-30 30-41 41-84	10-50 0-50 0-50 0-39	50 - 80 50 - 80 50 - 80	12-27 18-35 18-35 40-60	1.20-1.40 1.20-1.45 1.20-1.45 1.35-1.65	0.60-2.00 0.60-2.00 0.60-2.00 0.20-0.57	0.19-0.23 0.18-0.23 0.05-0.10	0.0-2.9 0.0-2.9 0.0-2.9	2.0-4.0 0.0-0.8 0.0-0.8	. 32	332	4
La: Lawrence	0-7 7-18 18-65	10-50 0-19 0-19	50-80 40-73 40-73	12-27 18-35 18-35	1.20-1.40 1.40-1.60 1.50-1.70	0.60-2.00 0.60-2.00 0.00-0.20	0.19-0.23 0.18-0.22 0.00-0.02	0.0-2.9 0.0-2.9 0.0-2.9	1.0-4.0	. 43	.43	m

Table 20.-Physical Properties of the Soils-Continued

factors	H ———		.32 5	.43 	.43 5	£ 4. 4. 8. 8. 8. 8. 8. 8. 8. 8. 8. 8. 8. 8. 8.	. 4. 5 4. 8 4. 8 4. 8 4. 8 4.	.43 .43 .43	. 32 . 28 . 28 . 28			
Erosion												
Ero			32 .32	.43		8 - 4 3 8 - 4 3 8 - 4 3 8 - 4 3						
_	Organic  matter 	Pat	2.0-4.0 0.0-0.8	0.5-3.0	1.0-4.0	0.000	2.0-4.0	0.00.00.00.00.00.00.00.00.00.00.00.00.0	2.0-4.0 0.5-1.0 0.0-0.8 0.0-0.8			
	Linear extensi- bility	Pat	0.0-2.9 0.0-2.9 0.0-2.9	0.0-2.9	0.0-2.9	0.012.9	0.00	0 - 2. 0 - 5. 0 - 5.	0.0-2.9 0.0-2.9 3.0-5.9			
	Available water capacity	In/in	0.20-0.26 0.17-0.22 0.17-0.22	0.18-0.23	0.15-0.23	0.19-0.23 0.18-0.22 0.00-0.02	0.18-0.23	. 22 - 0 . 18 - 0 . 00 - 0	0.18-0.23 0.18-0.22 0.13-0.19			
	Permea- bility (Ksat)	In/hr	0.60-2.00 0.60-2.00 0.60-2.00	0.60-2.00	0.60-2.00	0.60-2.00	000		0.60-2.00 0.60-2.00 0.60-2.00 0.20-0.57			
-	Moist   bulk   density	<u> 32/6</u>	1.20-1.40 1.20-1.40 1.20-1.40	1.20-1.60	1.20-1.40	1.20-1.40 1.40-1.60 1.50-1.70	20-1.40	.25-1.40 .30-1.50 .60-1.80	1.30-1.50 1.30-1.50 1.35-1.65 1.35-1.70			
	Clay	Pct	15-27 18-35 18-35	12-18	7-27	12-27 18-35 18-35 35-60		18-27 18-35 18-35 20-35	15-27 20-35 36-60 40-60			
-	Silt	Pct	50-80 40-73 50-80	50-80	50-80	50-80 40-73 50-80	1 1	50-80 50-80 50-80 50-80	50-80 50-80 40-73 40-60			
	Sand	Pct	10-50 0-19 0-50	0-50	10-50	0-50	0 - 50	0-50	10-50 0-50 0-19			
	Depth	티	0-10 10-42 42-65	0-9	0-11	0-6 6-25 25-37 37-62	0-9-65	0-6 6-28 28-37 37-80	0-9 9-18 18-62 62-80			
	Map symbol and soil name		Ld: Lindside	Me: Melvin	Ne, Nf: Newark	Nicholson	No, Np: Nolin	OtA, OtB: Otwood	PbA: Pembroke	Pm. Pits, loamy, frequently   flooded	Pq. Pits, quarry	RaF:

Table 20.-Physical Properties of the Soils-Continued

0.60-2.00   0.18-0.22   0.0-2.9   0.5-3.0   .37   0.60-2.00   0.08-0.16   0.0-2.9   0.0-0.8   .17   0.00-0.06   0.08-0.16   0.0-2.9   0.0-0.8   .17   0.00-0.06   0.19-0.23   0.0-2.9   1.0-3.0   .43   0.60-2.00   0.19-0.23   0.0-2.9   1.0-3.0   .43   0.00-0.20   0.18-0.22   0.0-2.9   0.0-0.8   .43   0.00-0.20   0.00-0.02   0.0-2.9   0.0-0.8   .43   0.00-0.20   0.00-0.02   0.0-2.9   0.0-0.8   .43   0.00-0.20   0.00-0.02   0.0-2.9   0.0-0.8   .43   0.00-0.20   0.00-0.02   0.0-2.9   0.0-0.8   .43   0.00-0.20   0.00-0.02   0.0-2.9   0.0-0.8   .43   0.00-0.20   0.00-0.02   0.0-2.9   0.0-0.8   .43   0.00-0.20   0.00-0.02   0.0-2.9   0.0-0.8   .43   0.00-0.20   0.00-0.02   0.0-2.9   0.0-0.8   .43   0.00-0.20   0.00-0.02   0.0-2.9   0.0-0.8   .43   0.00-0.20   0.00-0.02   0.0-2.9   0.0-2.9   0.0-2.9   0.00-0.20   0.00-0.02   0.00-0.20   0.0-2.9   0.0-2.9   0.00-0.20   0.00-0.20   0.0-2.9   0.0-2.9   0.0-2.9   0.0-2.9   0.00-0.20   0.00-0.20   0.00-0.20   0.0-2.9   0.0-2.9   0.0-2.9   0.00-0.20   0.00-0.20   0.00-0.20   0.0-2.9   0.0-2.9   0.0-2.9   0.00-0.20   0.00-0.20   0.00-0.20   0.0-2.9   0.0-2.9   0.0-2.9   0.0-2.9   0.00-0.20   0.00-0.20   0.00-0.20   0.0-2.9
0.08-0.16 0.0-2. 0.08-0.16 0.0-2. 0.08-0.16 0.0-2. 0.08-0.16 0.0-2. 0.19-0.23 0.0-2. 0.19-0.23 0.0-2. 0.19-0.23 0.0-2.
15-45
40-60
40-70

Table 20.-Physical Properties of the Soils-Continued

										Erosic	Erosion factors	ors
Map symbol	Depth	Sand	Silt	Clay	Moist	Permea-	Available Linear	Linear	Organic			
and soil name	_		_	_	bulk	bility	water	extensi-	matter	Κw	Ϋ́	Н
					density	(Ksat)	capacity	bility				
	티	Pct	Pct	Pct	<u>a/aa</u>	In/hr	In/in	Pct	Pct			
ZaB:												
Zanesville	8-0	10-50	20-80	12-27	12-27 1.35-1.40	0.60-2.00	0.19-0.23 0.0-2.9 1.0-2.0	0.0-2.9	1.0-2.0	. 43	.43	m
	8-23	0-19	40-73	18-35	18-35 1.35-1.45	0.60-2.00	0.17-0.22	0.0-2.9	0.0-0.8	.37	.37	
	23-45	0-19	40-73	18-33	18-33 1.50-1.75	0.00-0.20	0.00-0.02	0.0-2.9	0.0-0.8	.37	.37	
	45-56	20-45	15-53	20-40	20-40 1.50-1.70	0.20-0.57	0.00-0.02	0.0-2.9	0.0-0.8	. 28	.32	
	56-58	-	-	-	-	00.0-00.0	0.00-0.02	-	-	-	-	
zacz:												
Zanesville	0-5	10-80	20-80	12-27	12-27   1.35-1.40	0.60-2.00	0.19-0.23 0.0-2.9 1.0-2.0	0.0-2.9	1.0-2.0	.43	.43	т
	5-20	0-19	40-73	18-35	18-35 1.35-1.45	0.60-2.00	0.17-0.22	0.0-2.9	0.0-0.8	.37	.37	
	20-45	0-19	40-73	18-33	18-33 1.50-1.75	0.00-0.20	0.00-0.02	0.0-2.9	0.0-0.8	.37	.37	
	45-56	20-45	15-53	20-40	20-40 1.50-1.70	0.20-0.57	0.00-0.02	0.0-2.9	0.0-0.8	. 28	.32	
	26-58		-		-	0.00-00.0	0.00-0.02	!	<u> </u>	-		

Table 21.—Physical Properties of the Soils in Urban Areas

(Entries under "Erosion factors--T" apply to the entire profile. Absence of an entry indicates that data were not estimated)

										Erosion	n factor	i i
Map symbol and soil name	Depth	Sand	Silt	Clay	Moist	Permea- bility	Available water	Linear extensi-	Organic	Kw	ZĘ.	H
					density	(Ksat)	capacity	bility			!	
	ul I	Pct	Pat	Pat	<u>a/cc</u>	In/hr	In/in	Pct	Pct			
BrB, BrC, BrD:	8-0	10-50	50-80	12-27	1.20-1.40	0.60-2.00	0.14-0.18	0.0-2.	2.0-4.0	. 28	.37	Ŋ
	8-15	0-19	40-73	18-40	1.30-1.55		0.14-0.18	3.0-5.	0.0-1.0	. 24	.32	
	15-61   61-81	0-45	6E - 0   0 - 39	40-60	1.30-1.55		0.10-0.14    0.10-0.14	3.0-5.9	8.0-0.0	. 24 4. 4.	7 7 8	
Urban land.												
CoD, CoE:												
Caneyville	0-6	10-50	50-80		1.20-1.40 1.35-1.60		0.15-0.22	3.0-5.9	0.0-4.0	. 28	2.88	m
	11-27	0 - 44	0 - 0 6 - 0 6 - 1	40-60	1.35-1.60	0.00-0.20	0.12-0.18		8.0.0.0			
Urban land.												
Rock outcrop.												
CuB, CuC: Crider	6 - 0	10-50	50-80	15-27	1.20-1.40	0.60-2.00	0.19-0.23	0.0-2.	2.0-4.0	32	.32	Ŋ
	28-50	0-19	40-73	18-35	1.20-1.45		0.18-0.23		0.0-1.0	8 8 8	8 8 8	
	08-00	0 - 44	ວ ອນ 	40-60	cc.1-02.1 	0.20-0.57	0.12-0.18	3.0-5.	)   	87	8	
Urban land.												
FnB, FnC: Fredonia	0 - 5	10-50	50-80	15-27	1.30-1.50		0.18-0.22	0.0-2.	2.0-4.0	.37	.37	т
	5-22	0-19	40-60		1.30-1.60		0.13-0.18	3.0-5.9	0.0-0.8	. 28	.28	
	37-39	0 - 44	မ ၊ ၂၈ ၂	40-60	1.30-1.60		0.13-0.18	3.0-5.	8.0.0.0	 8   8	. I	
Vertrees	9-0	-5	50-80	15-27	1.20-1.40		0.18-0.22	0.0-2.	1.0-3.0	.37	.37	Ŋ
	6-15	0-19	40-60	35-60	1.40-1.65	0.20-0.60	0.14-0.18	3.0-5.9	8.0-0.0	7.78	 8 8 8 8	
Urban land.												

Table 21.-Physical Properties of the Soils in Urban Areas-Continued

										Erosion	n factors	Ors
Map symbol and soil name	Depth	Sand	Silt	Clay	Moist bulk density	Permea- bility (Ksat)	Available water capacity	Linear extensi- bility	Organic matter	Kw		FH
	티	Pct	Pat	Pat	g/cc	In/hr	In/in	Pot	Pct			
Frcd: Fredonia	0-3 3-22 22-37 37-39	10-50	50-80	18-27 40-60 40-60	1.30-1.50 1.30-1.60 1.30-1.60	0.60-2.00 0.06-0.60 0.06-0.20 0.00-0.00	0.18-0.22 0.13-0.18 0.13-0.18	3.0-2.9	0.00	1 2 8 8 1	37	м
Vertrees	0-3 3-15 15-80	10-50 0-19 0-44	50-80 40-60 0-39	15-27 35-60 40-60	1.20-1.40 1.40-1.65 1.45-1.65	0.60-2.00 0.20-0.60 0.06-0.20	0.18-0.22 0.14-0.18 0.10-0.16	3.0-5.9	2.0-4.0 0.0-0.8	.28	.37	ιΩ
Urban land.												
PeA: Pembroke	0-9 9-18 18-62 62-80	10-50 0-50 0-19 0-44	50-80 50-80 40-73 40-60	15-27 20-35 36-60 40-60	1.30-1.50 1.30-1.50 1.35-1.65 1.35-1.70	0.60-2.00 0.60-2.00 0.60-2.00	0.18-0.23 0.18-0.22 0.13-0.19	0.0-2.9 0.0-2.9 3.0-5.9	2.0-4.0 0.5-1.0 0.0-0.8	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	ιΩ
Urban land.												
UaC. Udorthents												
UaD. Udorthents, refuse substratum												
Ub: Urban land.												
Udorthents	0-65	0-44	0-39	40-60	1.45-1.65	0.06-0.20	0.10-0.16	3.0-5.9	0.1-1.0	. 28	. 28	1
Uc: Urban land.												
Udorthents, clayey substratum, hard bedrock 0-5 feet	0-48	0 - 44	0-39	40-60	1.45-1.65	0.00-0.20	0.10-0.16	3.0-5.9	0.0-0.5	. I 8	. I 8	1

Table 21.-Physical Properties of the Soils in Urban Areas-Continued

										Erosion	n factors	ors
Map symbol and soil name	Depth	Sand	silt	Clay	Moist bulk density	Permea- bility (Ksat)	Available water capacity	Linear extensi- bility	Organic matter	Kw	₩ ₩	H
	티	Pat	Pct	Pat	g/cc	In/hr	In/in	Pct	Pat			
Ud: Urban land.												
Udorthents, clayey substratum, hard bedrock >5 feet	0-70	0 - 44	0 - 39	40-60	1.45-1.65	0.00-0.20	0.10-0.16	3.9-5.9	0.0-0.5	. 28		1
Us: Urban land.												
Udorthents, smoothed.												
VtC3: Vertrees	0-3 3-20 20-80	0-19	40-73 0-39 0-39	28-40 35-60 40-60	28-40 1.20-1.40 35-60 1.40-1.65 40-60 1.45-1.65	0.60-2.00 0.20-0.60 0.06-0.20	0.14-0.22 0.10-0.16 0.10-0.16	0.0-2.9 3.0-5.9 3.0-5.9	0.0-1.0	288	288	4
Urban land.												
ZuB: Zanesville	0 - 8 8 - 2 3 2 3 - 4 5 4 5 - 5 6 5 6 - 5 8	10-50 0-19 0-19 20-45	50-80 40-73 40-73 15-53	12-27 18-35 18-33 20-40	12-27   1.35-1.40 18-35   1.35-1.45 18-33   1.50-1.75 20-40   1.50-1.70	0.60-2.00 0.60-2.00 0.00-0.20 0.20-0.57 0.00-0.00	0.19-0.23 0.17-0.22 0.00-0.02 0.00-0.02	0.00	0.00-0.8		.37	м
Urban land.												

Table 22.—Chemical Properties of the Soils

(Absence of an entry indicates that data were not estimated.

Map units that have Urban land as a major component were not rated and are not included in this table)

Map symbol and soil name	   Depth 	!	  Effective  cation-  exchange	reaction
		!	capacity	:
	<u>In</u>	meq/100 g		
		ļ	ļ	
BaB, BaC, BaD, BaE:	00			
Baxter	0-8   8-15	5.0-15 5.0-15	2.0-10 2.0-10	4.5-6.5 4.5-5.5
	15-61	5.0-15	2.0-10	4.5-5.5
	61-81	5.0-15	2.0-10	4.5-5.5
BbC3, BbD3:				
Baxter	0-3	5.0-15	2.0-10	4.5-6.5
	3-61	5.0-15	2.0-10	4.5-5.5
	61-81	5.0-15	2.0-10	4.5-5.5
CaB, CaC:	0 6		 	
Caneyville	0-6   6-11	5.0-15   10-20	 	5.1-6.0   5.1-6.0
	11-27	10-20	 	5.6-7.3
	27-29		i	3.0 7.3
CaC3:	-/ -/	i	İ	İ
Caneyville	0-3	5.0-15	i	5.1-6.0
	3-27	10-30	i	5.1-7.3
	27-31			
CnD, CnF:				
Caneyville	0-6	5.0-15		5.1-6.0
	6-11   11-27	10-20	 	5.1-6.0 5.6-7.3
	27-31		 	
Rock outcrop.			 	
CrB, CrC:			 	 
Crider	l   0-9	5.0-15	¦	   5.1-7.3
32 2 3 3	9-28	5.0-15		5.1-7.3
	28-50	5.0-20	i	4.5-6.0
	50-80	5.0-30	j	4.5-6.0
DAM.				
Dam, large			 	
Du:			 	 
Dunning	0-9	10-20	j	6.1-7.8
	9-25	10-20		6.1-7.8
	25-71	10-20	ļ	6.1-7.8
EkB:			ļ	
Elk	   0-10	5.0-15	! !	   4.5-6.5
	10-20	5.0-15		4.5-6.5
	20-65	5.0-15	ļ	4.5-6.5
EpB:	[ [		 	 
Epley	l   0-9	5.0-15		   4.5-7.3
	9-24	5.0-15	i	4.5-6.0
	24-41	10-30	j	4.5-6.0
	41-65	10-30	ļ	5.6-7.3
		!	   	

Table 22.—Chemical Properties of the Soils—Continued

Map symbol and soil name	Depth	exchange capacity	exchange capacity	reaction
	<u>In</u>	meq/100 g	meq/100 g	pН
FeB: Fredonia	0-5 5-22 22-37 37-39	   5.0-15   10-20   10-30 	     	   5.1-6.5   5.1-7.3   5.1-7.3
Vertrees	0-6 6-15 15-80	   5.0-15   5.0-15   5.0-20	   	   4.5-7.3   4.5-6.0   4.5-7.3
FeC: Fredonia	0-5 5-22 22-37 37-39	   5.0-15   10-20   10-30 	   	5.1-6.0   5.1-7.3   5.1-7.3 
Vertrees	0-6 6-15 15-80	5.0-15   5.0-15   5.0-20	   	4.5-7.3 4.5-6.0 4.5-7.3
FrC, FrD: Frondorf	0-5 5-18 18-26 26-30	     	2.0-8.0   2.0-6.0   2.0-6.0	4.5-5.5   4.5-5.5   4.5-5.5 
Gr: Grigsby	0-9 9-41 41-80	5.0-10   2.0-8.0   2.0-5.0	   	5.6-7.3 5.6-7.3 5.6-7.3
HaB: Hammack	0-9 9-30 30-41 41-84	   5.0-15   5.0-15   5.0-15   5.0-20	  	   5.1-7.3   5.1-6.5   4.5-6.0   4.5-6.0
La: Lawrence	0-7 7-18 18-65	   5.0-15   5.0-20   5.0-20	   	   4.5-6.5   4.5-5.5   4.5-5.5
Ld: Lindside	0-10 10-42 42-65	   5.0-15   5.0-20   5.0-20	     	   5.6-7.3   5.6-7.3   5.6-7.3
Me: Melvin	0-9 9-62	   5.0-15   5.0-20 	 	   6.1-7.8   6.1-7.3
Ne, Nf: Newark	0-11 11-65	   5.0-15   5.0-20	   	   5.6-7.8   5.6-7.3
NhA, NhB, NhC: Nicholson	0-6 6-25 25-37 37-62	   5.0-15   5.0-15   5.0-20   5.0-20	   	4.5-6.5 4.5-6.5 4.5-6.5 5.1-7.8

Table 22.—Chemical Properties of the Soils—Continued

		I	I	
Map symbol and soil name	Depth	exchange capacity	Effective  cation-  exchange  capacity	!
	<u>In</u>	meq/100 g	meq/100 g	рН
AT AT				
No, Np: Nolin	l l 0-9	   5.0-15	 	   5.6-7.3
	9-65	5.0-20		5.6-7.3
OtA, OtB:		į		
Otwood	0-6	5.0-15 5.0-15	2.0-10	4.5-7.3
	6-28 28-37	5.0-15	2.0-10 2.0-10	4.5-5.5
	37-80	5.0-20	2.0-10	4.5-5.5
_		İ		
PbA: Pembroke	   0-9	   5.0-15	 	   4.5-7.3
rembroke	9-18	5.0-15	 	4.5-6.0
	18-62	5.0-20		4.5-6.0
	62-80	5.0-30		4.5-6.0
Pm. Pits, loamy, frequently flooded		       		     
Pq. Pits, quarry		   		
RaF:				 
Ramsey	0-4	j	2.0-6.0	4.5-5.5
	4-19		1.0-3.0	4.5-5.5
	19-20 		1.0-3.0 	 
Frondorf	0-18		2.0-8.0	4.5-5.5
	18-26	ļ	2.0-6.0	4.5-5.5
	26-30		2.0-6.0	
Ro:			 	l I
Robertsville	0-10	5.0-15		5.1-6.5
	10-28	5.0-15		4.5-5.5
	28-40 40-70	5.0-20 5.0-20	 	4.5-5.5
	40-70	3.0-20	 	4.5-7.5
RxF:	İ	İ	İ	İ
Rock outcrop.				
Caneyville	0-6	   5.0-15	 	   5.1-6.0
04.107 1 - 12.0	6-11	10-20		5.1-6.0
	11-27	10-30		5.6-7.3
	27-29			
SaA, SaB:	] 		[ 	 
Sadler	0-9	5.0-15		4.5-7.3
	9-26	5.0-15		4.5-5.5
	26-56 56-65	5.0-15 5.0-20	 	4.5-5.5
ŀ	65-65	5.0-20		4.5-5.5
j		İ	İ	j
VrC3:				
Vertrees	0-3 3-20	5.0-15 5.0-15	 	4.5-7.3
	20-80	5.0-13		4.5-7.3
İ	İ	İ		İ

Table 22.—Chemical Properties of the Soils—Continued

Map symbol	Depth	Cation-	Effective	
and soil name		exchange	cation-	reaction
		capacity	exchange	
			capacity	
	<u>In</u>	meq/100 g	meq/100 g	PН
		ĺ	ĺ	ĺ
W.	İ	İ	İ	İ
Water	İ	İ	İ	İ
		İ	İ	İ
WeB:		İ	İ	İ
Wellston	0-8	5.0-15	i	5.1-6.5
	8-13	5.0-15	i	4.5-6.0
	13-30	5.0-15	i	4.5-6.0
	30-46	5.0-15	j	4.5-6.0
	46-48	j	j	j
WeC2:	İ	İ	İ	İ
Wellston	0-5	5.0-15	j	5.1-6.5
	5-30	5.0-15	j	4.5-6.0
	30-46	5.0-15	j	4.5-6.0
	46-50	j	j	i
	İ	İ	İ	İ
ZaB:	İ	İ	İ	İ
Zanesville	0-8	5.0-15	5.0-15	4.5-6.0
	8-23	5.0-15	5.0-15	4.5-5.5
	23-45	5.0-15	5.0-10	4.5-5.5
	45-56	5.0-20	2.0-10	4.5-5.5
	56-58	j	j	i
ZaC2:	İ	İ	İ	İ
Zanesville	0-5	5.0-15	5.0-15	4.5-6.0
	5-20	5.0-15	5.0-15	4.5-5.5
	20-45	5.0-15	5.0-10	4.5-5.5
	45-56	5.0-20	2.0-10	4.5-5.5
	56-58	j	i	i
	İ	İ	İ	İ
		•	•	•

Table 23.—Water Features

(Depths of layers are in feet. See text for definitions of terms used in this table. Estimates of the frequency of ponding and flooding apply to the whole year rather than to individual months. Absence of an entry indicates that the feature is not a concern or that data were not estimated. Map units that have Urban land as a major component were not rated and are not included in this table)

			Water	table		Ponding		Flooding	ding
Map symbol and soil name	Hydro-  logic  group	Month	Upper limit	Lower limit	Surface water depth	Duration	Frequency	Duration	Frequency
			꿆	F	F				
BaB, BaC, BaD, BaE, BbC3, BbD3: Baxter		Jan-Dec					None	1	None
CaB, CaC, CaC3: Caneyville	ت 	Jan-Dec					None		None
CnD, CnF: Caneyville	υ 	Jan-Dec		:			None	1	None
Rock outcrop	¦ 	Jan-Dec					None		None
Crider		Jan-Dec				1	None	1	None
DAM: Dam, large	¦ 	Jan-Dec				!	None		None
Duming	Α	January February March April May December	000000	000000	00.55.0	Long Long Long Long Brief Long	Frequent Frequent Frequent Frequent Frequent		None None None None None

Table 23.-Water Features-Continued

			Water table	table		Ponding		Flooding	ling
Map symbol and soil name	Hydro-   logic  group	Month	Upper	Lower	Surface    water     depth	Duration	Frequency	Duration	Frequency
			Ft	F	Et				
EkB: Elk									
	<u> </u>	January	-  -	-	<u> </u>	!	None	1	Rare
	_	February	-  -	-	_ : _	-	None	-	Rare
	_	March	-   	-	_ :	!	None	-	Rare
	<u> </u>	April	-  -	-	<u> </u>	!	None	:	Rare
		May	-    -	-	-  -	!	None	-	Rare
		December	 	 	 ¦	-	None		Rare
БрВ: Бр1еу	ບ								
	<u> </u>	January	1.5-2.0	-		-	None	-	None
		February	1.5-2.0	-	_  -	!	None	:	None
		March	1.5-2.0	-	-	:	None	-	None
		April	1.5-2.0	-	-	-	None	-	None
		December	1.5-2.0	-	-	-	None	-	None
FeB, FeC: Fredonia	υ	Jan-Dec			 		None		None
Vertrees		Jan-Dec		<u>-</u>	:	;	None		None
FrC, FrD: Frondorf		Jan-Dec	:		   	;	None		None
Grigsby		January	6.0-6.5		 		None	Brief	Frequent
	<u> </u>	February	6.0-6.5		:	!	None	Brief	Frequent
	_	March	6.0-0.9		<u> </u>	!	None	Brief	Frequent
	<u> </u>	April	6.0-6.5	>6.0	<u> </u>	-	None	Brief	Frequent
		May December	6.0-6.5				None	Very brief Brief	Frequent Frequent
HaB: Hammack		Jan-Dec					None		None

Table 23.-Water Features-Continued

			Mator	4 4 4		Daribad		ρα: ροο [¤	50:15
Mary Company	Tringing	M()	1-	P C C	44.5	7			0
and soil name	logic	WOIICII	limit	limit	water	Duration	Frequency	Duration	Frequency
	group				depth				
			ᆵ	Ft	먎				
La:									
Lawrence	บ								
		January	1.0-1.5	-	-	-	None	;	Rare
	_	February	1.0-1.5	-	_ :	-	None	:	Rare
	_	March	1.0-1.5	-	_ :	-	None	:	Rare
	_	April	1.0-1.5	-	_ :	-	None	:	Rare
		December	1.0-1.5		    -	-	None	-	Rare
Ľď:									
Lindside	ט								
		January	1.5-2.0	-	;	-	None		Frequent
		February	1.5-2.0	-	-	-	None	Very brief	Frequent
		March	1.5-2.0	-	-	-	None	Very brief	Frequent
		April	1.5-2.0	-	-	-	None	Very brief	Frequent
		May	:	-	-	-	None	Very brief	Frequent
		December	1.5-2.0	-	-	-	None	Very brief	Frequent
									1
Me: Melvin	Δ								
		January	0.0	>6.0	;	-	None	Long	Frequent
	_	February	0.0	0.9<	-	-	None	Long	Frequent
	_	March	0.0	0.9<	-	-	None	Long	Frequent
		April	0.0	>6.0	-	-	None	Long	Frequent
		May	0.0	0.9<	-	-	None	Brief	Frequent
		December	0.0	>6.0	<u>-</u>	-	None	Long	Frequent
: eN									
Newark	ט								
		January	1.0-1.5	0.9<	<u> </u>	-	None	Briet	Frequent
		February	1.0-1.5	0.9<	<u> </u>	-	None	Briet	Frequent
		March	1.0-1.5	0.9<	<u> </u>	-	None	Briet	Frequent
		April	1.0-1.5	0.9<	:	-	None	Brief	Frequent
		May	1.0-1.5	0.9<	:	-	None	Very brief	Frequent
		December	1.0-1.5	0.9<	:	:	None	Brief	Frequent
Nf:									
Newark	ט				_				
		January	1.0-1.5	0.0	0.5-3.0	Long	Frequent	-	None
		February	T-0-T	0.0	0.5-2.0	rong	Frequent	:	None
		March	1.0-1.5	0.0	0.5-3.0	Long	Frequent	:	None
		April	1.0-1.5	0.0	0.5-3.0	Briet	Frequent	:	None
		May	T-0-T	0.0	0.5-2.0	very brier	Frequent	:	None
		December	T-0-T	0.9	0.5-3.0	Briet	Frequent	:	None
			_	_	_		_		

Table 23.-Water Features-Continued

			Water	table		Ponding		Flooding	ling
Map symbol	Hvdro-	Month	Upper	Lower	Surface				
and soil name	logic		limit	limit	water	Duration	Frequency	Duration	Frequency
	group				depth				
			Ft	Ft	Ft				
Nha, NhB, NhC:									
Nicholson	บ	-	, L				, i		Q Q
		Dalidar y	1.01 1.01 1.01				Nono		None
		February	1 2 2 2		 		None		None
		March	1.3-2.0		 :	!	None	:	None
		April	1.5-2.0		 : :	! !	None	: :	None
No: Nolin	_ д								
		January	-	ł	-	-	None	Brief	Frequent
		February	-	1	-	-	None	Brief	Frequent
		March	-	-	-		None	Brief	Frequent
		April	-		-	!	None	Brief	Frequent
		May	-	1	1	!	None	Very brief	Frequent
		December	-	-	-		None	Brief	Frequent
: ax									
Nolin	м								
	_	January	<u>-</u>	:	0.5-2.0	Brief	Frequent	:	None
		February	- - -		0.5-2.0	Brief	Frequent	:	None
		March	- - -	1	0.5-2.0	Brief	Frequent	:	None
		April	- - -	1	0.5-2.0	Brief	Frequent	:	None
	_	May	<u> </u>	:	0.5-2.0	Very brief	Frequent	:	None
		December	<u> </u>	-	0.5-2.0	Brief	Frequent	!	None
OtA, OtB: Otwood	უ								
		January	1.5-2.0	;	-	!	None	;	Rare
		February	1.5-2.0	1	-	!	None	-	Rare
		March	1.5-2.0	-	- - -	-	None	-	Rare
	_	April	1.5-2.0	-	-	!	None	-	Rare
		May	- - -	1	- - -	!	None	:	Rare
		December	1.5-2.0	-	<u> </u>	:	None	!	Rare
PbA: Pembroke									
		Jan-Dec				:	None	:	None

Table 23.-Water Features-Continued

			Water	table		Ponding		Flooding	ling
Map symbol and soil name	Hydro- logic group	Month	Upper	Lower	Surface    water   depth	Duration	Frequency	Duration	Frequency
			Ft	Ft	Ft				
Pm: Pits, loamy, frequently flooded	¦								
		January	-	ł	-	-	None	Brief	Frequent
	_	February	-    -		-	-	None	Brief	Frequent
	_	March	_ :	-	<u> </u>	-	None	Brief	Frequent
		April	- - -	-	-	-	None	Brief	Frequent
		May	:	-	!	-	None	Very brief	Frequent
		December	 		 ¦	!	None	Briet	Frequent 
Pq: Pits, quarry		  Jan-Dec	   		 	-	None		None
Ramsey	Α	Jan-Dec					None		None
Frondorf	д	  Jan-Dec 	 		 		None		None
Ro: Robertsville	Α			- <del></del>					
		January		0.9	0.5-2.0	Long	Frequent	Brief	Occasional
		February	000	0.0	0.0-1	Long	Frequent	Briei	Occasional
		April		0.0	0.512.0	Long	Frequent	Brief	Occasional
		May	0.0	0.9<	0.5-2.0	Brief	Frequent		None
		December	 0.0	0.9<	0.5-2.0	Long	Frequent	Brief	Occasional
RxF: Rock outcrop		Jan-Dec					None		None
Caneyville	บ 	Jan-Dec	 				None	1	None
SaA, SaB: Sadler	ຶບ			- <del></del>					
		January February	1.5-2.0				None		None
		March	1.5-2.0	-	;	-	None		None
		April	1.5-2.0		 :	-	None	-	None
		December	1.5-2.0		:		None	-	None
		_	_	-	_		_		

Table 23.-Water Features-Continued

			Water table	table		Ponding		Flooding	ling
Map symbol	Hydro-	Month	Upper	Lower	Surface				
and soil name	logic		limit	limit	water	Duration	Frequency	Duration	Frequency
	group				depth				
			Ft	ъt	FL		_		
VrC3:					_				
Vertrees	щ								
		Jan-Dec	 ¦		<u> </u>	-	None	!	None
W:									
Water			_		_				
		Jan-Dec	   		<u> </u>	-	None	-	None
WeB, WeC2:									
Wellston	Д		_						
		Jan-Dec	 ¦	<u> </u>	<u> </u>	:	None	!	None
ZaB, ZaC2:									
Zanesville	_ ნ		_		_		_		
	_	January	1.5-2.0	-	-	:	None	;	None
	_	February	1.5-2.0	-	-	:	None	;	None
		March	1.5-2.0	-	-	:	None	:	None
		April	1.5-2.0	-	-	:	None	:	None
	_	December	1.5-2.0		-	:	None	;	None

Table 24.—Soil Features

(See text for definitions of terms used in this table. Absence of an entry indicates that the feature is not a concern or that data were not estimated. See table 25 for ratings for map units that have Urban land as a major component)

Lodmin neW		1 1 2 2	יסטים   סטייודהייידה			10.00	20,100
Tap Symbol		Dent to	ו ו ו ו ו ו ו ו ו ו ו ו ו ו ו ו ו ו ו		Foreittai	4	
alla sorr llame	Kind	to top	Thickness	Hardness	frost action	steel	Concrete
		띰	티				
BaB, BaC, BaD, BaE, BbC3, BbD3:							
Baxter	<u> </u>	¦ 	!	¦ 	None	High  -	High 
CaB, CaC, CaC3: Caneyville	Bedrock (lithic)	20-40		Indurated	None	  High	Moderate
CnD, CnF: Caneyville	Bedrock (lithic)	20-40		Indurated	None	High	Moderate
Rock outcrop	Bedrock (lithic)	0-0	:	Indurated	None	;	;
CrB, CrC: Crider	!		:		None	Moderate	Moderate
DAM: Dam, large	!		:		None	¦ 	!
Du: Dunning			;		None	High	Moderate
EKB: Elk	!				None	Moderate	Moderate
EpB: Epley	Bedrock (lithic)	48-80		Indurated	None	High	Moderate
FeB, FeC: Fredonia	Bedrock (lithic)	20-40		Indurated	None	High	Moderate
Vertrees			:		None	Moderate	Moderate
FrC, FrD: Frondorf	Bedrock (paralithic)	20-40		Very strongly cemented	None	Moderate	High
Gr: Grigsby	!		:		None	Low	Moderate
Нав: Наштаск			:		None	  Moderate 	Moderate

Table 24.-Soil Features-Continued

Map symbol		Restric	Restrictive layer		Potential	Risk of	corrosion
and soil name	, r	Depth		# ## ## ##	frost action	Uncoated	7000 4400 4400
		H H	띠				
La: Lawrence	Fragipan	18-32	¦ 	Noncemented	None	High	High
Ld: Lindside	-		¦ 		None	Moderate	Low
Me: Melvin	-		¦ 		None	High	Low
Ne, Nf: Newark	!	}	¦ 		None	High	Low
NhA, NhB, NhC: Nicholson	Fragipan	18-30	¦ 	Noncemented	None	High	Moderate
No, Np: Nolin	-		¦ 		None	Low	Moderate
OtA, OtB: Otwood	Fragipan	20-36	¦ 	Noncemented	None	Moderate	High
PbA: Pembroke	!		¦ 		None	Moderate	Moderate
Pm: Pits, loamy, frequently flooded	1				None		
Pq: Pits, quarry	-	1	¦ 		None		!
Raff: Ramsey	Bedrock (lithic)	10-20	¦ 	Indurated	None	Low	Moderate
Frondorf	Bedrock (paralithic)	20-40	¦ 	Indurated	None	Moderate	High
Ro: Robertsville	Fragipan	18-32		Noncemented	None	ніgh	High
RXF:	Bedrock (lithic)	0-0		Indurated	None		
Caneyville	Bedrock (lithic)	20-40		Indurated	None	High	Moderate

Table 24.-Soil Features-Continued

Map symbol		Restric	Restrictive layer		Potential	Risk of	Risk of corrosion
and soil name		Depth			for	Uncoated	
	Kind	to top	to top   Thickness	Hardness	frost action	steel	Concrete
		테	ᄪ				
SaA, SaB:							
Sadler	Fragipan	18-32	-	Noncemented	None	Moderate	High
	Bedrock (lithic)	50-80		Indurated			
VrC3:							
Vertrees	:	:	<u> </u>	:	None	Moderate	Moderate
• 10							
Water	;	;	;		None	:	;
WeB, WeC2: Wellston	  Bedrock (lithic)	40-72		Indurated	None	Moderate	  High
Zab. Zac.							
Zanesville	  Fragipan	20-32	-	Noncemented	None	Moderate	High
	Bedrock (lithic)	40-60		Indurated			

Table 25.—Soil Features for Urban Areas

(See text for definitions of terms used in this table. Absence of an entry indicates that the feature is not a concern or that data were not estimated)

Map symbol		Restric	Restrictive layer		Potential	Risk of	corrosion
and soil name	7 1 1	Depth		1 1 1 1 1	for to	Uncoated	
		H H	In		101000000000000000000000000000000000000	_	
BrD:							
baxcer	:	¦ 	¦ 	! !	None	пр. Пр. —	пртн    -
Urban land			;	!	None	!	!
CoD, CoE: Caneyville	Bedrock (lithic)	20-40	:	Indurated	None	High	Moderate
Urban land				:	None	¦ 	!
Rock outcrop	Bedrock (lithic)	0-0	¦ 	Indurated	None		¦ 
CuB, CuC: Crider	!	; 	¦ 	;	None	Moderate	Moderate
Urban land	1	¦ 	;		None		;
FnB, FnC, FnC2: Fredonia	Bedrock (lithic)	20-40	¦ 	Indurated	None	High	Moderate
Vertrees	1	¦ 		;	None	Moderate	Moderate
Urban land	1	¦ 	;		None		;
PeA: Pembroke	!	¦ 	;	;	None	Moderate	Moderate
Urban land	1	¦ 		;	None		
UaC: Udorthents	!		¦ 		None	Unknown	Unknown
UaD: Udorthents, refuse substratum					None	Unknown	Unknown
Ub: Urban land	!	¦ 	¦ 	;	None		;
Udorthents		¦ 	¦ 	¦ 	None	Unknown	Unknown

Table 25.-Soil Features for Urban Areas-Continued


Map symbol		Restric	Restrictive layer		Potential	Risk of	Risk of corrosion
and soil name		Depth			for	Uncoated	
	Kind	to top	Thickness	Hardness	frost action	steel	Concrete
		uI	uI				
Uc: Urban land		¦ 	:		None		:
Udorthents, clayey substratum, hard bedrock 0-5 feet	Bedrock (lithic)	12-60		Indurated	None	Moderate	Moderate
Ud: Urban land			¦ 		None		:
Udorthents, clayey substratum, hard bedrock >5 feet	Bedrock (lithic)	60-80		Indurated	None	Moderate	Moderate
Us: Urban land			¦ 		None	;	:
Udorthents, smoothed			:		None	Unknown	Unknown
VtC3: Vertrees			¦ 		None	Moderate	Moderate
Urban land	¦ 	¦ 	¦ 	¦ 	None	;	¦ 
ZuB: Zanesville	Fragipan Bedrock (lithic)	20-32		Noncemented Indurated	None	Moderate	High
Urban land	¦ 	¦ 	:	<u> </u>	None	;	:


Table 26.—Classification of the Soils

Soil name	Family or higher taxonomic class
Baxter	  Fine, mixed, semiactive, mesic Typic Paleudalfs
Caneyville	Fine, mixed, active, mesic Typic Hapludalfs
Crider	Fine-silty, mixed, active, mesic Typic Paleudalfs
Dunning	Fine, mixed, active, mesic Fluvaquentic Endoaquolls
Elk	Fine-silty, mixed, active, mesic Ultic Hapludalfs
Epley	Fine-silty, mixed, semiactive, mesic Oxyaquic Hapludalfs
Fredonia	Fine, mixed, active, mesic Typic Hapludalfs
Frondorf	Fine-loamy, mixed, active, mesic Ultic Hapludalfs
Grigsby	Coarse-loamy, mixed, active, mesic Dystric Fluventic Eutrudepts
Hammack	Fine-silty, mixed, semiactive, mesic Glossic Paleudalfs
Lawrence	Fine-silty, mixed, semiactive, mesic Aquic Fragiudalfs
Lindside	Fine-silty, mixed, active, mesic Fluvaquentic Eutrudepts
Melvin	Fine-silty, mixed, active, nonacid, mesic Fluvaquentic Endoaquepts
Newark	Fine-silty, mixed, active, nonacid, mesic Fluventic Endoaquepts
Nicholson	Fine-silty, mixed, active, mesic Oxyaquic Fragiudalfs
Nolin	Fine-silty, mixed, active, mesic Dystric Fluventic Eutrudepts
Otwood	Fine-silty, mixed, active, mesic Oxyaquic Fragiudalfs
Pembroke	Fine-silty, mixed, active, mesic Mollic Paleudalfs
Ramsey	Loamy, siliceous, subactive, mesic Lithic Dystrudepts
Robertsville	Fine-silty, mixed, semiactive, mesic Typic Fragiaqualfs
Sadler	Fine-silty, mixed, semiactive, mesic Oxyaquic Fraglossudalfs
Udorthents	Udorthents
Vertrees	Fine, mixed, semiactive, mesic Typic Paleudalfs
Wellston	Fine-silty, mixed, active, mesic Ultic Hapludalfs
Zanesville	Fine-silty, mixed, active, mesic Typic Fragiudalfs

## **NRCS Accessibility Statement**

The Natural Resources Conservation Service (NRCS) is committed to making its information accessible to all of its customers and employees. If you are experiencing accessibility issues and need assistance, please contact our Helpdesk by phone at 1-800-457-3642 or by e-mail at helpdesk@helpdesk.itc.nrcs.usda.gov. For assistance with publications that include maps, graphs, or similar forms of information, you may also wish to contact our State or local office. You can locate the correct office and phone number at <a href="http://offices.sc.egov.usda.gov/locator/app">http://offices.sc.egov.usda.gov/locator/app</a>.





County, farm or ranch

Medium or Small

Mine or quarry

RAILROAD

DAMS

PITS

### **SOIL LEGEND**

Map symbols consist of a combination of letters and numbers. The first two letters are listed alphabetically and represent the kind of soil. In most units, the first letter is a capital letter and the second letter is a small letter. A capital letter following the small letter indicates the class of slope. Symbols without a slope letter are for nearly level soils or miscellaneous areas. A number 2 following the slope letter indicates that the soil is moderately eroded, and a number 3 indicates that it is severely eroded.

#### SYMBOL NAME

BaB	Baxter gravelly silt loam, 2 to 6 percent slopes
BaC	Baxter gravelly silt loam, 6 to 12 percent slopes
BaD	Baxter gravelly silt loam, 12 to 20 percent slopes
BaE	Baxter gravelly silt loam, 20 to 30 percent slopes
BbC3	Baxter gravelly silty clay loam, 6 to 12 percent slopes, severely eroded
BbD3 BrB	Baxter gravelly silty clay loam, 12 to 20 percent slopes, severely eroded Baxter-Urban land complex, 2 to 6 percent slopes
BrC	Baxter-Urban land complex, 6 to 12 percent slopes
BrD	Baxter-Urban land complex, 12 to 20 percent slopes
CaB	Caneyville silt loam, 2 to 6 percent slopes
CaC	Caneyville silt loam, 6 to 12 percent slopes
CaC3	Caneyville silty clay, 6 to 12 percent slopes, severely eroded
CnD	Caneyville-Rock outcrop complex, 6 to 20 percent slopes
CnF	Caneyville-Rock outcrop complex, 20 to 60 percent slopes
CoD	Caneyville-Urban land-Rock outcrop complex, 6 to 20 percent slopes
CoE CrB	Caneyville-Urban land-Rock outcrop complex, 20 to 30 percent slopes Crider silt loam, 2 to 6 percent slopes
CrC	Crider silt loam, 6 to 12 percent slopes
CuB	Crider-Urban land complex, 2 to 6 percent slopes
CuC	Crider-Urban land complex, 6 to 12 percent slopes
DAM	Dam, large
Du	Dunning silty clay loam, ponded
EkB	Elk silt loam, 2 to 6 percent slopes, rarely flooded
EpB FeB	Epley silt loam, 2 to 6 percent slopes
FeC	Fredonia-Vertrees complex, 2 to 6 percent slopes, rocky Fredonia-Vertrees complex, 6 to 12 percent slopes, very rocky
FnB	Fredonia-Vertrees-Urban land complex, 2 to 6 percent slopes, rocky
FnC	Fredonia-Vertrees-Urban land complex, 6 to 12 percent slopes, very rocky
FnC2	Fredonia-Vertrees-Urban land complex, 6 to 12 percent slopes, eroded, rocky
FrC	Frondorf silt loam, 6 to 12 percent slopes
FrD	Frondorf silt loam, 12 to 20 percent slopes
Gr	Grigsby sandy loam, frequently flooded
HaB	Hammack silt loam, 2 to 6 percent slopes
La Ld	Lawrence silt loam, rarely flooded Lindside silt loam, frequently flooded
Me	Melvin silt loam, frequently flooded
Ne	Newark silt loam, frequently flooded
Nf	Newark silt loam, ponded
NhA	Nicholson silt loam, 0 to 2 percent slopes
NhB	Nicholson silt loam, 2 to 6 percent slopes
NhC	Nicholson silt loam, 6 to 12 percent slopes
No	Nolin silt loam, frequently flooded
Np OtA	Nolin silt loam, ponded Otwood silt loam, 0 to 2 percent slopes, rarely flooded
OtB	Otwood silt loam, 2 to 6 percent slopes, rarely flooded
PbA	Pembroke silt loam, 0 to 2 percent slopes
PeA	Pembroke-Urban land complex, 0 to 2 percent slopes
Pm	Pits, loamy, frequently flooded
Pq	Pits, quarry
RaF	Ramsey-Frondorf complex, 20 to 60 percent slopes
Ro RxF	Robertsville silt loam, ponded
SaA	Rock outcrop-Caneyville complex, 20 to 60 percent slopes Sadler silt loam, 0 to 2 percent slopes
SaB	Sadler silt loam, 2 to 6 percent slopes
UaC	Udorthents, 0 to 20 percent slopes
UaD	Udorthents, refuse substratum, 0 to 25 percent slopes
Ub	Urban land-Udorthents complex, 0 to 12 percent slopes
Uc	Urban land-Udorthents complex, clayey substratum, hard bedrock 0-5 feet, 0 to 12 percent slopes
Ud	Urban land-Udorthents complex, clayey substratum, hard bedrock > 5 feet, 0 to 12 percent slopes
Us	Urban land-Udorthents complex, smoothed, 0 to 15 percent slopes
VrC3 VtC3	Vertrees silty clay loam, 6 to 12 percent slopes, severely eroded  Vertrees-Urban land complex, 6 to 12 percent slopes, severely eroded
W	Water
WeB	Wellston silt loam, 2 to 6 percent slopes
WeC2	Wellston silt loam, 6 to 12 percent slopes, eroded
ZaB	Zanesville silt loam, 2 to 6 percent slopes
ZaC2	Zanesville silt loam, 6 to 12 percent slopes, eroded
ZuB	Zanesville-Urban land complex, 2 to 6 percent slopes

# CONVENTIONAL AND SPECIAL SYMBOLS LEGEND

### **CULTURAL FEATURES**


BOUNDARIES		MISCELLANEOUS CULTURAL FEATURES	
County or parish		Farmstead, house	•
Reservation (national forest or park, state forest or park, and large airport)	·	Church	İ
Field sheet matchline and neatline		School	i
AD HOC BOUNDARY (label) Small airport, airfield, park, oilfield,	Davis Airstrip	WATER FEATURES	
cemetery, or flood pool	POOL	DRAINAGE	
STATE COORDINATE TICK 1 890 000 FEET		Perennial, double line	
ROADS		Perennial, single line	
Divided (median shown if scale permits)		Intermittent	
Other roads		Drainage end	<b>→</b>
ROAD EMBLEM & DESIGNATIONS		MISCELLANEOUS WATER FEATURES	
Interstate	173	Spring Wet spot	~ <b>¥</b>
Federal	287	wei spoi	₹

\$2 1283

(label only)


### SPECIAL SYMBOLS FOR SOIL SURVEY


SOIL DELINEATIONS AND SYMBOLS	BaB BrB
Bedrock	TATATATATATATATATATATATATATATA
MISCELLANEOUS	
Rock outcrop (includes sandstone and sha	le) ∨
Severely eroded spot	=
Sinkhole	<b>♦</b>




North American Datum of 1983 (NAD83). GRS-80 Spheroid 1000-meter ticks: Universal Transverse Mercator, zone 16. Coordinate grid ticks and land division data, if shown, are approximately positioned. Digital data are available for this quadrangle.

QUARTER QUADRANGLE LOCATION





REEDYVILLE NW, (OVERSIZED) KENTUCKY 3.75 MINUTE SERIES SHEET NUMBER 1 OF 51



INDEX TO ADJOINING 3.75 MAPS


86° 22′30″ Joins sheet 12, Bristow NW SCALE 1:12000 This soil survey was compiled by the U.S. Department of Agriculture, Natural Resources Conservation Service. Base maps are orthophotographs prepared by the U.S. Department of Interior, Geological Survey, from 1993-1997 aerial photography. Hydrography information was acquired from the Natural Resources Conservation Service. BROWNSVILLE SW, KENTUCKY 3.75 MINUTE SERIES 0.5 SHEET NUMBER 6 OF 51 5 REEDYVILLE SE North American Datum of 1983 (NAD83). GRS-80 Spheroid 1000-meter ticks: Universal Transverse Mercator, zone 16. Coordinate grid ticks and land division data, if shown, are approximately positioned. Digital data are available for this quadrangle. Soil map delineations extending beyond the dashed white quadrangle neatline are for reference only and are included on adjacent map sheets. 11 BOWLING GREEN NORTH NE 11 12 13 12 BRISTOW NW 13 BRISTOW NE QUARTER QUADRANGLE LOCATION 0.5 INDEX TO ADJOINING 3.75 MAPS


37° 03′45″

86° 41′15″

North American Datum of 1983 (NAD83). GRS-80 Spheroid 1000-meter ticks: Universal Transverse Mercator, zone 16. Coordinate grid ticks and land division data, if shown, are approximately positioned. Digital data are available for this quadrangle.








SUGAR GROVE NE, KENTUCKY 3.75 MINUTE SERIES SHEET NUMBER 7 OF 51


86° 37′ 30″



North American Datum of 1983 (NAD83). GRS-80 Spheroid 1000-meter ticks: Universal Transverse Mercator, zone 16. Coordinate grid ticks and land division data, if shown, are approximately positioned. Digital data are available for this quadrangle.

QUARTER QUADRANGLE LOCATION





SMITHS GROVE NW, KENTUCKY
3.75 MINUTE SERIES
SHEET NUMBER 14 OF 51

86°11′15″


86° 07′30″



North American Datum of 1983 (NAD83). GRS-80 Spheroid 1000-meter ticks: Universal Transverse Mercator, zone 16. Coordinate grid ticks and land division data, if shown, are approximately positioned. Digital data are available for this quadrangle.

QUARTER QUADRANGLE LOCATION


0.5 0.5




SMITHS GROVE NE, KENTUCKY 3.75 MINUTE SERIES SHEET NUMBER 15 OF 51

North American Datum of 1983 (NAD83). GRS-80 Spheroid 1000-meter ticks: Universal Transverse Mercator, zone 16. Coordinate grid ticks and land division data, if shown, are approximately positioned. Digital data are available for this quadrangle.







SUGAR GROVE SE, KENTUCKY 3.75 MINUTE SERIES SHEET NUMBER 16 OF 51



KILOMETERS


Soil map delineations extending beyond the dashed white quadrangle neatline are for reference only and are included on adjacent map sheets.


INDEX TO ADJOINING 3.75 MAPS

This soil survey was compiled by the U.S. Department of Agriculture, Natural Resources Conservation Service. Base maps are orthophotographs prepared by the U.S. Department of Interior, Geological Survey, from 1993-1997 aerial photography. Hydrography information was acquired from the Natural Resources Conservation Service.

North American Datum of 1983 (NAD83). GRS-80 Spheroid 1000-meter ticks: Universal Transverse Mercator, zone 16. Coordinate grid ticks and land division data, if shown, are approximately positioned. Digital data are available for this quadrangle.







3.75 MINUTE SERIES SHEET NUMBER 26 OF 51

Soil map delineations extending beyond the dashed white quadrangle neatline are for reference only and are included on adjacent map sheets.



0.5

Soil map delineations extending beyond the dashed white quadrangle neatline are for reference only and are included on adjacent map sheets.

41 42 41 POLKVILLE SE 42 MEADOR SW

INDEX TO ADJOINING 3.75 MAPS


North American Datum of 1983 (NAD83). GRS-80 Spheroid 1000-meter ticks: Universal Transverse Mercator, zone 16. Coordinate grid ticks and land division data, if shown, are approximately positioned. Digital data are available for this quadrangle.


QUARTER QUADRANGLE LOCATION

This soil survey was compiled by the U.S. Department of Agriculture, Natural Resources Conservation Service. Base maps are orthophotographs prepared by the U.S. Department of Interior, Geological Survey, from 1993-1997 aerial photography. Hydrography information was acquired from the Natural Resources Conservation Service.

North American Datum of 1983 (NAD83). GRS-80 Spheroid 1000-meter ticks: Universal Transverse Mercator, zone 16. Coordinate grid ticks and land division data, if shown, are approximately positioned. Digital data are available for this quadrangle.







SOUTH UNION SE, KENTUCKY 3.75 MINUTE SERIES SHEET NUMBER 35 OF 51

Soil map delineations extending beyond the dashed white quadrangle neatline are for reference only and are included on adjacent map sheets.





86° 37′ 30″

INDEX TO ADJOINING 3.75 MAPS

North American Datum of 1983 (NAD83). GRS-80 Spheroid 1000-meter ticks: Universal Transverse Mercator, zone 16. Coordinate grid ticks and land division data, if shown, are approximately positioned. Digital data are available for this quadrangle.

QUARTER QUADRANGLE LOCATION






Soil map delineations extending beyond the dashed white quadrangle neatline are for reference only and are included on adjacent map sheets.

QUARTER QUADRANGLE LOCATION

0.5



Soil map delineations extending beyond the dashed white quadrangle neatline are for reference only and are included on adjacent map sheets.

INDEX TO ADJOINING 3.75 MAPS